

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:**

CC4/AXA18011794/R1PA3Q2

**Date:**

28/06/2021

REFERENCE

Handling Insurer: AXA Insurance Pte Ltd

Policy No:

P1680520

**Claimant Vehicle No :** PC3526A**Insured Vehicle No :**

SHD256M

Date of Loss: 09/06/2018

Nature of Claim:

TP

Claim No:

C0473936

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **PC3526A**

Make &amp; Model: KING LONG XMQ6118K5, 8.8 D 47 SEATERS (A)

Engine No: ISL89E5280B22036694

Reg. Date: 20/03/2015 (Man. Year: 2014)

Chassis No: LA6R1HSG2EB101510

Colour: Multi-colour

Odometer: 232986 km

Engine Capacity: 8849 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	11R22.5	Rear Tyre Size:	11R22.5 (D)
Front Left Side:	Firenza 8 mm	Rear Left Side:	Firenza 8/8 mm
Front Right Side:	Firenza 8 mm	Rear Right Side:	Firenza 8/8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	5,180.00	0.00	5,180.00	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,200.00	1,300.00	900.00	40.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>7,380.00</b>	<b>1,300.00</b>	<b>6,080.00</b>	<b>82.38</b>
<b>Global Sum Settlement (S\$)</b>		<b>0.00</b>		

INSPECTION

Date of Assignment: 27/06/2018

Date Inspected: 02/07/2018

Estimated Period of Repair: 5.0 days

Inspected At:

Almighty Automotive - Joo Koon (HQ)  
2C JALAN PESAWAT  
SINGAPORE 619359

---

**Adjuster:** MOHD RASUL**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 05 Dec 2019)	
<b>Parts:</b>	N/A	KING LONG XMQ6118K5 8.8 D 47 SEATERS (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for PC3526A)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*SIDE COMPARTMENT (RH)(CONSISTENT)	Repair	3,600.00 FS	*- FS
2	1		*REAR WHEEL ARCH COMPARTMENT (RH)(CONSISTENT)	Repair	1,580.00 FS	*- FS
					<b>Total Parts (S\$)</b>	<b>5,180.00</b>
						<b>0.00</b>

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	SPRAY PAINTING ON REAR AFFECTED AREA PORTION WITH ARTWORK	New	1,000.00	700.00
2	LABOUR & MISC.CHARGES:TO REMOVE THE AFFECTED PARTS & ALL RELEVANT ATTACHMENT & FITTINGS TO COMMENCE REPAIRS;CUT & WELD THE NECESSARY PARTS AS LISTED ABOVE:PANEL BEAT & RESHAPES THE AFFECTED AREAS:REPLACE THE DAMAGED COMPONENTS,REINSTALL & REALIGN ALL NECESSARY PARTS	New	1,200.00	600.00
<b>Gross Labour Cost (S\$)</b>			<b>2,200.00</b>	<b>1,300.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >