



## ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

### Repair Estimates

SLN 5714 A

Parts	(a) Cost / List Price Items	\$	4,641.85
	Plus/Less 25%	\$	1,160.46
	<b>Total of Cost / List</b>	\$	<b>3,481.39</b>
	(b) Nett Price Items		
	Less		
	<b>Total of Nett Item</b>		
	(c) Special Nett Items		
<b>Total Parts Cost</b>			
Labour		\$	3,620.00
<b>Total</b>		\$	<b>7,101.39</b>

The above total will be subjected to 7% G.S.T.

#### LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary items must be surveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

Name of Surveyor : Kenneth  
Company : LKK  
Survey conducted on : 8/7/18 at \_\_\_\_\_

#### Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 08 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ \_\_\_\_\_

(e) Signature of surveyor : Sc Date: 8/7/18



## ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

### Spare Parts

Vehicle No. : **SLN 5714 A**  
Make & Model : **TOYOTA PRIUS**  
Chassis No : **JTDKB3FU403557555**

Submit By : **Carmen Lim**  
Year Manufacture : **2017**  
Engine No. :  
**Cost / List**

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Front bumper <i>Bu</i>	1	\$450.80		—
2	Front bumper clip <i>me</i>	10	\$40.00		✓
3	Front bumper side retainer LH <i>sm</i>	1	\$107.20		X
4	LH front fender <i>Ry</i>	1	\$868.70		✓
5	LH front fender undershield	1	\$195.60		?
6	LH front fender undershield clip	10	\$25.00		?
7	LHF fender wording "HYBRID" <i>me</i>	1	\$44.17		✓
8 RH	<del>LH</del> front door <i>Ry</i>	1	\$1,121.75		✓
9 RH	<del>LH</del> front door weatherstip <i>sm</i>	1	\$211.69		X
10 RH	<del>LHF</del> door glass outer moulding <i>sm</i>	1	\$121.75		X
11	RH rear door <i>Ry</i>	1	\$1,121.75		✓
12	RH rear door weatherstip <i>sm</i>	1	\$211.69		X
13	RHR door glass outer moulding	1	\$121.75		?
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



## ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

### Labour

Vehicle No. : **SLN 5714 A** Submit By : **Carmen Lim**  
Make & Model : **TOYOTA PRIUS** Year of Manufacture : **2017**

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (FRONT BUMPER,LHF FENDER,LHF DOOR, RHR DOOR)	\$1,200.00	6001
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (FRONT BUMPER,LHF FENDER,LHF DOOR, RHR DOOR)	\$1,200.00	9001
3	To check wiring	\$50.00	201
4	To do wheel alignment.	\$120.00	601
5	To remove & refit Door trim, door glass, window regulator, door lock to assist work load.(LHF DOOR , RHR DOOR)	\$300.00	601
6	To tuff coat.	\$150.00	601
7	To do art work. <i>Mr</i>	\$600.00	2005N

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.