

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

| PRE-REPAIR INSPECTION REPORT | | | | | |
|--|---|---|----------------|-----------------|-------------------------|
| SOM | OMPO INSURANCE SINGAPORE PL | | | CS3/SMO18011827 | /Gz4be2 |
| 50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623 | | | Date: | 19-07-2018 | |
| | | | Code: | SMO | |
| 1. Policy Particulars :- (THIRD PARTY CLAIM) | | | | | |
| | Insured Veh. | SLX 5943C | Veh. Inspected | | JSM 1744 |
| | Policy No. | | Coverage (\$) | | 0.00 |
| | Claim No. | CMTD1802695/THE | Excess (\$) | | 0.00 |
| | Assign From | GRACE TEO | Assig | n Date | 28/06/2018 |
| 2. Vehicle Particulars & Condition | | | | | |
| | Make & Model | YAMAHA 135LC | c.c | | 135 |
| | Engine No. | HIDDEN | Year of Reg. | | |
| | Chassis No. | | Colour | | BLACK |
| | Odometer | 10857 KM | Steering | | IN ORDER |
| | Brakes | IN ORDER | Modifi | cation | NIL |
| | General | GOOD | | | |
| 3. Conditions of Tyres | | | | | |
| | | Size | Make | | Balance |
| | R/H Front Tyre | 70/90-17 | MAXXI | S | 4 mm |
| | L/H Front Tyre | | | | mm |
| | R/H Rear Tyre | 80/90-17 | MAXXI | S | 4 mm |
| | L/H Rear Tyre | | | | mm |
| 4. Description of Damages | | | | | |
| | THE VEHICLE SUS PORTION. | STAINED DAMAGES AT THE N/S BODY AND FRONT | | | |
| 5. General Information | | | | | |
| | Accident Date | 23/06/2018 | Inspec | t Date / Time | 29/06/2018 (02:30 PM) |
| | Survey held at | ASIA MOTORSPORTS SOLUTION PTE LTD | | | |
| | 568 GEYLANG ROAD SINGAPORE 389514 | | | | |
| 5a. Remarks | | | | | |
| | A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$3,800 | | | | |
| 5b. Estimate Days of Repair | | | | | |
| | ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days | | | | |

Report Ref No. CS3/SMO18011827/Gz4be2

Inspected By

XING GUO QIANG

M.MATAI, AMSAE-A

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

Automotive Assessor REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.