

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG18011890/DEA3Q2
Date: 10/08/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100365298
Claimant Vehicle No :	SHA3772K	Insured Vehicle No :	SFS14P
Date of Loss:	28/06/2018	Nature of Claim:	TP
		Claim No:	3887500669SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA3772K	Engine No:	D4FDEU409570
Make & Model:	HYUNDAI I40, 1.7 D CRDi (A)	Chassis No:	KMHLB41UMEU052487
Reg. Date:	29/04/2014 (Man. Year: 2014)	Odometer:	564861 km
Colour:	Blue		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	31,342.16	27,084.32	4,257.84	13.59
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,610.00	3,270.00	1,340.00	29.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	35,952.16	30,354.32	5,597.84	15.57
Approved Total (Overridden) (S\$)		24,000.00		

(S\$)	35,952.16	24,000.00	11,952.16	33.24
+ GST 7.00/7.00% (S\$)	2,516.65	1,680.00	836.65	33.24
Nett Amount (S\$)	38,468.81	25,680.00	12,788.81	33.24
+ Loss of Use (18.0 x S\$50.00/day) (S\$)		900.00		
+ Car Rental (18.0 x S\$117.28/day) (S\$)		2,111.04		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		28,693.04		
Global Sum Settlement (S\$)		24,150.00		

INSPECTION

Date of Assignment: 29/06/2018

Date Inspected: 29/06/2018

Inspected At:

Chunni Motor Work Pte Ltd (HQ)
 Blk 10 Ang Mo Kio Industrial Park 2A, #03-19 AMK Autopoint
 Singapore 568047

Estimated Period of Repair: 14.0 days

Adjuster: BRYAN TANI**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER COVER	Dented	562.30 FL	*562.30 FL
2	1		*FRONT BUMPER BRACKET RH	Serviceable	24.60 FL	*- FL
3	1		*HEADLAMP SUPPORT PANEL ASSY	Cracked	1,067.50 FL	*1,067.50 FL
4	1		*HEADLAMP (RH)	Mounting Broken	1,388.00 FL	*1,388.00 FL
5	1		*RADIATOR EXPANSION TANK	Not Necessary	48.00 FL	*- FL
6	1		*FRONT FENDER (RH)	Buckled	619.00 FL	*619.00 FL
7	1		*FRONT FENDER APRON PANEL (RH)	Dented	1,575.50 FL	*1,575.50 FL
8	1		*FRONT FENDER SHIELD (RH)	Deformed	169.80 FL	*169.80 FL
9	1		*FRONT DOOR (RH)	Buckled	1,403.00 FL	*1,403.00 FL
10	1		*FRONT DOOR RUBBER	Necessary	290.50 FL	*290.50 FL
11	1		*FRONT DOOR GEAR/REGULATOR (RH)	Cracked	785.50 FL	*785.50 FL
12	1		*FRONT DOOR HINGE UPPER (RH)	Bent	53.40 FL	*53.40 FL
13	1		*FRONT DOOR HINGE LOWER (RH)	Bent	53.40 FL	*53.40 FL
14	1		*FRONT DOOR CHECK (RH)	Bent	110.15 FL	*110.15 FL
15	1		*FRONT DOOR INNER LOCK (RH)	Damaged	348.95 FL	*348.95 FL
16	1		*FRONT DOOR KEY LOCK SET (RH)	Not Necessary	186.50 FL	*- FL
17	1		*FRONT DOOR OUTER HANDLE (RH)	Broken	98.75 FL	*98.75 FL
18	1		*FRONT DOOR OUTER MOULDING (LRH)	Bent	63.70 FL	*63.70 FL
19	1		*FRONT DOOR MORROR (RH)	Not Necessary	980.50 FL	*- FL
20	1		*FRONT DOOR POWER MOTOR	Not Necessary	950.90 FL	*- FL
21	1		*DOOR CENTRE PILLAR OUTER (RH)	Dented	1,786.20 FL	*1,786.20 FL
22	1		*FRONT WHEEL RIM (RH)	Distorted	351.90 FL	*351.90 FL
23	1		*FRONT WHEEL HUB CAP (RH)	Cut	150.70 FL	*150.70 FL
24	1		*FRONT WHEEL BEARING	Damaged	258.50 FL	*258.50 FL
25	1		*FRONT SHOCK ABSORBER (ASSY)(RH)	Distorted	342.20 FL	*342.20 FL
26	1		*FRONT SHOCK ABSORBER MOUNTING (RH)	Not Necessary	75.10 FL	*- FL
27	1		*FRONT DRIVE SHAFT (RH)	Distorted	1,069.55 FL	*1,069.55 FL
28	1		*RACK & PINION ASSY	Damaged	2,184.00 FL	*2,184.00 FL
29	1		*STG TIE END	Distorted	69.50 FL	*69.50 FL
30	1		*FRONT SUSPENSION LOWER ARM (RH)	Distorted	715.10 FL	*715.10 FL
31	1		*KNUCKLE ARM (RH)	Distorted	582.95 FL	*582.95 FL
32	1		*ENGINE UNDER COVER	Not Necessary	343.10 FL	*- FL
33	1		*ENGINE CROSSMEMBER	Distorted	2,236.90 FL	*2,236.90 FL
34	1		*DASHBOARD COMPLETE	Cracked/Deformed	2,688.00 FL	*2,688.00 FL
35	1		*ABS SENSOR	Not Necessary	261.50 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*REAR BUMPER	Repair	603.60 FL	*- FL
37	10		*REAR BUMPER CLIP	Serviceable	22.00 FL	*- FL
38	1		*REAR BUMPER BRACKET RH	Not Necessary	49.00 FL	*- FL
39	1		*REAR FENDER WITH HOUSING (RH)	Dented	4,736.80 FL	*4,736.80 FL
40	1		*REAR FENDER INNER LINING (RH)	Serviceable	164.40 FL	*- FL
41	1		*REAR WINDSCREEN MOULDING	Necessary	60.00 FL	*60.00 FL
42	1		*REAR DOOR (RH)	Buckled	1,351.10 FL	*1,351.10 FL
43	1		*REAR DOOR RUBBER (RH)	Necessary	280.50 FL	*280.50 FL
44	1		*REAR DOOR OUTER MOULDING (LRH)	Serviceable	212.15 FL	*- FL
45	1		*REAR DOOR GEAR/REGULATOR (RH)	Cracked	785.50 FL	*785.50 FL
46	1		*REAR DOOR POWER MOTOR (RH)	Not Necessary	530.50 FL	*- FL
47	1		*ROCKER PANEL OUTER GARNISH (RH)	Cracked	483.60 FL	*483.60 FL
48	1		*REAR TYRE RIM (RH)	Distorted	351.90 FL	*351.90 FL
49	1		*REAR WHEEL HUP-CAP (RH)	Bent	150.70 FL	*150.70 FL
50	1		*REAR WHEELBEARING ING & HUB	Damaged	401.40 FL	*401.40 FL
51	1		*REAR TRAILING ARM (RH)	Distorted	120.00 FL	*120.00 FL
52	1		*REAR ASSIST (RH)	Distorted	120.00 FL	*120.00 FL
53	1		*REAR SHOCK ABSORBER (RH)	Distorted	342.20 FL	*342.20 FL
54	1		*REAR SHOCK ABSORBER MOUNTING (RH)	Not Necessary	57.70 FL	*- FL
55	1		*STABILIZER BAR	Not Necessary	204.60 FL	*- FL
56	1		*STABILIZER LINK	Not Necessary	68.15 FL	*- FL
57	1		*REAR UPPER ARM (RH)	Distorted	335.75 FL	*335.75 FL
58	1		*REAR LOWER ARM (RH)	Distorted	204.35 FL	*204.35 FL
59	1		*REAR KNUCKLE ARM (RH)	Distorted	574.80 FL	*574.80 FL
60	1		*FRONT WINDSCREEN PILLAR OUTER (RH)	Dented	1,843.10 FL	*1,843.10 FL
61	1		*FRONT DOOR COMFORT LOGO (RH)	Cut	75.00 FS	*75.00 FS
62	1		*FRONT DOOR ADVERTISEMENT LOGO (RH)	Cut	100.00 FS	*100.00 FS
63	1		*FRONT TYRE (RH)	Serviceable	216.00 FS	*- FS
64	1		*REAR BUMPER ADVERTISEMENT LOGO	Necessary	50.00 FS	*50.00 FS
65	2		*REAR FENDER ADVERTISEMENT LOGO (LH/RH)	Necessary	200.00 FS	*200.00 FS
66	1		*REAR WINDSCREEN SEALANT	Necessary	46.00 FS	*46.00 FS
67	1		*REAR DOOR COMFORTDELGRO & APPS STICKER (RH)	Necessary	80.00 FS	*80.00 FS
68	1		*REAR TYRE (RH)	Serviceable	216.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	38,931.95	33,717.65
- List Item Discount on L Items 20.00/20.00% (S\$)	7,589.79	6,633.33
Total Parts (S\$)	31,342.16	27,084.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	1,700.00	1,200.00
2	SPRAY PAINTING CHARGE	New	1,400.00	1,000.00
3	WIRING CHARGE	New	50.00	30.00
4	TUFF KOTE	New	80.00	60.00
5	TOWING CHARGE	New	50.00	-
6	REMOVE/REFIX CUSHION & UPHOLSTERY REAR	New	80.00	80.00
7	REMOVE/REFIX REAR WINDSCREEN GLASS	New	100.00	80.00
8	REMOVE/REFIX REVERSE SENSOR	New	80.00	40.00
9	REMOVE/REFIX UNDERCARRIAGE (RR)	New	200.00	150.00
10	TRANSFER OF DOOR	New	160.00	120.00
11	REMOVE/REFIX UNDERCARRIAGE (FRT)	New	200.00	150.00
12	FOUR WHEEL ALIGNMENT	New	120.00	60.00
13	REMOVE/REFIX DASHBOARD	New	200.00	180.00
14	REMOVE/REFIX FRONT WINDSCREEN GLASS	New	100.00	80.00
15	REMOVE/REFIX CUSHION & UPHOLSTERY FRONT	New	90.00	40.00
Gross Labour Cost (S\$)			4,610.00	3,270.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >