# AH LIM MOTOR COMPANY

### 10 ANG MO KIO INDUSTRIAL PARK 2A #01-09 AMK AUTOPOINT Singapore 568047

Tel: 6483 1244

Fax: 6483 6170 Email: ahlimmc@singnet.com.sg

GST Reg No: M9-0009639-E

TP INSURER: SNG LEE BOON India International Insurance Pte Ltd (HQ)

SURVEYOR COPY

Singapore

Claimant Insurer:

Direct Asia Insurance (Singapore) Pte Ltd

PARTICULARS OF CLAIM

Claim Type:

THIRD PARTY

Ref. No:

Policy No:

Date of Loss:

Vehicle Reg. No.:

SLW4150K

Driveable?

Party At Fault:

**UNKNOWN** 

Driver (TP):

CHEROL MUKRI MOHAMMED

SHAJID

Make/Model:

AUDI A6, 2.0 TFSI MU (A)

Vehicle Reg. Date:

08/06/2009

20/06/2018

Vehicle Colour:

GREY

Engine No:

BPJ148730

Chassis No:

WAUZZZ4F39N055569

Odometer:

0 KM

Nor Where

Paint Type:

List Item Discount:

10.00 %

Total Loss?

Est. Duration of Repair

5/ 2dan

(day)

Description of

Accident/Loss

REFER TO THE SKETCH PLAN BY DRIVER

Remarks:

CAR NOT IN - TO BE ARRANGE

Present Location:

----

AH LIM MOTOR COMPANY (AMK)

COST OF CLAIMS		Amount
Parts		6,291.63
Miscellaneous Items		10.00
Labour		1,520.00
Paintwork Labour		0.00
Towing		0.00
	Gross Total (S\$)	7,821.63
	+ GST 7.00% (S\$)	547.51
	Nett Amount (S\$)	8,369.14

This claim is handled by: ZILA

Generated using Merimen e-Claims Internet Estimation & Adjusting System

#### REPAIR DETAILS

Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 22 Jun 2018)

Parts:

143

AUDI A6 2.0 TFSI MU (A) (Catalogue:Merimen Singapore 1.0)

Labour:

Repairer's

(Price-denominated Standard List)

Print Code: Ah Lim Motor Company/SLW4150K/22/06/2018 14:25

Validity:

These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers

with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### Estimates on Parts

No.	Qty	Part No.	Particulars		%Disc	%Depr	Amount
1	1		*FRONT GRILLE	Su	10.00	0.00	*593.65 FL >
2	1		*FRONT GRILLE	Sh	10.00	0.00	*93.65 FL X
3	1		*HEADLAMP WITH HID LH	an	10.00	0.00	*2,436.25 FL *
4	1		*HEADLAMP LOWER BEAM LH ( SIDE)		10.00	0.00	*24.10 FL *
5	2		*HEADLAMP CLIPS	m	10.00	0.00	*73.80 FL
6	1		*FRONT BUMPER	n	10.00	0.00	*1,842.45 FL
7	1		*FRONT BUMPER SIDE RETAINER LH	Sin	10.00	0.00	*37.65 FL >
8	12		*FRONT BUMPER CLIPS	Nn	10.00	0.00	*30.00 FL >
9	1		*FRONT BUMPER LOWER SIDE GRILLE LH	SM	10.00	0.00	*86.35 FL >
10	2		*FRONT BUMPER LOWER SIDE GRILLE CHROME MOULDING	Sm	10.00	0.00	*462.90 FL x
11	1		*FOGLAMP LH	1	10.00	0.00	*286.75 FL ×
12	1		*FRONT FENDER LH	n	10.00	0.00	*998.15 FL 🖈
13	10		*FRONT FENDER COWLING CLIPS	1~	10.00	0.00	*25.00 FL /
F=Fra	nchise	part. L=ListIt	temDisc.				,
			Sub Total (S\$)			6,990.70	
			- List Item Discount on L Items (S\$)			699.07	
			Total Par	ts (S\$)			6,291.63

Ah Lim Motor Company/SLW4150K/22/06/2018 14:25. Not valid without Reference section. Generated using Merimen e-Claims IEAS

> LKK Auto Consultants hence notify the Repairer of the following:

- . To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- · Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

## Estimates on Miscellaneous Items

No Qt	ty Particulars		Amount
Miscella	aneous Items		
1 1	OD/TP Case (Insurer)		10.00
		Sub Total (S\$)	10.00

## Estimates on Labour

No	Particulars	Lab.Type	Amount
Labo	our Items		
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING; WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS; TEST AND RECTIFY FOR PROPER FUNCTIONING.	New	20/ 40.00
2	TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.	New	Ma 80.00
3	TO REMOVE AND REINSTALL/REPLACE WIPER COMPARTMENT SUCH AS WIPER MOTORS AND WIPER BLADES.	New	69 280.00
4	TO SPRY ANTI-RUST COATING ON AFFECTED AREAS.	New	na 120.00
	TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD. TO KNOCK & REPAIR HEADLAMP TOP PANEL LH INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	New	259 500.00
6	TO SPRAY FRONT BUMPER; FRONT FENDER LH.	New	4001 500.00
	Gross Labou	r Cost (S\$)	1,520.00

Ah Lim Motor Company/SLW4150K/22/06/2018 14:25. Not valid without Reference section. Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >