

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTMSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807**Our File No:** CS/MSG18011941/UTD3E2**Date:** 14/11/2018REFERENCE

Insured/Claimant:	TEO HOCK HENG MARTIN	Policy No:	A28861354QMY
Date of Loss:	23/06/2018	Nature of Claim:	OD
		Claim No:	562301

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKX8620B	Engine No:	CYG007214
Make & Model:	AUDI A6, 1.8 TFSI Ultra (PI) (NAV) (A)	Chassis No:	WAUZZZ4G7GN034391
Reg. Date:	30/12/2015 (Man. Year: 2015)	Odometer:	40574 km
Colour:	White		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	S\$118,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/35ZR20	Rear Tyre Size:	255/35ZR20
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	34,391.50	23,226.20	11,165.30	32.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,400.00	3,390.00	6,010.00	63.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	43,791.50	26,616.20	17,175.30	39.22
- Excess (S\$)	750.00	750.00	0.00	0.00
(S\$)	43,041.50	25,866.20	17,175.30	39.90
+ GST 7.00/7.00% (S\$)	3,012.91	1,810.63	1,202.28	39.90
Nett Amount (S\$)	46,054.41	27,676.83	18,377.58	39.90

INSPECTION

Date of Assignment: 02/07/2018

Date Inspected: 03/07/2018 Inspected At:

Bluewel Automotive Service Pte Ltd (HQ)
1 KAKI BUKIT AVE 6 AUTOBAY @ KAKI
BUKIT #01-28/37/53/55 SINGAPORE
417883
Singapore 417883

Estimated Period of Repair: 10.0 days

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 14 Nov 2018)
Parts: 143	AUDI A6 1.8 TFSI Ultra (PI) (NAV) (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKX8620B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT LH FENDER (WCP)	Badly Dented	570.00 F	*570.00 F
2	1		*FRONT LH DOOR (WCP)	Badly Dented	1,498.00 F	*1,498.00 F
3	1		*FRONT LH DOOR SEAL (WCP)	Necessary	88.00 F	*88.00 F
4	1		*FRONT LH DOOR LOWER SEAL (WCP)	Not Necessary	72.00 F	*- F
5	1		*REAR LH DOOR (WCP)	Repair	1,498.00 F	*- F
6	1		*REAR LH DOOR SEAL (WCP)	Not Necessary	101.00 F	*- F
7	1		*REAR LH DOOR LOWER SEAL (WCP)	Not Necessary	71.00 F	*- F
8	1		*STEERING AIRBAG (WCP)	Activated	2,045.00 F	*2,045.00 F
9	1		*LH AIRBAG (WCP)	Activated	2,486.00 F	*2,486.00 F
10	1		*LH SIDE AIRBAG (WCP)	Not Necessary	895.00 F	*- F
11	1		*LH ROOF AIRBAG (WCP)	Activated	1,033.00 F	*1,033.00 F
12	1		*RH ROOF AIRBAG (WCP)	Activated	1,033.00 F	*1,033.00 F
13	1		*ROOF LINING (WCP)	Warped/Deformed	1,305.00 F	*1,305.00 F
14	1		*LH SEAT BELT (WCP)	Activated	706.00 F	*706.00 F
15	1		*RH SEAT BELT (WCP)	Activated	555.00 F	*555.00 F
16	1		*LH SEAT BELT BUCKLE (WCP)	Activated	122.00 F	*122.00 F
17	1		*RH SEAT BELT BUCKLE (WCP)	Activated	122.00 F	*122.00 F
18	1		*DASHBOARD (WCP)	Torn	2,930.00 F	*2,930.00 F
19	1		*FRONT LH UPPER ARM (WCP)	Bent	264.00 F	*264.00 F
20	1		*REAR LH UPPER LINK (WCP)	Bent	264.00 F	*264.00 F
21	1		*FRONT LH CONTROL ARM (WCP)	Bent	264.00 F	*264.00 F
22	1		*FRONT LH WISHBONE ARM (WCP)	Cracked	477.00 F	*477.00 F
23	1		*FRONT LH KNUCKLE ARM (WCP)	Cracked	725.00 F	*725.00 F
24	1		*FRONT ABSORBER (WCP)	Bent	279.00 F	*279.00 F
25	1		*SET FRONT LH ABSORBER MOUNTING (WCP)	Necessary	43.00 F	*43.00 F
26	1		*SUBFRAME (WCP)	Serviceable	2,172.00 F	*- F
27	1		*LOWER ARM BALL JOINT (WCP)	Not Necessary	92.00 F	*- F
28	1		*LH ABSORBER LOWER FORK (WCP)	Bent	113.00 F	*113.00 F
29	1		*STAB LINK (WCP)	Bent	66.00 F	*66.00 F
30	1		*STAB BAR (WCP)	Not Necessary	295.00 F	*- F
31	1		*STAB BUSH (WCP)	Not Necessary	7.00 F	*- F
32	1		*STAB BUSH BRACKET (WCP)	Not Necessary	6.00 F	*- F
33	1		*TIE ROD END (WCP)	Bent	106.00 F	*106.00 F
34	1		*RACK END (WCP)	Not Necessary	50.00 F	*- F
35	1		*AIRBAG CONTROL UNIT (WCP)	Activated	1,397.00 F	*1,397.00 F
36	1		*FRONT LH INNER SHIELD (SMALL)(WCP)	Torn	101.00 F	*101.00 F
37	1		*FRONT LH INNER SHIELD REAR (WCP)	Torn	115.00 F	*115.00 F
38	1		*FRONT WHEEL HOUSING SCREW SET (WCP)	Not Necessary	22.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
39	1		*REAR LH SEAT BELT (WCP)	Serviceable	295.00 F	*- F
40	1		*REAR RH SEAT BELT (WCP)	Serviceable	295.00 F	*- F
41	1		*REAR SEAT BELT CENTRE (WCP)	Serviceable	295.00 F	*- F
42	1		*REAR LH SEAT BUCKLE & CENTRE (WCP)	Not Necessary	170.00 F	*- F
43	1		*REAR RH SEAT BUCKLE (WCP)	Not Necessary	170.00 F	*- F
44	1		*LH SIDE SKIRT (WCP)	Repair	351.00 F	*- F
45	1		*FRONT BUMPER (WCP)	Cut/Bent	1,085.00 F	*1,085.00 F
46	1		*FRONT FENDER STICKER FOIL (WCP)	Not Necessary	46.00 F	*- F
47	1		*FRONT FENDER BRACKET (WCP)	Not Necessary	32.00 F	*- F
48	1		*FENDER CLOSING ELEMENT (WCP)	Not Necessary	20.00 F	*- F
49	1		*UPPER DOOR HINGE (WCP)	Not Necessary	47.00 F	*- F
50	1		*LOWER DOOR HINGE (WCP)	Not Necessary	47.00 F	*- F
51	1		*LH DOOR HANDLE (WCP)	Repair	235.00 F	*- F
52	1		*BATTERY CUT OFF FUSES (WCP)	Activated/Damaged	268.00 F	*268.00 F
53	1		*STEERING CLOCK SPRING (WCP)	Activated	398.00 F	*398.00 F
54	1		*FRONT WHEEL BEARING (WCP)	Necessary	286.00 F	*286.00 F
55	2		*WASHER TANK (WCP)	Damaged/Necessary	148.00 F	*148.00 F
56	1		*ESP SENSOR (WCP)	Not Necessary	1,553.00 F	*- F
57	1		*FRONT LH TYRE (\$250.00)(50%)(LOCAL PURCHASE)	Cut	770.00 FS	*125.00 FS
58	1		*FRONT LH SPORT RIM (LOCAL REPAIR)	Cut	919.60 FS	*120.00 FS

F=Franchise part. S=SpcNett.

Sub Total (\$\$) 31,418.60 21,137.00
+ Margin on L,N Items 10.00/10.00% (\$\$) 2,972.90 2,089.20

Total Parts (\$\$) 34,391.50 23,226.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING	New	150.00	120.00
2	REMOVE & REFIT FRONT DASHBOX ASSY	New	800.00	350.00
3	REMOVE & REFIT AIRBAG,ROOFING AIRBAG,SEAT BELT,CONTROL UNIT & COMPUTER RES	New	1,800.00	380.00
4	REMOVE & REFIT UNDERCARRIAGE	New	800.00	350.00
5	REMOVE & REFIT FRONT & REAR LH SIDE,KNOCKING,WELDING,CUT & JACK CHASSIS FRAME	New	2,800.00	1,000.00
6	RESPRAY PAINTING FRONT & REAR LH SIDE,TOUCH-UP & POLISHING	New	2,800.00	1,080.00
7	ELECTRICAL & FOCUS WIRING	New	150.00	30.00
8	COMPUTERISED & WHEELS ALIGNMENTS	New	100.00	80.00
Gross Labour Cost (S\$)			9,400.00	3,390.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >