

27/05/2018

ASS. REC. BY:

REF: CS/FCI18011942 / Avd3n2 Special Instruction

Surveyor

Adrian

ASSIGNMENT (Office)

(WS)

From (Person):

Sithara

of

FCI

Date/Time: 02/07/18 @ 9.58am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBA 9459Y

Insured:

SHC 0501K

at Workshop m/s

MCS Garage

Tel:

92700917

of

10 Kaki Bukit Road 2 # 03-25

Policy No:

Claim No:

D18005102MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

27/06/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS (up)

H.O.D. Endorsement:

Date/Time:

11.12am @ 2/7/18

Person Contacted:

Kendrick

Vehicle IN/OUT

Date/Time

Action/Instruction

(✓) Estimate

GBA 9459Y - NA / EQ I 18011846 / h4

DUA: 27/06/2018

SHC 0501K - NA / EQ I 18011846 / h4

DUA: 27/06/2018

3/7/18

Informed FCI pending workshop est via email

13/11/18

Adrian confirmed LS \$ 11,500 (Red 24,569.17, 68%)

13/11/18

Email preli revised to FCI

(08/11/13) wef

ASS. REC. BY:

REF: FCI

ASSIGNMENT

From:

Date: 02/07/18

Veh No:

GBA9459Y

Yr Regn:

108

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Estimated Cost:

ON TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

GBA9459Y

at Workshop m/s

MCS Garage

of 10 Kalki Bkt Rd 2 # 03-25 First Ear Centre

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS^{up}

Date:

Person Contacted:

Vehicle: IN / OUT

Truck / Trailer or

Make:

Mit two

c.c

2977

Colour

white

A/C: Insured / Std / NI / NA

No. Reading

198519

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

FB70BBA

10439

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

155 R15C

R:

155 R15C

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Ohtsu

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

02/07/18

Survey held at

MCS Garage

Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TR 1st Cap.

MV: \$30K (EST) LTA: \$18,147 (EST) NV: \$11,853

RECEIVED 14 NOV 2018

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2) 14/11 - typist

Report Format :

CWS

Lump Sum / I.B.I. (\$

11,500)

Days Of Repair:

10

Resurvey No. of Trip:

1

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

25x15=375

170+375

50

50

78

723



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18005102MFSH
Our ref: CS/FCI18011942/Avd3

Date : 2/11/2018

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LTD

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. GBA 9459Y


We thank you for your instruction on 2/7/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 2/7/2018 at the premises of M/s MCS GARAGE and have the following to report:-

Workshop Estimate Amount	: S\$36,069.17
Revised Estimate Amount	: S\$11,500.00 (LUMP SUM)
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the front portion



Comments/Present Status:
Damages Consistent

Yours faithfully,

ADRIAN LING WAI PING
B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	29-06-2018	Our Ref No. D18005102MFSH
Accident Date	27-06-2018	Claim Type. Third Party
Insured Vehicle	SHC0501K	Third Party Vehicle. GBA9459Y
Survey Location	10 KAKI BUKIT ROAD 2 #03-25 FIRST EAST CENTRE	11:12am kendrick vehicle
Contact Person.	MR KENDRICK	
Contact No.	92700917/ 92700917	Fax No. 0
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	MCS GARAGE	Attention. NIL
Cc : TP Solicitor	SATWANT & ASSOCIATES	TP Solicitor Fax No. 62995541
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/241926)



PRI Documents



Close



PRI Header Details

Claim No	D18005102MFSH	Policy No	D-18088937MFSH	Claimant S.No & Name	1 & SATWANT
Workshop Name	MCS GARAGE (Contact Person : MR KENDRICK)	Survey Location & Contact Details	10 KAKI BUKIT ROAD 2 #03-25 FIRST EAST CENTRE Mobile: 92700917 , Phone: 92700917 , Fax: 0 EmailId: MARGARETLIM@SATWANTLAW.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHC0501K	TP Vehicle No	GBA9459Y
PRI Recieved Date	29-06-2018 06:06:46 PM	Surveyor Appointed Date	02-07-2018 09:57:22 AM	Surveyor Accept Date	02-07-2018 1

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	02-07-2018	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

Upload Multiple Documents	
File Name	Action

Surveyor Job Remarks

Remarks		Save
---------	----------------------	-------------------------------------

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Tuesday, 13 November 2018 5:37 PM
To: 'Claim Workflow System'
Cc: 'SITHARA@MSFIRSTCAPITAL.COM.SG'; SUR
Subject: RE: SURVEY ASSESSMENT - D18005102MFSH/1, GBA 9459Y
Attachments: GBA 9459Y PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle GBA 9459Y
Date of survey: 2/7/2018
Number of days : 10 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAUTO)
Sent: Tuesday, 3 July 2018 8:43 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>
Cc: SITHARA@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18005102MFSH/1, GBA 9459Y

Dear Sir/Madam,

Please be informed that we have inspected the vehicle GBA 9459Y on 2/7/2018.

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Monday, 2 July 2018 11:14 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: SITHARA@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18005102MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]

Sent: Monday, 2 July 2018 9:58 AM

To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; SITHARA@MSFIRSTCAPITAL.COM.SG

Subject: PRI: SURVEY ASSESSMENT - D18005102MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Tuesday, 3 July 2018 8:43 AM
To: 'Claim Workflow System'
Cc: SITHARA@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18005102MFSH/1, GBA 9459Y

Dear Sir/Madam,

Please be informed that we have inspected the vehicle GBA 9459Y on 2/7/2018.

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Monday, 2 July 2018 11:14 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: SITHARA@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18005102MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Monday, 2 July 2018 9:58 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; SITHARA@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18005102MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team

Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



AVG

This email has been checked for viruses by AVG antivirus software.
www.avg.com

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Business
Owner ID: 3303B

Vehicle Details

Vehicle No.: GBA9459Y
Vehicle to be Exported: No
Intended Deregistration Date: 02 Nov 2018
Vehicle Make: MITSUBISHI
Vehicle Model: FB70BB1SRDEA
Primary Colour: White
Manufacturing Year: 2008
Engine No.: 4M42A56199
Chassis No.: FB70BBA10439
Maximum Power Output: -
Open Market Value: \$23,772.00
Original Registration Date: 07 Apr 2008
First Registration Date: 07 Apr 2008
Transfer Count: 2
Actual ARF Paid: \$1,189.00

Intended PARF Rebate Details

PARF Eligibility: No
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 06 Apr 2023
COE Category: C - Goods Vehicle & Bus
COE Period(Years): 5
PQP Paid: \$18,773.00
COE Rebate Amount: \$16,624.00
Total Rebate Amount: \$16,624.00

Message

Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.

The information contained herein is correct as at 02 Nov 2018

OK

$$\begin{aligned}
 \text{DOR: } & 27/6/18 \\
 \text{PARF: } & \text{NIL} \\
 \text{COE} &= \text{QP} \times \frac{\text{bal motor}}{5 \text{ yrs}} \\
 &= 18773 \times \frac{58}{60} \\
 &= 18147.73 \\
 \text{LTA} &= \text{PARF} + \text{COE} \\
 &= 18147.73 \\
 \text{~LTA} &= 18147
 \end{aligned}$$

MV: 30K.

FB70BBA10439.

MCS GarageTP 1st Cop
VeronP/E ~~Am~~ Adrian10 Kaki Bukit Road 2 #03-25, First East Centre Singapore 471868
Tel: 9270 0917 6538 4322

Vehicle No.: GBA 9459Y

Model: MITSUBISHI CANTER

QTY List Price:**Prices \$**

1	Front windscreen glass <i>shattered</i>	1413.40 ✓
1	Front windscreen rubber <i>new</i>	441.54 320.
1	Front windscreen pillar trim- RH <i>new</i>	182.63 x.
1	Front wiper panel garnish <i>cut</i>	619.25 ✓
2	Front wiper arm @ 89.92 <i>RH cut</i>	179.84 89.92
1	Front wiper motor <i>new</i>	415.72 x.
1	Front wiper panel sticker "CANTER" <i>new</i>	81.52 ✓
1	Front side mirror with stay- RH <i>new</i>	711.56 408.
1	Front side mirror stay cover <i>cut</i>	126.20 ✓
1	Front cab panel <i>Distorted</i>	1064.66 ✓
2	Front corner panels- R/L @ 251.62 <i>RH Distorted</i>	503.24 251.62.
1	Front grille assy <i>cracked</i>	453.63 ✓
2	Front headlamp- R/L @ 672.51 <i>RH cracked</i>	1345.02 672.51
2	Front headlamp brackets- R/L @ 110.65 <i>new</i>	221.30 x.
2	Front side lamps- R/L @ 242.65 <i>RH cracked</i>	485.30 242.65.
2	Front signal lamps- R/L @ 292.52 <i>RH cracked</i>	585.04 292.52.
1	Front bumper <i>Distorted</i>	999.86 ✓
2	Front bumper brackets- R/L @ 241.55 <i>Bent</i>	483.10 ✓
1	Front chassis crossmember- CTR <i>Repair</i>	826.65 x.
1	Front door- RH <i>Buckled</i>	1827.61 ✓
1	Front door outer handle <i>Not new</i>	140.62 x.
1	Front door arch garnish <i>Deformed</i>	210.52 ✓
1	Front door inner lock <i>Damaged</i>	586.86 367.
1	Front door insulation <i>new</i>	130.20 x.
1	Front door inner trim board <i>new</i>	641.26 x.
1	Front door glass outer moulding <i>Deformed</i>	142.62 ✓

Vehicle No.: GBA 9459Y

1	Front door glass run channel	268.72 *
1	Front door glass regulator	341.52 *
1	Front door glass regulator motor	581.95 *
1	Front door w/strip <i>lt</i>	251.59 ✓
1	Front door checker <i>HP new</i>	130.10 X
2	Front door hinges @ 196.75 <i>Cent</i>	<u>393.50</u> 230.
1	Front door pillar- RH outer	1407.60 *
1	Front door pillar- RH inner	609.93 *
1	Front door ^{lower garnish} rear plate- RH <i>lt.</i>	677.60 * 345
1	Front door power window control switch <i>HP new</i>	281.62 *
1	Front door pull handle <i>HP new</i>	191.63 *
1	Front step garnish- RH <i>lt</i>	241.55 ✓
1	Front wheel arch panel- RH <i>Repis</i>	584.68 *
1	Front wheel arch panel garnish <i>crushed</i>	182.64 ✓
2	Front cabin mounting @ 311.25	622.50 *
1	Front cabin mounting carrier	615.52 *
1	Front cabin rear mounting- RH <i>HP new</i>	281.95 *
1	Front cabin safety lock- RH	260.92 *
1	Air cleaner intake duct <i>lt</i>	269.93 ✓
1	Air con blower assy <i>new</i>	811.52 *
1	Air con cooling coil assy <i>crushed</i>	857.66 ✓
1	Air con heater assy <i>new</i>	671.21 *
1	Brake booster	856.95 *
1	Brake master pump <i>HP new</i>	244.63 *
1	Brake booster bracket	289.62 *
1	Dashboard <i>crushed</i>	1021.50 ✓
1	Dashboard panel <i>HP new</i>	812.60 *
1	Dashboard lower cover- RH	192.60 *
1	Steering column shaft	561.92 *
1	Steering column shaft cover <i>HP new</i>	141.20 *
1	Steering coupling box	561.92 *

Vehicle No.: GBA 9459Y

1	Steering coupling box joint	249.45 X
1	Speedo meter	961.69 X
1	Speedo meter cluster	241.66 X
1	Accelerator pedal	182.62 X
1	Brake air camber	280.93 X
2	Horn	173.80 X
1	Air con condenser	841.95 ✓
1	Air con electric fan	481.95 X
		33451.98
		(3212.81)
Subtotal		30239.17

14218.52

10663.89

25%

Less 10%

Special Nett Items:

1	Front no plate	40.00	30
1 Set	Front tyre- RH	220.00	X
1	Wiper blade	60.00	✓
1 Bot	I. U bracket	30.00	✓
	Brake fluid	40.00	✓
Subtotal		390.00	

Labour Charges:

Towing	100.00	60
To remove, refix F/windscreen	150.00	120
To checking F/electrical wiring	120.00	30
To checking dashboard	300.00	220
To remove, refix A/C cooling systems	250.00	200
To respray undercoating	180.00	60
To check wheel alignment	120.00	X
To remove, refix F/Interior trims to assist repair	120.00	60
To respray painting and etc	1500.00	1300
Panel beating, cut, weld, remove and replacing above parts	2500.00	1800
Subtotal		5440.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

3550

Subtotal

5440.00

total 14373.89

L/s: 11.5K

10 Days

35936.7



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18011942/Avd3n2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 21-11-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 501K	Veh. Inspected	GBA 9459Y
Policy No.	D-18088937MFSH	Coverage (\$)	0.00
Claim No.	D18005102MFSH	Excess (\$)	0.00
Assign From	SITHARA	Assign Date	02/07/2018

2. Vehicle Particulars & Condition

Make & Model	MITSUBISHI FUSO	c.c	2977
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	FB70BBA10439	Colour	WHITE
Odometer	198519	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195 R15C	OHTSU	6 mm
L/H Front Tyre	195 R15C	OHTSU	6 mm
R/H Rear Tyre	195 R15C	OHTSU	6 mm
L/H Rear Tyre	195 R15C	OHTSU	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	27/06/2018	Inspection Date	02/07/2018
Survey held at	MCS GARAGE 10 KAKI BUKIT ROAD 2 #03-25 FIRST EAST CENTRE SINGAPORE 417868		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	10 Working Days
-------------------------------------	-----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBA 9459Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT WINDSCREEN GLASS	SHATTERED	1,413.40	1,413.40
1	FRONT WINDSCREEN RUBBER	NECESSARY	441.54	320.00
1	FRONT WINDSCREEN PILLAR TRIM-RH	NOT NECESSARY	182.63	-
1	FRONT WIPER PANEL GARNISH	CUT	619.25	619.25
2	FRONT WIPER ARM @\$89.92	O/S CUT	179.84	89.92
1	FRONT WIPER MOTOR	NOT NECESSARY	415.72	-
1	FRONT WIPER PANEL STICKER "CANTER"	NECESSARY	81.52	81.52
1	FRONT SIDE MIRROR WITH STAY-RH	DAMAGED	711.56	408.00
1	FRONT SIDE MIRROR STAY COVER	CUT	126.20	126.20
1	FRONT CAB PANEL	DISTORTED	1,064.66	1,064.66
2	FRONT CORNER PANELS-R/L @\$251.62	O/S DISTORTED	503.24	251.62
1	FRONT GRILLE ASSY	CRACKED	453.63	453.63
2	FRONT HEADLAMP-R/L @\$672.51	O/S CRACKED	1,345.02	672.51
2	FRONT HEADLAMP BRACKETS-R/L @\$110.65	NOT NECESSARY	221.30	-
2	FRONT SIDE LAMPS-R/L @\$242.65	O/S CRACKED	485.30	242.65
2	FRONT SIGNAL LAMPS-R/L @\$292.52	O/S CRACKED	585.04	292.52
1	FRONT BUMPER	DISTORTED	999.86	999.86
2	FRONT BUMPER BRACKETS-R/L @\$241.55	BENT	483.10	483.10
1	FRONT CHASSIS CROSSMEMBER-CTR	TO REPAIR SEE LABOUR	826.65	-
1	FRONT DOOR-RH	BUCKLED	1,827.61	1,827.61
1	FRONT DOOR OUTER HANDLE	NOT NECESSARY	140.62	-
1	FRONT DOOR ARCH GARNISH	DEFORMED	210.52	210.52
1	FRONT DOOR INNER LOCK	DAMAGED	586.86	367.00
1	FRONT DOOR INSULATION	NOT NECESSARY	130.20	-
1	FRONT DOOR INNER TRIM BOARD	NOT NECESSARY	641.26	-
1	FRONT DOOR GLASS OUTER MOULDING	DEFORMED	142.62	142.62
1	FRONT DOOR GLASS RUN CHANNEL	NOT NECESSARY	268.72	-
1	FRONT DOOR GLASS REGULATOR	NOT NECESSARY	341.52	-
1	FRONT DOOR GLASS REGULATOR MOTOR	NOT NECESSARY	581.95	-
1	FRONT DOOR W/STRIP	CUT	251.59	251.59

Report Ref No. CS/FC118011942/Avd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT DOOR CHECKER	NOT NECESSARY	130.10	-
2	FRONT DOOR HINGES @\$196.75	BENT	393.50	230.00
1	FRONT DOOR PILLAR-RH OUTER	TO REPAIR SEE LABOUR	1,407.60	-
1	FRONT DOOR PILLAR-RH INNER	TO REPAIR SEE LABOUR	609.93	-
1	FRONT DOOR LOWER GARNISH RH	CUT	677.60	345.00
1	FRONT DOOR POWER WINDOW CONTROL SWITCH	NOT NECESSARY	281.62	-
1	FRONT DOOR PULL HANDLE	NOT NECESSARY	191.63	-
1	FRONT STEP GARNISH-RH	CUT	241.55	241.55
1	FRONT WHEEL ARCH PANEL-RH	TO REPAIR SEE LABOUR	584.68	-
1	FRONT WHEEL ARCH PANEL GARNISH	CRACKED	182.64	182.64
2	FRONT CABIN MOUNTING @\$311.25	NOT NECESSARY	622.50	-
1	FRONT CABIN MOUNTING CARRIER	NOT NECESSARY	615.52	-
1	FRONT CABIN REAR MOUNTING-RH	NOT NECESSARY	281.95	-
1	FRONT CABIN SAFETY LOCK-RH	NOT NECESSARY	260.92	-
1	AIR CLEANER INTAKE DUCT	CUT	269.93	269.93
1	AIR CON BLOWER ASSY	NOT NECESSARY	811.52	-
1	AIR CON COOLING COIL ASSY	CRACKED	857.66	857.66
1	AIR CON HEATER ASSY	NOT NECESSARY	671.21	-
1	BRAKE BOOSTER	NOT NECESSARY	856.95	-
1	BRAKE MASTER PUMP	NOT NECESSARY	244.63	-
1	BRAKE BOOSTER BRACKET	NOT NECESSARY	289.62	-
1	DASHBOARD	CRACKED	1,021.50	1,021.50
1	DASHBOARD PANEL	NOT NECESSARY	812.60	-
1	DASHBOARD LOWER COVER-RH	NOT NECESSARY	192.60	-
1	STEERING COLUMN SHAFT	NOT NECESSARY	561.92	-
1	STEERING COLUMN SHAFT COVER	NOT NECESSARY	141.20	-
1	STEERING COUPLING BOX	NOT NECESSARY	561.92	-
1	STEERING COUPLING BOX HOINT	NOT NECESSARY	249.45	-
1	SPEEDO METER	NOT NECESSARY	961.69	-
1	SPEEDO METER CLUSTER	NOT NECESSARY	241.66	-
1	ACCELERATOR PEDAL	NOT NECESSARY	182.62	-

Report Ref No. CS/FC118011942/Avd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BRAKE AIR CAMBER	NOT NECESSARY	280.93	-
2	HORN	NOT NECESSARY	173.80	-
1	AIR CON CONDENSER	DISTORTED	841.95	841.95
1	AIR CON ELECTRIC FAN	NOT NECESSARY	481.95	-
	LESS 10% DISCOUNT		-3,345.20	-
	LESS 25% DISCOUNT		-	-3,577.10
			30,106.78	10,731.31
	SPECIAL NETT ITEMS			
1	FRONT NO PLATE (SN)	BENT	40.00	30.00
1	SET FRONT TYRE-RH (SN)	NOT NECESSARY	220.00	-
1	WIPER BLADE (SN)	CUT	60.00	60.00
1	BOT I.U BRACKET (SN)	NECESSARY	30.00	30.00
1	BRAKE FLUID (SN)	NECESSARY	40.00	40.00
			390.00	160.00
	LABOUR			
	TOWING.		100.00	60.00
	TO REMOVE,REFIX F/WINDSCREEN.		150.00	120.00
	TO CHECKING F/ELECTRICAL WIRING.		120.00	30.00
	TO CHECKING DASHBOARD.		300.00	220.00
	TO REMOVE,REFIX A/C COOLING SYSTEMS.		250.00	200.00
	TO RESPRAY UNDERCOATING.		180.00	60.00
	TO CHECK WHEEL ALIGNMENT.	NOT NECESSARY	120.00	-
	TO REMOVE,REFIX F/INTERIOR TRIMS TO ASSIST REPAIR.		120.00	60.00
	TO RESPRAY PAINTING AND ETC.		1,500.00	1,300.00
	PANEL BEATING,CUT,WELD,REMOVE AND REPLACING ABOVE PARTS.INCLUSIVE OF THE REPAIR OF FRONT CHASSIS CROSSMEMBER-CTR,FRONT DOOR PILLAR-RH OUTER,FRONT DOOR PILLAR-RH INNER AND FRONT WHEEL ARCH PANEL-RH.		2,600.00	1,500.00
			5,440.00	3,550.00
	GRAND TOTAL		35,936.78	14,441.31

Report Ref No. CS/FCI18011942/Avd3n2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			11,500.00
---	--	--	-----------

Report Ref No. CS/FCI18011942/Avd3n2

MARKET VALUE: \$30,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$18,147.00=NETT VALUE: \$11,853.00

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.