

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793J . Tel: 6741-1730 / 731 . Fax: 6744-5746. Email: liusbros@gmail.com

Invoice/Ref No: YN5845B180519

Estimate**Customer**

Name: AIG Asia Pacific Insurance Pte Ltd

Address Motor Claims Department

78 Shenton Way #07-16

AIG Building Singapore 079120

Date: 29-06-18

Vehicle No: YN5845B

Model/Make: Mitsubishi

Canter FEB21ER3SDEB (CBU)

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Rh Tail Lamp <i>Cne</i>	\$ 245.00	
2	Tail Lamp Bracket <i>sent</i>	\$ 185.00	
3	Tailgate Lower "L" Bracket <i>sent</i>	\$ 650.00	
4	Tailgate Lower "L" Bracket Ruber <i>nn</i>	\$ 170.00	X
5	Safety Bar With Bracket <i>sent</i>	\$ 1,200.00	SN 10005.2
6	Safety Bar Blinker Lamp <i>Cne</i>	\$ 480.00	SN 4505.2
	To check all wiring & electrical component for proper function	\$ 30.00	20
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 480.00	400
	To putty & spray painting & including touch up paint on accident affect	\$ 400.00	380
	To apply Rust Proofing , reseal tuff-coating treatment on accident area	\$ 50.00	X

Total Parts & Labour of estimate for damaged vehicle

\$3,890.00

Total amount in Lump Sum Basis for repaired vehicle

SDLS:



M/s Liu's Brother Auto Engrg Wks

not Allowed
 2/5 \$2150
 3 day.
 2/7/18

9-595
 252
 446.25
 S.N - 1450
 10km - 800
 2696.25
 2157

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: