

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ERGO Insurance Pte. Ltd.
5 Temasek Boulevard, #04-01 Suntec Tower Five
Singapore 038985

Our File No: CS/EGI18011965/NVD3E2

Date: 19/09/2018

REFERENCE

Insured/Claimant:	SING LIAN CRANES PTE.LTD	Policy No:	DMCV17S017843
Date of Loss:	27/06/2018	Nature of Claim:	OD
		Claim No:	N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	XE99E	Engine No:	6WG1421157
Make & Model:	ISUZU CYH52T, 15.7 D (M)	Chassis No:	JALCYH52TE7000112
Reg. Date:	09/09/2014 (Man. Year: 2014)	Odometer:	392 km
Colour:	White		
Engine Capacity:	15681 cc		
Market Value/New Car Price:	S\$220,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	295/80 R22.5	Rear Tyre Size:	295/80 R22.5
Front Left Side:	Firenza 5 mm	Rear Left Side:	Linglong 5 mm
Front Right Side:	Firenza 5 mm	Rear Right Side:	Linglong 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	25,015.95	19,740.95	5,275.00	21.09
Miscellaneous Items	10.70	10.70	0.00	0.00
Labour	4,640.00	3,170.00	1,470.00	31.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	29,666.65	22,921.65	6,745.00	22.74
Approved Total (Overridden) (\$\$)		18,300.00		
- Excess (\$\$)	0.00	1,500.00	-1,500.00	
(\$\$)	29,666.65	16,800.00	12,866.65	43.37
+ GST 7.00/7.00% (\$\$)	2,076.67	1,176.00	900.67	43.37
Nett Amount (\$\$)	31,743.32	17,976.00	13,767.32	43.37

INSPECTION

Date of Assignment:	02/07/2018 Present Location:	Lee Kuan Hwa Motor Service (Sungei Kadut)
Date Inspected:	03/07/2018 Inspected At:	24 Sungei Kadut Street 4 Singapore 729050
Estimated Period of Repair:	8.0 days	

Adjuster: Muhammad Nazril Bin Abdullah

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 19 Sep 2018)	
Parts:	N/A	ISUZU CYH52T 15.7 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for XE99E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Rear tail gate (WCP)	Broken	480.00 F	*480.00 F
2	1		*Rear side gate RH (WCP)	Cracked	480.00 F	*480.00 F
3	5		*Rear side gate hinges (WCP)	Deformed	200.00 F	*200.00 F
4	1		*Rear bumper (WCP)	Broken	800.00 F	*800.00 F
5	1		*Rear bumper bracket (2PCS) (WCP)	Deformed-1pc only	600.00 F	*300.00 F
6	1		*Rear number plate (WCP)	Dented	15.00 F	*15.00 F
7	2		*Rear number plate lamp (WCP)	Cracked	60.00 F	*60.00 F
8	1		*Rear lamp (WCP)	Broken	285.00 F	*285.00 F
9	1		*Rear lamp bracket (WCP)	Deformed	250.00 F	*250.00 F
10	1		*Rear mudguard (WCP)	Dented	260.00 F	*260.00 F
11	1		*Rear mudflat (WCP)	Broken	45.00 F	*45.00 F
12	1		*Rear mudflat bar (WCP)	Necessary	30.00 F	*30.00 F
13	1		*Rear tyre	Cut	600.00 F	*360.00 FS
14	1		*Rear gear box housing (WCP)	Dented	9,300.00 F	*5,500.00 F
15	2		*Rear gear box housing arm mounting (WCP)	Dented	600.00 F	*600.00 F
16	1		*Rear body lower chassis bar (WCP)	Dented	280.00 F	*280.00 F
17	1		*Rear hydraulic cyL chassis (WCP)	Cracked	3,600.00 F	*3,600.00 F
18	4		*Rear hydraulic pipe (WCP)	Dented	360.00 F	*360.00 F
19	2		*Rear hydraulic hose (WCP)	Deformed	280.00 F	*280.00 F
20	1		*Rear hydraulic cyL (WCP)	Broken	1,800.00 F	*1,800.00 F
21	1		*Rear valve Po check (WCP)	Necessary	290.00 F	*290.00 F
22	4		*Rear hose guide (WCP)	Deformed	260.00 F	*260.00 F
23	18		*Rear hydraulic oil (WCP)	Necessary	108.00 F	*108.00 F
24	8		*Rear bolt & nut (WCP)	Necessary	96.00 F	*96.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
25	18		*Rear gear box oil (WCP)	Necessary	144.00 F	*144.00 F
26	1		*Rear safety lamp (WCP)	Cracked	180.00 F	*180.00 F
<u>Supplementary #1</u>						
27	1		*Rear Tool Box (WCP)	Damaged	350.00 F	*150.00 F
					<hr/>	
					Sub Total (S\$)	21,753.00 17,213.00
					+ Margin on L,N Items 15.00/15.00% (S\$)	3,262.95 2,527.95
					<hr/>	
					Total Parts (S\$)	25,015.95 19,740.95
					<hr/>	

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	OD/TP Case (Insurer)	10.70	10.70
Sub Total (\$\$)			10.70	10.70

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	To towing	New	200.00	0.00
2	To wiring	New	80.00	50.00
3	To repair rear body labour	New	680.00	400.00
4	To repair & repair labour	New	600.00	500.00
5	To repair & replace hydraulic , pipe, pump, etc.labour	New	1,200.00	1,000.00
6	To replace gear box housing labour	New	1,200.00	720.00
7	To spray putty	New	680.00	500.00
Gross Labour Cost (\$\$)			4,640.00	3,170.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >