Our Ref:



ComfortDelGro Engineering

205 Braddell Road S(579701)

ACCIDENT REPAIR ESTIMATE

Type of Claim :	TP	Vehicle No.	SLF6224H
Type of Claim .		Make & Model	HONDA VEZEL HYBRID 1.5X A
		Year of Manufacture	2016
		Chassis No.	RU31208462
Ins Company :AlG	G VS EQ	Engine No.	LEB5908472
Excess :		Policy No.	: <u></u>
Date of Accident : 25	.06.2018	Time of Accident	09:55
Suggested Days of Repair :		In-house Vehicle Asse	essor
Repair Estimate		Case Owner	: WILLIAM
		Signature	:
Parts (a) Cost / List Price Items	\$ -	Contact No	
Plus/Less 20%	\$ -	Frt Counter Operation	on
Total of Cost / List	\$ -	63837103 – Patrick Tia 63837730 - Brenda No	
		63837466 – Rohani	
(b) Nett Price Items	\$ -	braddell_cr@sparkcarca	are.com
Less	-1:1	Workshop Operation	1
Total of Nett Item		63837656 - Ngo Toh W 63837362 -	ee
Total of Nett Item		63838115 - William Wa	ng
(c) Special Nett Items	\$ -	63838115 - Andrew G	
Total Parts Cost (Appendix A)	\$ -	braddell_operation@spa	
Labour (Appendix B)	\$ 4,150.00		a.
Total Repair Cost	\$ 4,150.00		Nor Norhaine Reanny Bepains
The above total will be subjected t	to 7% G.S.T.		
		11	
Name of Surveyor	3	Kenners	5
Company	:	CKK	
Survey conducted on		29/6/18 at	
Remarks By Surveyor			
(a) The repair of this vehicle is	authorized / is not au	thorized until further notice.	
(b) Recommended Days of Re	epair :	day(s)	
(c) Resurvey	: Required / N	Not-Required	
(d) Excess	:\$		
(e) Signature of surveyor	: Le	29/6/18 Date	B:

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701) Tel: 63837168 / 63837466 Fax:62844284,62815767

Spare Parts

Vehicle No		SLF6224H	Case Owner	WILLIAM
Make & Model	:	HONDA VEZEL HYBRID 1.	Year Manufacture	2016
Chassis No	:	RU31208462	Engine No	 LEB5908472
Sales Order	:		Supplier	
Order By	:		Type of Claim	<u>TP</u>

S/No	Part Description		QTY	Cost	List Price	Nett Price	S/N	Disposition By Surveyor
4	Rear bumper	Bu	1	Price	Price	Price	3/14	Julyeyor
1 2	Rear bumper corner LH	Buz	1					
_	Rear bumper reflector LH	1706	1					?
3	Rear bumper retainer LH	cm	1					1
4			_					
5	Rear bumper clips	Bro	1					,_
6	Taillamp LH	Ry	1					
7	Tailgate	147	1					7
8	Tailgate badge logo		1					- '
9	Tailgate emblem - VEZEL	New	1					
10	Tailgate emblem - HYBRID	M	1					7
11	Tailgate weatherstrip		1					-
12		m	1					-
13	Tailgate upper lock	N	1					X
14	r tour mindooroom modiumg	M	1					
15	Rear windscreen sealant	Me	1					
16	Rear windscreen inner seal	NEL	1					
7	Taillamp panel LH	By	1					
18	Rear end panel		1					7
19	Rear end panel inner garnish	cas	1					~
20	LH rear fender	Br	1					
21	LH rear fender inner garnish		1					?
22	LH rear fender inner shield	Sh	1					×
23	LH rear fender inner shield clips	nn	8					X
24	LH rear wheel arch protector	Bu	1					
25	Tailgate outer garnish	4	1					7
26	0		1			:e)te:		
27	0		1			:Signature:		
28	0		1		led by Repairer	<u>PolwoniaA</u>		
29	0		1	nsurance Company	mort levorage lenit of	toeldus si		
30	0		1	THE PARAMETER	nodification(s) is allow ntary item(s) must be	Control of the Contro		

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

re subject to confirmation

- Vevruser grind (2) had begemeb years of
 - To tesurvey before/after spray painting
 - the hard et of the following:

LKK Anto Consultants hence notify

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701) Tel: 63837168 / 63837466 Fax:62844284,62815767

Labour

Vehicle No. : SLF6224H Case Owner : WILLIAM

Make & Model : NDA VEZEL HYBRID 1.5X A Year of Manufacture : 2016

S/No	Labour Description	Esimated Price	Adjusted Price
1	To remove/refit rear windscreen to facilitate repairs.	\$120.00	
2	To transfer tailgate parts and fittings to new tailgate.	\$100.00	Pa
3	To mount vehicle on black hawk floor bench in order to re-align chassis members or body structure.	\$250.00	X
4	To remove/refit cushions & upholstery to facilitate repairs.	\$180.00	1201
5	To remove/refit fuel tank to facilitate repairs.	\$80.00	~
6	Labour charges to repair and panel beat LH rear fender inner structure, bootfloor panel, LH rear door, cutting/welding and replacing damaged parts.	\$1,600.00	12001
7	To transfer reverse sensor to new rear bumper.	\$80.00	601
8	To check wiring functions.	\$40.00	201
9	To putty, apply primer & spray-paint the rear bumper, tailgate, tailgate outer garnish, rear end panel, bootloor panel, LH rear fender, LH rear fender inner structure, LH rear door & affected areas.	\$1,500.00	12001
10	To apply rust-proofing on repaired/replaced panels.	\$200.00	901

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.