

INSURANCE

INS. CASE OWNER:

CC6 /EQI1801

1983

LKK:

IDAC:

Surveyor:

Guo Qiang

DOI:

29/6/18

Date / Time:

2/7/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

GBD 1602L

Name of Insured:

500W Flow Machinery Co.

Insured Tel No.:

HP:

D.O.A:

12/5/18

Excess Sec II :SS

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

LEE THIN ALBE

Driver Tel No.:

(V/L-YES/NO)

Claim No.:

0181800120-76

Policy No.:

0181800120-003456

Make / Model:

Tugora

Place of Accident:

YORK HILL & CHIN SWEE KO

OI GIA REPORT:

YES / NO

Insured Liability:

Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:

hong
nan

INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

URGENT

Date/ Time	STAGE	DATE / PIC
4/5/18	Non-Reporting ltr (1st):	
2/7/18	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	
	After call ltr to OI:	
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	☒
	After call ltr to OI:	☐
	Authorisation To Act:	☐
	Release Voucher:	☐
	Final Repair Bill:	☐
	Car Rental Invoice:	☐
	Towing Invoice:	☐
	LTA / GIA:	☐
	Medical Bill:	☐
	PIR:	☐
	Mandate/Reject Instruction:	☐
	LOD:	☐
	Payment Breakdown Form:	☐
	Post-Repair Photos:	☐
	Others:	☐

PRELIMINARY ADVICE Date/Time:		Sent By:	
FINALIZATION Date/Time:		Confirm with:	
Repair Cost:	SS	(days) Reduction:	%
FINAL SETTLEMENT Date/Time:		Confirm with:	
Final Liability:	% 100	(Agreed / Assessed) BOIA S/N No.:	for
Repair Cost:	SS		
Loss of Rental (LOR):	SS	(days)	
Loss of Use (LOU):	SS	(S x days)	
Loss of Income (LOI):	SS	(S x days)	
LOR only ☐ LOU only ☐	LOR + LOU ☐ LOR + LOI ☐	[Tick only one]	
GIA/LTA Search	SS		
Medical:	SS		
Disbursement:	SS	(e.g. Tow/ Independent)	
Legal Cost	SS		
Total:	SS	Global Sum SS:	
FINAL PAYMENT Date/Time:		Confirm with:	
Payee 1:	SS	Name 1:	
Payee 2: (Strike if N.A.)	SS	Name 2:	
Payee 3: (Strike if N.A.)	SS	Name 3:	

COPY SENT

 1) Claim status: Normal/Reject/Private Settle
 2) Report Format:
 3) Survey fee:

230.00

(08/11/13) wef

ASS. REC. BY:

REF: EQI

ASSIGNMENT

From:

Date:

29/06/2018

Estimated Cost:

On: ☒ TP / ☐ WS / ☐ TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MV

To inspect Vehicle No:

AP33J

at Workshop m/s

Hong nam motor

of

316 lavender street, 33888

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Pauline 062998439

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

\$6500 6800

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lump Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS up

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

AP33J

Yr Regn:

21 Nov 2014

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Piaggio X10 125 c.c 124

Colour:

white

A/C: Insured / Std / NI / NA

Sp. Reading:

-

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

ZAPM761000000 2980

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: ☒ S/Rim / STD A/Rim or

Tyre Size:

F:

120/70-15

R:

150/70-15

BS / DUN / EXNOVA / GY / FS / LIZA / MIP / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

mm

D.O.A.

D.O.I.

29-06-18

Survey held at

w/s

3pm

Des. of Damages: ☒ Frt / ☒ Rear / ☒ D/S / ☒ W/S / ☐ U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

\$1000 / year.

Net Value: 4113

Submit LIS \$700 CBEL \$6330.45 / 47% (- excluded

MV: \$680.00

LTA: \$2687.00

NV: \$4113.00

check items \$3579.30)

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

\$ + RS, SI

Photos

Others

TOTAL

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Invs (\$)

☐

: Weekend (\$)

Report Format:

Lump Sum / I.B.I. (\$)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
EQ INSURANCE COMPANY LTD		Ref : CC6/EQI18011983/jb3	
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Date : 02-07-2018	
		Code : EQI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBD 1602L	Veh. Inspected	AP 33J
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	02/07/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	12/05/2018	Inspection Date	
Survey held at	HONG NAN MOTOR AGENCY 316 LAVENDER ST SINGAPORE 338818		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

HONG NAN MOTOR AGENCY

316 Lavender Street Singapore 338818
Tel : 62998439 / 62995271 Fax : 62993487

EQ Insurance Company Ltd

Attn : Motor Insurance Dept (Third Party Claim)

Dear Sir / Madam ,

Re : Accident involving with GBD1602L (your insured) & AP33J on 12.05.2018

4 Days .
lump sum repair .
After repair photos .
Guo Q:Ang - 82880282
29/6/18

Repair Cost

Handle bar / BT ?	\$	457.50 /
Left brake master pump ?	\$	285.00 ?
Left brake lever / cut ?	\$	52.50 /
Front brake disc - right ?	\$	390.00 ?
Meter assy complete / CRA	\$	1,080.00 /
Instrument group cover / CRA	\$	195.00 /
Front fork & under bracket assy ?	\$	1,598.00 ?
Steering cone upper set ?	\$	47.50 ?
Lower steering bearing cone ?	\$	96.00 ?
Front left turn indicator assy / CRA	\$	78.00 /
Front shield - top crowling / cut	\$	385.00 /
Front lower shield / cut	\$	265.00 /
Top visor lid / CRA	\$	185.00 /
Right centre lid / cut	\$	180.00 /
Left deflector / mis.	\$	180.00 /
Right deflector / mis.	\$	187.50 /
Right centre lid cover X NN	\$	187.50 X
Left centre lid cover / mis.	\$	85.00 X /
Upper handle bar cover / ee	\$	85.00 /
Handle bar centre cover X NN	\$	195.00 X
Front mudguard / cut	\$	120.00 X /
Wheel compartment cover front R - CRA	\$	220.00 /
Front dashboard assy / CRA	\$	185.00 /
Left dashboard door / cut	\$	385.00 /
Right dashboard door X NN	\$	58.00 X
Right dashboard door lid / BR	\$	58.00 /
Left dashboard door lid / BR	\$	28.00 /
Dashboard corner cover right ?	\$	28.00 ?

Dashboard corner cover left ?
 Dash front left cover / mis
 Dash front right cover / mis
 Dash button panel x 11
 Dash button panel - re
 Exhaust pipe complete assy ?
 Head lamp stay ?
 Left floor board bracket ?
 Windscreen - CRA
 Front dashboard cover - cut
 Front meter dash cover - cut
 Front glove compartment - CRA
 Left central side cover - cut
 Left step board - cut
 Centre console lid ?
 Left pillion step board - cut
 Right rider step board - cut
 Right pillion step rubber - cut
 Right pillion step rubber button - dec
 Left spoiler x / cut
 Right spoiler x / cut
 Right side cover - CRA
 Right side cover guard - cut
 Right side cover top cover - CRA
 Right pillion grab bar top - cut
 Right pillion grab bar bottom - cut
 Tail light center cover - re
 Left side cover guard - cut
 Left side cover top cover - CRA
 Tail right light assy - CRA

Less : 10%

Add :
 Transport - 2 way
 Front number plate
 Alignment
 Fixing & Removal Labour

Total

LKK Auto Consultants hence notify
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

\$	45.00	?
\$	45.00	/
\$	38.00	/
\$	38.00	
\$	382.50	/
\$	980.00	?
\$	198.00	?
\$	154.50	?
\$	800.00	/
\$	128.00	/
\$	165.00	/
\$	280.00	/
\$	180.00	/
\$	260.00	/
\$	155.00	?
\$	45.00	/
\$	85.00	/
\$	35.00	/
\$	5.00	/
\$	295.00	/
\$	295.00	/
\$	330.00	/
\$	165.00	/
\$	180.00	/
\$	62.00	/
\$	99.00	/
\$	80.00	/
\$	165.00	/
\$	180.00	/
\$	384.00	/
\$	13,550.50	9095
\$	(1,355.05)	
\$	12,195.45	8185.5
\$	120.00	80
\$	15.00	10 BT
\$	150.00	40
\$	850.00	450
\$	13,330.45	580

8765.5

20% : 7000

Reprint limit : 4113

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 792C

Vehicle Details

Vehicle No.: AP33J
Vehicle to be Exported: No
Intended Deregistration Date: 11 Nov 2019
Vehicle Make: PIAGGIO
Vehicle Model: X10 125 ABS
Primary Colour: Black
Manufacturing Year: 2014
Engine No.: M761M1004877
Chassis No.: ZAPM7610000002980
Maximum Power Output: -
Open Market Value: \$5,568.00
Original Registration Date: 21 Nov 2014
First Registration Date: 21 Nov 2014
Transfer Count: 3
Actual ARF Paid: \$836.00

Intended PARF Rebate Details

PARF Eligibility: No
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 20 Nov 2024
COE Category: D - Motorcycle
COE Period(Years): 10
QP Paid: \$4,189.00
COE Rebate Amount: \$2,104.00
Total Rebate Amount: \$2,104.00

The information contained herein is correct as at 11 Nov 2019

$$\frac{77}{120} \times 4189 = 2687$$

OK

Catherine Chong (LKK Auto)

From: roGer pauLine <line_lhy@hotmail.com>
Sent: Thursday, 28 June, 2018 2:30 PM
To: assignments@lkkauto.com
Subject: Fw: ap33j third party claim - eq insurance
Attachments: ap33j ins claim 22052018 (1).jpg; ap33j ins claim 22052018 (10).jpg; ap33j ins claim 22052018 (11).jpg; ap33j ins claim 22052018 (12).jpg; ap33j ins claim 22052018 (13).jpg; ap33j ins claim 22052018 (14).jpg; ap33j ins claim 22052018 (2).jpg; ap33j ins claim 22052018 (3).jpg; ap33j ins claim 22052018 (4).jpg; ap33j ins claim 22052018 (5).jpg; ap33j ins claim 22052018 (6).jpg; ap33j ins claim 22052018 (7).jpg; ap33j ins claim 22052018 (8).jpg; ap33j ins claim 22052018 (9).jpg

hi

pls kindly send your surveyor to our workshop

TP EBL

enclosed all the docs

thx

best regards

pauline

hong nan motor agency
316 lavender street
singapore 338818
tel : 62998439
fax : 62993487



Virus-free. www.avast.com

Shu Pei (LKKAUTO)

From: Joel Goh <joel.goh@eqinsurance.com.sg>
Sent: Tuesday, 3 July 2018 9:55 AM
To: Shu Pei (LKKAUTO)
Cc: Admin A; Joy Irene (LKKAUTO)
Subject: RE: Direct Settlement - Accident Involving GBD1602L (OI : EQI - DM18HO01250-JG) AND AP33J (TP : LKK REF -CC6/EQI18011983/jb3) on 12.05.2018
Attachments: GBD1602L.pdf

Dear Shu Pei

Attached our insured's accident report as per your request.

Best Regards,

Joel Goh
Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190
www.eqinsurance.com.sg

A Member of Citystate

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.

From: Shu Pei (LKKAUTO) [mailto:shupeil@lkkauto.com]
Sent: Monday, July 2, 2018 4:12 PM
To: Joel Goh
Cc: Admin A; Joy Irene (LKKAUTO)
Subject: Direct Settlement - Accident Involving GBD1602L (OI : EQI - TBA) AND AP33J (TP : LKK REF - CC6/EQI18011983/jb3) on 12.05.2018

WITHOUT PREJUDICE

Dear Joel,

We refer to the above matter.

This is a TP direct settlement case from M/s Hong Nan Motor Agency.

Enclosed for your perusal is:

- TP's GIA report
- Estimated cost of repair

Please be informed that preliminary advice is not ready yet.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Joy and she can be contacted at DID: 6749 5792.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Report Remarks Entry - CC6/EQI18011983/Ggb3

Remarks

Remarks

JOEL CALLED IN****WKSP PASS LAWYER ***JOEL ASK FOR
REPAIR DAY & FINALIZE AMOUNT

Add

New remarks Added

Remarks 1	By	On
☐ AP 33J ; GBD 1602L	LSP	2/7/2018 3:58:05 PM
☐ EST ;\$13330.45 ---- SUR :XGQ ---WKSP : HONG NAN MOTOR AGENCY	LSP	5/7/2018 3:24:10 PM
☐ FILE PASS TO JOY	LSP	4/7/2018 9:19:52 AM
☐ PENDING SURVEY	LSP	4/7/2018 9:19:56 AM
☐ ESTIMATE & SURVEYOR ASSGNMENT PAPER PASS TO HANDLER	LSP	6/7/2018 8:47:34 AM
☐ BOLA 4 (a) -100%	JIB	20/7/2018 8:51:05 AM
☐ ASSIGN & EST. PASS TO GUO Q/ TO FINALIZE	JIB	20/7/2018 9:14:26 AM
☐ -	JIB	2/7/2019 2:28:10 PM
☐ TRANSFER : JOY TO VIVIAN, FILE PAS TO VIVIAN	JIB	2/7/2019 2:28:04 PM
☐ FILE TRANSFER TO CECILIA	LSL1	16/10/2019 9:10:49 AM
☐ SEND LOI	CPL	24/10/2019 12:55:21 PM
☐ JOEL CALLED IN****WKSP PASS LAWYER ***JOEL ASK FOR REPAIR DAY & FINALIZE AMOUNT	LSP	1/11/2019 4:28:01 PM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD

Ref : CC6/EQI18011983/Ggb3s2

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEXSINGAPORE 069110

Date : 11-11-2019



Code : EQI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBD 1602L	Veh. Inspected	AP 33J
Policy No.	DMCPHQ17-003456	Coverage (\$)	0.00
Claim No.	DM18HO01250-JG	Excess (\$)	0.00
Assign From		Assign Date	29/06/2018

2. Vehicle Particulars & Condition

Make & Model	PIAGGIO X10 125	c.c	124
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	ZAPM7610000002980	Colour	WHITE
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	120/70-15	MICHELIN	5 mm
L/H Front Tyre			mm
R/H Rear Tyre	150/70-15	MICHELIN	5 mm
L/H Rear Tyre			mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION, O/S AND N/S BODY.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	12/05/2018	Inspection Date	29/06/2018
Survey held at	HONG NAN MOTOR AGENCY 316 LAVENDER ST SINGAPORE 338818		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. AP 33J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	HANDLE BAR	BENT	457.50	457.50
1	LEFT BRAKE MATER PUMP	* CHECK	285.00	-
1	LEFT BRAKE LEVER	CUT	52.50	52.50
1	FRONT BRAKE DISC - RIGHT	* CHECK	390.00	-
1	METER ASSY COMPLETE	CRACKED	1,080.00	1,080.00
1	INSTRUMENT GROUP COVER	CRACKED	195.00	195.00
1	FRONT FORK & UNDER BRACKET ASSY	* CHECK	1,598.00	-
1	SET STEERING CONE UPPER	* CHECK	47.50	-
1	LOWER STEERING BEARING CONE	* CHECK	96.00	-
1	FRONT LEFT TURN INDICATOR ASSY	CRACKED	78.00	78.00
1	FRONT SHIELD - TOP COWLING	CUT	385.00	385.00
1	FRONT LOWER SHIELD	CUT	265.00	265.00
1	TOP VISOR LID	CRACKED	185.00	185.00
1	RIGHT CENTRE LID	CUT	180.00	180.00
1	LEFT DEFLECTOR	MISSING	180.00	180.00
1	RIGHT DEFLECTOR	MISSING	187.50	187.50
1	RIGHT CENTRE LID COVER	NOT NECESSARY	187.50	-
1	LEFT CENTRE LID COVER	MISSING	85.00	85.00
1	UPPER HANDLE BAR COVER	DEFORMED	85.00	85.00
1	HANDLE BAR CENTRE COVER	NOT NECESSARY	195.00	-
1	FRONT MUDGUARD	CUT	120.00	120.00
1	WHEEL COMPARTMENT COVER FRONT	CRACKED	220.00	220.00
1	FRONT DASHBOARD ASSY	CRACKED	185.00	185.00
1	LEFT DASHBOARD DOOR	CUT	385.00	385.00
1	RIGHT DASHBOARD DOOR	NOT NECESSARY	58.00	-
1	RIGHT DASHBOARD DOOR LID	BROKEN	58.00	58.00
1	LEFT DASHBOARD DOOR LID	BROKEN	28.00	28.00
1	DASHBOARD CORNER COVER RIGHT	* CHECK	28.00	-
1	DASHBOARD CORNER COVER LEFT	* CHECK	45.00	-
1	DASH FRONT LEFT COVER	MISSING	45.00	45.00
1	DASH FRONT RIGHT COVER	MISSING	38.00	38.00

Report Ref No. CC6/EQ18011983/Ggb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	DASH BUTTON PANEL	NOT NECESSARY	38.00	-
1	DASH BUTTON PANEL	DEFORMED	382.50	382.50
1	EXHAUST PIPE COMPLETE ASSY	* CHECK	980.00	-
1	HEAD LAMP STAY	* CHECK	198.00	-
1	LEFT FLOOR BOARD BRACKET	* CHECK	154.50	-
1	WINDSCREEN	CRACKED	800.00	800.00
1	FRONT DASHBOARD COVER	CUT	128.00	128.00
1	FRONT METER DASH COVER	CUT	165.00	165.00
1	FRONT GLOVE COMPARTMENT	CRACKED	280.00	280.00
1	LEFT CENTRAL SIDE COVER	CUT	180.00	180.00
1	LEFT STEP BOARD	CUT	260.00	260.00
1	CENTRE CONSOLE LID	* CHECK	155.00	-
1	LEFT PILLION STEP BOARD	CUT	45.00	45.00
1	RIGHT RIDER STEP BOARD	CUT	85.00	85.00
1	RIGHT PILLION STEP RUBBER	CUT	35.00	35.00
1	RIGHT PILLION STEP RUBBER BUTTON	NECESSARY	5.00	5.00
1	LEFT SPOILER	CUT	295.00	295.00
1	RIGHT SPOILER	CUT	295.00	295.00
1	RIGHT SIDE COVER	CRACKED	330.00	330.00
1	RIGHT SIDE COVER GUARD	CUT	165.00	165.00
1	RIGHT SIDE COVER TOP COVER	CRACKED	180.00	180.00
1	RIGHT PILLION GRAB BAR TOP	CUT	62.00	62.00
1	RIGHT PILLION GRAB BAR BOTTOM	CUT	99.00	99.00
1	TAIL LIGHT CENTER COVER	DEFORMED	80.00	80.00
1	LEFT SIDE COVER GUARD	CUT	165.00	165.00
1	LEFT SIDE COVER TOP COVER	CRACKED	180.00	180.00
1	TAIL RIGHT LIGHT ASSY	CRACKED	384.00	384.00
	LESS 10% DISCOUNT		-1,355.05	-909.50
			12,195.45	8,185.50
	SPECIAL NETT ITEMS			
1	FRONT NUMBER PLATE (SN)	BENT	15.00	10.00
			15.00	10.00

Report Ref No. CC6/EQI18011983/Ggb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TRANSPORT - 2 WAY.		120.00	80.00
	ALIGNMENT.		150.00	40.00
	FIXING & REMOVAL LABOUR.		850.00	450.00
			1,120.00	570.00
	GRAND TOTAL		13,330.45	8,765.50
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$3,579.30 NETT)			7,000.00

Report Ref No. CC6/EQ118011983/Ggb3s2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.