

REF: CS1 /SPF18011987 /B qbs2

Special Instruction:

L/S: \$ 5400.00

Third Parties:

Claimant:

Surveyor: 2 Appraiser.

Workshop: Leafy Greens

From (Person): Abdul Rahman of SPF Date/Time: 14/05/2018

Estimated Cost: _____ Bill to: _____

OD/TP Re-inspection / (Evaluation)

To Inspect Vehicle No: 9D6 2002Y Insured: QX 7478

at Workshop m/s Isafe Garage Tel: 25 Kaki Bulat Rd 4 #05-67
of _____

Policy No: _____ Claim No: AEED/108/009/2017/133D

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 21092017

(Client's Record)

H.O.D. Endorsement/Date: _____

Date/Time: _____ Person Contacted: _____ Vehicle IN / OUT _____

Date/Time: 11/11/20 Confirmed with 11/11/20 Final Fig 11/11/20, 11 days (Red \$ 11 / 11 %; Original 11 days)

Date/Time: 12/1/18 Submit Final Fig 5000, 4 days (Red \$ 400 / 7 %; Original 7 days)

Date/Time	Action/Instruction
	SDG 2002Y - X
	QX 74-1B - CSI/SPF1703523/KHbsj
	QA. 210917
	<i>[Signature]</i> 11/7/2
	URGENT

Para(1) : Parts found not replaced	(To highlight <i>R or UB, LR, Etc</i>)
------------------------------------	---

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

RECEIVED 12 JUL 2018

Para(3) : Nett Value

Market Value :

Salvage Value :

Nett Value : _____

Inspected/
Evaluated by:

<i>Fee Charged:</i>

Basic & Add	
Transport	
Photos	
Others	
Total	

Date: _____

1) Date/Time 12/2/18 File Pass to trjwtr

2) Date/Time _____ File Return to _____

3) Date/Time _____ File Pass to _____

4) Date/Time _____ File Return to _____

5) Date/Time _____ File Pass to _____

6) Date/Time File Return to

Catherine Chong (LKK Auto)

From: Abdul Rahman MOHAMAD SALIM (SPF)
<Abdul_Rahman_Mohamad_Salim@spf.gov.sg>
Sent: Monday, 14 May, 2018 3:11 PM
To: Catherine Chong (LKK Auto)
Cc: 'Olivia Lau'; Rosalyn TAN (SPF); Frankie THAY (SPF)
Subject: SDG2002Y - Request Paper Survey
Attachments: SDG2002Y LOD of C Paglar.pdf

Your Ref: SDG2002Y
Our Ref : AEMD/105/009/2017/133B

Dear Cath,

Your preceding mail and our assignment on 7 Dec 2017 have reference.

Attached as requested.

Regards

Abdul Rahman (Mr)
Accident Claims Officer
Automotive Engineering & Management Division
Police Logistics Department
Singapore Police Force
DID: (65) 6478 4840 | FAX: (65) 6478 4848



HOME TEAM
TRANSFORMATION 2025
One Home, One Team
Building Our Future Together

WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

From: Catherine Chong (LKK Auto) [mailto:admin-d@lkkauto.com]
Sent: Saturday, 12 May 2018 3:30 PM
To: Abdul Rahman MOHAMAD SALIM (SPF) <Abdul_Rahman_Mohamad_Salim@spf.gov.sg>
Subject: Request Paper Survey

Dear Mr Abdul Rahman,

Kindly refer to the attachment.

Please assist provide us the LOD for all vehicle for us conduct Paper Survey.

Best Regards,

Catherine Chong | Admin
LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



SINGAPORE POLICE FORCE

SPF Accidents Claims Section
Automotive Engg & Mgmt Div
Police Logistics Department
No. 1 Mount Pleasant Road
Block 8 Old Police Academy
#02-12 Singapore 298333

Your Ref : SDG2002Y

Our Ref : AEMD/105/009/2017/133B

Date : 7 December 2017

Tel: 64784840

Fax: 64784848

LKK Auto Consultants Pte Ltd
Paya Ubi Industrial Park
51 Ubi Avenue 1 #01/02-25
Singapore 408933

Via Fax only: 62564315

Dear Sir,

ACCIDENT INVOLVING GOVT VEHICLE QX747B AND OTHER VEHICLE SDG2002Y ON 21 SEPTEMBER 2017

We refer to the above matter.

- 2 Please arrange for a **Paper Survey Inspection** of vehicle no. **SDG2002Y** which has been repaired at **M/s Isafe Garage** of **25 Kaki Bukit Road 4 #05-67, Synergy@KB**, Singapore **417800**.
- 3 Estimates were provided by the workshop.
- 4 Thank you.

Yours faithfully,

Abdul Rahman
Accident Claims Officer
for Assistant Director

cc : Messrs C Paglar & Co via fax: 65368706 (FYI, pls)

A FORCE FOR THE NATION

LCL APPRAISER PTE LTD

47A Edgefield Plains #13-16 Singapore 828714
Hp: 90688689 Email: clappraiser@yahoo.com
Reg No: 201000228E

VEHICLE INSPECTION REPORT

To: Lam Kok Meng
C/o: Isafe Garage
25 Kaki Bukit Road 4
#05-67 Synergy@KB, Singapore 417800

Date : 16 October 2017
Our ref : ISG/09/1703/TP

Accident Date : 21 September 2017
Inspection Date : 29 September 2017
Repairer Name : Isafe Garage
25 Kaki Bukit Road 4
#05-67 Synergy@KB, Singapore 417800

Type of Survey : Third Party

PARTICULARS OF VEHICLE

Registration No : SDG 2002 Y
Make / Model : Audi A7
Chassis No : WAUZZZ4G2GN081540
Engine No : CYP006076

Year / Capacity : 2016 / 1984 cc
Colour : Black
Mileage : 20568

CONDITION OF TYRES

	Make	Size	Thread Balance	Rim
Front Nearside	Pirelli	255/40 R19	5 mm	Sport
Front Offside	Pirelli	255/40 R19	5 mm	Sport
Rear Nearside	Good Year	255/40 R19	5 mm	Sport
Rear Offside	Good Year	255/40 R19	5 mm	Sport

GENERAL DESCRIPTION OF DAMAGE VEHICLE

The impact damages sustained on the vehicle at the time of inspection is on the rear portion.
(Details refer to the photographs attached)

Enclosed number of photographs: 54 copies

REMARKS

This inspection was conducted entirely on a "WITHOUT PREJUDICE" basis and we have not given authorization and instruction to the repairer to proceed with the repair

RECOMMENDATIONS

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a **Lump Sum of \$ 5,400.00** on a contractual basis.

Under normal circumstances, the repair period would be about **7 (Seven)** working days.

ECL APPRAISER PTE LTD

Vehicle Registration No: SDG 2002 Y

Our Ref No: ISG/09/1703/TP

Qty	Description	Conditions	Repairer's Estimate	Revised Amount
-----	-------------	------------	---------------------	----------------

SPARE PARTS - LIST ITEMS

1	Rear boot lid	Repair	\$ 3,218.60	
1	Rear boot logo	Necessary	\$ 105.60	\$ 105.60 NAC ✓
1	Rear boot rubber	Intact	\$ 198.00	
1	Rear boot "A7" emblem	Necessary	\$ 81.40	\$ 81.40 NAC ✓
1	Rear boot "TFSi" emblem	Necessary	\$ 81.40	\$ 81.40 NAC ✓
2	Rear taillamps	Damage	\$ 2,134.00	\$ 2,134.00 DM ✓
1	Rear bumper	Damage	\$ 2,248.40	\$ 2,248.40 DM ✓
1	Rear bumper lower spoiler	Damage	\$ 422.40	\$ 422.40 DM ✓
1	Rear bumper reinforcement	Intact	\$ 825.00	
2	Rear bumper side retainers	Necessary	\$ 83.60	\$ 83.60 NAC ✓
2	Rear bumper PDC sensors	Damage	\$ 457.60	\$ 457.60 DM ✓
			\$ 9,856.00	\$ 5,614.40
			Less 5%	\$ 280.72
Total Cost - List Items			\$ 9,363.20	\$ 5,333.68

Total cost of parts

\$ 9,363.20 \$ 5,333.68

CCL APPRAISER PTE LTD

Vehicle Registration No: SDG 2002 Y

Our Ref No: ISG/09/1703/TP

S/No	Description	Repairer's Estimate	Revised Amount
	Total cost of parts c/f	\$ 9,363.20	\$ 5,333.68

LABOUR

1	To remove, refit, replaced damaged lamps and check up rear electrical wiring	\$ 80.00	\$ 50.00 ✓
2	To remove and refit inner garnishes, inner trim to assist repair.	\$ 150.00	\$ 120.00 ^{80.00} ✓
3	To remove and refit rear reverse sensor.	\$ 120.00	\$ 80.00 ^{60.00}
4	To apply undercoating on repaired and replaced panel.	\$ 100.00	\$ 30.00 ✓
5	To provide labour charges, workmanship to dismantle above damaged parts, repair including cut and weld ; re-align body structure and damaged consistent to the accident.	\$ 800.00	\$ 600.00 ^{400.00} ✓
6	To respray painting include polishing and waxing on the changed body parts, repaired portions where consistent to the accident.	\$ 750.00	\$ 500.00 ^{400.00} ✓

GRAND TOTAL

\$ 11,363.20 \$ 6,713.68

L/S 5000 l=

Repair days 4



10/7/18

C L APPRAISER PTE LTD

Vehicle Registration No: SDG 2002 Y

Our Ref No: ISG/09/1703/TP

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a **Lump Sum Repair Contract of : S 5,400.00**

By accepting to carry out the repairs on a contract lump sum basis, the repairer has the discretion to replace the damaged parts with used, reconditioned or new parts, or to repair it to a roadworthy condition.

Note: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage / item in this survey, kindly notified the company within seven (7) from the date hereof. Otherwise, the revised amount shall be deem to be vaild.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicle and/or other accident in other legal proceedings.

C L APPRAISER PTE LTD



Cheong K. H
Automotive Appraiser



51 UBI AVE 1, #01/02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 6256 3561 FAX: (065) 6256 4315

Your Ref: AEMD/105/009/2017/133B

Date: 13th July 2018

Our Ref: CS1/SPF18011987/Bqbs2

M/s Automotive Engineering & MGT Division

Accident Claim Section

(Singapore Police Force)

1 Mount Pleasant Road

Blk 8 Old Police Academy

Singapore 298333

(The Motor Claims Department)

Attn: Abdul Rahman

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO:
SDG 2002Y INSURED VEHICLE: QX 747B ACCIDENT DATE: 21/09/2017**

We thank you for your instruction on 14/05/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SDG 2002Y from M/s CL Appraiser Pte Ltd.
- b) Colour damaged vehicle photographs of SDG 2002Y.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SDG 2002Y
Make & Model	: Audi A7
Year of Registration	: 2016
Chassis Number	: WAUZZZ4G2GN081540
Engine Capacity	: 1984 cc

2. We recommend that the repairs of the entire damage require about 4 (Four) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDG 2002Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BOOT LID	TO REPAIR SEE LABOUR	3,218.60	-
1	REAR BOOT LOGO	NECESSARY	105.60	105.60
1	REAR BOOT RUBBER	INTACT	198.00	-
1	REAR BOOT "A7" EMBLEM	NECESSARY	81.40	81.40
1	REAR BOOT "TFSI" EMBLEM	NECESSARY	81.40	81.40
2	REAR TAILLAMPS	DAMAGED	2,134.00	2,134.00
1	REAR BUMPER	DAMAGED	2,248.40	2,248.40
1	REAR BUMPER LOWER SPOILER	DAMAGED	422.40	422.40
1	REAR BUMPER REINFORCEMENT	INTACT	825.00	-
2	REAR BUMPER SIDE RETAINERS	NECESSARY	83.60	83.60
2	REAR BUMPER PDC SENSORS	DAMAGED	457.60	457.60
	LESS 5% DISCOUNT		-492.80	-280.72
			9,363.20	5,333.68
	<u>LABOUR</u>			
	TO REMOVE, REFIT, REPLACED DAMAGED LAMPS AND CHECK UP REAR ELECTRICAL WIRING.		80.00	50.00
	TO REMOVE AND REFIT INNER GARNISHES, INNER TRIM TO ASSIST REPAIR.		150.00	80.00
	TO REMOVE AND REFIT REAR REVERSE SENSOR.		120.00	60.00
	TO APPLY UNDERCOATING ON REPAIRED AND REPLACED PANEL.		100.00	30.00
	TO PROVIDE LABOUR CHARGES, WORKMANSHIP TO DISMANTLE ABOVE DAMAGED PARTS, REPAIR INCLUDING CUT AND WELD; RE-ALIGN BODY STRUCTURE AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF REAR BOOT LID.		800.00	400.00
	TO RESPRAY PAINTING INCLUDING POLISHING AND WAXING ON THE CHANGED BODY PARTS, REPAIRED PORTIONS WHERE CONSISTENT TO THE ACCIDENT.		750.00	400.00
			2,000.00	1,020.00
	GRAND TOTAL		11,363.20	6,353.68

Report Ref No. CS1/SPF18011987/Bqbs2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			5,000.00
---	--	--	----------

Report Ref No. CS1/SPF18011987/Bqbs2

LIM TEOW GUAN

Asst. Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.