

ASS. REC. BY:

REF: CS/FCI18011994/Kad3ⁿ²

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

WS

FROM (Person):

Karen Tan

of

FCI

Date/Time:

27/10 @ 4:21pm

Estimated Cost:

Bill to:

OD TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLQ 4036P

Insured:

SHB 6646S

at Workshop m/s:

Esteem Performance

Tel:

64841221

of

81K 5033 AMK Ind. Park 2 # 01-251

Policy No:

b-18088936MFSH

Claim No:

D18005103MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

27/06/2018

03/07/2018

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS

(DS)

Date/Time:

4:44pm @ 27/10

Person Contacted:

Jenny

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SLQ4036P-X
	SHB 6646S - CS/FCI 18010887 / R1SD3 DUA: 4/6/2018
04/27/18 @ 4:39pm	revised to Karen Tan by email.
	Kennete Analised final fig 817147.05, 12 days - Ched 88984.70, 34%

ASS. REC. BY:

REF: FCZ /

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s Estuon

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 12 days Res.: Yes or No

Lum Sum: 1.8.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: S1Q 4038P Yr Regn: 07, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Altis c.c. 1598

Colour: A. Brown A/C: Insured / Std / NI / NA

Sp. Reading: 51910 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MRC053RE1A104561718

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/45R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal. 7 mm

L/Bal. 7 mm

D.O.A. 27/8/18

Survey held at _____

Rear

R/Bal. 7 mm

L/Bal. 7 mm

D.O.I. 3/7/18

Des. of Damages: Fnt / Rear / O/S / N/S / UIC / Rooftop or

old body

The UIC / Chassis frame / Body Structure affected due to collision. ✓

Date / Time Action / Instruction

17 File pass to Catherine

RECEIVED 04 DEC 2018

Date/Time, File Pass to?

10/3/18 tracy

Date/Time, File Return to?

: Prell. Report

: Final Report

Days Of Repair: 12

Resurvey No. of Trip: 3

16x15 = 240

Survey Fee:

Transportation:

S - RS - SI

Fixtures

Others

TOTAL

170 + 240
50
50 + 50 + 50
36
412/18
646

Add Fee: : Site Insp (\$)

: Interview (\$)

: Tech Invs (\$)

: Weekend (\$)

Report Format: TP

Lump Sum / I.B.I: (\$ 17148.05)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18005103MFSH

Date: 04 July 2018

Our Ref: CS/FCI18011994/Kqd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLQ 4036P

Please be informed that we had conducted the inspection of the abovementioned vehicle on 03/07/2018 at the premises of M/s ESTEEM PERFORMANCE, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>25,525.69</u>
Revised Estimate Amount	: S\$ <u>15,323.93</u>
"Check" Items Amount	: S\$ <u>4,292.14</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages at the o/s body. The undercarriage & body structure affected due to collision.



Yours faithfully

KONG SENG CHEONG
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	29-06-2018	Our Ref No. D18005103MFSH
Accident Date	27-06-2018	Claim Type. Third Party
Insured Vehicle	SHB6646S	Third Party Vehicle. SLQ4036P
Survey Location	BLK 5033 ANG MO KIO, IND PARK 2 #01-251/259	
Contact Person.	JENNY CHONG	
Contact No.	64841221/ 0	Fax No. 64847829
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	ESTEEM PERFORMANCE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
 This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/241931)



PRI Documents



Close



PRI Header Details

Claim No	D18005103MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & ESTEEM P
Workshop Name	ESTEEM PERFORMANCE PTE LTD (Contact Person : JENNY CHONG)	Survey Location & Contact Details	BLK 5033 ANG MO KIO, IND PARK 2 #01-251/259 Mobile: 0 , Phone: 64841221 , Fax: 64847829 EmailId: JENNY@ESTEEMPERF.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHB6646S	TP Vehicle No	SLQ4036P
PRI Recieved Date	29-06-2018 08:21:32 PM	Surveyor Appointed Date	02-07-2018 04:20:13 PM	Surveyor Accept Date	02-07-2018 0

Survey Report Upload

Surveyor Inspection Date *:	<input type="text"/>	Surveyor Report Date	02-07-2018	Upload Survey Report *:	<input type="button" value="Choose File"/>
------------------------------------	----------------------	-----------------------------	------------	--------------------------------	--

Vehicle Particulars

Make	<input type="text" value="Please Select Make"/>	Model	<input type="text" value="Please Select Model"/>	Year	<input type="text" value="Select Year"/>
Chasis No	<input type="text"/>	Engine No	<input type="text"/>	Mileage	<input type="text"/>
Color	<input type="text"/>	Cubic Capacity	<input type="text"/>		

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Wednesday, 4 July 2018 4:39 PM
To: 'Claim Workflow System'; assignments
Cc: KARENTAN@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18005103MFSH/1
Attachments: CSFCI18011994Kqd3.pdf

Dear Karen,

Enclosed herewith preliminary advice of SLQ 4036P.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Monday, 2 July 2018 4:50 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: KARENTAN@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18005103MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Monday, 2 July 2018 4:21 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; KARENTAN@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18005103MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

First report = LKK
= data.

Y. Wang LKK call, vehicle at SMK



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SLQ 4036 P

Parts	(a) Cost / List Price Items	\$	<u>25,634.25</u>
	Plus/Less 25%	\$	<u>6,408.56</u>
	Total of Cost / List	\$	<u><u>19,225.69</u></u>
	(b) Nett Price Items		_____
	Less		_____
	Total of Nett Item		_____
	(c) Special Nett Items	\$	<u>250.00</u>
Total Parts Cost		\$	<u><u>19,475.69</u></u>
Labour		\$	<u>6,050.00</u>
Total		\$	<u><u>25,525.69</u></u>

Not Authorized
Resurvey by paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

26/11/18

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenneth

Company : LKK

Survey conducted on : 31/7/18 at _____

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 12 day(s)

(c) Resurvey : Required / ~~Not Required~~

(d) Excess : \$ _____

(e) Signature of surveyor : Lc Date: 31/7/18



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : SLQ 4036 P
 Make & Model : TOYOTA ALTIS
 Chassis No : MR053REH104561718

Submit By : Carmen Lim
 Year Manufacture : 2016
 Engine No. : _____

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Wiper panel garnish	1	\$503.90		? X SVC
2	Wiper panel garnish RH	1	\$57.80		? X SVC
3	Bonnet	1	\$1,240.40		X
4	Bonnet hinge RH	1	\$52.70		X
5	Headlamp RH	1	\$2,816.10		✓
6	Front support panel (complete)	1	\$1,107.40		✓
7	Headlamp panel RH	1	WITH ITEM NO.6		
8	Front bumper	1	\$571.20		✓
9	Front bumper clip	10	\$38.90		✓
10	Front bumper reinforcement	1	\$376.21		X
11	Front bumper side retainer LH	1	\$67.80		✓
12	Front bumper side retainer RH	1	\$67.80		✓
13	Front bumper bracket LH	1	\$97.30		X
14	Front bumper bracket RH	1	\$97.30		X
15	Front bumper sponge	1	\$94.10		X
16	Washer tank	1	\$157.80		✓
17	Washer tank pump	1	\$197.60		? X SVC
18	RH front fender	1	\$858.70		
19	RH front fender undershield	1	\$171.20		
20	RH front fender undershield clip	10	\$32.10		
21	RHF fender wording "VVT-i"	1	\$48.70		
22	RH wing mirror	1	\$959.75		✓
23	RH wing mirror (signal lamp)	1	\$76.80		X

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spare Parts

Vehicle No. : SLQ 4036 P
 Make & Model : TOYOTA ALTIS
 Chassis No. : MR053REH104561718

Submit By : Carmen Lim
 Year Manufacture : 2016
 Engine No. : _____

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	RH wing mirror (cover) <i>MIU</i>	1	\$65.70		✓
25	RH front lower arm <i>B₁</i>	1	\$326.41		✓
26	RH front shock absorber <i>B₁</i>	1	\$411.70		✓
27	RH front shock absorber top mouting	1	\$195.80		? ✓ <i>BT</i>
28	RH front shock absorber stopper	1	\$45.80		? <i>X SVC</i>
29	RH front knuckle arm <i>B₁</i>	1	\$521.50		—
30	RH front knuckle bearing <i>MI</i>	1	\$102.81		—
31	RH front wheel hub <i>B₁</i>	1	\$211.64		✓
32	RH front wheel hub lock nut	1	\$20.20		? <i>X SVC</i>
33	RH front tie rod	1	WITH ITEM NO.38		? <i>X SVC</i>
34	RH front tie rod end	1	\$137.35		? <i>X SVC</i>
35	RH front drive shaft	1	\$1,436.20		? <i>BT ✓</i>
36	RH anti roll bar link <i>B₁</i>	1	\$187.20		✓
37	RH anti roll bar bush	1	\$29.75		? <i>rec ✓</i>
38	Steering rack <i>BT/MI</i>	1	\$1,620.40		✓
39	RH front rim <i>MI</i>	1	\$1,644.50		✓
40	RH front tyre <i>MI</i>	1	\$250.00	S.N 150	<i>608m</i>
41	RH front wheel housing <i>MI</i>	1	\$512.70		? <i>X</i>
42	RH front door <i>B₁</i>	1	\$1,274.80		✓
43	RH front door hinge top <i>B₁</i>	1	\$78.33		—
44	RH front door hinge bottom <i>B₁</i>	1	\$78.33		—
45	RH front door lock <i>MI</i>	1	\$375.60		✓
46	RH front door catch <i>MI</i>	1	\$24.24		<i>X</i>

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spare Parts

Vehicle No. : SLQ 4036 P
 Make & Model : TOYOTA ALTIS
 Chassis No : MR053REH104561718

Submit By : Carmen Lim
 Year Manufacture : 2016
 Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
47	RH front door checker	1	\$195.70		? X SVC
48	RH front door weatherstip	1	\$178.43		? X SVC
49	RH front weatherstip (body)	1	\$303.90		? X SVC
50	RH front door trim	1	\$922.75		? X SVC
51	RHF door glass outer moulding	1	\$135.10		X
52	RHF power window motor	1	\$498.75		? X SVC
53	RHF power window regulator	1	\$201.12		? X SVC
54	RH rear door	1	\$1,373.40		✓
55	RH rear door hinge top	1	\$78.34		X
56	RH rear door hinge bottom	1	\$78.34		✓
57	RH rear door lock	1	\$376.70		✓
58	RH rear door catch	1	\$24.02		X
59	RH rear door checker	1	\$186.70		X
60	RH rear door weatherstip	1	\$178.43		? X SVC
61	RH rear weatherstip (body)	1	\$297.60		X
62	RH rear door trim	1	\$511.60		X
63	RHR door glass outer moulding	1	\$145.70		X
64	RHR power window motor	1	\$407.80		X
65	RHR power window regulator	1	\$175.75		X
66	RH rocker panel	1	\$371.60		✓
67					
68					
69					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No. : SLQ 4036 P Submit By : Carmen Lim
Make & Model : TOYOTA ALTIS Year of Manufacture : 2016

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (BONNET,FRONT BUMPER,SUPPORT PANEL, RHF FENDER,RHF DOOR,RHR DOOR,RH ROCKER PANEL, RHR FENDER,RH CENTRE PILLAR,RHF DOOR STAND PILLAR,RHF WHEEL HOUSE,RH SIDE MIRROR)	\$2,400.00	1400
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (BONNET,FRONT BUMPER,SUPPORT PANEL, RHF FENDER,RHF DOOR,RHR DOOR,RH ROCKER PANEL, RHR FENDER,RH CENTRE PILLAR,RHF DOOR STAND PILLAR,RHF WHEEL HOUSE,RH SIDE MIRROR)	\$2,400.00	1400
3	To check wiring & focus headlamp	\$50.00	20
4	To remove & refit radiator, condenser to assist work load, to top up A/C gas.	\$150.00	100
5	To remove & refit undercarriage to assist work load.	\$250.00	240
6	To do wheel alignment.	\$120.00	80
7	To remove & refit Door trim, door glass, window regulator, door lock to assist work load. (RHF DOOR & RHR DOOR)	\$300.00	120
8	To tuff coat	\$300.00	150
9	Towing	\$80.00	250

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

Final - UCR
- Insura

8 way USK call, vehicle not work

Kg



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperv.com.sg

Repair Estimates

SLQ 4036 P

Parts	(a) Cost / List Price Items	\$	25,634.25
	Plus/Less <u>25%</u>	\$	6,408.56
	Total of Cost / List	\$	19,225.69
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items	\$	250.00
Total Parts Cost		\$	19,475.69
Labour		\$	6,050.00
Total		\$	25,525.69

Finalised
 1807.76
 4505.44
 13516.32
 150
 13660.32
 2560
 17226.32
 17147.05 ✓ ok
 Not Authorized
 Resurvey by person

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenneth

Company : CKC

Survey conducted on : 317118 at 15:10

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 12 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : Lc Date: 317118



**ESTEEM
PERFORMANCE**

ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : SLQ 4036 P
Make & Model : TOYOTA ALTIS
Chassis No : MR053REH104561718

Submit By : Carmen Lim
Year Manufacture : 2016
Engine No. : _____

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Wiper panel garnish <i>Sn</i>	1	\$503.90		<i>X</i>
2	Wiper panel garnish RH <i>Sn</i>	1	\$57.80		<i>X</i>
	Bonnet <i>R</i>	1	\$1,240.40		<i>X</i>
4	Bonnet hinge RH <i>R</i>	1	\$52.70		<i>X</i>
(5)	Headlamp RH <i>CM</i>	1	\$2,816.10	✓	<i>✓</i>
(6)	Front support panel (complete) <i>R</i>	1	\$1,107.40	✓	<i>✓</i>
7	Headlamp panel RH	1	WITH ITEM NO.6		
(8)	Front bumper <i>Bul/ins</i>	1	\$571.20	✓	<i>✓</i>
9	Front bumper clip <i>R</i>	10	\$38.90	✓	<i>✓</i>
10	Front bumper reinforcement <i>R</i>	1	\$376.21		<i>X</i>
11	Front bumper side retainer LH <i>Sn</i>	1	\$67.80		<i>X</i>
(12)	Front bumper side retainer RH <i>CM</i>	1	\$67.80	✓	<i>✓</i>
13	Front bumper bracket LH <i>R</i>	1	\$97.30		<i>X</i>
14	Front bumper bracket RH <i>R</i>	1	\$97.30		<i>X</i>
15	Front bumper sponge <i>Sn</i>	1	\$94.10		<i>X</i>
(16)	Washer tank <i>Del</i>	1	\$157.80	✓	<i>✓</i>
17	Washer tank pump <i>Sn</i>	1	\$197.60		<i>X</i>
(18)	RH front fender <i>R</i>	1	\$858.70	✓	<i>✓</i>
(19)	RH front fender undershield <i>CM</i>	1	\$171.20	✓	<i>✓</i>
20	RH front fender undershield clip <i>Sn</i>	10	\$32.10	✓	<i>✓</i>
21	RHF fender wording "VVT-i" <i>R</i>	1	\$48.70	✓	<i>✓</i>
(22)	RH wing mirror <i>Del/CM</i>	1	\$959.75	✓	<i>✓</i>
23	RH wing mirror (signal lamp) <i>Sn</i>	1	\$76.80		<i>X</i>

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Blk 5033 Ang Mo Kio Industrial Park 2 #01-259 Singapore 569536 Tel: 64841221 Fax: 64847829
Company Reg No. 200005485N / GST No. 20-0005485-N

6829.65 ✓

Alan, Steven

Spare Parts

Vehicle No. : SLQ 4036 P
 Make & Model : TOYOTA ALTIS
 Chassis No : MR053REH104561718

Submit By : Carmen Lim
 Year Manufacture : 2016
 Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	RH wing mirror (cover)	1	\$65.70	✓	✓
25	RH front lower arm	1	\$326.41	✓	✓
26	RH front shock absorber	1	\$411.70	✓	✓
27	RH front shock absorber top mouting	1	\$195.80	✓	ⓧ
	RH front shock absorber stopper	1	\$45.80		ⓧ
29	RH front knuckle arm	1	\$521.50	✓	—
30	RH front knuckle bearing	1	\$102.81	✓	—
31	RH front wheel hub	1	\$211.64	✓	✓
32	RH front wheel hub lock nut	1	\$20.20		ⓧ
33	RH front tie rod	1	WITH ITEM NO.38		ⓧ
34	RH front tie rod end	1	\$137.35		ⓧ
35	RH front drive shaft	1	\$1,436.20	✓	ⓧ
36	RH anti roll bar link	1	\$187.20	✓	✓
37	RH anti roll bar bush	1	\$29.75	✓	ⓧ
38	Steering rack	1	\$1,620.40	✓	✓
39	RH front rim	1	\$1,644.50	✓	✓
	RH front tyre	1	\$250.00	S.N. 150 S.N.	6080
41	RH front wheel housing	1	\$512.70		ⓧ
42	RH front door	1	\$1,274.80	✓	✓
43	RH front door hinge top	1	\$78.33	✓	—
44	RH front door hinge bottom	1	\$78.33	✓	—
45	RH front door lock	1	\$375.60	✓	✓
46	RH front door catch	1	\$24.24		ⓧ

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

2580667
 150 (S.N.)

Spare Parts

Vehicle No. : SLQ 4036 P
 Make & Model : TOYOTA ALTIS
 Chassis No : MR053REH104561718

Submit By : Carmen Lim
 Year Manufacture : 2016
 Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
47	RH front door checker	1	\$195.70		X
48	RH front door weatherstip	1	\$178.43		X
49	RH front weatherstip (body)	1	\$303.90		X
50	RH front door trim	1	\$922.75		X
51	RHF door glass outer moulding	1	\$135.10		X
	RHF power window motor	1	\$498.75		X
53	RHF power window regulator	1	\$201.12		X
54	RH rear door	1	\$1,373.40	✓	✓
55	RH rear door hinge top	1	\$78.34		X
56	RH rear door hinge bottom	1	\$78.34	✓	✓
57	RH rear door lock	1	\$376.70		X
58	RH rear door catch	1	\$24.02		X
59	RH rear door checker	1	\$186.70		X
60	RH rear door weatherstip	1	\$178.43		X
61	RH rear weatherstip (body)	1	\$297.60		X
62	RH rear door trim	1	\$511.60		X
63	RHR door glass outer moulding	1	\$145.70		X
	RHR power window motor	1	\$407.80		X
65	RHR power window regulator	1	\$175.75		X
66	RH rocker panel	1	\$371.60	✓	✓
67					
68					
69					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

1823-34



ESTEEM PERFORMANCE PTE LTD

Blk 6033 Ang Mo Kio, Ind Park 2 #01-251/250, 699538.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemparf.com.sg

Labour

Vehicle No. : SLQ 4036 P Submit By : Carmen Lim
Make & Model : TOYOTA ALTIS Year of Manufacture : 2016

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (BONNET,FRONT BUMPER,SUPPORT PANEL, RHF FENDER,RHF DOOR,RHR DOOR,RH ROCKER PANEL, RHR FENDER,RH CENTRE PILLAR,RHF DOOR STAND PILLAR,RHF WHEEL HOUSE,RH SIDE MIRROR)	\$2,400.00	1400
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (BONNET,FRONT BUMPER,SUPPORT PANEL, RHF FENDER,RHF DOOR,RHR DOOR,RH ROCKER PANEL, RHR FENDER,RH CENTRE PILLAR,RHF DOOR STAND PILLAR,RHF WHEEL HOUSE,RH SIDE MIRROR)	\$2,400.00	1400
3	To check wiring & focus headlamp	\$50.00	20
4	To remove & refit radiator, condenser to assist work load, to top up A/C gas.	\$150.00	100
5	To remove & refit undercarriage to assist work load.	\$250.00	240
6	To do wheel alignment.	\$120.00	80
7	To remove & refit Door trim, door glass, window regulator, door lock to assist work load. (RHF DOOR & RHR DOOR)	\$300.00	120
8	To tuff coat	\$300.00	150
9	Towing	\$80.00	250

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

ESTEEM PERFORMANCE PTE LTD

BLK 5033 ANG MO KIO INDUSTRIAL PARK 2
#01-259 SINGAPORE 569536

Tel:64841221 Fax:64847829

Spare Parts

Vehicle No. : SLQ 4036 P
 Make & Model : TOYOTA ALTIS
 Chassis No : MR053REH104561718

Submit By : CARMEN LIM
 Year Manufacture : 2016
 Engine No. :

Cost / List

Supplementary

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	RH FRONT LOWER ARM BALL JOINT <i>AM</i>	1	\$175.60		✓
2	ANTI ROLL BAR <i>Orl</i>	1	\$379.40		✓
3	ANTI ROLL BAR BRACKET RH <i>Orl</i>	1	\$51.70	missing	✓
4	AUTO OIL <i>new one</i>	4 LTR	\$105.70		X
5	RH FRONT FENDER INNER GARNISH <i>cm</i>	1	\$95.70		✓
6		1			
7		1			
8		1			
9		1			
10		1			
11		1			
12		1			
13		1			
14		1			
15		1			
16		1			
17		1			
18		1			
19		1			
20		4			
21		1			
22		1			
23		1			

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge

208-10



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18011994/Kqd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 10-12-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHB 6646S	Veh. Inspected	SLQ 4036P
Policy No.	D-18088936MFSH	Coverage (\$)	0.00
Claim No.	D18005103MFSH	Excess (\$)	0.00
Assign From	KARENT	Assign Date	02/07/2018
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA ALTIS (A)	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	MR053REH104561718	Colour	METALLIC BROWN
Odometer	51910	Steering	JAMMED
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/45 R17	MICHELIN	7 mm
L/H Front Tyre	215/45 R17	MICHELIN	7 mm
R/H Rear Tyre	215/45 R17	MICHELIN	7 mm
L/H Rear Tyre	215/45 R17	MICHELIN	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY, THE UNDERCARRIAGE AND BODY STRUCTURE AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	27/06/2018	Inspection Date	03/07/2018
Survey held at	ESTEEM PERFORMANCE PTE LTD BLK 5033 ANG MO KIO INDUSTRIAL PARK 2 #01-259 SINGAPORE 569536		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		12 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLQ 4036P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	WIPER PANEL GARNISH	SERVICEABLE	503.90	-
1	WIPER PANEL GARNISH RH	SERVICEABLE	57.80	-
1	BONNET	TO REPAIR SEE LABOUR	1,240.40	-
1	BONNET HINGE RH	TO REPAIR SEE LABOUR	52.70	-
1	HEADLAMP RH	CRACKED	2,816.10	2,816.10
1	FRONT SUPPORT PANEL (COMPLETE) }	BENT	1,107.40	1,107.40
1	HEADLAMP PANEL RH }		-	-
1	FRONT BUMPER	BUCKLED / CRACKED	571.20	571.20
10	FRONT BUMPER CLIP	NECESSARY	38.90	38.90
1	FRONT BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	376.21	-
1	FRONT BUMPER SIDE RETAINER LH	SERVICEABLE	67.80	-
1	FRONT BUMPER SIDE RETAINER RH	CRACKED	67.80	67.80
1	FRONT BUMPER BRACKET LH	TO REPAIR SEE LABOUR	97.30	-
1	FRONT BUMPER BRACKET RH	TO REPAIR SEE LABOUR	97.30	-
1	FRONT BUMPER SPONGE	SERVICEABLE	94.10	-
1	WASHER TANK	DENTED	157.80	157.80
1	WASHER TANK PUMP	SERVICEABLE	197.60	-
1	RH FRONT FENDER	BENT	858.70	858.70
1	RH FRONT FENDER UNDERSHIELD	CRACKED	171.20	171.20
10	RH FRONT FENDER UNDERSHIELD CLIP	NECESSARY	32.10	32.10
1	RHF FENDER WORDING "VVT-I"	NECESSARY	48.70	48.70
1	RH WING MIRROR	DENTED / CRACKED	959.75	959.75
1	RH WING MIRROR (SIGNAL LAMP)	SERVICEABLE	76.80	-
1	RH WING MIRROR (COVER)	MISSING	65.70	65.70
1	RH FRONT LOWER ARM	BENT	326.41	326.41
1	RH FRONT SHOCK ABSORBER	BENT	411.70	411.70

Report Ref No. CS/FCI18011994/Kqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	RH FRONT SHOCK ABSORBER TOP MOUNTING	BENT	195.80	195.80
1	RH FRONT SHOCK ABSORBER STOPPER	SERVICEABLE	45.80	-
1	RH FRONT KNUCKLE ARM	BENT	521.50	521.50
1	RH FRONT KNUCKLE BEARING	NECESSARY	102.81	102.81
1	RH FRONT WHEEL HUB	BENT	211.64	211.64
1	RH FRONT WHEEL HUB LOCK NUT	SERVICEABLE	20.20	-
1	STEERING RACK }	BENT / JAMMED	1,620.40	1,620.40
1	RH FRONT TIE ROD }		-	-
1	RH FRONT TIE ROD END	SERVICEABLE	137.35	-
1	RH FRONT DRIVE SHAFT	BENT	1,436.20	1,436.20
1	RH ANTI ROLL BAR LINK	BENT	187.20	187.20
1	RH ANTI ROLL BAR BUSH	NECESSARY	29.75	29.75
1	RH FRONT RIM	DENTED	1,644.50	1,644.50
1	RH FRONT WHEEL HOUSING	TO REPAIR SEE LABOUR	512.70	-
1	RH FRONT DOOR	BENT	1,274.80	1,274.80
1	RH FRONT DOOR HINGE TOP	BENT	78.33	78.33
1	RH FRONT DOOR HINGE BOTTOM	BENT	78.33	78.33
1	RH FRONT DOOR LOCK	DENTED	375.60	375.60
1	RH FRONT DOOR CATCH	TO REPAIR SEE LABOUR	24.24	-
1	RH FRONT DOOR CHECKER	SERVICEABLE	195.70	-
1	RH FRONT DOOR WEATHERSTRIP	SERVICEABLE	178.43	-
1	RH FRONT WEATHERSTRIP (BODY)	SERVICEABLE	303.90	-
1	RH FRONT DOOR TRIM	SERVICEABLE	922.75	-
1	RHF DOOR GLASS OUTER MOULDING	SERVICEABLE	135.10	-
1	RHF POWER WINDOW MOTOR	SERVICEABLE	498.75	-
1	RHF POWER WINDOW REGULATOR	SERVICEABLE	201.12	-
1	RH REAR DOOR	BENT	1,373.40	1,373.40
1	RH REAR DOOR HINGE TOP	TO REPAIR SEE LABOUR	78.34	-
1	RH REAR DOOR HINGE BOTTOM	BENT	78.34	78.34
1	RH REAR DOOR LOCK	TO REPAIR SEE LABOUR	376.70	-

Report Ref No. CS/FCI18011994/Kqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	RH REAR DOOR CATCH	TO REPAIR SEE LABOUR	24.02	-
1	RH REAR DOOR CHECKER	SERVICEABLE	186.70	-
1	RH REAR DOOR WEATHERSTRIP	SERVICEABLE	178.43	-
1	RH REAR WEATHERSTRIP (BODY)	SERVICEABLE	297.60	-
1	RH REAR DOOR TRIM	SERVICEABLE	511.60	-
1	RHR DOOR GLASS OUTER MOULDING	SERVICEABLE	145.70	-
1	RHR POWER WINDOW MOTOR	TO REPAIR SEE LABOUR	407.80	-
1	RHR POWER WINDOW REGULATOR	SERVICEABLE	175.75	-
1	RH ROCKER PANEL	BENT	371.60	371.60
1	RH FRONT LOWER ARM BALL JOINT (ADDITIONAL)	BENT	175.60	175.60
1	ANTI ROLL BAR (ADDITIONAL)	DISTORTED	379.40	379.40
1	ANTI ROLL BAR BRACKET RH (ADDITIONAL)	DISTORTED	51.70	51.70
4	LTR AUTO OIL (SN)	NOT NECESSARY	105.70	-
1	RH FRONT FENDER INNER GARNISH (ADDITIONAL)	CRACKED	95.70	95.70
	LESS 25% DISCOUNT		-6,610.58	-4,479.01
			19,831.77	13,437.05
	SPECIAL NETT ITEMS			
1	RH FRONT TYRE (60%)(SN)	CUT	250.00	150.00
			250.00	150.00
	LABOUR			
	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA (BONNET,FRONT BUMPER,SUPPORT PANEL,RHF FENDER,RHF DOOR,RHR DOOR,RH ROCKER PANEL,RHR FENDER,RH CENTRE PILLAR,RHF DOOR STAND PILLAR,RHF WHEEL HOUSE,RH SIDE MIRROR).INCLUSIVE OF THE REPAIR OF BONNER,BONNET HINGE RH,FRONT BUMPER REINFORCEMENT,FRONT BUMPER BRACKET LH,FRONT BUMPER BRACKET RH,RH FRONT WHEEL HOUSING,RH FRONT DOOR CATCH,RH REAR DOOR HINGE TOP,RH REAR DOOR LOCK,RH REAR DOOR CATCH AND RHR POWER WINDOW MOTOR.		2,400.00	1,400.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (BONNET, FRONT BUMPER, SUPPORT PANEL, RHF FENDER, RHF DOOR, RHR DOOR, RH ROCKER PANEL, RHR FENDER, RH CENTRE PILLAR, RHF DOOR STAND PILLAR, RHF WHEEL HOUSE, RH SIDE MIRROR).		2,400.00	1,400.00
	TO CHECK WIRING & FOCUS HEADLAMP.		50.00	20.00
	TO REMOVE & REFIT RADIATOR, CONDENSER TO ASSIST WORK LOAD, TO TOP UP A/C GAS.		150.00	100.00
	TO REMOVE & REFIT UNDERCARRIAGE TO ASSIST WORK LOAD.		250.00	240.00
	TO DO WHEEL ALIGNMENT.		120.00	80.00
	TO REMOVE & REFIT DOOR TRIM, DOOR GLASS, WINDOW REGULATOR, DOOR LOCK TO ASSIST WORK LOAD (RHF DOOR & RHR DOOR).		300.00	120.00
	TO TUFF COAT.		300.00	150.00
	TOWING.		80.00	50.00
			6,050.00	3,560.00
	GRAND TOTAL		26,131.77	17,147.05
RECOMMENDED COST OF REPAIRS				17,147.05

Report Ref No. CS/FC118011994/Kqd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.