

27/03/2002

SS: REC. BY:

REF: 063/MS(718008384/B sb'et)

Special Instruction:

Survivor
Melmen

Tatiana Sebastian

ASSIGNMENT (Office)

From (Person):

Monica Chung

of

mslh

Date/Time:

03072018

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBE 6343X

Insured:

SDW 2188K

at Workshop m/s

One Zone Autocare

Tel:

9230 8294

of

7800n Lee St #01-05

Policy No:

10118175

Claim No:

557553

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

03062018

CA / REV / REP. / REV 24 HRS ^{wp}

Date/Time:

08052018 9.31am

Person Contacted:

Eric

H.O.D. Endorsement

Vehicle IN / OUT

Date/Time	Action/Instruction (X) Estimate	Do Not Finalize
	GBE 6343X - X	
	SDW 2188K - X	
		Estimate charge 11
	HC \$ 1,500.00 / 4 days	
	(\$ 5,852.60 Red - 80%)	

18/7/2018 P

RECEIVED 18 JUL 2018

REF:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

G B E 6343X

Yr Regn:

30/1/2016

Type: M.Car / M.Cycle / Bus / ☒ Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Nissan NV200

C.C 1461

Colour

Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

67575

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

VSKYBAM 70E 0120148

Gen. Cond: Good / ☒ Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: ☒ S/Rim / STD A/Rim or

Tyre Size:

F: 205/55 R16

R: "

BS / DUN / EXNOVA / GY / FS / LIZA / ☒ MIO / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

3/5/18

D.O.I.

10/5/18

Survey held at

One zone

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

* Repair Estimate : S\$ 3000 - 4000

* 5 days

23/5/18

Submit PRS report.

21/5/2018

RECEIVED 24 MAY 2018

Date/Time, File Pass to?

☐

Preli. Report

☐

Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

) S + RS. \$

) Photos

) Others

TOTAL

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

120

10

130

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 May 2018		07 May 2018 16:20 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	Tan Ai Hwa, ID: S1611585A								
Main Claimant:	Windale Maintenance Pte Ltd, Co. Reg. No.: 200719335E								
Vehicle Reg. No.:	GBE6343X	Date of Loss:	03/05/2018 18:00 - :59 [27 Months and 3 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 557553	Policy/Cover Note No.:	10118175 (Comprehensive) Coverage: 04/04/2018 - 03/04/2019						
Vehicle Reg. No. (Insured):	SDW2188K	Policy No. (Claimant):							
		Excess:							
Repairer:	One Zone Autocare (HQ) 7 SOON LEE STREET, #01-05 I SPACE BUILDING, 627608 Jurong Island - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 05/07/2018]								
Driver/Custodian (Insured):	CHONG BI XUAN (27 / Female), NRIC: S9113554Z, Tel: +6597351807								
Adj Asg. Remarks:	on WP. Please contact us ASAP if you cannot attend this assignment.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> MSIG_SG (03/07/2018): Report Send Back Alerts - GBE6343X (TP) 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete 									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

One Zone Autocare
No 7 Soon Lee Street
Ispace Building #01-05
Singapore 627608
Business Reg. no: 53150343K

INVOICE

Name: Windale Maintenance Pte Ltd

Date of Invoice: 17/5/2018

One Zone Autocare
No 7 Soon Lee Street
Ispace Building #01-05
Singapore 627608

Claim Type: Third Party

Date of Accident: 3/5/2018

Vehicle Reg No: GBE6343X

Claimant: Windale Maintenance
Pte Ltd

Vehicle Make/Model: Nissan NV200 1.5

Description

Amount (S\$)


Lump Sum Repair as per recommendation

3,000.00

Total

3,000.00

Singapore Dollar: Three thousand dollars only.



SINCERE
APPRAISAL SERVICES PTE LTD

SINCERE APPRAISAL SERVICES PTE LTD Co.Reg no: 201800639R

60 Paya Lebar Road #07-41 Paya Lebar Square Singapore 409051

Tel : 6636 4628 Fax : 6636 4638 E-mail : sincereappraisal@gmail.com

INVOICE

RIAZ LLC
ADVOCATES AND SOLICITORS
133 New Bridge Road
#09-09 Chinatown Point
Singapore 059413


Invoice No: 170518-256
Our ref: 256/TP/2018
Date: 17/5/2018

Claim Type: Third Party	Date of Loss: 3/5/2018
Vehicle Reg No: GBE6343X	Windale Maintenance Pte Ltd
Vehicle Make/Model: Nissan NV200 1.5	Claimant: Ltd
Description	Amount (S\$)
1. Professional Fee (including Transport, 24 Photographs and Miscellaneous charges)	584
Total	584
Singapore Dollar: Five hundred and eighty four dollars only.	

Cheques should be crossed A/C PAYEE and made payable to Sincere Appraisal Services Pte Ltd



Sincere Appraisal Services Pte Ltd



SINCERE

APPRAISAL SERVICES PTE LTD

VEHICLE DAMAGE INSPECTION REPORT

Our Ref: 256/TP/2018

Date: 17/5/2018

REFERENCE

Date of loss: 3/5/2018
Claimant: Windale Maintenance Pte Ltd

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBE6343X	Make &	Nissan
Reg date:	30/1/2016	Model	NV200 1.5
Colour:	Silver	Engine No:	K9KC400D055195
Type:	Motor Car	Chassis No:	VSKYBAM20Z0120148
Type of Claims:	Third Party	Odometer No:	67595km
		Engine Cap:	1461cc

CONDITION OF VEHICLE AT THE TIME OF SURVEY (STATIC ONLY)

General Condition: Good	Steering: Good	Engine Modification: Nil
Paint work: Good	Handbrake: Good	Pre-accident
	Footbrake: Good	Damage: Nil

CONDITION OF TYRES

Front Left Size: Michelin 205/55ZR16 70%	Front Right Size: Michelin 205/55ZR16 70%
Rear Left Size: Michelin 205/55ZR16 70%	Rear Right Size: Michelin 205/55ZR16 70%

The above percentages represent the remaining life of the tyre threads

COST OF REPAIRS


Parts	Repairer S\$	Adjuster S\$
	\$ 5,382.60	\$ 2,013.50
Labour	\$ 1,970.00	\$ 1,690.00
Calculated Cost (S\$) :	\$ 7,352.60	\$ 3,703.50

Recommended Lump Sum Repair Cost (S\$) : \$ 3,000.00

Date of Assignment: 8/5/2018
Date Inspected: 8/5/2018
Est. repair Period: 10 days

Inspected At: One Zone Autocare
No 7 Soon Lee Street
Ispace Building #01-05
Singapore 627608

POINT OF IMPACT

Damaged at right hand rear portion.	
-------------------------------------	--

BRIEF CIRCUMSTANCES OF ACCIDENT

The Insured's vehicle collided onto the Third Party's vehicle along Geylang Bahru, Block 84.

GENERAL DESCRIPTION OF DAMAGES

Our visual inspection of the vehicle revealed that the damages noted are at the right hand rear portion.

SPECIAL REMARKS

We have inspected the actual damages found on the vehicle and recommend the replacement of parts and repairs accordingly. The estimated repair cost is \$7,352.60. The repairer has agreed to undertake the repairs at our adjusted lump sum amount of \$3,000.00.

We have not authorised the repair. Under normal circumstances, estimated 10 working days are required to repair the vehicle.

We are pleased to advise that the inspection work was carried out accordingly, and hereby submit our Inspection Report and photographs.



Dave Chang
Automotive Appraiser
AUTO. ENG, CAE, CGI
MIRTE, MSAAA, MTM

Automotive Appraiser: Dave Chang

Please note that this report is solely based on our findings at the time and place of inspection. This inspection has been carried out to our best knowledge and ability. Any other liability is hereby excluded.

ANNEX A

REPAIR DETAILS

Recommended Parts

No	Qty	Description	Condition	Repairer's Amount	Adjuster's Amount
1	1	Rear bumper assy	warped/grazed	\$ 1,150.00	\$ 1,150.00 CUTV
2	1	Rear right fender assy	repair	\$ 4,813.00	\$ 5,800.00 650
		Less 30%		\$ 5,963.00	\$ 1,150.00 5,813.00
				\$ 1,788.90	\$ 345.00 1,443.90
				\$ 4,174.10	\$ 805.00 430.00
3	1	Rear bumper sponge	warped/necessary	\$ 196.00	\$ 196.00 98.00 455.00 CUTV
4	1	Rear right bumper reflector	necessary/bent	\$ 60.00	\$ 60.00 CRAY
5	2	Rear right door panel hinges @ 50.50	bent	\$ 220.00	\$ 101.00 220.00 BT V
6	1	Rear right taillamp	cracked	\$ 689.00	\$ 310.00 689.00 CUTV
		Less 10%		\$ 1,165.00	\$ 1,165.00 569.00
				\$ 116.50	\$ 116.50 56.00
				\$ 1,048.50	\$ 1,048.50 512.90
<u>Special Nett Items</u>					
1	12	Rear bumper clips	necessary	\$ 50.00	\$ 30.00 30.00 NECV
2	1	Rear right door glass sealant	necessary	\$ 80.00	\$ 80.00 NN X
3	1	Rear left door '70km/h' sticker	necessary	\$ 30.00	\$ 30.00 NN
				\$ 160.00	\$ 160.00 30.00
Total Parts				\$ 5,382.60	\$ 2,013.50

279.71
492.17

ANNEX B

REPAIR DETAILS

Recommended Labour

No	Description	Repairer's Amount	Adjuster's Amount
1	Labour for panel beating, cut, weld, straighten rear right, rear affected area and replace rear right and rear damaged parts.	\$ 800.00	\$ 700.00 <i>400.00 + 100.00</i>
2	To putty and spray painting rear right and rear portion.	\$ 800.00	\$ 700.00 <i>200.00 + 100.00</i>
3	To check wiring and rear taillamp.	\$ 50.00	\$ 30.00
4	To apply anti rust proofing to rear right affected area.	\$ 100.00	\$ 80.00 <i>30.00</i>
5	To remove and install rear inner garnish and trim to facilitate the repair.	\$ 120.00	\$ 100.00 <i>50.00</i>
6	Towing service.	\$ 100.00	\$ 80.00 <i>NN</i>
Total labour :		\$ 1,970.00	\$ 1,690.00 <i>910.00 / 710.00</i>

ANNEX C

REPAIR DETAILS

Adjusted Repair Cost

	Repairer's Amount	Adjuster's Amount
Total parts :	\$ 5,382.60	\$ 2,013.50 <i>979.50</i>
Total labour :	\$ 1,970.00	\$ 1,690.00 <i>710.00</i>
Total repair cost :	\$ 7,352.60	\$ 3,703.50 <i>1689</i>

Adjusted Repair Cost (Lump Sum Repair)

\$ 3,000.00
L/S
4
repair days 5 days



































...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 May 2018		07 May 2018 16:20 Edit Adj Rpt	S\$1,500.00 Edit Estimates	S\$1,500.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	Tan Ai Hwa, ID: S1611585A								
Main Claimant:	Windale Maintenance Pte Ltd, Co. Reg. No.: 200719335E								
Vehicle Reg. No.:	GBE6343X	Date of Loss:	03/05/2018 18:00 - :59 [27 Months and 3 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 557553	Policy/Cover Note No.:	10118175 (Comprehensive) Coverage: 04/04/2018 - 03/04/2019						
Vehicle Reg. No. (Insured):	SDW2188K	Policy No. (Claimant):							
		Excess:							
Repairer:	One Zone Autocare (HQ) 7 SOON LEE STREET, #01-05 I SPACE BUILDING, 627608 Jurong Island - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 05/07/2018]								
Driver/Custodian (Insured):	CHONG BI XUAN (27 / Female), NRIC: S9113554Z, Tel: +6597351807								
Adj Asg. Remarks:	on WP. Please contact us ASAP if you cannot attend this assignment.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> MSIG_SG (03/07/2018): Report Send Back Alerts - GBE6343X (TP) 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***GBE6343X (557553)**
[SDW2188K]
TP
Windale Maintenance Pte Ltd
May 3 2018 6:00PM
[Tan Ai Hwa]
One Zone Autocare

Upload Documents		Upload Photos	Compose New Letter	View View in Browser	
Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print	
1	07/05/18 15:17	Accident Statement From: SC - Reg. No: SDW2188K, Claimant: TAN AI HWA	 Load HTM	<input checked="" type="checkbox"/>	
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	11/05/18 12:47	General View	 Load JPG	<input checked="" type="checkbox"/>	
2	11/05/18 12:47	General View	 Load JPG	<input checked="" type="checkbox"/>	
3	11/05/18 12:47	General View	 Load JPG	<input checked="" type="checkbox"/>	
4	11/05/18 12:47	General View	 Load JPG	<input checked="" type="checkbox"/>	
5	11/05/18 12:47	General View	 Load JPG	<input checked="" type="checkbox"/>	
6	11/05/18 12:47	General View	 Load JPG	<input checked="" type="checkbox"/>	
7	11/05/18 12:47	General View	 Load JPG	<input checked="" type="checkbox"/>	
8	11/05/18 12:47	General View	 Load JPG	<input checked="" type="checkbox"/>	
9	11/05/18 12:47	General View	 Load JPG	<input checked="" type="checkbox"/>	
10	11/05/18 12:47	General View	 Load JPG	<input checked="" type="checkbox"/>	
11	11/05/18 12:47	General View	 Load JPG	<input checked="" type="checkbox"/>	
12	11/05/18 12:47	General View	 Load JPG	<input checked="" type="checkbox"/>	
13	11/05/18 12:47	General View	 Load JPG	<input checked="" type="checkbox"/>	
14	11/05/18 12:47	General View	 Load JPG	<input checked="" type="checkbox"/>	
15	11/05/18 12:47	General View	 Load JPG	<input checked="" type="checkbox"/>	
16	11/05/18 12:47	General View	 Load JPG	<input checked="" type="checkbox"/>	
17	11/05/18 12:47	General View	 Load JPG	<input checked="" type="checkbox"/>	
18	11/05/18 12:47	General View	 Load JPG	<input checked="" type="checkbox"/>	
19	11/05/18 12:47	General View	 Load JPG	<input checked="" type="checkbox"/>	
20	11/05/18 12:47	General View	 Load JPG	<input checked="" type="checkbox"/>	
21	11/05/18 12:47	General View	 Load JPG	<input checked="" type="checkbox"/>	
22	11/05/18 12:47	General View	 Load JPG	<input checked="" type="checkbox"/>	
23	11/05/18 12:47	General View	 Load JPG	<input checked="" type="checkbox"/>	
24	11/05/18 12:47	General View	 Load JPG	<input checked="" type="checkbox"/>	
25	11/05/18 12:47	General View	 Load JPG	<input checked="" type="checkbox"/>	
26	11/05/18 12:47	General View	 Load JPG	<input checked="" type="checkbox"/>	
27	11/05/18 12:47	General View	 Load JPG	<input checked="" type="checkbox"/>	
28	11/05/18 12:47	General View	 Load JPG	<input checked="" type="checkbox"/>	
29	11/05/18 12:47	General View	 Load JPG	<input checked="" type="checkbox"/>	
30	11/05/18 12:47	General View	 Load JPG	<input checked="" type="checkbox"/>	
31	11/05/18 12:47	General View	 Load JPG	<input checked="" type="checkbox"/>	
32	11/05/18 12:47	General View	 Load JPG	<input checked="" type="checkbox"/>	
33	11/05/18 12:47	General View	 Load JPG	<input checked="" type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail Print
34	11/05/18 12:47	General View		Load JPG <input checked="" type="checkbox"/>
35	11/05/18 12:47	General View		Load JPG <input checked="" type="checkbox"/>
36	11/05/18 12:47	General View		Load JPG <input checked="" type="checkbox"/>
37	11/05/18 12:47	General View		Load JPG <input checked="" type="checkbox"/>
38	11/05/18 12:47	General View		Load JPG <input checked="" type="checkbox"/>
39	11/05/18 12:47	General View		Load JPG <input checked="" type="checkbox"/>
40	11/05/18 12:47	General View		Load JPG <input checked="" type="checkbox"/>
41	11/05/18 12:47	General View		Load JPG <input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail Print
1	07/05/18 15:17	Third Party Accident Report From:SC - Reg. No: SDW2188K, Claimant: TAN AI HWA		Load PDF <input type="checkbox"/>
2	07/05/18 15:17	Third Party PRI GBE6343X From:SC - Reg. No: SDW2188K, Claimant: TAN AI HWA		Load PDF <input type="checkbox"/>
3	07/05/18 15:37	email trails from workshop		Load PDF <input type="checkbox"/>
4	02/07/18 17:01	REPAIR INVOICE, SURVEY INVOICE, SURVEY REPORT		Load PDF <input type="checkbox"/>
5	02/07/18 17:01	SURVEY coloured photos		Load PDF <input type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	18/07/18 12:04	PRS Invoice		Load PDF <input type="checkbox"/>
2	18/07/18 12:08	PHO		Load PDF <input type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 100px; width: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18008384/BSBE2-1

Date: 18/07/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 10118175

Claimant Vehicle
No : GBE6343X

Insured Vehicle No : SDW2188K

Date of Loss: 03/05/2018

Nature of Claim: TP Claim No: 557553

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBE6343X

Make & Model: NISSAN NV200, 1.5 D ABS AIRBAG 2WD 6DR (M)

Engine No: K9KC400D055195

Reg. Date: 30/01/2016 (Man. Year: 2015)

Chassis No: VSKYBAM20Z0120148

Colour: Silver

Odometer: 67595 km

Engine Capacity: 1461 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55Z R16

Rear Tyre Size: 205/55Z R16

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,382.60	997.91	4,384.69	81.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,970.00	910.00	1,060.00	53.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,352.60	1,907.91	5,444.69	74.05
Approved Total (Overridden) (S\$)		1,500.00		
Nett Amount (S\$)	7,352.60	1,500.00	5,852.60	79.60

INSPECTION

Date of Assignment: 07/05/2018

Date Inspected: 10/05/2018 Inspected At:

One Zone Autocare (HQ)
7 SOON LEE STREET, #01-05 I SPACE
BUILDING
Singapore 627608

Estimated Period of Repair: 4.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Hiew May Fung