

ASS. REC. BY:

REF: es/FCI18012040 / Uqd3/n2

Special Instruction:

Surveyor:

Manus

ASSIGNMENT (Office)

CWS

From (Person): Lurene jaw

of

FCI

Date/Time: 3/7/18 @ 9:57 am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLC 5986P

Insured:

SHC 7144L

at Workshop n/s

Trans Eurokars

Tel:

91277 928

of

5 ubi close

Policy No:

Claim No:

D18005104MFSTH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

25/06/2018

(Client's Record)

5/7/2018 @ 4pm

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 10:40am @ 3/7/18

Person Contacted:

Ronald

Vehicle IN (OUT)

Date/Time

Action/Instruction

(✓)

Estimate kindly ask for TP's VF to be forwarded.

SLC 5986P - X

SHC 7144L - X

(08/11/13) wof

REF: FCI

ASS. REC. BY:

ASSIGNMENT

From: Date: 5/7/2018

Estimated Cost:

ON ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLC 5986 P

at Workshop m/s Trans Eurokars

of 5 ubi close

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

4pm @ owner writing

Make of Veh:

Ronald

Kindly ask for TP's VF to be forwarded

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent?: Yes or No

CA / PR Seen: Consistent?: Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 13.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (up)

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SLC 5986 Yr Regn: 5T16

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

me 2 de 6

c.c.

1998

Colour:

Red

A/C: Insured / Std / NI / NA

Sp. Reading:

46284

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JM6GJ107260233214

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/55R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

6

mm

Rear

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

25/6/18

D.O.I.

5/7/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rf.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

according from repairer Ronald No video footage
for door scratched.11/10/18 Conf. and find by 5274.28 with cotheine.
Used 5704.05, 5712

RECEIVED 11 OCT 2018

Date/Time, File Pass to?

☐

: Preli. Report

11/10/18

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Report Format:

7P

Lump Sum / I.B.I. (\$

5274.28)

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

170

50

50

36

306



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18012040/Uqd3

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 03-07-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 7144L	Veh. Inspected	SLC 5986P
Policy No.		Coverage (\$)	0.00
Claim No.	D18005104MFSH	Excess (\$)	0.00
Assign From	CWS (LURENE JAW)	Assign Date	03/07/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	25/06/2018	Inspection Date
Survey held at	TRANS EUROKARS PTE LTD NO 5 UBI CLOSE SINGAPORE 408605	

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18005104MFSH

Date: 06 July 2018

Our Ref: CS/FCI18012040/Uqd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLC 5986P

Please be informed that we had conducted the inspection of the abovementioned vehicle on 05/07/2018 at the premises of M/s TRANS EUROKARS, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>10,884.28</u>
Revised Estimate Amount	: S\$ <u>3,920.23</u>
"Check" Items Amount	: S\$ <u>1,890.00</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages at the o/s front portion.



Yours faithfully

CHUA KANG SENG
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	29-06-2018	Our Ref No. D18005104MFSH
Accident Date	25-06-2018	Claim Type. Third Party
Insured Vehicle	SHC7144L	Third Party Vehicle. SLC5986P
Survey Location	5 UBI CLOSE,	
Contact Person.	RONALD YAP	
Contact No.	63958899/ 91277928	Fax No. 0
Survey Type	WITHOUT PREJUDICE: KINDLY ASK FOR TP'S VF TO BE FORWARDED TO US SOONEST.	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TRANS EUROKARS PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/241930)



PRI Documents



Close



PRI Header Details

Claim No	D18005104MFSH	Policy No	D-18088937MFSH	Claimant S.No & Name	1 & TRANS EL
Workshop Name	TRANS EUROKARS PTE LTD (Contact Person : RONALD YAP)	Survey Location & Contact Details	5 UBI CLOSE, Mobile: 91277928 , Phone: 63958899 , Fax: 0 EmailId: RONALD.YAP@EUROKARS.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: KINDLY ASK FOR TP'S VF TO BE I SOONEST.		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHC7144L	TP Vehicle No	SLC5986P
PRI Recieved Date	29-06-2018 06:13:45 PM	Surveyor Appointed Date	03-07-2018 09:56:35 AM	Surveyor Accept Date	03-07-2018 1

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	03-07-2018	Upload Survey Report *:	Choose File
-----------------------------	----------------------	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

Upload Multiple Documents	
File Name	Action

Surveyor Job Remarks

Remarks		Save
---------	----------------------	-------------------------------------

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 6 July 2018 1:06 PM
To: 'Claim Workflow System'; assignments
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18005104MFSH/1
Attachments: CSFCI18012040Uqd3.pdf

Dear Lurene,

Enclosed herewith preliminary advice of SLC 5986P.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 3 July 2018 10:47 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18005104MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 3 July 2018 9:57 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; LURENEJAW@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18005104MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System



TRANS EUROKARS PTE LTD
NO:5 UBI CLOSE, SINGAPORE 408605
ESTIMATE COST OF REPAIRS



FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSE SINGAPORE 068877 ATTN.: MOTOR CLAIMS FAX:		NAME: Ms Chew Li-May ADDRESS: 97 Jalan Sendudok #03-59 Singapore 769474 TEL: 97494470	WIP: 19866 EXCESS: DATE: 26-Jun-18
VEH NO:	SLC5986P	DATE IN:	CONTACT PERSON: Ronald 63957875
CHASSIS NO:	JM6GJ1072G0233214	MILEAGE:	TYPE OF CLAIM: THIRD PARTY CLAIM
MODEL:	MAZDA6 2.0L	DATE REG.: 19-May-16	POLICY NO.:

NATURE OF WORKS

Parts Description

NO	QTY			REVISED	PRICES
1	FRONT BUMPER	1	MGHP9-50-031CBB	de/hay	\$ 1,096.40
2	RETAINER RHS	1	MGHP9-50-0T1B	re	\$ 16.20
3	CLIP, FRONT BUMPER	6	MB455-56-135	re	\$ 19.20
4	FASTENER, FRONT BUMPER	2	MB45A-56-146A	re	\$ 5.60
5	GROMMET, FRONT BUMPER	2	MGHP9-50-0Z5	re	\$ 5.40
6	FRONT FENDER RHS	1	MGHP9-52-111A	Body ID	\$ 365.40
7	STAY(RHS), FENDER	1	MGHY9-52-10YD	re	\$ 51.60
8	MUDGUARD RHS	1	MGHP9-56-130K	re	\$ 108.80
9	FASTENER, MUDGUARD	17	MB45A-56-146A	re	\$ 47.60
10	HEADLAMP RHS	1	MGLJ7-51-0K0B	cu	\$ 917.60
11	CLIP, HEADLAMP	2	MFB01-50-133C	re	\$ 7.60
12	RIVET, HEADLAMP	1	MB092-51-833	re	\$ 3.30
13	FRONT WHEEL RIM RHS	1	M9965-07-7570	R	\$ 1,277.10
14	WHEEL BEARING RHS	1	MKD35-33-04XE	re	\$ 539.70
15	KNUCKLE RHS	1	MGHP9-33-021A	re	\$ 387.70
16	FRONT TYRE RHS	1		re	\$ 400.00
	TOTAL PARTS				\$ 5,249.20
	LESS 10%				\$ 524.92
	TOTAL PARTS COST				\$ 4,724.28

Labour Description

1	MZ-BR-FRONT7	TO REPLACE FRONT BUMPER AND FRONT FENDER. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	660	990	\$ 1,980.00
2	MZ-SP-SFRT07	TO RESPRAY FRONT BUMPER AND FRONT FENDER.		1260	\$ 1,890.00
3	MZ-BR-AXNSUP	TO REPLACE AXLE AND SUSPENSION MECHANISM.		111X	\$ 660.00

4	MZ-BR-WHEBAL	TO MOUNT SPORT RIM AND CONDUCT WHEEL BALANCING.	111	NETT	\$ 120.00
5	MZ-BR-WHEALI	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT.	250	NETT	\$ 560.00
6	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	111 X		\$ 250.00
7	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	120		\$ 250.00
8	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	150		\$ 350.00
9	MZ-BR-SUNDRI	SUNDRIES.	111 30	NETT	\$ 100.00
				TOTAL LABOUR	\$ - \$ 6,160.00
				TOTAL PARTS	\$ - \$ 4,724.28
				TOTAL	\$ - \$ 10,884.28
				LESS EXCESS	\$ - \$ -
				TOTAL AFTER EXCESS	\$ -
				GST 7%	\$ - \$ -
				GRAND TOTAL	\$ - \$ -

TRANS EUROKARS PTE LTD

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

Authorised Signature

LKK Auto Consultancy hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

10798.33



TRANS EUROKARS PTE LTD
NO:5 UBI CLOSE, SINGAPORE 408605
FINALISED COST OF REPAIRS



FIRST CAPITAL INSURANCE LTD		NAME : Ms Chew Li-May		WIP : 19866	
36 ROBINSON ROAD		ADDRESS : 97 Jalan Sendudok		EXCESS :	
#16-01 CITY HOUSE		#03-59		DATE: 26-Jun-18	
SINGAPORE 068877		Singapore 769474			
ATTN. : MOTOR CLAIMS		TEL : 97494470			
FAX :					
VEH NO :	SLC5986P	DATE IN :		CONTACT PERSON :	Ronald 63957875
CHASSIS NO :	JM6GJ1072G0233214	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA6 2.0L	DATE REG.:	19-May-16	POLICY NO. :	

NATURE OF WORKS					
Parts Description					
NO	QTY			REVISED	PRICES
1	FRONT BUMPER	1	MGHP9-50-031CBB	\$ 1,096.40	\$ 1,096.40
2	RETAINER RHS	1	MGHP9-50-0T1B	\$ 16.20	\$ 16.20
3	CLIP, FRONT BUMPER	6	MB455-56-135	\$ 19.20	\$ 19.20
4	FASTENER, FRONT BUMPER	2	MB45A-56-146A	\$ 5.60	\$ 5.60
5	GROMMET, FRONT BUMPER	2	MGHP9-50-0Z5	\$ 5.40	\$ 5.40
6	FRONT FENDER RHS	1	MGHP9-52-111A	\$ 365.40	\$ 365.40
7	STAY(RHS), FENDER	1	MGHY9-52-10YD	\$ 51.60	\$ 51.60
8	MUDGUARD RHS	1	MGHP9-56-130K	\$ 108.80	\$ 108.80
9	FASTENER, MUDGUARD	17	MB45A-56-146A	\$ 47.60	\$ 47.60
10	HEADLAMP RHS	1	MGLJ7-51-0K0B	\$ 917.60	\$ 917.60
11	CLIP, HEADLAMP	2	MFB01-50-133C	\$ 7.60	\$ 7.60
12	RIVET, HEADLAMP	1	MB092-51-833	\$ 3.30	\$ 3.30
13	FRONT WHEEL RIM RHS	1	M9965-07-7570		\$ 1,277.10
14	WHEEL BEARING RHS	1	MKD35-33-04XE		\$ 539.70
15	KNUCKLE RHS	1	MGHP9-33-021A		\$ 387.70
16	FRONT TYRE RHS	1			\$ 400.00
17	TANK, WASHER	1	MGHR1-67-481	\$ 104.50	\$ 104.50
TOTAL PARTS				\$ 2,749.20	\$ 5,249.20
LESS 10%				\$ 274.92	\$ 524.92
TOTAL PARTS COST				\$ 2,474.28	\$ 4,724.28

Labour Description						
1	MZ-BR-FRONT7	TO REPLACE FRONT BUMPER AND FRONT FENDER. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.			\$ 990.00	\$ 1,980.00
2	MZ-SP-SFRT07	TO RESPRAY FRONT BUMPER AND FRONT FENDER.			\$ 1,260.00	\$ 1,890.00
3	MZ-BR-AXNSUP	TO REPLACE AXLE AND SUSPENSION MECHANISM.				\$ 660.00

4	MZ-BR-WHEBAL	TO MOUNT SPORT RIM AND CONDUCT WHEEL BALANCING.		\$ 120.00
5	MZ-BR-WHEALI	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT.	\$ 250.00	\$ 560.00
6	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.		\$ 250.00
7	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	\$ 120.00	\$ 250.00
8	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	\$ 150.00	\$ 350.00
9	MZ-BR-SUNDRI	SUNDRIES.	\$ 30.00	\$ 100.00
			TOTAL LABOUR	\$ 2,800.00 \$ 6,160.00
			TOTAL PARTS	\$ 2,474.28 \$ 4,724.28
			TOTAL	\$ 5,274.28 \$ 10,884.28
			LESS EXCESS	\$ - \$ -
			TOTAL AFTER EXCESS	\$ 5,274.28
			GST 7%	\$ 369.20 \$ -
			GRAND TOTAL	\$ 5,643.48 \$ -

REMARKS:

4 REPAIR DAYS (exclude preparation of estimate, wait for survey/authorization/spare parts, Sat/Sun/PH)

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18012040/Uqd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 17-10-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 7144L	Veh. Inspected	SLC 5986P	
Policy No.	D-18088937MFSH	Coverage (\$)	0.00	
Claim No.	D18005104MFSH	Excess (\$)	0.00	
Assign From	LURENE	Assign Date	03/07/2018	
2. Vehicle Particulars & Condition				
Make & Model	MAZDA 6 (A)	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JM6GJ1072G0233214	Colour	RED	
Odometer	46284	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/55 R17	TOYO	6 mm	
L/H Front Tyre	225/55 R17	TOYO	6 mm	
R/H Rear Tyre	225/55 R17	TOYO	6 mm	
L/H Rear Tyre	225/55 R17	TOYO	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	25/06/2018	Inspection Date	05/07/2018	
Survey held at	TRANS EUROKARS PTE LTD NO 5 UBI CLOSE SINGAPORE 408605			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLC 5986P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	DEFORMED / WARPED	1,096.40	1,096.40
1	RETAINER RHS	BENT	16.20	16.20
6	CLIP, FRONT BUMPER	NECESSARY	19.20	19.20
2	FASTENER, FRONT BUMPER	NECESSARY	5.60	5.60
2	GROMMET, FRONT BUMPER	NECESSARY	5.40	5.40
1	FRONT FENDER RHS	BADLY DENTED	365.40	365.40
1	STAY (RHS), FENDER	NECESSARY	51.60	51.60
1	MUDGUARD RHS	DEFORMED	108.80	108.80
17	FASTENER MUDGUARD	NECESSARY	47.60	47.60
1	HEADLAMP RHS	CUT	917.60	917.60
2	CLIP, HEADLAMP	NECESSARY	7.60	7.60
1	RIVET, HEADLAMP	NECESSARY	3.30	3.30
1	FRONT WHEEL RIM RHS	TO REPAIR SEE LABOUR	1,277.10	-
1	WHEEL BEARING RHS	NOT NECESSARY	539.70	-
1	KNUCKLE RHS	NOT NECESSARY	387.70	-
1	FRONT TYRE RHS	NOT NECESSARY	400.00	-
1	TANK, WASHER (ADDITIONAL)	DEFORMED	104.50	104.50
	LESS 10% DISCOUNT		-535.37	-274.92
			4,818.33	2,474.28
SPECIAL NETT ITEMS				
1	SUNDRIES (SN)	NECESSARY	100.00	30.00
			100.00	30.00
LABOUR				
	TO REPLACE FRONT BUMPER AND FRONT FENDER. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT. INCLUSIVE OF THE REPAIR OF FRONT WHEEL RIM RHS.		1,980.00	990.00
	TO RESPRAY FRONT BUMPER AND FRONT FENDER.		1,890.00	1,260.00
	TO REPLACE AXLE AND SUSPENSION MECHANISM.	NOT NECESSARY	660.00	-

Report Ref No. CS/FCI18012040/Uqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO MOUNT SPORT RIM AND CONDUCT WHEEL BALANCING.	NOT NECESSARY	120.00	-
	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT.		560.00	250.00
	TO CARRY-OUT BODY CAVITY PRESERVATION.	NOT NECESSARY	250.00	-
	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		250.00	120.00
	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		350.00	150.00
			6,060.00	2,770.00
	GRAND TOTAL		10,978.33	5,274.28
RECOMMENDED COST OF REPAIRS				5,274.28

Report Ref No. CS/FCI18012040/Uqd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.