



陳林坤峰私人有限公司  
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216  
Tel : 68585151 ( 24 Hours ) Fax : 68580877  
GST Regn. No. : M2-8922054-2

FWD Insurance Insured's Veh No : SLX9978B  
Date of Accident : 01 July 2018

Miss Teo Beng Swan Janet

Date : 02 July 2018

Estimate To Repair SKU1231C - Honda FIT 1.3G CVT ABS D/AIRBAG 2WD  
Chassis No : GK31015870

S/No	Quantity	Description	Amount
		<u>LIST ITEMS</u>	
01	1 pc	o/s front fender	\$ 435.00
02	1 pc	front fender inner liner	\$ 71.50
03	4 pc	front fender inner liner clips @ \$3.50	\$ 14.00
04	1 pc	front fender air baffle	\$ 18.00
05	1 pc	o/s front door	\$ 757.00
06	1 ps	front door window frame matt tape sticker	\$ 30.50
07	1 pc	front door outer weatherstrip molding	\$ 43.90
08	1 pc	front door window glass channel weatherstrip	\$ 33.10
09	1 pc	o/s front shock absorber	\$ 310.00
10	1 pc	front shock absorber top mount	\$ 36.80
11	1 pc	front wheel bearing	\$ 168.00
12	1 pc	front wheel bearing with hub	\$ 138.30
13	1 pc	front lower arm	\$ 160.00
14	1 pc	front wheel kunckle	\$ 230.00
			\$ 2,446.10
		Less 20 %	\$ 489.22
			\$ 1,956.88
		<u>SPECIAL NETT ITEMS</u>	
15	1 pc	o/s front wheel rim	\$ 500.00
16	1 pc	front wheel tyre	\$ 350.00
			\$ 850.00
		<u>LABOUR &amp; MISC. CHARGES</u>	
01		To transfer of o/s front door fittings and perform water seepage test.	\$ 180.00
02		To rust-proofing of the affected areas.	\$ 150.00
03		To check electrical lighting concerned.	\$ 40.00
04		To drop o/s front suspension undercarriage parts, remove and renewal of the necessary parts, to perform final checking and testing.	\$ 300.00
05		To check steering geometry and computer wheel alignment.	\$ 150.00
06		To transfer of o/s front tyre, rim and on wheel balancing.	\$ 50.00
07		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 550.00
08		Putty and spray painting of the affected portion.	\$ 780.00
			\$ 2,200.00
		Total	\$ 5,006.88