




## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CC4/ASM18012055/T1pb3s2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: STACEY NG			Date : 13-11-2019	
			Code : ASM	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	CB 7553D	Veh. Inspected	SLQ 6217X	
Policy No.	P0986645	Coverage (\$)	0.00	
Claim No.	S8M00MX9	Excess (\$)	0.00	
Assign From	STACEY NG	Assign Date	03/07/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	MITSUBISHI LANCER EX 1.6	c.c	1590	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JMYSRCY1AGU007059	Colour	RED	
Odometer	063962	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	205/50 R16	ACHILLES	6 mm	
L/H Front Tyre	205/50 R16	ACHILLES	6 mm	
R/H Rear Tyre	205/50 R16	ACHILLES	6 mm	
L/H Rear Tyre	205/50 R16	ACHILLES	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.				
REPAIR CONDITION SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	22/06/2018	Inspection Date	01/10/2018	
Survey held at	6 BENOI SECTOR			
Repairer	VERMOGEN ACE PTE LTD			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>12 Working Days</b>		