

Signature

REF:

NS/INC 18012121/81602

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

YP 5795B

Policy No:

5087982488-01 230218-200219

Claims No:

MT/1001280-002

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHB 2196

Yr Regn:

Mar, 2016

Type: M.Car / M.Cycle / Bus / Van / Lorry / ☒ Prime Mover /

Truck / Trailer or

Make:

Toyota Prins

C.C.

1798

Colour:

Maroon

A/C:

Insured / Std / NI / NA

Sp. Reading

251296

T/Radio:

Insured / Std / NI / NA

Eng/No:

2ZR1669491

C/No:

5TDKN36U305767589

Gen. Cond:

Good / Fair / Poor / Burnt

Steering:

Insured / Jammed / Leaked / Burnt or

Brake:

Insured / Jammed / Leaked / Burnt or

Modi:

Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65 R15

R:

195/65 R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Falken

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

30/6/2012

D.O.I.

3/7/2018

Survey held at

SMART

Des. of Damages:

Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

SHB 2196 - CCH / AXA 16007835 / Klyb3g

DA: 250416 FAX / 06 / 18 / 2145

17/7/18 Final fig \$ 2328.62 confirmed by email (Red 7752.08, 7710) NTUC

- YP 5795B

RECEIVED 18 JUL 2018

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

18/7 - typist

Days Of Repair:

4

Resurvey No. of Trip:

1

Survey Fee:

160

Transportation:

) S + RS \$

) Photos:

) Others:

TOTAL

160

Report Format:

TP

Lump Sum / I.B.I. (\$

2328.62

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Veron Chen (LKKAUTO)

From: mtreg <mtreg@income.com.sg>
Sent: Wednesday, 18 July 2018 8:34 AM
To: Veron Chen (LKKAUTO)
Subject: FW: REQUEST FOR CLAIM NUMBER

Hi,

Claim created.

With Regards

Samsia
Senior Admin Assistant, Motor Insurance
www.income.com.sg



From: Veron Chen (LKKAUTO) [mailto:veronchen@lkkauto.com]
Sent: Tuesday, July 17, 2018 4:55 PM
To: mtreg <mtreg@income.com.sg>
Subject: REQUEST FOR CLAIM NUMBER

Dear Sir/Madam,

Kindly provides us the claim number.

S/NO	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle
1	MT/1001280-002	SMRT TAXIS PTE LTD	SHB 219G	YP 5795B

D.O.A	Time of Accident	Estimate	Tentative repair cost
30/6/2018	20:00	\$10,080.70	\$2,328.62

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

eBaoTech

Hello, NAC_PAYA_UBI_800601

[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No.

Date of Account

Vehicle No. (For Motor)

YP5795B

[Search](#)

Select	Policy No.	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured	Policy Date
<input checked="" type="radio"/>	5087982488-01	DHEERAN PTE LTD	201602015E	GCV	Comprehensive	YP5795B	Yes	02/2019

[Continue](#)

> Back to OneMotoring

Enquire Transfer Fee

Vehicle Details

Vehicle No. :	SHB219G
Vehicle Type :	H10 - Public Transport Taxi (Motor Car)
Vehicle Attachment 1 :	Air-Con (Taxi)
Vehicle Scheme :	Taxi (Company)
Vehicle Make :	TOYOTA
Vehicle Model :	PRIUS TAXI (SMRT)
Chassis No. :	JTDKN36U305767589
Propellant :	Petrol-Electric
Engine No. :	2ZR1669491
Motor No. :	3JM1669491
Engine Capacity :	1798 cc
Power Rating :	60.0 kW
Maximum Power Output :	100.0 kW (134 bhp)
Maximum Laden Weight :	1805 kg
Unladen Weight :	1370 kg
Year Of Manufacture :	2015
Original Registration Date :	11 Mar 2016
Lifespan Expiry Date :	10 Mar 2024
COE Category :	A - Car up to 1600cc & 97kW (130bhp)
PQP Paid :	\$39,633.00
COE Expiry Date :	10 Mar 2024
Road Tax Expiry Date :	10 Sep 2018
PARF Eligibility Expiry Date :	10 Mar 2024
Inspection Due Date :	10 Sep 2018
Intended Transfer Date :	04 Jul 2018
CO2 Emission :	92.00 (g/km)
CEV/VES Rebate Utilised Amount :	\$28,312.00
CO Emission :	-
HC Emission :	-
NOx Emission :	-
PM Emission :	-

The current road tax expiry is 10 Sep 2018. You may renew the road tax from 11 Jun 2018 with all pre-requisite(s) fulfilled. If the road tax is renewed after 10 Sep 2018, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable (From 11 Sep 2018 to 10 Mar 2019)

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Sub Total :			25.00
Nett Road Tax Amount (After Offsetting Over Payment) :	510.00	-	510.00
Total Amount Payable :			535.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

You may print this page for reference.

OK

Print

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	02/07/2018 10:57
Date Of Accident	30/06/2018 20:00
Exact Location Of Accident	CHANGI ROAD TOWARDS GEYLANG SERAI (NEAR LOR 107)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB219G
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18090213MFSH
Cover Note Number	

Driver

Name of Driver	LING WAI PING
NRIC No	S1268254I
Date Of Birth	07/01/1957
Occupation	OUTDOOR
Date Of Driving Pass	05/06/1976
Driving Experience	42 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	11
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident


I WAS TRAVELLING ALONG CHANGI ROAD TOWARDS GEYLANG SERAI (NEAR LOR 107). AS I SLOWED DOWN, SUDDENLY I FELT AN IMPACT AT THE REAR OF MY TAXI. A VEHICLE YP5795B HAD COLLIDED ONTO THE REAR OF MY TAXI.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE TOO BIG
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YP5795B
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	RAMASAMYCHOKKALINGAM SIVA RAMA KRISHNAN
NRIC/Passport Number	G923221T
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	



$\boxed{A} \rightarrow \text{SHB 219 G}$

2/7/18

$\boxed{B} \rightarrow YP\ 5795\ B$

df

[illegible]

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature _____
Date & Time: _____

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

© 2004 Blackwell Publishing Ltd *Journal of Internal Medicine* 255: 111–117

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)

Date & Time: 2/7/18
10.40 am

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

GIA/MA/SMART/PTC/...

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB219G
 Ref. No : TAX/06/18/2145
 Reg. Date : 11/03/2016
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS
 Name of Driver : LING WAI PING
 Type of Accident : HEAD TO REAR
 Date / Time of Accident : 30/06/2018 08:00:00 PM
 Accident Reported Date / Time : 02/07/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024096808
 Special Instruction to ARC, if any :
 YP5795B - NTUC - LKK
 Prepared Date : 02/07/2018 11:24:03 AM



Sathya Sai
 3/7/2018

3 days


 still

- Part by Part repair
- Question mark item photo
- Photo before paint.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U305767589

Mileage :

0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,014.00	0.00
Total Spray Painting Charges	: 1,674.00	0.00
Total Material Charges	: 5,193.92	5,193.92
Other Charges	: 700.00	0.00
TOTAL	: 8,581.92	0.00
Lum Sum Total	: 0.00	0.00
No. of Repair Days	: 7.00	0.00 3 days
Prepared / Adjusted By	:	
Arc / Surveyor Sing Off Date	: 02/07/2018 07:10:23 PM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 02/07/2018 07:10:23 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount :	Prepared Date :

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	1,014.00	0.00 600
Total Labour	1,014.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	0.00 200
TO RESPRAY BUMPER BEAM	180.00	0.00 ?
TO RESPRAY REAR PANEL	180.00	0.00 ?
TO RESPRAY TAIL GATE	378.00	0.00 X
TO RESPRAY REAR FENDER LH	378.00	0.00 X
TO RESPRAY SPOILER	180.00	0.00 X
Total Spray Painting & Panel Beating	1,674.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 50
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00 50
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00 60
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	0.00 60
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	0.00 50
TO REPLACE SUNDRY PARTS	100.00	0.00 20
TO WASH AND VACUUM	60.00	0.00 X
Total Other Costs	700.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
52159-47905		6505548	BUMPER REAR ✓ <i>LT</i>	1	458.60	25.00	343.95	Replace	Replace	No
			PIXEL STICKER ✓ <i>NEC</i>	2	60.00	0.00	120.00	Replace	Replace	No
90467-07211			BUMPER CLIPS ✓ <i>NEC</i>	10	2.10	25.00	15.75	Replace	Replace	No
52576-47020		6505550	BUMPER SIDE RETAINER RR/LH ✓ <i>CRK</i>	1	94.80	25.00	71.10	Replace	Replace	No
52575-47020		6505549	BUMPER SIDE RETAINER RR/RH X	1	94.80	25.00	71.10	Replace	Replace	No
76088-47020		6505617	BUMPER LIP COVER ✓ <i>CRK</i> RR/LH	1	72.20	25.00	54.15	Replace	Replace	No
76087-47020		6505618	BUMPER LIP COVER X RR/RH	1	118.10	25.00	88.57	Replace	Replace	No
76891-47020		6505619	BUMPER LIP REAR ✓ <i>CRK</i>	1	228.90	25.00	171.67	Replace	Replace	No
52592-47021			BUMPER SEAL, RR LH ?	1	88.90	25.00	66.67	Replace	Replace	No
58308-47011			UNDER COVER SUB-ASSY, RR FLOOR ?	1	514.50	25.00	385.87	Replace	Replace	No
81561-47170		6505461	TAIL LAMP LH X	1	548.40	10.00	493.56	Replace	Replace	No
52563-47010			TAIL LAMP BRACKET, LH X	1	30.70	25.00	23.02	Replace	Replace	No
			SENSOR REVERSE. ?	1	180.00	0.00	180.00	Replace	Replace	No
52023-12240		6505547	BUMPER REINFORCEMENT ? REAR	1	205.70	25.00	154.27	Replace	Replace	No
52016-47030			ARM SUB-ASSY, RR BUMPER LH ?	1	139.60	25.00	104.70	Replace	Replace	No
52015-47050			ARM SUB-ASSY, RR BUMPER RH ?	1	139.60	25.00	104.70	Replace	Replace	No
58307-47060		6505522	END PANEL ?	1	602.10	25.00	451.57	Replace	Replace	No
	COMMO N	4006314	SEALANT SIKAFLEX X	1	37.00	0.00	37.00	Replace	Replace	No
67005-47241			TAILGATE ASY X	1	1,007.90	25.00	755.92	Replace	Replace	No
75374-47051			NAME PLATE (HYBRID) X	1	51.90	25.00	38.92	Replace	Replace	No
61602-47091		6505476	FENDER RR/LH X	1	766.80	25.00	575.10	Replace	Replace	No
			STICKER DECAL SMRT X	1	7.80	0.00	7.80	Replace	Replace	No
			STICKER DECAL 6555 8888 X	1	21.60	0.00	21.60	Replace	Replace	No
76085-47910		6505620	SPOILER REAR X	1	953.70	25.00	715.27	Replace	Replace	No
89997-30070			ANTENNA, ELECTRICAL LOWER REAR ?	1	157.40	10.00	141.66	Replace	Replace	No
TOTAL MATERIALS								5,193.97	5,193.92	
TOTAL MATERIALS(Discounted)							5,193.92	5,193.92		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
-------------	---------	-----------	-----	-----------------	--------------	------------------	-----------	----------------	----------



6-7.18/12.11


6.7.18/16.11

SMRT Accident Vehicle Repair Estimates

3-7-18/16.11

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB219G
 Ref. No : TAX/06/18/2145
 Reg. Date : 11/03/2016
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS
 Name of Driver : LING WAI PING
 Type of Accident : HEAD TO REAR
 Date / Time of Accident : 30/06/2018 08:00:00 PM
 Accident Reported Date / Time : 02/07/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by : Sathya
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024096808
 Special Instruction to ARC, if any :
 YP5795B - NTUC - LKK
 BEFORE PAINT PHOTO, Question mark item photo, part by part repair, FOR CHECK ITEM AND REPLACE ITEM
 PLEASE CALL SURVEYOR SATHYA (LKK) & Email : SathyaSai@lkkauto.com/ HP:9807 2012
 Prepared Date : 02/07/2018 11:24:03 AM



Recording Camera

☒ ☐

Radio Antenna

☒ ☐
1st witness

Date 3-7-18

2nd witness

Date

251296
 4/7/18

9/7/18 13:35
 Supplementary

R2 bumper & KIT to Refa to the Supplementary pay 161

161 00P463
 SHENG AUTO PTE LTD

Vehicle Return Date: 9-7-2018

Vehicle Return Time: 12:00 am

SMRT staff sign: _____

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U305767589

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,014.00	600.00
Total Spray Painting Charges	: 1,674.00	200.00
Total Material Charges	: 2,389.10	1,690.18
Other Charges	: 700.00	290.00
TOTAL	: 5,777.10 10,080.20	2,780.18
Lump Sum Total	: 0.00	0.00
No. of Repair Days	: 7.00	4.00 ✓
Prepared / Adjusted By	:	SATHYA (LKK)
Arc / Surveyor Sing Off Date	: 02/07/2018 07:10:23 PM	03/07/2018 04:11:17 PM

M

LKK

Prepared / Adjusted Date :

Remarks :

Prepared Date : 02/07/2018 07:10:23 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : QN-1807-0329

Invoice No :

Quotation Date : 14/7

Invoice Date :

Invoice Amount : 0.00

Prepared Date : 7/3/2018 4:11:59 PM

~~1690.18 x~~
~~+ 600.00~~
~~+ 490.00~~
~~2780.18~~

1238.62
+ 600
+ 490
2328.62 @ 4 days
Confirmed.

Section D - Details of Repair Estimates**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	1,014.00	600.00 ✓
Total Labour	1,014.00	600.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	200.00 ✓
TO RESPRAY BUMPER BEAM	180.00	0.00
TO RESPRAY REAR PANEL	180.00	0.00
TO RESPRAY TAIL GATE	378.00	0.00
TO RESPRAY REAR FENDER LH	378.00	0.00
TO RESPRAY SPOILER	180.00	0.00
Total Spray Painting & Panel Beating	1,674.00	200.00 ✓

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	50.00 ✓
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	50.00 ✓
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	60.00 ✓
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	60.00 ✓
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	50.00 ✓
TO REPLACE SUNDRY PARTS	100.00	20.00 ✓
TO WASH AND VACUUM	60.00	0.00
Total Other Costs	700.00	290.00

10080-70

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached	
52159-47905		6505548	BUMPER REAR	1	458.60	25.00	343.95	Replace	Replace	No	CUT
			PIXEL STICKER	2	60.00 ¹²⁰	0.00	120.00	Replace	Replace	No	
90467-07211			BUMPER CLIPS	10	2.10 ²¹	25.00	15.75	Replace	Replace	No	NEC
52576-47020		6505550	BUMPER SIDE RETAINER RR/LH	1	94.80	25.00	71.10	Replace	Replace	No	CRK
52575-47020		6505549	BUMPER SIDE RETAINER RR/RH	0	94.80	25.00	0.00	Replace	Not given	No	NN
76088-47020		6505617	BUMPER LIP COVER RR/LH	1	72.20	25.00	54.15	Replace	Replace	No	CRK
76087-47020		6505618	BUMPER LIP COVER RR/RH	0	118.10	25.00	0.00	Replace	Not given	No	NN
76891-47020		6505619	BUMPER LIP REAR	1	228.90	25.00	171.67	Replace	Replace	No	CRK
52592-47021			BUMPER SEAL, RR LH	1	88.90	25.00	66.68	Replace	Check	No	NN
58308-47011			UNDER COVER SUB-ASSY, RR FLOOR	1	514.50	25.00	385.88	Replace	Check	No	
81561-47170		6505461	TAIL LAMP LH	0	548.40	10.00	0.00	Replace	Not given	No	
52563-47010			TAIL LAMP BRACKET, LH	0	30.70	25.00	0.00	Replace	Not given	No	
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace	No	DMG
52023-12240		6505547	BUMPER REINFORCEMENT REAR	1	205.70	25.00	154.28	Replace	Replace	No	DT
52016-47030			ARM SUB-ASSY, RR BUMPER LH	1	139.60	25.00	104.70	Replace	Replace	No	DT
52015-47050			ARM SUB-ASSY, RR BUMPER RH	1	139.60	25.00	104.70	Replace	Check	No	NN
58307-47060		6505522	END PANEL	1	602.10	25.00	451.58 ⁰	Replace	Replace	No	R
	COMMO N	4006314	SEALANT SIKAFLEX	0	37.00	0.00	0.00	Replace	Not given	No	
67005-47241			TAILGATE ASY	0	1,007.90	25.00	0.00	Replace	Not given	No	
75374-47051			NAME PLATE (HYBRID)	0	51.90	25.00	0.00	Replace	Not given	No	
61602-47091		6505476	FENDER RR/LH	0	766.80	25.00	0.00	Replace	Not given	No	
			STICKER DECAL SMRT	0	7.80	0.00	0.00	Replace	Not given	No	NN
			STICKER DECAL 6555 8888	0	21.60	0.00	0.00	Replace	Not given	No	
76085-47910		6505620	SPOILER REAR	0	953.70	25.00	0.00	Replace	Not given	No	
89997-30070			ANTENNA, ELECTRICAL LOWER REAR	1	157.40	10.00	141.66	Replace	Check	No	
52563-47010			TAIL LAMP BRACKET, LH	1	30.70	25.00	23.02	Replace	Replace	No	DT
TOTAL MATERIALS							2,389.11	1,690.18			
TOTAL MATERIALS(Discounted)							2,389.10	1,690.18			

Added Spare Parts / Material Usage After Surveyor Signed off

6692.70

Veron Chen (LKKAuto)

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) <YeoPohsuan@smrt.com.sg>
Sent: Tuesday, 17 July 2018 3:15 PM
To: Sathya Sai (LKK Auto)
Cc: SUR; CS A Team
Subject: RE: SHB219G

Hi

Amount confirmed @\$2,328.62 (4 days) as per your recommendation, thanks.

Regards
Poh Suan

-----Original Message-----

From: Sathya Sai (LKK Auto) [mailto:SathyaSai@lkkauto.com]
Sent: Tuesday, 17 July 2018 9:15 AM
To: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)
Cc: SUR; CS A Team
Subject: RE: SHB219G

Good Day,

There is a mistake in your calculations as the end panel was given as repair not replaced. Please refer to the attached for the amended COR for finalisation.

Thank you

Best Regards,
Sathya Sai | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 9807 2012 | Email: SathyaSai@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) [mailto:YeoPohsuan@smrt.com.sg]
Sent: Monday, 16 July, 2018 5:08 PM
To: Sathya Sai (LKK Auto)
Cc: SUR; CS A Team
Subject: SHB219G

Hi Sathya,

Attached herewith the repair estimate of SHB 219G having Case No: TAX/06/18/2145.

There is no change to the approved amount of \$2,780.18 @ 4 working days under part by part repair.

Cost of Repair invoice will be generated as approved.

Please finalize with me within 7 working day, thanks.

Thanks & Regards
Poh Suan

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)
Sent: Monday, 16 July 2018 3:12 PM
To: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)
Subject: Scan Data from FX-D421D6

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18012121/Bvbe2

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE Date: 01-08-2018
189556

Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YP 5795B	Veh. Inspected	SHB 219G
Policy No.	5087982488-01	Coverage (\$)	0.00
Claim No.	MT/1001280-002	Excess (\$)	0.00
Assign From		Assign Date	03/07/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	JTDKN36U305767589	Colour	MAROON
Odometer	251296	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	FALKEN	6 mm
L/H Front Tyre	195/65 R15	FALKEN	6 mm
R/H Rear Tyre	195/65 R15	FALKEN	6 mm
L/H Rear Tyre	195/65 R15	FALKEN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	30/06/2018	Inspection Date	03/07/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	-----------------------

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 219G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	BUMPER REAR (DISC 25%)	CUT	458.60	343.95
10	BUMPER CLIPS @\$2.10 (DISC 25%)	NECESSARY	21.00	15.75
1	BUMPER SIDE RETAINER RR/LH (DISC 25%)	CRACKED	94.80	71.10
1	BUMPER LIP COVER RR/LH (DISC 25%)	CRACKED	72.20	54.15
1	BUMPER LIP REAR (DISC 25%)	CRACKED	228.90	171.67
1	BUMPER REINFORCEMENT REAR (DISC 25%)	DENTED	205.70	154.28
1	ARM SUB-ASSY, RR BUMPER LH (DISC 25%)	DENTED	139.60	104.70
1	TAIL LAMP BRACKET, LH (DISC 25%)	DENTED	30.70	23.02
2	PIXEL STICKER @\$60.00 (SN)	NECESSARY	120.00	120.00
1	SENSOR REVERSE (SN)	DAMAGED	180.00	180.00
1	BUMPER SIDE RETAINER RR/RH	NOT NECESSARY	94.80	-
1	BUMPER LIP COVER RR/RH	NOT NECESSARY	118.10	-
1	BUMPER SEAL, RR LH	NOT NECESSARY	88.90	-
1	UNDER CPVER SUB-ASSY, RR FLOOR	NOT NECESSARY	514.50	-
1	TAIL LAMP LH	NOT NECESSARY	548.40	-
1	TAIL LAMP BRACKET, LH	NOT NECESSARY	30.70	-
1	ARM SUB-ASSY, RR BUMPER RH	NOT NECESSARY	139.60	-
1	SEALANT SILAFLEX	NOT NECESSARY	37.00	-
1	TAILGATE ASY	NOT NECESSARY	1,007.90	-
1	NAME PLATE (HYBRID)	NOT NECESSARY	51.90	-
1	FENDER RR/LH	NOT NECESSARY	766.80	-
1	STICKER DECAL SMRT	NOT NECESSARY	7.80	-
1	STICKER DECAL 6555 8888	NOT NECESSARY	21.60	-
1	SPOILER REAR	NOT NECESSARY	953.70	-
1	ANTENNA, ELECTRICAL LOWER REAR	NOT NECESSARY	157.40	-
1	END PANEL	TO REPAIR SEE LABOUR	602.10	-
			6,692.70	1,238.62
<u>LABOUR</u>				
PANEL BEATING & BODY WORK. INCLUSIVE OF THE REPAIR OF END PANEL.			1,014.00	600.00

Report Ref No. NS/INC18012121/Bvbe2



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPRAY PAINT.		1,674.00	200.00
	TO CHECK WIRING AND SYSTEM FUNCTION.		80.00	50.00
	TO APPLY RUST-PROOFING ON AFFECTED AREA.		100.00	50.00
	TO TEST AND REFIX REVERSE SENSOR SYSTEM.		120.00	60.00
	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.		120.00	60.00
	TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE.		120.00	50.00
	TO REPLACE SUNDRY PARTS.		100.00	20.00
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
			3,388.00	1,090.00
GRAND TOTAL			10,080.70	2,328.62
RECOMMENDED COST OF REPAIRS				2,328.62

Report Ref No. NS/INC18012121/Bvbe2

ANG BRYAN TANI

Automotive Assessor / Investigator

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.