

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref: CC4/ASM18012160/Kpb3s2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: KIAN CHUAN			Date: 06-09-2019 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	XE 3382S	Veh. Inspected	SJX 9519S
	Policy No.	GA257125/1	Coverage (\$)	0.00
	Claim No.	S8M00N6O	Excess (\$)	0.00
	Assign From	KIAN CHUAN	Assign Date	04/07/2018
2. Vehicle Particulars & Condition				
	Make & Model	LEXUS GS300 (A)	c.c	2995
	Engine No.	HIDDEN	Year of Reg.	2010
	Chassis No.	JTHBH96S505068309	Colour	METALLIC DARK GREY
	Odometer	64020	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/50ZR17	FALKEN	8 mm
	L/H Front Tyre	225/50ZR17	FALKEN	8 mm
	R/H Rear Tyre	225/50ZR17	FALKEN	8 mm
	L/H Rear Tyre	225/50ZR17	FALKEN	8 mm
4.	Description of Damages			
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.			
	DAMAGES SEE DETAILS.			
5.	General Information			
	Accident Date	02/07/2018	Inspection Date	04/07/2018
	Survey held at	AH LIM MOTOR COMPANY		
		NO 10 ANG MO KIO IND PK 2A #01-09 AMK AUTOPOINT SINGAPORE 568047		
5a.	Remarks			
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b.	Estimate Days of Repair			
	ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days			