

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

ASMIRA BINTE MOHAMED YUSOFF
BLK 348B YISHUN AVE 11
#12-563
S 762348

Tp Ching.

Poh Kim.

Date :19.07.2018
Vehicle no :SGU 1292 Z
Make/Model :TOYOTA WISH
Accident date :03.07.2018

No	DESCRIPTION	Qty	Amount (\$S)
List Items			
1	Rear windscreen rubber <i>new</i>	1	\$ 92.7 ✓
2	Rear tailgate <i>Dented</i>	1	\$ 1403.5 1210.50
3	Rear tailgate hinges @ \$94.50 <i>NE new</i>	2	\$ 139 ✓
4	Rear tailgate shock absorber @ \$252.60 <i>NE new</i>	2	\$ 505.2 ✓
5	Rear tailgate centro logo <i>NEC</i>	1	\$ 61.2 ✓
6	Rear tailgate handle <i>NE new</i>	1	\$ 240.8 ✓
7	Rear tailgate upper lock <i>Dented</i>	1	\$ 81.5 ✓
8	Rear tailgate lower lock <i>NE new</i>	1	\$ 38.3 ✓
9	Rear tailgate inner handle <i>NE new</i>	1	\$ 30.9 ✓
10	Rear tailgate inner board <i>NE new</i>	1	\$ 391.5 ✓
11	Rear tailgate weather strip <i>NE</i>	1	\$ 351.9 ✓
12	Rear lamp @ \$612.60 <i>crushed</i>	2	\$ 1225.2 808
13	Rear lamp housing @ \$136.90 <i>Repair</i>	2	\$ 273.8 ✓
14	Rear lamp lower bracket @ \$68.70 <i>NE new</i>	2	\$ 137.4 ✓
15	Rear number plate lamp @ \$58.20 <i>NE new</i>	2	\$ 116.4 ✓
16	Rear end panel <i>Dented</i>	1	\$ 571.8 ✓
17	Rear end panel inner top garnish <i>crushed</i>	1	\$ 295.7 ✓
18	Rear bumper <i>Dented</i>	1	\$ 941.5 557.80
19	Rear bumper side holder @ \$61.20 <i>NE</i>	2	\$ 122.4 ✓
20	Rear bumper bracket @ \$48.50 <i>Dented</i>	2	\$ 97 ✓
21	Rear bumper reflector @ \$68.20 <i>Dented</i>	2	\$ 126.4 ✓
22	Rear bumper clips (1set) <i>NE</i>	1	\$ 70 30
23	Rear fender @ \$922.40 <i>Repair</i>	2	\$ 1844.8 ✓
24	Rear fender inner garnish @ \$723.10 <i>RT Dented</i>	2	\$ 1446.2 680.50
25	Rear fender inner shield @ \$225.90 <i>NE new</i>	2	\$ 451.8 ✓
26	Rear fender quarter glass rubber @ \$429.20 <i>NE new</i>	2	\$ 858.4 ✓
27	Rear spare tyre top board <i>NE new</i>	1	\$ 619.2 ✓
28	Rear spare tyre inner garnish <i>NE new</i>	1	\$ 350.2 ✓
29	Rear spare tyre well <i>Repair</i>	1	\$ 543.1 ✓
30	Rear spare tyre well insulation @ \$162.00 <i>NE new</i>	3	\$ 486 ✓
31	Rear spare tyre carriage	1	\$ 346.9 ✓
32	Rear exhaust pipe	1	\$ 1085.7 ✓
33	Rear exhaust pipe mounting	1	\$ 108 ✓
			\$ 15454.4
Less 25% Disc			\$ 3863.6
Total			\$ 11590.8

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

ASMIRA BINTE MOHAMED YUSOFF
BLK 348B YISHUN AVE 11
#12-563
S 762348

Date :19.07.2018
Vehicle no :SGU 1292 Z
Make/Model :TOYOTA WISH
Accident date :03.07.2018

No	Description	Qty	Amount (\$S)
----	-------------	-----	--------------

Special Nett Items

1	Rear bumper reverse sensor <i>Damaged</i>	1	\$ 380 <i>200</i>
2	Rear number plate <i>Not</i>	1	\$ 50 <i>x</i>
2	Rear number plate holder <i>Not</i>	1	\$ 50 <i>x</i>
	<i>Rear Camera. Damaged</i>		
	<i>480.380</i>	Total	\$ 480

Labour Costs

1	To supply rear windscreen sealant	\$ 50 <i>✓</i>
2	To supply rear end panel inner sealant	\$ 200 <i>60</i>
3	Remove & reinstall rear windscreen & quarter glass	\$ 380 <i>120</i>
4	Remove & reinstall reverse sensor	\$ 150 <i>50</i>
5	Remove & reinstall petrol tank	\$ 200 <i>x</i>
6	Remove & reinstall boot lid inner garnish	\$ 200 <i>80</i>
7	Remove & reinstall exhaust pipe	\$ 150 <i>x</i>
8	Remove, replace & repair consistent to the accident	\$ 2500 <i>80</i>
9	Respray painting	\$ 1800 <i>70</i>
10	Tuff kote	\$ 150 <i>40</i>
11	To check wiring	\$ 50 <i>30</i>
	Total	\$ 5830

Grand Total \$ 17900.8

total: 6333.8
2/5: 5K.
06 Days.

(5K)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: