

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE*

Chong

VEHICLE NO : SHD 3194M

DATE 2/7/2018 17:03

MAKE :

P/P-

Chong

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper			\$ 603.60	<i>xR</i>
	Rear Bumper Reinforcement			\$ 504.35	<i>?</i>
	Rear Bumper Reinforcement Bracket (LH/RH)		\$ 180.00	\$ 360.00	<i>?</i>
	Rear Bumper Side Bracket			\$ 49.00	<i>?</i>
	Rear Bumper Clips			\$ 22.00	<i>/acc</i>
	Rear Bumper Sponge			\$ 143.40	<i>?</i>
	Rear Bumper Under Cover			\$ 225.00	<i>best</i>
	SUB TOTAL			\$ 1,907.35	
	LESS 20%			\$ 381.47	
	DISCOUNTED TOTAL			\$ 1,525.88	
	Rear Bumper Reverse Sensor			\$ 135.70	<i>Nett ^{SVC}</i>
	Rear Bumper Advertisement Logo			\$ 50.00	<i>Nett ^{acc}</i>
	Rear Fender Advertisement Logo (LH/RH)		\$ 100.00	\$ 200.00	<i>Nett ^{acc}</i>
				\$ 385.70	
	Labour Charge				
	Panel Beating			\$ 350.00	<i>200</i>
	Spray Painting Charge			\$ 250.00	<i>200</i>
	Wiring Charge			\$ 50.00	<i>20</i>
	R/Refix Reverse Sensor			\$ 120.00	<i>20</i>
	TOTAL LABOUR			\$ 770.00	
	ESTIMATE TOTAL			\$ 2,681.58	

*NA2 LKIC
 3/7/18 1045
 P/P
 2 days
 before AFR repair photo*

LKK Auto Consultants hence identify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.