

ASS. REC. BY:

REF: CS/FCI 18012195/Gvd3

Special Instruction:

Surveyor

ASSIGNMENT (Office)

From (Person):

Karen Tan

of

FCI

Date/Time: 4/7/18 @ 3:03pm

Estimated Cost:

Bill to:

OD / FP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLQ 2828J

Insured:

SH 8236S

at Workshop m/s

Trans Eurocars

Tel:

91277928

of

5 ubi close

Policy No:

Claim No:

D18005170 MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A. 30/06/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

(DS)

11/7/2018 @ 9am

H.O.D. Endorsement:

Date/Time:

3:11pm @ 4/7/18

Person Contacted:

Ronald

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SLQ 2828 J-X

SH 8236S - CS/FCI 16024425/Kvb2

DoA: 19/12/2016

13/7/18

Email preti revised to FCI

16/8/18

@ 3:45pm Ronald will remind Catherine to finalised

21/8/18

Final fa \$ 8641.07 confirmed by email (Reel 4288.93, 3379)

ASSIGNMENT

From: _____ Date: 11/07/2018

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SLQ 2828 Jat Workshop m/s Trans Euro Kairsof No. 5 ubi close

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record) 9am @ owner waitingMake of Veh: Ronald

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (wp)

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLQ 2828 J Yr Regn: 27 Jul 2017Type: M.Cycle / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mazda 5 2.0 c.c 1998Colour: Grey A/C: Insured / Std / NI / NASp. Reading: 2e/82 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: IM6CW10714-0125979Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / R/Rim or

Tyre Size: F: 205/55R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal. 6 mmL/Bal. 6 mm

D.O.A. _____

Survey held at W/SDes. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Rear

R/Bal. 6 mmL/Bal. 6 mmD.O.I. 11-07-189AM

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 21 AUG 2018

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report

1)

Date/Time, File Return to?

2) 21/8 - typistDays Of Repair: 6Resurvey No. of Trip: -Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

\$ + RS \$

Photos

Others

TOTAL

2715 = 30

1707 30

50

25

275

Report Format: CWSLump Sum / I.B.I. (\$) 8641.07



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18005170MFSH
Our ref: CS/FCI18012195/Gvd3

Date: 13/7/2018

The Motor Claims Department
M/s First Capital Insurance Limited

WITHOUT PREJUDICE

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SLQ 2828J


We thank you for your instruction on 4/7/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 11/7/2018 at the premises of M/s TRANS EUROKARS PTE LTD and have the following to report:-

Workshop Estimate Amount	:S\$12,580.00
Revised Estimate Amount	:S\$8,641.07
"Check" Items Amount	:S\$
Market Value	:S\$
LTA Reimbursement Value	:S\$
Nett Value	:S\$

Description of Damage:

The vehicle sustained damages at the n/s body



Comments/Present Status:

Damages Consistent

Yours faithfully,

XING GUO QIANG (HP 8288 0282)

M.MATAI, AMSAE-A

Automotive Assessor

Job Sheet (/ClaimWS/Surveyor/JobSheet/242027)



PRI Documents



Close X

PRI Header Details

Claim No	D18005170MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & TRANS EL
Workshop Name	TRANS EUROKARS PTE LTD (Contact Person : RONALD YAP)	Survey Location & Contact Details	5 UBI CLOSE Mobile: 91277928 , Phone: 63958899 , Fax: 0 EmailId: RONALD.YAP@EUROKARS.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	DIRECT SETTLEMENT:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SH8236S	TP Vehicle No	SLQ2828J
PRI Recieved Date	03-07-2018 07:36:58 PM	Surveyor Appointed Date	04-07-2018 03:01:57 PM	Surveyor Accept Date	04-07-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	04-07-2018	Upload Survey Report *:	Choose File
-----------------------------	----------------------	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

MOTOR SURVEY ASSIGNMENT

Date	03-07-2018	Our Ref No. D18005170MFSH
Accident Date	30-06-2018	Claim Type. Third Party
Insured Vehicle	SH8236S	Third Party Vehicle. SLQ2828J
Survey Location	5 UBI CLOSE	
Contact Person.	RONALD YAP	
Contact No.	63958899/ 91277928	Fax No. 0
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TRANS EUROKARS PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Friday, 13 July 2018 8:38 AM
To: 'Claim Workflow System'
Cc: KARENTAN@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18005170MFSH/1, SLQ 2828J
Attachments: SLQ 2828J PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SLQ 2828J
Date of survey: 11/7/2018
Number of days :6 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 4 July 2018 3:13 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: KARENTAN@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18005170MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Wednesday, 4 July 2018 3:02 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; KARENTAN@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18005170MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



AVG

This email has been checked for viruses by AVG antivirus software.
www.avg.com

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9951A
Vehicle Details	
Vehicle No.:	SLQ2828J
Vehicle to be Exported:	No
Intended De-registration Date:	12 Jul 2018
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA5 WAGON 2.0 AT EU6
Primary Colour:	Grey
Manufacturing Year:	2017
Engine No.:	PE10512907
Chassis No.:	JM6CW1071H0125979
Maximum Power Output:	111.0 kW (148 bhp)
Open Market Value:	\$17,509.00
Original Registration Date:	27 Jul 2017
First Registration Date:	27 Jul 2017
Transfer Count:	0
Actual ARF Paid:	\$17,509.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Jul 2027
PARF Rebate Amount:	\$13,131.00
Intended COE Rebate Details	
COE Expiry Date:	26 Jul 2027
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$55,000.00
COE Rebate Amount:	\$49,706.00
Total Rebate Amount:	\$62,837.00

The information contained herein is correct as at 12 Jul 2018

OK



TRANS EUROKARS PTE LT
NO:5 UBI CLOSE, SINGAPORE
ESTIMATE COST OF REPAIR

GROUP

000

FIRST CAPITAL INSURANCE LTD		NAME : Mr Chang Jin Teck	
36 ROBINSON ROAD		ADDRESS : Blk 6 Bedok Reservoir	
#16-01 CITY HOUSE		#04-18	
SINGAPORE 068877		Singapore 479234	
ATTN. :	MOTOR CLAIMS	TEL :	96910045
FAX :			
VEH NO :	SLQ2828J	DATE IN :	
CHASSIS NO :	JM6CW1071H0125979	MILEAGE :	
MODEL :	MAZDA5	DATE REG.:	27-Jul-17

NATURE OF WORKS

Parts Description

NO	Parts Description	QTY	
1	LHS FRONT FENDER / PD	1	N
2	STAY(LHS), FRONT FENDER X NN	1	N
3	LHS FRONT DOOR / PD	1	N
4	HINGE LOWER(LHS), FRONT DOOR X NN	1	N
5	HINGE UPPER(LHS), FRONT DOOR X NN	1	N
6	FASTENER, FRONT DOOR	1	N
7	FASTENER, FRONT DOOR	1	N
8	GROMMET, FRONT DOOR	2	N
9	GROMMET, FRONT DOOR	1	N
10	GROMMET, FRONT DOOR	9	N
11	HANDLE(LHS), OUTER repair X	1	N
12	LHS SIDE MIRROR ASSY / Cut	1	N
13	COVER(LHS), SIDE MIRROR repair X	1	N
14	LAMP(LHS), SIDE TURN X NN	1	N
15	GLASS(LHS), SIDE MIRROR X NN	1	N
16	GARNISH(LHS), SIDE MIRROR / Side	1	N
17	STRIPE SIDE(LHS), FRONT DOOR / Side	1	N
18	STRIPE UPPER(LHS), FRONT DOOR / Side	1	N
19	LHS REAR DOOR / PD	1	N
20	FASTENER, REAR DOOR	2	N
21	FASTENER, REAR DOOR	1	N
22	GROMMET, REAR DOOR	1	N
23	GROMMET, REAR DOOR	1	N
24	FASTENER, REAR DOOR	1	N
25	GROMMET, REAR DOOR	6	N
26	GROMMET, REAR DOOR	3	N
27	GROMMET, REAR DOOR	2	N
28	TAPE PROTECTOR, REAR DOOR	1	N
29	TAPE PROTECTOR, REAR DOOR	1	N
30	TAPE PROTECTOR, REAR DOOR	1	N

307. +	20014
1,147. +	
12.3 +	
3. +	3-Jul-18
4.4 +	
2.8 +	
25.2 +	
360.7 +	
71.7 +	7875
49. +	CLAIM
65.6 +	
1,364.5 +	
9.8 +	
3.4 +	
10. +	PRICES
8.9 +	\$ 307.00 ✓
3. +	\$ 29.10 ✓
16.8 +	\$ 1,147.00 ✓
8.1 +	\$ 44.20 ✓
6.6 +	\$ 46.70 ✓
2.5 +	\$ 12.30 ✓
2.5 +	\$ 3.00 ✓
3.3 +	\$ 4.40 ✓
5.4 +	\$ 2.80 ✓
7. +	\$ 25.20 ✓
29.1 +	\$ 113.20 ✓
33.4 +	\$ 360.70 ✓
289.7 +	\$ 86.20 ✓
6.6 +	\$ 262.60 ✓
3. +	\$ 65.60 ✓
3,862.3	\$ 71.70 ✓
x	\$ 49.00 ✓
90. x	\$ 65.60 ✓
3,476.07 *	\$ 1,364.50 ✓
000	\$ 9.80 ✓
	\$ 3.40 ✓
1,980. +	\$ 10.00 ✓
2,205. +	\$ 8.90 ✓
660. +	\$ 3.00 ✓
120. +	\$ 16.80 ✓
180. +	\$ 8.10 ✓
20. +	\$ 6.60 ✓
5,165. +	\$ 2.50 ✓
000	\$ 2.50 ✓
	\$ 3.30 ✓
3,476.07 +	
5,165. +	
8,641.07	

31	TAPE SEAL, REAR DOOR	2	MS05B-72-512	\$	5.40	✓
32	VALVE ONEWAY, REAR DOOR	1	MC235-72-512	\$	4.30	
33	FASTENER, GARNISH	2	ME120-51-W24	\$	7.00	✓
34	STRIPE SIDE(LHS), REAR DOOR	1	MC513-50-8W2B	\$	29.10	✓
35	STRIPE UPPER(LHS), REAR DOOR	1	MC513-50-8W4A	\$	33.40	✓
36	MOULD(LHS), FRONT DOOR	1	MC513-50-650A	\$	41.00	
37	MOULD(LHS), REAR DOOR	1	MC235-50-670C	\$	44.80	
38	COVER(LHS), RAIL-CENTER	1	MC513-73-8D0E	\$	289.70	✓
39	CLIP, COVER RAIL	2	MC235-72-8C1A	\$	6.60	✓
40	GROMMET, COVER RAIL	1	MB01W-51-142B	\$	3.00	✓
TOTAL PARTS				\$	4,600.00	
LESS 10%				\$	460.00	
TOTAL PARTS COST				\$	4,140.00	

Labour Description				
1		TO REPLACE LHS FRONT FENDER, LHS FRONT DOOR AND LHS REAR DOOR. TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	✓ 1980	\$ 2,640.00
2		TO RESPRAY LHS FRONT FENDER, LHS FRONT DOOR, LHS REAR DOOR, LHS RAIL COVER AND LHS REAR FENDER.	✓ 2205 2520	\$ 3,780.00
3	MZ-BR-DOORME	TO TRANSFER THE DOOR MECHANISM.	✓ 660	\$ 1,320.00
4	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	✓ 120	\$ 250.00
5	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	✓ 180	\$ 350.00
6	MZ-BR-SUNDRI	SUNDRIES.	✓ 20	NETT \$ 100.00

TOTAL LABOUR	\$ -	\$ 8,440.00
TOTAL PARTS	\$ -	\$ 4,140.00
TOTAL	\$ -	\$ 12,580.00
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

6 Days.

before part photos.

Gino Ai y - 82880282

11/7/18.

[Signature]
16/7/18

REMARKS:
THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Authorised Signature
Acknowledged by Repairer
Signature:
Date:

12,930



TRANS EUROKARS PTE LTD
NO:5 UBI CLOSE, SINGAPORE 408605
FINALIZATION COST OF REPAIRS



FIRST CAPITAL INSURANCE LTD		NAME : Mr Chang Jin Teck		WIP : 20014	
36 ROBINSON ROAD		ADDRESS : Blk 6 Bedok Reservoir View		EXCESS :	
#16-01 CITY HOUSE		#04-18		DATE: 3-Jul-18	
SINGAPORE 068877		Singapore 479234			
ATTN : MOTOR CLAIMS		TEL : 96910045			
FAX :					
VEH NO :	SLQ2828J	DATE IN :		CONTACT PERSON :	RONALD 6395 7875
CHASSIS NO :	JM6CW1071H0125979	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA5	DATE REG.:	27-Jul-17	POLICY NO. :	
NATURE OF WORKS					
Parts Description					
NO	QTY			REVISED	PRICES
1	LHS FRONT FENDER	1	MCG37-52-211	\$ 307.00	\$ 307.00
2	STAY(LHS), FRONT FENDER	1	MC513-52-240	\$ -	\$ 29.10
3	LHS FRONT DOOR	1	MC5Y3-59-02XE	\$ 1,147.00	\$ 1,147.00
4	HINGE LOWER(LHS), FRONT DOOR	1	MF151-58-210C	\$ -	\$ 44.20
5	HINGE UPPER(LHS), FRONT DOOR	1	MC235-59-210C	\$ -	\$ 46.70
6	FASTENER, FRONT DOOR	1	MC235-59-762B	\$ 12.30	\$ 12.30
7	FASTENER, FRONT DOOR	1	MGD7A-50-EA1	\$ 3.00	\$ 3.00
8	GROMMET, FRONT DOOR	2	MBF67-51-261	\$ 4.40	\$ 4.40
9	GROMMET, FRONT DOOR	1	M9991-00-501	\$ 2.80	\$ 2.80
10	GROMMET, FRONT DOOR	9	MGJ6A-58-975	\$ 25.20	\$ 25.20
11	HANDLE(LHS), OUTER	1	MG22C-59-410R27	\$ -	\$ 113.20
12	LHS SIDE MIRROR ASSY	1	MC310-69-181B	\$ 360.70	\$ 360.70
13	COVER(LHS), SIDE MIRROR	1	ML208-69-1A7A27	\$ -	\$ 86.20
14	LAMP(LHS), SIDE TURN	1	ML208-69-182A	\$ -	\$ 262.60
15	GLASS(LHS), SIDE MIRROR	1	MC235-69-1G7	\$ -	\$ 65.60
16	GARNISH(LHS), SIDE MIRROR	1	MC513-69-16YA	\$ 71.70	\$ 71.70
17	STRIPE SIDE(LHS), FRONT DOOR	1	MC235-50-8W3B	\$ 49.00	\$ 49.00
18	STRIPE UPPER(LHS), FRONT DOOR	1	MC235-50-8W1A	\$ 65.60	\$ 65.60
19	LHS REAR DOOR	1	MC5Y3-73-02XE	\$ 1,364.50	\$ 1,364.50
20	FASTENER, REAR DOOR	2	MC513-72-762	\$ 9.80	\$ 9.80
21	FASTENER, REAR DOOR	1	MBP4K-58-762	\$ 3.40	\$ 3.40
22	GROMMET, REAR DOOR	1	MC514-72-918	\$ 10.00	\$ 10.00
23	GROMMET, REAR DOOR	1	MC513-72-918	\$ 8.90	\$ 8.90
24	FASTENER, REAR DOOR	1	MGD7A-50-EA1	\$ 3.00	\$ 3.00
25	GROMMET, REAR DOOR	6	MGJ6A-58-975	\$ 16.80	\$ 16.80
26	GROMMET, REAR DOOR	3	MC235-58-975	\$ 8.10	\$ 8.10
27	GROMMET, REAR DOOR	2	MA001-56-053	\$ 6.60	\$ 6.60
28	TAPE PROTECTOR, REAR DOOR	1	MC273-72-864A	\$ 2.50	\$ 2.50
29	TAPE PROTECTOR, REAR DOOR	1	MC513-72-864A	\$ 2.50	\$ 2.50
30	TAPE PROTECTOR, REAR DOOR	1	MG043-62-864A	\$ 3.30	\$ 3.30

31	TAPE SEAL, REAR DOOR	2	MS05B-72-512	\$ 5.40	\$ 5.40
32	VALVE ONEWAY, REAR DOOR	1	MC235-72-512	\$ -	\$ 4.30
33	FASTENER, GARNISH	2	ME120-51-W24	\$ 7.00	\$ 7.00
34	STRIPE SIDE(LHS), REAR DOOR	1	MC513-50-8W2B	\$ 29.10	\$ 29.10
35	STRIPE UPPER(LHS), REAR DOOR	1	MC513-50-8W4A	\$ 33.40	\$ 33.40
36	MOULD(LHS), FRONT DOOR	1	MC513-50-650A	\$ -	\$ 41.00
37	MOULD(LHS), REAR DOOR	1	MC235-50-670C	\$ -	\$ 44.80
38	COVER(LHS), RAIL-CENTER	1	MC513-73-8D0E	\$ 289.70	\$ 289.70
39	CLIP, COVER RAIL	2	MC235-72-8C1A	\$ 6.60	\$ 6.60
40	GROMMET, COVER RAIL	1	MB01W-51-142B	\$ 3.00	\$ 3.00
TOTAL PARTS				\$ 3,862.30	\$ 4,600.00
LESS 10%				\$ 386.23	\$ 460.00
TOTAL PARTS COST				\$ 3,476.07	\$ 4,140.00

Labour Description

1		TO REPLACE LHS FRONT FENDER, LHS FRONT DOOR AND LHS REAR DOOR. TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	\$ 1,980.00	\$ 2,640.00
2		TO RESPRAY LHS FRONT FENDER, LHS FRONT DOOR, LHS REAR DOOR, LHS RAIL COVER AND LHS REAR FENDER.	\$ 2,205.00	\$ 3,780.00
3	MZ-BR-DOORME	TO TRANSFER THE DOOR MECHANISM.	\$ 660.00	\$ 1,320.00
4	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	\$ 120.00	\$ 250.00
5	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	\$ 180.00	\$ 350.00
6	MZ-BR-SUNDRI	SUNDRIES.	\$ 20.00	\$ 100.00
SUPPLEMENTARY LABOUR				
1		INSTALL SOUNDPROOF (Seperate Invoice)	\$ 350.00	

TOTAL LABOUR	\$ 5,515.00	\$ 8,440.00
TOTAL PARTS	\$ 3,476.07	\$ 4,140.00
TOTAL	\$ 8,991.07	\$ 12,580.00
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ 8,991.07	
GST 7%	\$ 629.37	\$ -
GRAND TOTAL	\$ 9,620.44	\$ -

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Tuesday, 21 August 2018 11:36 AM
To: 'jessicahs@eurokars.com.sg'; SUR; CS A Team; Admin A
Subject: RE: finalization FIRST SLQ2828J MAZDA5 LH.xlsx

Dear Jessica,

Noted with thanks.

Kindly send Final invoice and all supporting documents to First Capital Ins Ltd.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: jessicahs@eurokars.com.sg <jessicahs@eurokars.com.sg>
Sent: Tuesday, 21 August 2018 11:30 AM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>; SUR <sur@lkkauto.com>; CS A Team <cs-a@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: RE: finalization FIRST SLQ2828J MAZDA5 LH.xlsx

Dear Veron,

Thank you so much.

We will invoice accordingly.

Thank you very much.

Regards,

Jessica Shastri

Admin Executive – Insurance Claims

Eurokars Group of Companies

(Porsche, Rolls Royce, Saab, Mini, Mazda, Mc.Laren)

Eurokars Centre

12 Sungei Kadut Avenue

Singapore 729648

Tel: +65 63633003

DID: +65 63602863

Fax: +65 63602899

From: Veron Chen (LKKAUTO) [mailto:veronchen@lkkauto.com]
Sent: Tuesday, August 21, 2018 11:24 AM
To: Jessica Harry Shastri <jessicahs@eurokars.com.sg>; SUR <sur@lkkauto.com>; CS A Team <cs-a@lkkauto.com>;

Admin A <admin-a@lkkauto.com>

Subject: RE: finalization FIRST SLQ2828J MAZDA5 LH.xlsx

Dear Jessica,

WITHOUT PREJUDICE

We refer to conversation with our Guo Qiang and Ronald this morning.

INSTALL SOUNDPROOF-\$350/- will separate invoice.

Therefore final amount \$8641.07 before GST @ 6 working days.

Kindly check and confirm.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: jessicahs@eurokars.com.sg <jessicahs@eurokars.com.sg>

Sent: Monday, 20 August 2018 4:13 PM

To: SUR <sur@lkkauto.com>; CS A Team <cs-a@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Subject: finalization FIRST SLQ2828J MAZDA5 LH.xlsx

Dear Guo Qing,

Please find our computation attached for your agreement.

COR: \$8991.07 before GST

7 repair days (not including preparation of estimate, wait for survey/authorization/spare parts, Sat/Sun/PH)

Appreciate your confirming the above as soon as possible.

Thank you very much.

Regards,

Jessica Shastri

Admin Executive – Insurance Claims

Eurokars Group of Companies

(Porsche, Rolls Royce, Saab, Mini, Mazda, Mc.Laren)

Eurokars Centre

12 Sungei Kadut Avenue

Singapore 729648

Tel: +65 63633003

DID: +65 63602863

Fax: +65 63602899



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18012195/Gvd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 24-08-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 8236S	Veh. Inspected	SLQ 2828J	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18005170MFSH	Excess (\$)	0.00	
Assign From	KARENT	Assign Date	04/07/2018	
2. Vehicle Particulars & Condition				
Make & Model	MAZDA 5 2.0	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JM6CW1071H0125979	Colour	GREY	
Odometer	20182	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	TOYO	6 mm	
L/H Front Tyre	205/55 R16	TOYO	6 mm	
R/H Rear Tyre	205/55 R16	TOYO	6 mm	
L/H Rear Tyre	205/55 R16	TOYO	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	30/06/2018	Inspection Date	11/07/2018	
Survey held at	TRANS EUROKARS PTE LTD NO 5 UBI CLOSE SINGAPORE 408605			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLQ 2828J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	LHS FRONT FENDER	DENTED	307.00	307.00
1	STAY (LHS),FRONT FENDER	NOT NECESSARY	29.10	-
1	LHS FRONT DOOR	DENTED	1,147.00	1,147.00
1	HINGE LOWER (LHS),FRONT DOOR	NOT NECESSARY	44.20	-
1	HINGE UPPER (LHS),FRONT DOOR	NOT NECESSARY	46.70	-
1	FASTENER,FRONT DOOR	NECESSARY	12.30	12.30
1	FASTENER,FRONT DOOR	NECESSARY	3.00	3.00
2	GROMMET,FRONT DOOR	NECESSARY	4.40	4.40
1	GROMMET,FRONT DOOR	NECESSARY	2.80	2.80
9	GROMMET,FRONT DOOR	NECESSARY	25.20	25.20
1	HANDLE (LHS),OUTER	TO REPAIR SEE LABOUR	113.20	-
1	LHS SIDE MIRROR ASSY	CUT	360.70	360.70
1	COVER (LHS),SIDE MIRROR	TO REPAIR SEE LABOUR	86.20	-
1	LAMP (LHS),SIDE TURN	NOT NECESSARY	262.60	-
1	GLASS (LHS),SIDE MIRROR	NOT NECESSARY	65.60	-
1	GARNISH (LHS),SIDE MIRROR	SCRATCHED	71.70	71.70
1	STRIPE SIDE (LHS),FRONT DOOR	NECESSARY	49.00	49.00
1	STRIPE UPPER (LHS),FRONT DOOR	NECESSARY	65.60	65.60
1	LHS REAR DOOR	DENTED	1,364.50	1,364.50
2	FASTENER,REAR DOOR	NECESSARY	9.80	9.80
1	FASTENER,REAR DOOR	NECESSARY	3.40	3.40
1	GROMMET,REAR DOOR	NECESSARY	10.00	10.00
1	GROMMET,REAR DOOR	NECESSARY	8.90	8.90
1	FASTENER,REAR DOOR	NECESSARY	3.00	3.00
6	GROMMET,REAR DOOR	NECESSARY	16.80	16.80
3	GROMMET,REAR DOOR	NECESSARY	8.10	8.10
2	GROMMET,REAR DOOR	NECESSARY	6.60	6.60
1	TAPE PROTECTOR,REAR DOOR	NECESSARY	2.50	2.50
1	TAPE PROTECTOR,REAR DOOR	NECESSARY	2.50	2.50

Report Ref No. CS/FCI18012195/Gvd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	TAPE PROTECTOR,REAR DOOR	NECESSARY	3.30	3.30
2	TAPE SEAL,REAR DOOR	NECESSARY	5.40	5.40
1	VALVE ONEWAY,REAR DOOR	NOT NECESSARY	4.30	-
2	FASTENER,GARNISH	NECESSARY	7.00	7.00
1	STRIPE SIDE (LHS),REAR DOOR	NECESSARY	29.10	29.10
1	STRIPE UPPER (LHS),REAR DOOR	NECESSARY	33.40	33.40
1	MOULD (LHS),FRONT DOOR	NOT NECESSARY	41.00	-
1	MOULD (LHS),REAR DOOR	NOT NECESSARY	44.80	-
1	COVER (LHS),RAIL-CENTER	DEFORMED	289.70	289.70
2	CLIP,COVER RAIL	NECESSARY	6.60	6.60
1	GROMMET,COVER RAIL	NECESSARY	3.00	3.00
	LESS 10% DISCOUNT		-460.00	-386.23
			4,140.00	3,476.07
	SPECIAL NETT ITEMS			
1	SUNDRIES (SN)	NECESSARY	100.00	20.00
			100.00	20.00
	LABOUR			
	TO REPLACE LHS FRONT FENDER,LHS FRONT DOOR AND LHS REAR DOOR.TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.INCLUSIVE OF THE REPAIR OF HANDLE (LHS),OUTER AND COVER (LHS),SIDE MIRROR.		2,640.00	1,980.00
	TO RESPRAY LHS FRONT FENDER.LHS FRONT DOOR,LHS REAR DOOR,LHS RAIL COVER AND LHS REAR FENDER.		3,780.00	2,205.00
	TO TRANSFER THE DOOR MECHANISM.		1,320.00	660.00
	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		250.00	120.00
	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		350.00	180.00
	INSTALL SOUNDPROOF. (PAID BY OWNER)		350.00	-
			8,690.00	5,145.00
	GRAND TOTAL		12,930.00	8,641.07

Report Ref No. CS/FCI18012195/Gvd3n2



RECOMMENDED COST OF REPAIRS			8,641.07
-----------------------------	--	--	----------

Report Ref No. CS/FCI18012195/Gvd3n2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.