

ASS. REC. BY:

REF: CS3 / ICS 18012201 / R2403⁸² Special Instruction

Ass. Verifier:

Rasul

ASSIGNMENT (Office)

From (Person):

Janice Goh

of

ECICS

Date/Time:

4/7/18 @ 12:29 pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJT 8577B

Insured:

SJH 7359J

at Workshop m/s:

AMA Autocare

Tel:

8778 3636

of

36 Toh Guan Rd East #01-36

Policy No:

Claim No:

DMPC1800255H/DL

Sum Insured:

Excess:

Make of Veh:

D.O.A.

02/07/2018

(Client's Record)

05/07/2018

CA / REV / REP. / REV 24 HRS

Cup)

H.O.D. Endorsement

Date/Time:

2:49pm @ 4/7/18

Person Contacted:

Melvin

Vehicle IN / OUT

| Date/Time | Action/Instruction (X) Estimate |
|-----------|--|
| | SJT 8577B - CC6 / AIG 14013755 / UH29392 NOA: 16/7/114 |
| | SJH 7359J - X |
| | Range 10K - 11K |
| 5/7/18 | dismantled. Repair days 2 |
| | TG Lim Lim 3/7/18 |

28/11/13 wef
ASS. REC. BY: RABONE

REF: ECICS

44740

COE XPIRY: 2019/NOV

ASSIGNMENT

From: _____ Date: 05/07/2018
Estimated Cost: _____
OD WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: SJT 8577B
at Workshop m/s AMA Autocare
of 36 Joh Guan Rd East # 01-36
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

Veh No: SJT 8577B Yr Regn: 2009 / NOV
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____
Make: NISSAN LATI ISLAT c.c. 1498
Colour: WHITE A/C: Insured / Std / NI / NA
Sp. Reading: 141169 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: JN1BAAL1120021514
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Order / Jammed / Leaked / Burnt or _____
Brake: Order / Jammed / Leaked / Burnt or _____
Modi: Nil / SRim / STD A/Rim or _____
Tyre Size: F: 185/85R15
R: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

| | |
|-----|-----|
| N/S | O/S |
| | |

Bal. or Market Value: 18K
IDAC Accident Rpt: _____ Consistent?: Yes or No
GIA / PR Seen: _____ Consistent?: Yes or No
Est. Repairs: 8 days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS lup
Date: _____ Person Contacted: _____
Vehicle: IN / OUT

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or FIRENZA
Front 6 mm Rear 6 mm
R/Bal. 6 mm R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. 02/07/18 D.O.I. 05/07/18
Survey held at AMA AUTOMOTIVE
Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or _____
The UIC / Chassis frame / Body Structure affected due to collision.

| Date / Time | Action / Instruction |
|-----------------|--|
| <u>06/07/18</u> | <u>repair limit to repair this vehicle is 5K</u> |
| <u>1/8</u> | <u>Submit PRE report. (repair range \$10K - \$11K)</u> |
| | |
| | |

Jimetto
1/8/18

Date/Time, File Pass to? : Preli. Report
 : Final Report

Days Of Repair: 8
Resurvey No. of Trip: 1

Date/Time, File Return to? 2) _____

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech. Invs (\$)
 : Weekend (\$)

| | |
|-----------------|--|
| Survey Fee: | |
| Transportation: | |
| \$ + RS. SI | |
| Photos | |
| Others | |
| TOTAL | |

Report Format: PRE
Lump Sum / I.B.I: (\$ _____)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ECICS LTD

Ref : CS3/ICS18012201/R1z4d3

7 TEMASEK BOULEVARD
#10-01 SUNTEC TOWER ONE
SINGAPORE 038987

Date : 04-07-2018



Code : ICS

1. Policy Particulars :- (THIRD PARTY CLAIM)

| | | | |
|--------------|-----------------|----------------|------------|
| Insured Veh. | SJH 7359J | Veh. Inspected | SJT 8577B |
| Policy No. | | Coverage (\$) | 0.00 |
| Claim No. | DMPC1800255H/DL | Excess (\$) | 0.00 |
| Assign From | JANICE GOH | Assign Date | 04/07/2018 |

2. Vehicle Particulars & Condition

| | | | |
|--------------|--------|--------------|---|
| Make & Model | | c.c | 0 |
| Engine No. | HIDDEN | Year of Reg. | |
| Chassis No. | | Colour | |
| Odometer | - | Steering | |
| Brakes | | Modification | |
| General | | | |

3. Conditions of Tyres

| | Size | Make | Balance |
|----------------|------|------|---------|
| R/H Front Tyre | | | mm |
| L/H Front Tyre | | | mm |
| R/H Rear Tyre | | | mm |
| L/H Rear Tyre | | | mm |

4. Description of Damages

| | |
|--|--|
| | |
|--|--|

5. General Information

| | | | |
|----------------|--|-----------------|--|
| Accident Date | 02/07/2018 | Inspection Date | |
| Survey held at | AMA AUTOMOTIVE PTE. LTD. 36 TOH GUAN ROAD EAST #03-36 SINGAPORE 608580 | | |

5a. Remarks

| |
|--|
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. |
|--|

Nivitha (LKK Auto)

From: ECICS Claims <claims@ecics.com.sg>
Sent: Wednesday, 4 July 2018 12:29 PM
To: Weng Kit; assignments@lkkauto.com
Cc: 'Jerone'; Desmond Lee Ker Wen (ECICS, Claims); ECICS Claims
Subject: RE: Our Ref: SJT 8577B (wk) PRE-REPAIR SURVEY NOTICE ACCIDENT INVOLVING SJT 8577B & SJH 7359J ALONG OUTSIDE HILLVIEW REGENCY ON 2 JULY 2018 ; Our ref DMPC1800255H/DL
Attachments: 20180704120247234.pdf

Without Prejudice

Dear Weng Kit

Thank you for your email.
We are not agreeable with your surveyor and we will appoint LKK for the PRS.

Aside to LKK

Please assist to arrange TP PRS.

Thank you.

Regards,
Janice Goh
Claims Division
DID: +65 6303 0182
FAX: +65 6338 9267

ECICS Limited
7 Temasek Boulevard, #10-01 Suntec Tower One, Singapore 038987

WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to motorsurvey@ecics.com.sg directly.

Please bear with us should we take longer to response as we are currently experiencing a high volume of claims. Thank you for your kind patience and understanding.

From: Weng Kit [mailto:wengkit@chiaarul.com]
Sent: Wednesday, 4 July, 2018 12:22 PM
To: ECICS Claims
Cc: 'Jerone'; Desmond Lee Ker Wen (ECICS, Claims)
Subject: RE: Our Ref: SJT 8577B (wk) PRE-REPAIR SURVEY NOTICE ACCIDENT INVOLVING SJT 8577B & SJH 7359J ALONG OUTSIDE HILLVIEW REGENCY ON 2 JULY 2018

Dear Sirs,

We refer to your email below.

Our client is not agreeable to your list of motor surveyors.

We are instructed by our client to propose the list of their surveyor as the mutual surveyor / single joint expert for your consideration as follows:

Sincere Appraisal - Mr Dave

Best Regards,

Mr Weng Kit
M/s Chia S Arul LLC
151 Chin Swee Road
#03-09 Manhattan House
Singapore 169876
Tel: (65) 6733 4647 Fax: (65) 6733 8183

This e-mail is from M/s Chia S Arul LLC, a firm of Advocates and Solicitors in Singapore, and is intended solely for the named addressee. It contains confidential and /or legally privileged information. If the e-mail has reached you in error, please delete the e-mail immediately and inform us of the error. You may contact us at info@chiaarul.com. Internet communications cannot be guaranteed to be secured or error-free as information could be intercepted, corrupted, lost, arrive late or contain viruses. The sender therefore does not accept liability for any errors or omissions in the context of this message which arise as a result of Internet transmission.

From: ECICS Claims [mailto:claims@ecics.com.sg]
Sent: Wednesday, July 4, 2018 12:09 PM
To: Weng Kit
Cc: 'Jerone'; ECICS Claims; Desmond Lee Ker Wen (ECICS, Claims)
Subject: RE: Our Ref: SJT 8577B (wk) PRE-REPAIR SURVEY NOTICE ACCIDENT INVOLVING SJT 8577B & SJH 7359J ALONG OUTSIDE HILLVIEW REGENCY ON 2 JULY 2018

Our Claim no: DMPC1800255H/DL

Without prejudice

Dear Weng Kit

Thank you for your email.

Our insured has not reported the accident to us. As such, we are unable to advise on the liability now.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client's workshop. We propose to use one of the motor surveyors named in the list below to conduct the joint pre-repair survey as a single joint expert:

1. LKK
2. JP knight
3. Formteam
4. Appraisal Associates
5. Autoprobe
6. Raleigh

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

Thank you.

Regards,
Janice Goh
Claims Division
DID: +65 6303 0182

FAX: +65 6338 9267

ECICS Limited

7 Temasek Boulevard, #10-01 Suntec Tower One, Singapore 038987

WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to motorsurvey@ecics.com.sg directly.

*****Please bear with us should we take longer to response as we are currently experiencing a high volume of claims. Thank you for your kind patience and understanding.*****

From: Weng Kit [mailto:wengkit@chiaarul.com]

Sent: Wednesday, 4 July, 2018 12:04 PM

To: ECICS Claims

Cc: 'Jerone'

Subject: Our Ref: SJT 8577B (wk) PRE-REPAIR SURVEY NOTICE ACCIDENT INVOLVING SJT 8577B & SJH 7359J ALONG OUTSIDE HILLVIEW REGENCY ON 2 JULY 2018

Dear Sirs,

We refer to the above matter.

Attached is a copy of our pre-repair inspection notice dated 4 July 2018 for your attention.

Best Regards,

Mr Weng Kit

M/s Chia S Arul LLC

151 Chin Swee Road

#03-09 Manhattan House

Singapore 169876

Tel: (65) 6733 4647 Fax: (65) 6733 8183

This e-mail is from M/s Chia S Arul LLC, a firm of Advocates and Solicitors in Singapore, and is intended solely for the named addressee. It contains confidential and /or legally privileged information. If the e-mail has reached you in error, please delete the e-mail immediately and inform us of the error. You may contact us at info@chiaarul.com. Internet communications cannot be guaranteed to be secured or error-free as information could be intercepted, corrupted, lost, arrive late or contain viruses. The sender therefore does not accept liability for any errors or omissions in the context of this message which arise as a result of Internet transmission.

follow us on  facebook  follow us on twitter  visit our website ecics.com.sg 

This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in his message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

CHIA S ARUL LLC
ADVOCATES & SOLICITORS
UEN 201330709H

ARULCHELVAN S

Our Ref : SJT 8577B (wk)

Your Ref : To be advised

4 July 2018

ECICS Limited

BY EMAIL

Dear Sirs,

RE: PROPERTY DAMAGE CLAIM
CLAIMANT : CHUNG SOH MEI
ACCIDENT INVOLVING SJT 8577B & SJH 7359J ALONG OUTSIDE HILLVIEW
REGENCY ON 2 JULY 2018
PRE-REPAIR SURVEY NOTICE

1. We act for Chung Soh Mei, the owner of motor vehicle no. SJT 8577B which was involved in the aforesaid accident.
2. We hereby in compliance with the Pre-Action Protocol for Non-Injury Motor Accident Claims, Appendix C of the State Courts Practice Directions Amendment No. 1 of 2016 ("the NIMA Protocol") give you **NOTICE** that we are claiming against your insured motor vehicle no. SJH 7359J for damages, costs and disbursements as a result of your insured driver's negligence.
3. Please let us know if you wish to conduct a pre-repair survey on our client's motor vehicle at:

| | |
|----------------|---|
| Workshop | AMA Autocare Pte Ltd |
| Address | 36 Toh Guan Road East #01 - 36 Singapore 608580 |
| Contact Person | Mr. Melvin (8778 3636) |

4. Pursuant to paragraph 2.3 of the NIMA Protocol, in the event we do not receive your response within next two (2) working days (excluding any Saturday, Sunday or public holiday), our client will instruct the workshop to commence appraisal and repairs to the damaged motor vehicle without further reference to you.
5. Please advise the appointed surveyor to endorse on page 2 of this letter after the completion of each inspection.

Yours faithfully,

MR ARULCHELVAN S
cc: Client (By Email)

151 CHIN SWEE ROAD • #03-09
MANHATTAN HOUSE • SINGAPORE 169876
TEL : (65) 6733 4647 • FAX : (65) 6733 8183 (not for Service of Court documents)
EMAIL : info@chiaarul.com

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

| | |
|----------------------------|--|
| Date Of Report | 03/07/2018 16:45 |
| Date Of Accident | 02/07/2018 18:15 |
| Exact Location Of Accident | OUTSIDE HILLVIEW REGENCY 26 BUKIT BATOK EAST AVE 2 |
| Country/State of Loss | SINGAPORE |

DETAILS OF OWN VEHICLE

| | |
|-----------------------------|----------------------|
| Vehicle Registration Number | SJT8577B |
| Insured/Policyholder | |
| Name Of Registered Owner | CHUNG SOH MEI |
| NRIC No | S0124474D |
| Email Address | NOEMAIL |
| Mobile Phone No | (LOCAL) +65-81133745 |
| Alternative Phone No | OFFICE-81133745 |

Vehicle Particulars

| | |
|--|-----------------|
| Manufacturer | NISSAN |
| Model | LATIO 1.5 SEDAN |
| Exact Purpose for which vehicle was being used at time of accident | PRIVATE |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO |
| If No, Please state action to be taken | THIRD PARTY |
| Vehicle Category | PRIVATE CAR |

Insurance Company

| | |
|---------------------------|---------------|
| Name of Insurance Company | AVIVA LTD |
| Type Of Coverage | COMPREHENSIVE |
| Fleet Policy | NO |
| Policy Number | 10740997 |
| Cover Note Number | |

Driver

| | |
|----------------------|-------------------------|
| Name of Driver | ONG WEI CHAO TIMOTHY |
| NRIC No | S8835333A |
| Date Of Birth | 20/09/1988 |
| Occupation | INDOOR |
| Date Of Driving Pass | 05/06/2007 |
| Driving Experience | 11 YEARS AND 0 MONTHS |
| Gender | MALE |
| Mobile Number | (LOCAL) +65-81133745 |
| Fax Number | |
| Contact Number | |
| EEmail Address | TIMOTHY_OWC@HOTMAIL.COM |

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

| Vehicle Owner Particulars | |
|--------------------------------|------------------------------------|
| Owner ID Type: | Singapore NRIC |
| Owner ID: | 4474D |
| Vehicle Details | |
| Vehicle No.: | SJT8577B |
| Vehicle to be Exported: | No |
| Intended De-registration Date: | 06 Jul 2018 |
| Vehicle Make: | NISSAN |
| Vehicle Model: | LATIO 1.5L AT ABS D/AIRBAG 2WD 4DR |
| Primary Colour: | White |
| Manufacturing Year: | 2009 |
| Engine No.: | HR15110657B |
| Chassis No.: | JN1BAAC11Z0021514 |
| Maximum Power Output: | 80.0 kW (107 bhp) |
| Open Market Value: | \$17,916.00 |
| Original Registration Date: | 02 Nov 2009 ✓ |
| First Registration Date: | 02 Nov 2009 |
| Transfer Count: | 1 |
| Actual ARF Paid: | \$17,916.00 |
| Intended PARF Rebate Details | |
| PARF Eligibility: | Yes |
| PARF Eligibility Expiry Date: | 01 Nov 2019 |
| PARF Rebate Amount: | \$9,853.00 |
| Intended COE Rebate Details | |
| COE Expiry Date: | 01 Nov 2019 |
| COE Category: | A - Car (1600cc & below) |
| COE Period(Years): | 10 |
| QP Paid: | \$18,899.00 |
| COE Rebate Amount: | \$2,494.00 |
| Total Rebate Amount: | \$12,347.00 |

The information contained herein is correct as at 06 Jul 2018

OK

18,000
 12,347

 5653

 (5K)

Condition (CON):

(01) Bent (2) Dented (3) Distorted (4) Cracked (5) Cut (6) Scratched
 (07) Deformed (08) Shifted (09) Buckled (10) Broken (11) Necessary
 (12) Missing (13) Torn (14) Unconfirmed (15) Not Working

MOTOR CAR (UC)

ACTION (AC)

(1) Replace (✓) (2) Repair (X) (3) Check (?)
 (4) Not Consistent (NC)

Aug 2003

Vehicle No: **SJT 8577B**

Undercarriage

| NAC | INC | Item | CON | AC | Qty |
|------|--------|---------------------------------|-----|----|-----|
| 1372 | 995163 | Frt LH Shock Absorber | | | |
| 1373 | 991944 | Frt LH Shock Absorber Mounting | | | |
| 1374 | 990632 | Frt LH Coil Spring | | | |
| 1375 | 995198 | Frt LH Knuckle Arm | | | |
| 1376 | 995199 | Frt LH Knuckle Arm Bearing | JM | ✓ | |
| 1377 | 995178 | Frt LH Lower Arm | BT | ✓ | |
| 1378 | 995169 | Frt LH Upper Arm | | | |
| 1379 | 995183 | Frt LH Tie Rod | | | |
| 1380 | 995143 | Frt LH Drive Shaft | | | |
| 1381 | 990661 | Frt LH Control Arm | | | |
| 1382 | 992062 | Frt LH Trailing Arm | | | |
| 1383 | 991848 | Frt LH Leaf Spring | | | |
| 1384 | 991293 | Frt LH Brake Disc Rotor | | | |
| 1385 | 991281 | Frt LH Brake Caliper | | | |
| 1386 | 991292 | Frt LH Brake Pipe | | | |
| 1387 | 991287 | Frt LH Brake Hose | | | |
| 1388 | 991295 | Frt LH Brake Sensor Wire | | | |
| 1389 | 991989 | Frt Stay Bar Bracket | | | |
| 1390 | 994455 | Steering Rack & Pinion | | | |
| 1391 | 994435 | Steering Cross Member | | | |
| 1392 | 994519 | Frt Sub Frame | | | |
| 1393 | 992003 | Frt Sub Frame Mounting | | | |
| 1394 | 991217 | Frt Anti Roll Bar | | | |
| 1395 | 991219 | Frt Anti Roll Bar Linkage | | | |
| 1396 | 990887 | Engine Block | | | |
| 1397 | 990890 | Engine Block Gasket | | | |
| 1398 | 990972 | Engine Oil Sump | | | |
| 1399 | 990960 | Engine Oil | | | |
| 1400 | 992224 | Gear Box Assy | | | |
| 1401 | 992229 | Gear Box Gasket | | | |
| 1402 | 992241 | Gear Box Oil Sump | | | |
| 1403 | 992257 | Gear Oil | | | |
| 1210 | 990534 | Centre Exhaust Pipe Assy | | | |
| 1211 | 990532 | Centre Exhaust Mounting | | | |
| 1404 | 991134 | Floor Panel | | | |
| 1405 | 993719 | Rear LH Shock Absorber | | | |
| 1406 | 993723 | Rear LH Shock Absorber Mounting | | | |
| 1407 | 993170 | Rear LH Coil Spring | | | |
| 1408 | 993550 | Rear LH Knuckle Arm | | | |
| 1409 | 993551 | Rear LH Knuckle Arm Bearing | | | |
| 1410 | 993597 | Rear LH Lower Arm | | | |
| 1411 | 993884 | Rear LH Upper Arm | | | |
| 1412 | 995161 | Rear LH Drive Shaft | | | |
| 1413 | 995216 | Rear LH Control Arm | | | |
| 1414 | 993881 | Rear LH Trailing Arm | | | |
| 1415 | 993573 | Rear LH Leaf Spring | | | |
| 1416 | 992941 | Rear LH Brake Disc Rotor | | | |
| 1417 | 992937 | Rear LH Brake Caliper Assy | | | |
| 1418 | 990434 | Rear LH Brake Pipe | | | |
| 1419 | 992946 | Rear LH Brake Hose | | | |
| 1420 | 993819 | Rear Sub Frame | | | |
| 1421 | 993820 | Rear Sub Frame Mounting | | | |
| 1422 | 992813 | Rear Anti Roll Bar | | | |
| 1423 | 990168 | Rear Anti Roll Bar Linkage | | | |
| 1424 | 990202 | Axle Beam | | | |
| 1425 | 990170 | Rear Axle Panhard Rod | | | |
| 1426 | 990810 | Differential Assy | | | |
| 1427 | 992706 | Propeller Shaft | | | |

| NAC | INC | Item | CON | AC | Qty |
|------|--------|---------------------------------|-----|----|-----|
| 1428 | 991935 | Frt RH Shock Absorber | | | |
| 1429 | 991944 | Frt RH Shock Absorber Mounting | | | |
| 1430 | 990632 | Frt RH Coil Spring | | | |
| 1431 | 991844 | Frt RH Knuckle Arm | | | |
| 1432 | 991845 | Frt RH Knuckle Arm Bearing | | | |
| 1433 | 991851 | Frt RH Lower Arm | | | |
| 1434 | 992064 | Frt RH Upper Arm | | | |
| 1435 | 992040 | Frt RH Tie Rod | | | |
| 1436 | 991692 | Frt RH Drive Shaft | | | |
| 1437 | 990661 | Frt RH Control Arm | | | |
| 1438 | 992062 | Frt RH Trailing Arm | | | |
| 1439 | 991848 | Frt RH Leaf Spring | | | |
| 1440 | 991293 | Frt RH Brake Disc Rotor | | | |
| 1441 | 991281 | Frt RH Brake Caliper | | | |
| 1442 | 991292 | Frt RH Brake Pipe | | | |
| 1443 | 991287 | Frt RH Brake Hose | | | |
| 1444 | 991295 | Frt RH Brake Sensor Wire | | | |
| 1445 | 993720 | Rear RH Shock Absorber | | | |
| 1446 | 993723 | Rear RH Shock Absorber Mounting | | | |
| 1447 | 993173 | Rear RH Coil Spring | | | |
| 1448 | 993550 | Rear RH Knuckle Arm | | | |
| 1449 | 993551 | Rear RH Knuckle Arm Bearing | JM | ✓ | |
| 1450 | 993601 | Rear RH Lower Arm | | | |
| 1451 | 993885 | Rear RH Upper Arm | | | |
| 1452 | 993322 | Rear RH Drive Shaft | | | |
| 1453 | 993178 | Rear RH Control Arm | | | |
| 1454 | 995117 | Rear RH Trailing Arm | | | |
| 1455 | 995110 | Rear RH Leaf Spring | | | |
| 1456 | 992942 | Rear RH Brake Disc Rotor | | | |
| 1457 | 992938 | Rear RH Brake Caliper Assy | | | |
| 1458 | 990434 | Rear RH Brake Pipe | | | |
| 1459 | 992947 | Rear RH Brake Hose | | | |

No of Items: _____ Assessor: _____

MOTORCAR (Rear)

Rear Portion

Vehicle No: **SJT 8577B**

| NAC | INC | Item | CON | ACQ | Qt |
|------|--------|-----------------------------|-----|-----|----|
| 1137 | 993626 | Rear Number Plate | | | |
| 1138 | 993627 | Rear Number Plate Base | | | |
| 1139 | 993630 | Rear Number Plate Garnish | | | |
| 1140 | 993632 | Rear Number Plate Lamp | | | |
| 1141 | 992958 | Rear Bumper | | | |
| 1142 | 993085 | Rear Bumper Upper | | | |
| 1143 | 993017 | Rear Bumper Lower | | | |
| 1144 | 993054 | Rear Bumper Side | | | |
| 1145 | 993103 | Rear Bumper Tow Cover | | | |
| 1146 | 992341 | Rear Bumper Clips | | | |
| 1147 | 992976 | Rear Bumper Bracket | | | |
| 1148 | 993068 | Rear Bumper Side Retainer | | | |
| 1149 | 993045 | Rear Bumper Reinforcement | | | |
| 1150 | 992970 | Rear Bumper Beam | | | |
| 1151 | 993077 | Rear Bumper Sponge | | | |
| 1152 | 992999 | Rear Bumper Damper | | | |
| 1153 | 993040 | Rear Bumper Protector | | | |
| 1154 | 993036 | Rear Bumper Pad | | | |
| 1155 | 993026 | Rear Bumper Moulding | | | |
| 1156 | 993044 | Rear Bumper Reflector | | | |
| 1157 | 993023 | Rear Bumper Lower Spoiler | | | |
| 1158 | 994023 | Reverse Sensor | UB | X | |
| 1159 | 993327 | Rear End Panel | | | |
| 1160 | 993339 | Rear End Panel Top Garnish | | | |
| 1161 | 993333 | Rear End Panel Inner Trim | | | |
| 1162 | 990333 | Boot Compartment Inner Trim | | | |
| 1163 | 993851 | Rear LH Taillamp | | | |
| 1164 | 993853 | Rear LH Taillamp Garnish | | | |
| 1165 | 993859 | Rear LH Taillamp Panel | | | |
| 1166 | 995116 | Rear RH Taillamp | | | |
| 1167 | 993853 | Rear RH Taillamp Garnish | | | |
| 1168 | 993859 | Rear RH Taillamp Panel | | | |
| 1169 | 993554 | Rear Apron Panel | | | |
| 1170 | 992895 | Bootlid | | | |
| 1171 | 991328 | Bootlid Emblem | | | |
| 1172 | 990356 | Bootlid Handle | | | |
| 1173 | 995250 | Bootlid Moulding | | | |
| 1174 | 990376 | Bootlid Reflector | | | |
| 1175 | 995222 | Bootlid Lamp LH | | | |
| 1176 | 992899 | Bootlid Lamp RH | | | |
| 1177 | 995243 | Bootlid Lock | | | |
| 1178 | 990377 | Bootlid Rubber | | | |
| 1179 | 990382 | Bootlid Hinge | | | |
| 1180 | 993877 | Bootlid Spoiler | | | |
| 1181 | 994543 | Tailgate | | | |
| 1182 | 991328 | Tailgate Emblem | | | |
| 1183 | 994643 | Tailgate Outer Handle | | | |
| 1184 | 994640 | Tailgate Moulding | | | |
| 1185 | 994545 | Tailgate Garnish | | | |
| 1186 | 994648 | Tailgate Reflector | | | |
| 1187 | 994549 | Tailgate Lamp | | | |
| 1188 | 994646 | Tailgate Protector | | | |
| 1189 | 994676 | Tailgate Wiper Arm | | | |
| 1190 | 994677 | Tailgate Wiper Blade | | | |
| 1191 | 994679 | Tailgate Wiper Nozzle | | | |
| 1192 | 994555 | Tailgate Wiper Motor | | | |
| 1193 | 994602 | Tailgate Glass | | | |
| 1194 | 994606 | Tailgate Glass Rubber | | | |
| 1195 | 994604 | Tailgate Glass Moulding | | | |
| 1196 | 994607 | Tailgate Glass Sealant | | | |
| 1197 | 994629 | Tailgate Lock | | | |
| 1198 | 994651 | Tailgate Rubber | | | |
| 1199 | 994611 | Tailgate Hinge | | | |
| 1200 | 994594 | Tailgate Damper | | | |
| 1201 | 994613 | Tailgate Inner Board | | | |

| NAC | INC | Item | CON | ACQ | Qt |
|------|--------|--------------------------------|-----|-----|-----|
| 1202 | 993784 | Spare Tyre Board | | | |
| 1203 | 994328 | Spare Tyre Panel | | | |
| 1204 | 995065 | Spare Tyre | | | |
| 1205 | 994326 | Spare Tyre Lock Screw | | | |
| 1206 | 993787 | Spare Tyre Cover | | | |
| 1207 | 995323 | Triangle Breakdown Sign | | | |
| 1208 | 990507 | CD Changer Assy | | | |
| 1209 | 990164 | Antenna | | | |
| 1210 | 990534 | Centre Exhaust Pipe Assy | | | |
| 1211 | 990532 | Centre Exhaust Mounting | | | |
| 1212 | 993364 | Rear Exhaust Pipe | | | |
| 1213 | 993357 | Rear Exhaust Chrome Pipe | | | |
| 1214 | 993361 | Rear Exhaust Mounting | | | |
| 1215 | 993358 | Rear Exhaust Heat Shield | | | |
| 1216 | 995223 | Rear LH Chassis Member | | | |
| 1217 | 993165 | Rear RH Chassis Member | | | |
| 1218 | 993436 | Rear LH Fender | | | |
| 1219 | 993449 | Rear LH Fender Protector | | | |
| 1220 | 993420 | Rear LH Fender Inner Panel | | | |
| 1221 | 993431 | Rear LH Fender Inner Trim | | | |
| 1222 | 993415 | Rear LH Fender Inner Garnish | | | |
| 1223 | 993425 | Rear LH Fender Inner Shield | | | |
| 1224 | 993621 | Rear LH Mudflap | | | |
| 1225 | 993933 | Rear LH Wheel Rim | | | |
| 1226 | 994025 | Rear LH Rim Cover | | | |
| 1227 | 995065 | Rear LH Tyre | | | |
| 1228 | 993456 | Rear RH Fender | | | |
| 1229 | 993450 | Rear RH Fender Protector | | | |
| 1230 | 993420 | Rear RH Fender Inner Panel | | | |
| 1231 | 993431 | Rear RH Fender Inner Trim | | | |
| 1232 | 993415 | Rear RH Fender Inner Garnish | | | |
| 1233 | 993425 | Rear RH Fender Inner Shield | | | |
| 1234 | 993622 | Rear RH Mudflap | | | |
| 1235 | 993934 | Rear RH Wheel Rim | | | 947 |
| 1236 | 994025 | Rear RH Rim Cover | | | |
| 1237 | 995065 | Rear RH Tyre | | | |
| 1238 | 995162 | Rear Fender Extension Panel LH | | | |
| 1239 | 993401 | Rear Fender Extension Panel RH | | | |
| 1240 | 993430 | Rear Fender Inner Top Garnish | | | |
| 1241 | 993673 | Rear Fender 1/4 Glass | | | |
| 1242 | 993452 | Rear Fender 1/4 Glass Rubber | | | |
| 1243 | 993453 | Rear Fender 1/4 Glass Sealant | | | |
| 1244 | 993949 | Rear Windscreen Glass | | | |
| 1245 | 993976 | Rear Windscreen Rubber | | | |
| 1246 | 993961 | Rear Windscreen Moulding | | | |
| 1247 | 993955 | Rear Windscreen Sealant | | | |
| 1248 | 994729 | Third Brake Light | | | |
| 1249 | 993385 | Rear Fender Air Grille | | | |
| 1250 | 992167 | Fuel Lid | | | |
| 1251 | 992168 | Fuel Neck | | | |
| 1252 | 992179 | Fuel Tank | | | |
| 1253 | 992184 | Fuel Tank Bracket | | | |
| 1254 | 992191 | Fuel Tank Float | | | |
| 1255 | 990247 | Sticker | | | |

No of Items: _____

Assessor: _____

MOTOR CAR (LH)

Left Portion

| NAC | INC | Item | CON | AC | Qty |
|------|--------|-----------------------------------|-----|----|-----|
| 1255 | 995326 | Frt LH Door | DIS | ✓ | |
| 1256 | 995140 | Frt LH Door Protector | | | |
| 1257 | 995104 | Frt LH Door Hinge | BT | ✓ | 2 |
| 1258 | 995142 | Frt LH Door Wing Mirror | SCR | R | X |
| 1259 | 995102 | Frt LH Door Garnish | | | |
| 1260 | 991593 | Frt LH Door Glass Outer Moulding | | | |
| 1261 | 991588 | Frt LH Door Glass Inner Moulding | | | |
| 1262 | 995103 | Frt LH Door Glass | | | |
| 1263 | 991595 | Frt LH Door Glass Regulator | BT | ✓ | |
| 1264 | 991596 | Frt LH Door Glass Regulator Motor | UB | X | |
| 1265 | 991662 | Frt LH Door Rubber | CUT | ✓ | |
| 1266 | 991636 | Frt LH Door Outer Handle | | | |
| 1267 | 991607 | Frt LH Door Inner Handle | | | |
| 1268 | 991625 | Frt LH Door Lock w/Key | | | |
| 1269 | 991624 | Frt LH Door Lock | | | |
| 1270 | 991562 | Frt LH Door Central Lock | | | |
| 1271 | 991675 | Frt LH Door Switch | | | |
| 1272 | 991617 | Frt LH Door Inner Trim Board | BR | ✓ | |
| 1273 | 991568 | Frt LH Door Checker | UB | X | |
| 1274 | 991575 | Frt LH Door Felt | NEG | ✓ | |
| 1275 | 991688 | Frt LH Door Wire Harness | | | |
| 1276 | 991683 | Frt LH Door Window Glass Pillar | | | |
| 1277 | 991640 | Frt LH Door Outer Pillar | | | |
| 1278 | 991613 | Frt LH Door Inner Pillar | | | |
| 1279 | 991646 | Frt LH Door Pillar Inner Garnish | | | |
| 1280 | 990554 | Centre Pillar LH | | | |
| 1281 | 990542 | Centre Inner Pillar LH | | | |
| 1282 | 990517 | Centre Pillar Upper Garnish LH | | | |
| 1283 | 990564 | Centre Pillar Lower Garnish LH | | | |
| 1284 | 991670 | Frt LH Door Step Garnish | | | |
| 1285 | 994052 | Rocker Panel LH | | | |
| 1286 | 994049 | Rocker Panel Inner Panel LH | | | |
| 1287 | 994046 | Rocker Panel Garnish LH | | | |
| 1288 | 994055 | Rocker Panel Outer Side Skirt LH | BR | ✓ | |
| 1004 | 991300 | Frt Bumper | CUT | ✓ | |
| 1006 | 991325 | Frt Bumper Bracket | | | |
| 1007 | 991462 | Frt Bumper Side Retainer LH | BR | ✓ | 1 |
| 1008 | 991433 | Frt Bumper Reinforcement | | | |
| 1010 | 991468 | Frt Bumper Sponge | | | |
| 1011 | 991427 | Frt Bumper Protector | | | |
| 1014 | 991301 | Frt Bumper Moulding | | | |
| 1015 | 991407 | Frt Bumper Lower Spoiler | | | |
| 1029 | 995153 | Frt LH Headlamp Assy | | | |
| 1031 | 995088 | Frt LH Side Lamp | | | |
| 1096 | 995070 | Frt LH Fender | DIS | ✓ | |
| 1098 | 995147 | Frt LH Fender Lamp | | | |
| 1099 | 995148 | Frt LH Fender Protector | | | |
| | | Frt LH Speaker | BR | ✓ | |

Vehicle No: **SJT 8577 B**

| NAC | INC | Item | CON | AC | Qty |
|------|--------|-------------------------------------|-----|----|-----|
| 1289 | 995156 | Rear LH Door | DD | ✓ | |
| 1290 | 993282 | Rear LH Door Protector | | | |
| 1291 | 995194 | Rear LH Door Hinge LOWAV | BT | ✓ | 1 |
| 1292 | 993228 | Rear LH Door Garnish | | | |
| 1293 | 993278 | Rear LH Door Glass Outer Moulding | | | |
| 1294 | 993231 | Rear LH Door Glass Inner Moulding | | | |
| 1295 | 995190 | Rear LH Door Glass | | | |
| 1296 | 993238 | Rear LH Door Glass Regulator | BT | ✓ | |
| 1297 | 995192 | Rear LH Door Glass Regulator Motor | UB | X | |
| 1298 | 993294 | Rear LH Door Rubber | | | |
| 1299 | 993275 | Rear LH Door Outer Handle | | | |
| 1300 | 993250 | Rear LH Door Inner Handle | | | |
| 1301 | 993261 | Rear LH Door Lock | | | |
| 1302 | 993256 | Rear LH Door Inner Trim Board | | | |
| 1303 | 993218 | Rear LH Door Checker - | | | |
| 1304 | 993230 | Rear LH Door Glass Channel | | | |
| 1305 | 993242 | Rear LH Door Glass Triangle Garnish | | | |
| 1306 | 993285 | Rear LH Door 1/4 Glass | | | |
| 1307 | 993288 | Rear LH Door 1/4 Glass Rubber | | | |
| 1308 | 993287 | Rear LH Door 1/4 Glass Pillar | | | |
| 1309 | 993305 | Rear LH Door Step Garnish | | | |
| 1310 | 993309 | Rear LH Door Switch | | | |
| 1311 | 994070 | Roof Top Panel | | | |
| 1312 | 994098 | Roof Top Moulding | | | |
| 1313 | 994085 | Roof Top Air-bag | | | |
| 1314 | 994084 | Roof Top Air-bag Sensor | | | |
| 1315 | 994083 | Roof Top Air-bag Control Unit | | | |
| 1141 | 992958 | Rear Bumper | CUT | ✓ | |
| 1147 | 992976 | Rear Bumper Bracket | | | |
| 1148 | 993068 | Rear Bumper Side Retainer | | | |
| 1149 | 993045 | Rear Bumper Reinforcement | | | |
| 1151 | 993077 | Rear Bumper Sponge | | | |
| 1153 | 993040 | Rear Bumper Protector | | | |
| 1155 | 993026 | Rear Bumper Moulding | | | |
| 1157 | 993023 | Rear Bumper Lower Spoiler | | | |
| 1163 | 993851 | Rear LH Taillamp | | | |
| 1218 | 993436 | Rear LH Fender | DIS | ✓ | |
| 1219 | 993449 | Rear LH Fender Protector | | | |
| 1136 | 990247 | Sticker | | | |

No of Items: _____ Assessor: _____

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'ed | Status |
|------|--|---------------|--|--|--|-------------|---|
| Main | 02 Aug 2018 09:19 Edit Reg | | 04 Jul 2018 00:00 Edit Adj Rpt | S\$0.00 Edit Estimates | S\$0.00 View Rpt | | Pending for Survey Report Cancel Case |

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

| | | | |
|-----------------------------|--|------------------------|---|
| Insured: | -, Co. Reg. No.: -, Email: email@yahoo.com | | |
| Main Claimant: | CHUNG SOH MEI | | |
| Vehicle Reg. No.: | SJT8577B | Date of Loss: | 02/07/2018 18:00 - :59 [104 Months From LTA Reg Date (Man Yr)] |
| Claim Type: | TP | Policy/Cover Note No.: | |
| Vehicle Reg. No. (Insured): | SJH7359J | Policy No. (Claimant): | |
| | | Excess: | |
| Repairer: | Ama Automotive Pte Ltd () 36 Toh Guan Road East #01-36, 608580 Jurong East - Tel: | | |
| Handling Insurer: | ECICS Limited (HQ) - Tel: 63374779 /6303 0178 | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 17/07/2018] | | |

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. | | | | | | | | | |

Claim Documents

***SJT8577B**
[SJH7359J]
TP
CHUNG SOH MEI
Jul 2 2018 6:00PM
[-]
Ama Automotive Pte Ltd

View

| Photos/Images | | | 3 per page | <input checked="" type="checkbox"/> |
|---------------|-----------------|-----------------------------------|------------|-------------------------------------|
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 1 | 11/07/18 19:53 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 2 | 11/07/18 19:53 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 3 | 11/07/18 19:53 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 4 | 11/07/18 19:53 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 5 | 11/07/18 19:53 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 6 | 11/07/18 19:53 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 7 | 11/07/18 19:53 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 8 | 11/07/18 19:53 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 9 | 11/07/18 19:53 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 10 | 11/07/18 19:53 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 11 | 11/07/18 19:53 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 12 | 11/07/18 19:53 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 13 | 11/07/18 19:53 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 14 | 11/07/18 19:53 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 15 | 11/07/18 19:53 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 16 | 11/07/18 19:53 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 17 | 11/07/18 19:53 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 18 | 11/07/18 19:53 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 19 | 11/07/18 19:53 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 20 | 11/07/18 19:53 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 21 | 11/07/18 19:53 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 22 | 11/07/18 19:53 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 23 | 11/07/18 19:53 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 24 | 11/07/18 19:53 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 25 | 11/07/18 19:53 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 26 | 11/07/18 19:53 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 27 | 11/07/18 19:53 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 28 | 11/07/18 19:53 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 29 | 11/07/18 19:53 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 30 | 11/07/18 19:53 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 31 | 11/07/18 19:53 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 32 | 11/07/18 19:53 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 33 | 11/07/18 19:53 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 34 | 11/07/18 19:53 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 35 | 11/07/18 19:53 | General View | Load JPG | <input checked="" type="checkbox"/> |

| Photos/Images | | | | <input checked="" type="checkbox"/> |
|---------------|-----------------|-----------------------------------|--|-------------------------------------|
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 36 | 11/07/18 19:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 37 | 11/07/18 19:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 38 | 11/07/18 19:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 39 | 11/07/18 19:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 40 | 11/07/18 19:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 41 | 11/07/18 19:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 42 | 11/07/18 19:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 43 | 11/07/18 19:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 44 | 11/07/18 19:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 45 | 11/07/18 19:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 46 | 11/07/18 19:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 47 | 11/07/18 19:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 48 | 11/07/18 19:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 49 | 11/07/18 19:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 50 | 11/07/18 19:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 51 | 11/07/18 19:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 52 | 11/07/18 19:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 53 | 11/07/18 19:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 54 | 11/07/18 19:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 55 | 11/07/18 19:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 56 | 11/07/18 19:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 57 | 11/07/18 19:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 58 | 11/07/18 19:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 59 | 11/07/18 19:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 60 | 11/07/18 19:53 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 61 | 11/07/18 19:53 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 62 | 11/07/18 19:53 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 63 | 11/07/18 19:53 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 64 | 11/07/18 19:53 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 65 | 11/07/18 19:53 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 66 | 11/07/18 19:53 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 67 | 11/07/18 19:53 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 68 | 11/07/18 19:53 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 69 | 11/07/18 19:53 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 70 | 11/07/18 19:53 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 71 | 11/07/18 19:53 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 72 | 11/07/18 19:53 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 73 | 11/07/18 19:53 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 74 | 11/07/18 19:53 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 75 | 11/07/18 19:53 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 76 | 11/07/18 19:53 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 77 | 11/07/18 19:53 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 78 | 11/07/18 19:53 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 79 | 11/07/18 19:53 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 80 | 11/07/18 19:53 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 81 | 11/07/18 19:53 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 82 | 11/07/18 19:53 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 83 | 11/07/18 19:53 | Dismantled Parts | Load JPG | <input checked="" type="checkbox"/> |

| Photos/Images | | | | |
|---------------|-----------------|-----------------------------------|---|-----------------|
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | | Thumbnail Print |
| 84 | 11/07/18 19:53 | Dismantled Parts | 1 | Load JPG ✓ |
| 85 | 11/07/18 19:53 | Dismantled Parts | 1 | Load JPG ✓ |
| 86 | 11/07/18 19:53 | Dismantled Parts | 1 | Load JPG ✓ |
| 87 | 11/07/18 19:53 | Dismantled Parts | 1 | Load JPG ✓ |
| 88 | 11/07/18 19:53 | Dismantled Parts | 1 | Load JPG ✓ |
| 89 | 11/07/18 19:53 | Dismantled Parts | 1 | Load JPG ✓ |
| 90 | 11/07/18 19:53 | Dismantled Parts | 1 | Load JPG ✓ |
| 91 | 11/07/18 19:53 | Dismantled Parts | 1 | Load JPG ✓ |
| 92 | 11/07/18 19:53 | Dismantled Parts | 1 | Load JPG ✓ |
| 93 | 11/07/18 19:53 | Dismantled Parts | 1 | Load JPG ✓ |
| 94 | 11/07/18 19:53 | Dismantled Parts | 1 | Load JPG ✓ |
| 95 | 11/07/18 19:53 | Dismantled Parts | 1 | Load JPG ✓ |
| 96 | 11/07/18 19:53 | Dismantled Parts | 1 | Load JPG ✓ |
| 97 | 11/07/18 19:53 | Dismantled Parts | 1 | Load JPG ✓ |
| 98 | 11/07/18 19:53 | Dismantled Parts | 1 | Load JPG ✓ |
| 99 | 11/07/18 19:53 | Dismantled Parts | 1 | Load JPG ✓ |
| 100 | 11/07/18 19:53 | Dismantled Parts | 1 | Load JPG ✓ |
| 101 | 11/07/18 19:53 | Dismantled Parts | 1 | Load JPG ✓ |
| 102 | 11/07/18 19:53 | Dismantled Parts | 1 | Load JPG ✓ |
| 103 | 11/07/18 19:53 | Dismantled Parts | 1 | Load JPG ✓ |
| 104 | 11/07/18 19:53 | Dismantled Parts | 1 | Load JPG ✓ |
| 105 | 11/07/18 19:53 | Dismantled Parts | 1 | Load JPG ✓ |
| 106 | 11/07/18 19:53 | Dismantled Parts | 1 | Load JPG ✓ |
| 107 | 11/07/18 19:53 | Dismantled Parts | 1 | Load JPG ✓ |
| 108 | 11/07/18 19:53 | Dismantled Parts | 1 | Load JPG ✓ |
| 109 | 11/07/18 19:53 | Dismantled Parts | 1 | Load JPG ✓ |
| 110 | 11/07/18 19:53 | Dismantled Parts | 1 | Load JPG ✓ |
| 111 | 11/07/18 19:53 | Dismantled Parts | 1 | Load JPG ✓ |
| 112 | 11/07/18 19:53 | Dismantled Parts | 1 | Load JPG ✓ |
| 113 | 11/07/18 19:53 | Dismantled Parts | 1 | Load JPG ✓ |
| 114 | 11/07/18 19:53 | Dismantled Parts | 1 | Load JPG ✓ |
| 115 | 11/07/18 19:53 | Dismantled Parts | 1 | Load JPG ✓ |
| 116 | 11/07/18 19:53 | Dismantled Parts | 1 | Load JPG ✓ |
| 117 | 11/07/18 19:53 | Dismantled Parts | 1 | Load JPG ✓ |
| 118 | 11/07/18 19:53 | Dismantled Parts | 1 | Load JPG ✓ |

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/ICS18012201/R1Z4D3S2
Date: 02/08/2018

REFERENCE

| | | | |
|------------------------------|---------------|-----------------------------|----------|
| Handling Insurer: | ECICS Limited | Policy No: | |
| Claimant Vehicle No : | SJT8577B | Insured Vehicle No : | SJH7359J |
| Date of Loss: | 02/07/2018 | Nature of Claim: | TP |
| | | Claim No: | N/A |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No: | SJT8577B | Engine No: | HR15110657B |
| Make & Model: | NISSAN LATIO, 1.5 (A) | Chassis No: | JN1BAAC11Z0021514 |
| Reg. Date: | 02/11/2009 (Man. Year: 2009) | Odometer: | 141169 km |
| Colour: | White | | |
| Engine Capacity: | 1498 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | | |
|--------------------------|------|-------------------------|-----|--------------------------|-----|
| General Condition: | Fair | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: | |

CONDITION OF TYRES

| | | | |
|-------------------|--------------|------------------|--------------|
| Front Tyre Size: | 185/65R15 | Rear Tyre Size: | 185/65R15 |
| Front Left Side: | Firenza 6 mm | Rear Left Side: | Firenza 6 mm |
| Front Right Side: | Firenza 6 mm | Rear Right Side: | Firenza 6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--------------------------|-------------|-------------|-------------|--------|
| Parts | 0.00 | 0.00 | 0.00 | |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 0.00 | 0.00 | 0.00 | |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Nett Amount (S\$) | 0.00 | 0.00 | 0.00 | |

INSPECTION

| | | | |
|-----------------------------|------------|---------------|--|
| Date of Assignment: | 04/07/2018 | | |
| Date Inspected: | 05/07/2018 | Inspected At: | Ama Automotive Pte Ltd 36 Toh Guan Road East #01-36 Singapore 608580 |
| Estimated Period of Repair: | 8.0 days | | |

Adjuster: MOHD RASUL

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$10,000.00 - \$11,000.00

REPAIR DETAILS

Reference

| | |
|----------------------------|--|
| Part Source: MRM-SG | Version: 1.0 (Last Synchronised: 02 Aug 2018) |
| Parts: 144 | NISSAN LATIO 1.5 (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for SJT8577B) |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. |

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >