

INS. CASE OWNER:

Kay King

CC3, LCR 180

12/21, R/L, 3/23

LKK:

IDAC:

Surveyor:

Rasm

DOI:

ASSIGNMENT

5/7/18

Date/Time:

4/7/18

Registered in Merimen:

4/7/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SUH 4560P

Name of Insured:

LCR P/L

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

28/6/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

CHUA KOK SIAH

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

90 02452435G

Policy No.:

09999 4823

Make / Model:

Honda

Place of Accident:

BULUT TIRAH EXPRESSWAY

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SJR 1000E

SUH 4560P

SUH 3200K



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

6/7

CMT

SUH 3200K - X

SUH 4560P - CMT / LCR 180 07/15/18; 21/04/18; 04/10/18

9/7/18

- 3 vch cc. Old was 2nd car.
- Sent letter to OI via email.

17/5/19

- Fle -> typermanet etc

- PINKUERO

- ORIGINAL TP LOD IN

19/07/19

- 98% UNAPPROVED APPROVAL TO AIG
- AIG APPROVED UNAPPROVED.
- CONFIRMED AMOUNT SAME AS LOD.
- ALL DONE IN ORBIT.
- TO close.

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

24/5/19 9/7/18

After call ltr to OI:

(By email)

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

P/P

S\$ 28,242.45

(11 days)

Reduction:

10 %

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

CAROLINE

Email

Call

Final Liability:

%

100

(Agreed / Assessed)

BOLA S/N No.:

28 (3rd and)

If NO or B 28, Ass. Lia:

0%

Repair Cost:

(w/gar)

S\$ 30,249.42

Loss of Rental (LOR):

S\$

(days)

Loss of Use (LOU):

1500

S\$

1,500.00

x 15

days)

Loss of Income (LOI):

S\$

(\$ x days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

7.45

S\$

7.45

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

31,726.87

S\$

Total:

S\$

31,726.87

Global Sum S\$:

-

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

30,226.87

Name 1:

PERFORMANCE MOTORS LIMITED

Payee 2: (Strike if N.A.)

S\$

1,500.00

Name 2:

SINE DARTY SERVICES PTE LTD

Payee 3: (Strike if N.A.)

S\$

Name 3:

-

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$320.00

COPY SENT

08/11/13) waf
ASS. REC. BY: Pam

REF: LCR

1000/1000? -P
1065 u

ASSIGNMENT

From: _____ Date: 05/07/2018

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: SLH 3200 K
at Workshop m/s Performance Motor
of 303 Alexandra Road

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: Kevin

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 11 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (up)

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLH 3200 K Yr Regn: 2016 / OCT

Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: B.M.W 730LT c.c. 1998

Colour: WHITE A/C: Insured / Std / NI / NA

Sp. Reading: 25112 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBA TE020X 0h 245194

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Order / Jammed / Leaked / Burnt or

Brake: Order / Jammed / Leaked / Burnt or

Modi: Nil / 8/Rim / STD A/Rim or

Tyre Size: F: 245/50R18

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 28/06/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

R/Bal. 6 mm

L/Bal. 6 mm

D.O.I. 05/07/18

PERFORMANCE

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

PIP # 28242.45 (Reol # 6133) (840)

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Survey Fee:

Transportation:

____ \$ + RS, ____ \$

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ _____)

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

In

GST REG. NO : M2 - 0020081 - X

04 JUL 2018

E S T I M A T E

Estimate No. : b1 47553
Date Estimated : 04/07/2018
Prepared By : Kevin Leong Wai Kit

Page No. : 1 of 6

- ESTIMATE REPAIR FOR -

Sime Darby Services Private Limited
305 Alexandra Road
#02-01 Vantage Automotive Centre
Singapore 159942

- ACCOUNT - 121

AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLH3200K	G245194	31/10/2016	730Li	0

DESCRIPTION

To replace rear bumper, rear tail end panel, boot, reinforcement & all attachment cause by accident.

Painting on rear bumper, boot, end panel & trunk floor

To replace rear exhaust silencer including alignment system and conduct checks for leak.

To check electrical wiring systems and lightings at the rear section for proper function.

To transfer lock mechanism from old to new bootlid including conduct checks on new bootlid central locking system for proper function.

To carry out body cavity preservation.
(Per panel).

To carry out body cavity preservation.
(For cut panel).

To supply rear emboss number plate.

Sundries.

VALUE

~~3400~~ 5100.00

~~3015~~ 3350.00

~~451~~ 531.00

~~150~~ 177.00

~~451~~ 531.00

~~100~~ 118.00

~~451~~ 531.00

~~50~~ 83.00

~~150~~ 150.00

Total Labour 1: 10,571.00

DESCRIPTION

CLAMPING BUSH
REAR SILENCER WITH EXHAUST FLAP
COMPLETE TAIL PANEL
TRUNK LID LH HINGE
TRUNK LID RH HINGE
TAILGATE ALUMINIUM
OUTER PANEL TAIL TRIM

QTY	PRIC
1	66.80
1	1,777.60
1	1,026.90
1	182.60
1	182.60
1	2,107.20
1	718.85

VALUE

~~new?~~ 66.80
~~BT?~~ 1,777.60
~~new~~ 1,026.90
~~new~~ 182.60
~~new~~ 182.60
~~new~~ 2,107.20
~~new~~ 718.85

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 47553
Date Estimated : 04/07/2018
Prepared By : Kevin Leong Wai Kit

Page No. : 2 of 6

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLH3200K	G245194	31/10/2016	730Li	0

DESCRIPTION

QTY

PRIC

VALUE

REAR BUMPER ADAPTER	1	77.65	DE 77.65
REAR BUMPER CARRIER	1	898.50	PA 898.50
REAR BUMPER CENTRE GUIDE	1	51.50	DE 51.50
REAR LH MOUNT LATERAL	1	142.55	MM 142.55
REAR RH MOUNT LATERAL	1	142.55	142.55
LH TRIM EXHAUST TAILPIPE	1	247.20	HA 247.20
RH TRIM EXHAUST TAILPIPE	1	247.20	HA 247.20
REAR LH MOULDING ROCKER PANEL	1	51.50	MC 51.50
REAR RH MOULDING ROCKER PANEL	1	51.50	MC 51.50
TRIM REAR PRIMED	1	216.45	DE 216.45
REAR BUMPER PANEL PRIMED (PDC)	1	1,586.85	DE 1,586.85
REAR BUMPER TOWING EYE COVER PRIMED	1	55.70	MC 55.70
LEFT PROTECTION FOIL	1	11.30	11.30
RIGHT PROTECTION FOIL	1	11.30	11.30
GRIP TRUNK LID (RFK)	1	201.85	XMM 201.85
GRIP TRUNK LID (RFK)	1	201.85	201.85
Holder camera	1	9.75	9.75
BOOTLID CHROME TRIM STRIP	1	176.10	176.10
LETTERING 730Li	1	62.55	MC 62.55
REAR PLAQUE 82MM	1	69.50	MC 69.50
TENSION SPRING	1	68.80	68.80
SPINDLE DRIVE RH	1	467.40	MM 467.40
TRIM TAILGATE BOTTOM PRIMED	1	233.45	DE 233.45
Warning sign	1	38.00	38.00
LOADING SILL COVER	1	132.70	MM 132.70
FLOOR CARPET LUGGAGE COMPARTMENT	1	553.60	553.60
Schlaufe Loop	1	19.65	19.65
Partition, luggage, compartment	1	243.15	243.15
TRUNK LID GASKET (RFK)	1	100.60	MC 100.60
Boot trim rail	1	111.40	MM 111.40
REAR RH LIGHT IN TRUNK LID	1	473.65	CAH 473.65
REAR LH LIGHT IN THE SIDE PANEL	1	735.95	MM 735.95
REAR RH LIGHT IN THE SIDE PANEL	1	735.95	MM 735.95
DECOUPING RING PDC TORQUE CONVERTER	4	5.05	20.20
ULTRASONIC SENSOR ALPINWEISS (U300)	2	380.65	MM 761.30
REVERSING CAMERA	1	681.10	761.10
BLIND RIVET AVIBVLB	30	0.55	16.50 24.20
SCREW (SF PLUS M5X15)	10	0.55	5.50 2.20
(DG/SL) BODY ADHESIVE K5B (195ML)	1	281.55	281.55
(DG) CLEANER R1 (100ML)	1	23.85	23.85
PUNCH RIVET N4	30	0.55	16.50 11.55
(S/L) SEAM SEAL 300ML	1	33.80	33.80

Total Parts : 16,329.95

16338.20

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 47553
Date Estimated : 04/07/2018
Prepared By : Kevin Leong Wai Kit

Page No. : 3 of 6

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLH3200K	G245194	31/10/2016	730Li	0

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims CD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 05/07/18 @ 1045 Excess \$/_____

Surveyor's Name Rasul Sign _____

Surveyor's Tel 90010068 Authorized Yes / No _____

Authorized Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No _____

Surveyor's E-mail rasul@lkkauto.com

No. of Working Days Recommended 8 days

26900.95

Labour 1	:	10,571.00
Parts	:	16,329.95
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,883.07
Grand Total	:	28,784.02

34834.70

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 47553
Date Estimated : 04/07/2018
Prepared By : Kevin Leong Wai Kit

Page No. :

REPAIR FOR -
Sime Darby Services Private Limited
305 Alexandra Road
#02-01 Vantage Automotive Centre

Singapore 159942

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SLH3200K	G245194	31/10/2016	730Li	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
# To replace boot lid smart opener control unit and top and bottom sensor line include programming and conducting checks for proper function	562.00		562.00
# To mount vehicle on celette bench to facilitate re-alignment of body/chassis in accordance with BMW specifications	2508.00		2,508.00
# To remove and install boot compartment carpets and garnish to facilitate repairs	230.00		230.00
# To Remove & install electrical wiring, control units & battery at the rear section to facilitate repairs.	451.00		451.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# SEALING STRIP *	2.90	1.00		2.90 <i>neu</i>
# SEALING STRIP *	2.90	1.00		2.90 <i>neu</i>
# CLAMPING BUSH *	66.80	1.00		66.80 <i>neu</i>
# FRONT SILENCER *	1,681.40	1.00		1,681.40 <i>bt</i>
# INTERMEDIATE PIPE *	563.40	1.00		563.40 <i>bt</i>
# RH TOP SIDE MEMBER EXTENSION *	58.65	1.00		58.65 <i>neu</i>
# RR TRUNK FLOOR CROSS MEMBER *	120.75	1.00		120.75 <i>bt</i>
# REAR LUGGAGE COMPARTMENT FLOOR *	275.90	1.00		275.90 <i>bt</i>
# FOAM SEAL *	2.70	1.00		2.70
# GASKET *	5.25	2.00		10.50 <i>neu</i>
# CLIP (WEISS) *	1.25	4.00		5.00
# CLIP (WEISS) *	1.25	2.00		2.50
# REAR SILENCER HEAT INSULATOR *	130.15	1.00		130.15 <i>bt</i>
# REAR SILENCER HEAT INSULATION FRT *	111.50	1.00		111.50 <i>bt</i>
# REAR SILENCER RH HEAT INSULATOR *	130.15	1.00		130.15 <i>bt</i>
# REAR RH WATER GUTTER COVER *	23.05	1.00		23.05 <i>neu</i>
# REAR DIFFUSER *	139.75	1.00		139.75 <i>neu</i>
# (S/L) GUTTER STRIP *	111.40	1.00		111.40 <i>neu</i>
# PLUG BLACK D=5MM *	0.90	10.00		9.00 <i>neu</i>
# SENSOR WIRE FOR SMART OPENER TOP *	42.10	1.00		42.10 <i>neu</i>
# SENSOR WIRE FOR SMART OPENER BOTTOM *	40.50	1.00		40.50 <i>neu</i>
# CONTROL UNIT SMART OPENER *	468.85	1.00		468.85 <i>neu</i>
# EXPANDING NUT *	0.55	9.00		4.95
# EXPANDING NUT *	0.55	1.00		0.55 <i>neu</i>
# RR RH REAR REFLECTOR *	36.25	1.00		36.25

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



SUPPLEMENTARY

# (S/L) RUBBER BUFFER *	1.97	5.00	9.85 <i>ABC ✓</i>
# RH WATER CHANNEL *	37.95	1.00	37.95 <i>ABC ✓</i>
# REAR RH MOULDING *	74.10	1.00	74.10 <i>ABC ✓</i>
# BLIND RIVET AVIBVLB *	0.55	20.00	11.00 <i>ABC ✓</i>

Total Labour :	3,300.00
Total Parts :	4,174.50 <i>✓</i>
Total Labour & Parts :	7,474.50

34375.45

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 47553
Date Estimated : 04/07/2018
Prepared By : Kevin Leong Wai Kit

Page No. :

REPAIR FOR -
Sime Darby Services Private Limited
305 Alexandra Road
#02-01 Vantage Automotive Centre

Singapore 159942

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEAGE		
SLH3200K	G245194	31/10/2016	730Li	0		
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT			
* To replace rear bumper and attachments, boot lid and attachments, tail end panel, RH top side member extension, rear trunk floor cross member, rear luggage compartment floor, rear trim, bottom tailgate trim, rear RH light in side panel, rear RH moulding include pulling and straightening on accident areas and knocking out dents caused by the accident	5100.00		5,100.00	✓		
To spray paint rear bumper, boot lid, tail end panel and trunk floor panel	3015.00		3,015.00	✓		
* To replace rear, front and intermediate exhaust silencer include alignment of system and conducting checks for leak	451.00		451.00	✓		
(A) * To remove and install electrical wirings, control units and battery at the rear section to facilitate repairs	451.00		451.00	✓	(A)	
To transfer lock mechanism from old to new boot lid include conducting checks on new boot lid central locking system for proper function	451.00		451.00	✓		
* To carry out body cavity preservation (Per panel)	100.00		100.00	✓		
To carry out body cavity preservation (For cut panel)	451.00		451.00	✓		
To supply rear emboss number plate	83.00		83.00	✓		
# To replace boot lid smart opener control unit and top and bottom sensor line include programming and conducting checks for proper function	562.00		562.00	✓	(A)	
# To mount vehicle on culette bench to facilitate re-alignment of body/chassis in accordance with BMW specifications	2508.00		2,508.00	✓	(A)	
# To remove and install boot compartment carpets and garnish to facilitate repairs	230.00		230.00	✓	(A)	

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



FINAL REPORT

Sundries

150.00

150.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# SEALING STRIP *	2.90	1.00		2.90
# SEALING STRIP *	2.90	1.00		2.90
# CLAMPING BUSH *	66.80	1.00		66.80
CLAMPING BUSH	66.80	1.00		66.80
# FRONT SILENCER *	1,681.40	1.00		1,681.40
# INTERMEDIATE PIPE *	563.40	1.00		563.40
REAR SILENCER WITH EXHAUST FLAP	1,777.60	1.00		1,777.60
# RH TOP SIDE MEMBER EXTENSION *	58.65	1.00		58.65
# RR TRUNK FLOOR CROSS MEMBER *	120.75	1.00		120.75
COMPLETE TAIL PANEL	1,026.90	1.00		1,026.90
TAILGATE ALUMINIUM	2,107.20	1.00		2,107.20
# REAR LUGGAGE COMPARTMENT FLOOR *	275.90	1.00		275.90
REAR BUMPER ADAPTER	77.65	1.00		77.65
REAR BUMPER CARRIER	898.50	1.00		898.50
REAR BUMPER CENTRE GUIDE	51.50	1.00		51.50
LH TRIM EXHAUST TAILPIPE	247.20	1.00		247.20
RH TRIM EXHAUST TAILPIPE	247.20	1.00		247.20
REAR LH MOULDING ROCKER PANEL	51.50	1.00		51.50
REAR RH MOULDING ROCKER PANEL	51.50	1.00		51.50
TRIM REAR PRIMED	216.45	1.00		216.45
REAR BUMPER PANEL PRIMED (PDC)	1,586.85	1.00		1,586.85
REAR BUMPER TOWING EYE COVER PRIMED	55.70	1.00		55.70
# FOAM SEAL *	2.70	1.00		2.70
# GASKET *	5.25	2.00		10.50
LETTERING 730LI	62.55	1.00		62.55
REAR PLAQUE 82MM	69.50	1.00		69.50
TRIM TAILGATE BOTTOM PRIMED	233.45	1.00		233.45
# CLIP (WEISS) *	1.25	4.00		5.00
# CLIP (WEISS) *	1.25	2.00		2.50
# REAR SILENCER HEAT INSULATOR *	130.15	1.00		130.15
# REAR SILENCER HEAT INSULATION FRT *	111.50	1.00		111.50
# REAR SILENCER RH HEAT INSULATOR *	130.15	1.00		130.15
# REAR RH WATER GUTTER COVER *	23.05	1.00		23.05
# REAR DIFFUSER *	139.75	1.00		139.75
TRUNK LID GASKET (RFK)	100.60	1.00		100.60
# (S/L) GUTTER STRIP *	111.40	1.00		111.40
# PLUG BLACK D=5MM *	0.90	10.00		9.00
# SENSOR WIRE FOR SMART OPENER TOP *	42.10	1.00		42.10
# SENSOR WIRE FOR SMART OPENER BOTTOM *	40.50	1.00		40.50
# CONTROL UNIT SMART OPENER *	468.85	1.00		468.85
# EXPANDING NUT *	0.55	9.00		4.95
# EXPANDING NUT *	0.55	1.00		0.55
# RR RH REAR REFLECTOR *	36.25	1.00		36.25
REAR RH LIGHT IN TRUNK LID	473.65	1.00		473.65
# (S/L) RUBBER BUFFER *	1.97	5.00		9.85
# RH WATER CHANNEL *	37.95	1.00		37.95
REAR RH LIGHT IN THE SIDE PANEL	735.95	1.00		735.95
# REAR RH MOULDING *	74.10	1.00		74.10
# BLIND RIVET AVIBVLB *	0.55	20.00		11.00
BLIND RIVET AVIBVLB	0.55	30.00		16.50
SCREW (SF PLUS M5X15)	0.55	10.00		5.50

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



FINAL REPORT

(DG/SL) BODY ADHESIVE K5B (195ML)	281.55	1.00	281.55
PUNCH RIVET N4	0.55	30.00	16.50
(DG) CLEANER R1 (100ML)	23.85	1.00	23.85
(S/L) SEAM SEAL 300ML	33.80	1.00	33.80

SUPPLEMENTARY ITEMS

Total Labour :	13,552.00
Total Parts :	14,690.45
Total Labour & Parts :	28,242.45
Deduction for Excess :	0.00
Total Repair Costs less Excess:	28,242.45
GST @7%:	1,976.97
Grand Total :	30,219.42

Hsiao Tong (LKKAUTO)

From: PBSP <pml-pbsp@simedarby.com.sg>
Sent: Friday, 22 March 2019 5:16 PM
To: Hsiao Tong (LKKAUTO); Rasul (LKKAUTO)
Subject: Re: FINAL REPORT / SLH3200K

urgent reminder

From: PBSP
Sent: Monday, 4 March 2019 3:18:35 PM
To: Hsiao Tong (LKKAUTO); Rasul
Subject: FINAL REPORT / SLH3200K

Dear Sirs

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour : 17,455.00
Total Parts : 14,690.45
Total Labour & Parts : 32,145.45

Repair days: 11

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**AIG THIRD PARTY EXPRESS SETTLEMENT
FOR ACCIDENTS ON OR AFTER 1ST JUNE 2008
(PAYMENT BREAKDOWN)**

Vehicle No:	SLH3200K	Model:	BMW
Date of Accident:	28.06.2018		

Global Sum Settlement:	[] Yes	[] No	
Repair Estimate	: \$	28,784.02	
Final Repair Cost	: \$	30,219.42	
Loss of Use	: \$	1,500.00	15 days at \$100.00 per day
Rental (if any)	: \$	---	days
LTA / GIA Search Fee	: \$	7.45	
Others	: \$	---	
	: \$	---	
Final Settlement Sum	: \$	31,726.87	

Is Third Party Workshop GIA Registered? [] YES [] NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ (%)

B) For GIA Registered Workshop: BOLA Application: Yes / No
BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown

1)	Performance Motor Limited	: \$	30,219.42
2)	Performance Motor Limited	: \$	7.45
3)	Sime Darby Services Pte Ltd	: \$	1,500.00

Signed by appointed surveyor

Date

**Please attach all the supporting documents to the form.
Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act;
Survey Report; Medical Report / Bill (if any)**

Print Received Message

This mail is associated with :

***SLH3200K (9062452473SG)**

[SLH4560P]

TP

SIME DARBY SERVICES PRIVATE LIMITED

Jun 28 2018 6:00PM

[LCRF PTE LTD]

Performance Motors Limited

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 19/07/2019 14:15 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$31726.87) - SLH3200K - Claim Handler: Gan, Angie-GL

Approved:31726.87.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	05 Jul 2018 Edit Reg		05 Jul 2018 00:00 Edit Adj Rpt	S\$28,242.45 Edit Estimates	S\$28,242.45 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	LCRF PTE LTD, Co. Reg. No.: 201624597K		
Main Claimant:	SIME DARBY SERVICES PRIVATE LIMITED, Co. Reg. No.: 197501065W		
Vehicle Reg. No.:	SLH3200K	Date of Loss:	28/06/2018 18:00 - :59 [19 Months and 28 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 9062452473SG	Policy/Cover Note No.:	0999994823
Vehicle Reg. No. (Insured):	SLH4560P	Policy No. (Claimant):	B29040568MCY
		Excess:	
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Gan, Angie-GL] Angiegeokling.Gan@aig.com		
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 13/07/2018]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG_EXPRESS (19/07/2019): Alert - Adj Mandate Approved (S\$31726.87) - SLH3200K - Claim Handler: Gan, Angie...

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLH3200K (9062452473SG)
[SLH4560P]

TP

SIME DARBY SERVICES PRIVATE LIMITED

Jun 28 2018 6:00PM

[LCRF PTE LTD]

Performance Motors Limited

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser ▼		
Letters/Correspondences			1 per page ▼	☒	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown		Edit	
Photos/Images			3 per page ▼	☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	17/05/19 08:20	Odometer Reading		Load JPG	☒
2	17/05/19 08:20	Chassis Number		Load JPG	☒
3	17/05/19 08:20	General View		Load JPG	☒
4	17/05/19 08:20	General View		Load JPG	☒
5	17/05/19 08:20	General View		Load JPG	☒
6	17/05/19 08:20	General View		Load JPG	☒
7	17/05/19 08:20	General View		Load JPG	☒
8	17/05/19 08:20	General View		Load JPG	☒
9	17/05/19 08:20	General View		Load JPG	☒
10	17/05/19 08:20	General View		Load JPG	☒
11	17/05/19 08:20	General View		Load JPG	☒
12	17/05/19 08:20	General View		Load JPG	☒
13	17/05/19 08:20	General View		Load JPG	☒
14	17/05/19 08:20	General View		Load JPG	☒
15	17/05/19 08:20	General View		Load JPG	☒
16	17/05/19 08:20	General View		Load JPG	☒
17	17/05/19 08:20	General View		Load JPG	☒
18	17/05/19 08:20	General View		Load JPG	☒
19	17/05/19 08:20	General View		Load JPG	☒
20	17/05/19 08:20	General View		Load JPG	☒
21	17/05/19 08:20	General View		Load JPG	☒
22	17/05/19 08:20	General View		Load JPG	☒
23	17/05/19 08:20	General View		Load JPG	☒
24	17/05/19 08:20	General View		Load JPG	☒
25	17/05/19 08:20	General View		Load JPG	☒
26	17/05/19 08:20	General View		Load JPG	☒
27	17/05/19 08:20	General View		Load JPG	☒
28	17/05/19 08:20	General View		Load JPG	☒
29	17/05/19 08:20	General View		Load JPG	☒
30	17/05/19 08:20	General View		Load JPG	☒
31	17/05/19 08:20	General View		Load JPG	☒
32	17/05/19 08:20	General View		Load JPG	☒

Letters/Correspondences			1 per page ▼	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
33	17/05/19 08:20	General View	 Load JPG	☒
34	17/05/19 08:20	General View	 Load JPG	☒
35	17/05/19 08:20	General View	 Load JPG	☒
36	17/05/19 08:20	General View	 Load JPG	☒
37	17/05/19 08:20	General View	 Load JPG	☒
38	17/05/19 08:20	General View	 Load JPG	☒
39	17/05/19 08:20	General View	 Load JPG	☒
40	17/05/19 08:20	General View	 Load JPG	☒
41	17/05/19 08:20	General View	 Load JPG	☒
42	17/05/19 08:20	General View	 Load JPG	☒
43	17/05/19 08:20	General View	 Load JPG	☒
44	17/05/19 08:20	General View	 Load JPG	☒
45	17/05/19 08:20	General View	 Load JPG	☒
46	17/05/19 08:20	General View	 Load JPG	☒
47	17/05/19 08:20	General View	 Load JPG	☒
48	17/05/19 08:20	General View	 Load JPG	☒
49	17/05/19 08:20	General View	 Load JPG	☒
50	17/05/19 08:20	General View	 Load JPG	☒
51	17/05/19 08:20	General View	 Load JPG	☒
52	17/05/19 08:20	General View	 Load JPG	☒
53	17/05/19 08:20	General View	 Load JPG	☒
54	17/05/19 08:20	General View	 Load JPG	☒
55	17/05/19 08:20	General View	 Load JPG	☒
56	17/05/19 08:20	General View	 Load JPG	☒
57	17/05/19 08:20	General View	 Load JPG	☒
58	17/05/19 08:20	General View	 Load JPG	☒
59	17/05/19 08:20	General View	 Load JPG	☒
60	17/05/19 08:20	General View	 Load JPG	☒
61	17/05/19 08:20	General View	 Load JPG	☒
62	17/05/19 08:20	General View	 Load JPG	☒
63	17/05/19 08:20	General View	 Load JPG	☒
64	17/05/19 08:20	General View	 Load JPG	☒
65	17/05/19 08:20	General View	 Load JPG	☒
66	17/05/19 08:20	General View	 Load JPG	☒
67	17/05/19 08:20	General View	 Load JPG	☒
68	17/05/19 08:20	General View	 Load JPG	☒
69	17/05/19 08:20	General View	 Load JPG	☒
70	17/05/19 08:20	General View	 Load JPG	☒
71	17/05/19 08:20	General View	 Load JPG	☒
72	17/05/19 08:20	General View	 Load JPG	☒
73	17/05/19 08:21	Reinspection Photo	 Load JPG	☒
74	17/05/19 08:21	Reinspection Photo	 Load JPG	☒
75	17/05/19 08:21	Reinspection Photo	 Load JPG	☒
76	17/05/19 08:21	Reinspection Photo	 Load JPG	☒
77	17/05/19 08:21	Reinspection Photo	 Load JPG	☒
78	17/05/19 08:21	Reinspection Photo	 Load JPG	☒
79	17/05/19 08:21	Reinspection Photo	 Load JPG	☒
80	17/05/19 08:21	Reinspection Photo	 Load JPG	☒

Letters/Correspondences			1 per page ▼	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
81	17/05/19 08:21	Reinspection Photo	 Load JPG	☒
82	17/05/19 08:21	Reinspection Photo	 Load JPG	☒
83	17/05/19 08:21	Reinspection Photo	 Load JPG	☒
84	17/05/19 08:21	Reinspection Photo	 Load JPG	☒
85	17/05/19 08:21	Reinspection Photo	 Load JPG	☒
86	17/05/19 08:21	Reinspection Photo	 Load JPG	☒
87	17/05/19 08:21	Reinspection Photo	 Load JPG	☒
88	17/05/19 08:21	Reinspection Photo	 Load JPG	☒
89	17/05/19 08:21	Reinspection Photo	 Load JPG	☒
90	17/05/19 08:21	Reinspection Photo	 Load JPG	☒
91	17/05/19 08:21	Reinspection Photo	 Load JPG	☒
92	17/05/19 08:21	Reinspection Photo	 Load JPG	☒
93	17/05/19 08:21	Reinspection Photo	 Load JPG	☒
94	17/05/19 08:21	Reinspection Photo	 Load JPG	☒
95	17/05/19 08:21	Reinspection Photo	 Load JPG	☒
96	17/05/19 08:21	Reinspection Photo	 Load JPG	☒
97	17/05/19 08:21	Reinspection Photo	 Load JPG	☒
98	17/05/19 08:21	Reinspection Photo	 Load JPG	☒
99	17/05/19 08:21	Reinspection Photo	 Load JPG	☒
100	17/05/19 08:21	Reinspection Photo	 Load JPG	☒
101	17/05/19 08:21	Reinspection Photo	 Load JPG	☒
102	17/05/19 08:21	Reinspection Photo	 Load JPG	☒
103	17/05/19 08:21	Reinspection Photo	 Load JPG	☒
104	17/05/19 08:21	Reinspection Photo	 Load JPG	☒
105	17/05/19 08:21	Reinspection Photo	 Load JPG	☒
106	17/05/19 08:21	Reinspection Photo	 Load JPG	☒
107	17/05/19 08:21	Reinspection Photo	 Load JPG	☒
108	17/05/19 08:21	Reinspection Photo	 Load JPG	☒
109	17/05/19 08:21	Reinspection Photo	 Load JPG	☒
110	17/05/19 08:21	Reinspection Photo	 Load JPG	☒
111	17/05/19 08:21	Reinspection Photo	 Load JPG	☒
112	17/05/19 08:21	Reinspection Photo	 Load JPG	☒
113	17/05/19 08:21	Reinspection Photo	 Load JPG	☒
114	17/05/19 08:21	Reinspection Photo	 Load JPG	☒
115	17/05/19 08:21	Reinspection Photo	 Load JPG	☒
116	17/05/19 08:21	Reinspection Photo	 Load JPG	☒
117	17/05/19 08:21	Reinspection Photo	 Load JPG	☒
118	17/05/19 08:21	Reinspection Photo	 Load JPG	☒
119	17/05/19 08:21	Reinspection Photo	 Load JPG	☒
120	17/05/19 08:21	Reinspection Photo	 Load JPG	☒
121	17/05/19 08:21	Reinspection Photo	 Load JPG	☒
122	17/05/19 08:21	Reinspection Photo	 Load JPG	☒
123	17/05/19 08:21	Reinspection Photo	 Load JPG	☒
124	17/05/19 08:21	Reinspection Photo	 Load JPG	☒
125	17/05/19 08:21	Reinspection Photo	 Load JPG	☒
126	17/05/19 08:21	Reinspection Photo	 Load JPG	☒
127	17/05/19 08:21	Reinspection Photo	 Load JPG	☒
128	17/05/19 08:21	Reinspection Photo	Load JPG	☒

Letters/Correspondences			1 per page ▼	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
129	17/05/19 08:21	Reinspection Photo		☒
130	17/05/19 08:21	Reinspection Photo		☒
131	17/05/19 08:21	Reinspection Photo		☒
132	17/05/19 08:21	Reinspection Photo		☒
133	17/05/19 08:22	Reinspection Photo		☒
134	17/05/19 08:22	Reinspection Photo		☒
135	17/05/19 08:22	Reinspection Photo		☒
136	17/05/19 08:22	Reinspection Photo		☒
137	17/05/19 08:22	Reinspection Photo		☒
138	17/05/19 08:22	Reinspection Photo		☒
139	17/05/19 08:22	Reinspection Photo		☒
140	17/05/19 08:22	Reinspection Photo		☒
141	17/05/19 08:22	Reinspection Photo		☒
142	17/05/19 08:22	Reinspection Photo		☒
143	17/05/19 08:22	Reinspection Photo		☒
144	17/05/19 08:22	Reinspection Photo		☒
145	17/05/19 08:22	Reinspection Photo		☒
146	17/05/19 08:22	Reinspection Photo		☒
147	17/05/19 08:22	Reinspection Photo		☒
148	17/05/19 08:22	Reinspection Photo		☒
149	17/05/19 08:22	Reinspection Photo		☒
150	17/05/19 08:22	Reinspection Photo		☒
151	17/05/19 08:22	Reinspection Photo		☒
152	17/05/19 08:22	Reinspection Photo		☒
153	17/05/19 08:22	Reinspection Photo		☒
154	17/05/19 08:22	Reinspection Photo		☒
155	17/05/19 08:22	Reinspection Photo		☒
156	17/05/19 08:22	Reinspection Photo		☒
157	17/05/19 08:22	Reinspection Photo		☒
158	17/05/19 08:22	Reinspection Photo		☒
159	17/05/19 08:22	Reinspection Photo		☒
160	17/05/19 08:22	Reinspection Photo		☒
161	17/05/19 08:22	Reinspection Photo		☒
162	17/05/19 08:22	Reinspection Photo		☒
163	17/05/19 08:22	Reinspection Photo		☒
164	17/05/19 08:22	Reinspection Photo		☒
165	17/05/19 08:22	Reinspection Photo		☒
166	17/05/19 08:22	Reinspection Photo		☒
167	17/05/19 08:22	Reinspection Photo		☒
168	17/05/19 08:22	Reinspection Photo		☒
Documentation			1 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	04/07/18 18:56	TP ESTIMATE		☐
2	04/07/18 19:03	TP GIA REPORT- 1		☐
3	04/07/18 19:03	TP GIA REPORT-2		☐
4	10/07/18 12:07	TP ESTIMATE - MARKED		☐
5	17/07/19 11:51	LTA SEARCH RECEIPT		☐
6	17/07/19 11:54	TP TAX INVOICE		☐
7	24/07/19 18:20	AUTHORISATION TO ACT		☐

Letters/Correspondences			1 per page ▼	✓
No	Finalized On			
8	24/07/19 18:20	LKK Auto Consultants Pte Ltd (HQ)		
		LETTER TO OI		Thumbnail Print
9	24/07/19 18:20	RELEASE VOUCHER		Load PDF
				Load PDF
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		
1	05/07/18 09:12	OI GIA REPORT		Thumbnail Print
				Load PDF

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLH4560P (Insd veh)	Model:	BMW 730LI 2.0 LED NAV HUD
	SLH3200K (TP veh)		SR (A)
Date of Accident:	28/06/2018		

Global Sum Settlement	:	[]	Yes	[X]	No
Repair Estimate	:	\$			37,273.13
Final Repair Cost	:	\$			30,219.42
Loss of Use	:	\$			1,500.00
Rental (if any)	:	\$			15.00 days at \$100.00 per day
LTA / GIA Search Fee	:	\$			7.45
Others:	:	\$			
	:	\$			
Final Settlement Sum	:	\$			31,726.87
Is Third Party Workshop GIA Registered? [X] YES [] NO (Kindly indicate below)					
A) For <u>Non GIA Registered Workshop</u> :			Agreed Liability _____ (%)		
B) For <u>GIA Registered Workshop</u> :			BOLA Applicable: Yes/ No BOLA Scenario No: <u>28</u>		
BOLA Liability: <u>100</u> (%)			Assessed Liability (*): <u>0</u> (%)		
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.					
Remarks _____					

Payment Instruction: Payee's Breakdown			
1)	Performance Motors Limited	:	\$ 30,226.87
2)	SIME DARBY SERVICES PRIVATE LIMITED	:	\$ 1,500.00
3)		:	\$
4)		:	\$

NUR SHAQILAH BTE ABDOL WAHAB

LKK Auto Consultants Pte Ltd

24 Jul
2019

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/LCR18012221/R1HA3S2
Date: 24/07/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994823
Claimant Vehicle No: SLH3200K Insured Vehicle No: SLH4560P
Date of Loss: 28/06/2018 Nature of Claim: TP Claim No: 9062452473SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLH3200K
Make & Model: BMW 730LI, 2.0 LED NAV HUD SR (A) Engine No: 26359649B48B20B
Reg. Date: 31/10/2016 (Man. Year: 2016) Chassis No: WBA7E020X0G245194
Colour: White Odometer: 25112 km
Engine Capacity: 1998 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/50R18 Rear Tyre Size: 245/50R18
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	20,745.70	14,923.45	5,822.25	28.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	14,089.00	13,319.00	770.00	5.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	34,834.70	28,242.45	6,592.25	18.92
+ GST 7.00/7.00% (S\$)	2,438.43	1,976.97	461.46	18.92
Nett Amount (S\$)	37,273.13	30,219.42	7,053.71	18.92
+ Loss of Use (15.0 x S\$100.00/day) (S\$)		1,500.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		31,726.87		

INSPECTION

Date of Assignment: 05/07/2018
Date Inspected: 05/07/2018 Inspected At: Performance Motors Limited (Alexandra)
303 Alexandra Road, Sime Darby Performance Centre
Singapore 159941
Estimated Period of Repair: 11.0 days

Adjuster: MOHD RASUL

Manager: VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*CLAMPING BUSH	Necessary	66.80 FS	*66.80 FS
2	1		*REAR SILENCER WITH EXHAUST FLAP	Bent	1,777.60 FS	*1,777.60 FS
3	1		*COMPLETE TAIL PANEL	Buckled	1,026.90 FS	*1,026.90 FS
4	1		*TRUNK LID LH HINGE	Not Necessary	182.60 FS	*- FS
5	1		*TRUNK LID RH HINGE	Not Necessary	182.60 FS	*- FS
6	1		*TAILGATE ALUMINIUM	Bent	2,107.20 FS	*2,107.20 FS
7	1		*OUTER PANEL TAIL TRIM	Not Necessary	718.85 FS	*- FS
8	1		*REAR BUMPER ADAPTER	Deformed	77.65 FS	*77.65 FS
9	1		*REAR BUMPER CARRIER	Bent	898.50 FS	*898.50 FS
10	1		*REAR BUMPER CENTRE GUIDE	Deformed	51.50 FS	*51.50 FS
11	1		*REAR LH MOUNT LATERAL	Not Necessary	142.55 FS	*- FS
12	1		*REAR RH MOUNT LATERAL	Not Necessary	142.55 FS	*- FS
13	1		*LH TRIM EXHAUST TAILPIPE	Bent	247.20 FS	*247.20 FS
14	1		*RH TRIM EXHAUST TAILPIPE	Bent	247.20 FS	*247.20 FS
15	1		*REAR LH MOULDING ROCKER PANEL	Necessary	51.50 FS	*51.50 FS
16	1		*REAR RH MOULDING ROCKER PANEL	Necessary	51.50 FS	*51.50 FS
17	1		*TRIM REAR PRIMED	Deformed	216.45 FS	*216.45 FS
18	1		*REAR BUMPER PANEL PRIMED (PDC)	Deformed	1,586.85 FS	*1,586.85 FS
19	1		*REAR BUMPER TOWING EYE COVER PRIMED	Missing	55.70 FS	*55.70 FS
20	1		*LEFT PROTECTION FOIL	Not Necessary	11.30 FS	*- FS
21	1		*RIGHT PROTECTION FOIL	Not Necessary	11.30 FS	*- FS
22	1		*GRIP TRUNK LID (RFK)	Not Necessary	201.85 FS	*- FS
23	1		*GRIP TRUNK LID (RFK)	Not Necessary	201.85 FS	*- FS
24	1		*HOLDER CAMERA	Not Necessary	9.75 FS	*- FS
25	1		*BOOTLID CHROME TRIM STRIP	Not Necessary	176.10 FS	*- FS
26	1		*LETTERING 730LI	Necessary	62.55 FS	*62.55 FS
27	1		*REAR PLAQUE 82MM	Necessary	69.50 FS	*69.50 FS
28	1		*TENSION SPRING	Not Necessary	68.80 FS	*- FS
29	1		*SPINDLE DRIVE RH	Not Necessary	467.40 FS	*- FS
30	1		*TRIM TAILGATE BOTTOM PRIMED	Deformed	233.45 FS	*233.45 FS
31	1		*WARNING SIGN	Not Necessary	38.00 FS	*- FS
32	1		*LOADING SILL COVER	Not Necessary	132.70 FS	*- FS
33	1		*FLOOR CARPET LUGGAGE COMPARTMENT	Not Necessary	553.60 FS	*- FS
34	1		*SCHLAUFE LOOP	Not Necessary	19.65 FS	*- FS
35	1		*PARTITION, LUGGAGE, COMPARTMENT	Not Necessary	243.15 FS	*- FS
36	1		*TRUNK LID GASKET (RFK)	Necessary	100.60 FS	*100.60 FS
37	1		*BOOT TRIM RAIL	Not Necessary	111.40 FS	*- FS
38	1		*REAR RH LIGHT IN TRUNK LID	Cracked	473.65 FS	*473.65 FS
39	1		*REAR LH LIGHT IN THE SIDE PANEL	Not Necessary	735.95 FS	*- FS
40	1		*REAR RH LIGHT IN THE SIDE PANEL	Broken	735.95 FS	*735.95 FS
41	4		*DECOUPING RING PDC TORQUE CONVERTER	Not Necessary	20.20 FS	*- FS
42	2		*ULTRASONIC SENSOR ALPINWEISS (U300)	Not Necessary	761.30 FS	*- FS
43	1		*REVERSING CAMERA	Not Necessary	681.10 FS	*- FS
44	1		*BLIND RIVET AVIBVLB	Necessary 30pcs Only	24.20 FS	*16.50 FS
		44pcs				
45	10		*SCREW (SF PLUS M5X5)	Necessary	5.50 FS	*5.50 FS
46	1		*(DG/SL) BODY ADHESIVE K5B (195ML)	Necessary	281.55 FS	*281.55 FS
47	1		*(DG) CLEANER R1 (100ML)	Necessary	23.85 FS	*23.85 FS
48	1		*PUNCH RIVET N4	Necessary	16.50 FS	*16.50 FS
		30pcs				
49	1		*(S/L) SEAM SEAL 300ML	Necessary	33.80 FS	*33.80 FS
50	1		*REAR EMBOSS NUMBER PLATE	Scratched	83.00 FS	*83.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
51	1		*SUNDRIES	Necessary	150.00 FS	*150.00 FS
52	1		*SEALING STRIP	Necessary	2.90 FS	*2.90 FS
53	1		*SEALING STRIP	Necessary	2.90 FS	*2.90 FS
54	1		*CLAMPING BUSH	Necessary	66.80 FS	*66.80 FS
55	1		*FRONT SILENCER	Bent	1,681.40 FS	*1,681.40 FS
56	1		*INTERMEDIATE PIPE	Bent	563.40 FS	*563.40 FS
57	1		*RH TOP SIDE MEMBER EXTENSION	Cracked	58.65 FS	*58.65 FS
58	1		*RR TRUNK FLOOR CROSS MEMBER	Bent	120.75 FS	*120.75 FS
59	1		*REAR LUGGAGE COMPARTMENT FLOOR	Bent	275.90 FS	*275.90 FS
60	1		*FOAM SEAL	Necessary	2.70 FS	*2.70 FS
61	2		*GASKET	Necessary	10.50 FS	*10.50 FS
62	4		*CLIP (WEISS)	Necessary	5.00 FS	*5.00 FS
63	2		*CLIP (WEISS)	Necessary	2.50 FS	*2.50 FS
64	1		*REAR SILENCER HEAT INSULATOR	Bent	130.15 FS	*130.15 FS
65	1		*REAR SILENCER HEAT INSULATOR FRT	Bent	111.50 FS	*111.50 FS
66	1		*REAR SILENCER RH HEAT INSULATOR	Bent	130.15 FS	*130.15 FS
67	1		*REAR RH WATER GUTTER COVER	Cut	23.05 FS	*23.05 FS
68	1		*REAR DIFFUSER	Cracked	139.75 FS	*139.75 FS
69	1		*(S/L) GUTTER STRIP	Cut	111.40 FS	*111.40 FS
70	10		*PLUG BLACK D=5MM	Necessary	9.00 FS	*9.00 FS
71	1		*SENSOR WIRE FOR SMART OPENER TOP	Cut	42.10 FS	*42.10 FS
72	1		*SENSOR WIRE FOR SMART OPENER BOTTOM	Cut	40.50 FS	*40.50 FS
73	1		*CONTROL UNIT SMART OPENER	Necessary	468.85 FS	*468.85 FS
74	9		*EXPANDING NUT	Necessary	4.95 FS	*4.95 FS
75	1		*EXPANDING NUT	Necessary	0.55 FS	*0.55 FS
76	1		*RR RH REAR REFLECTOR	Necessary	36.25 FS	*36.25 FS
77	5		*(S/L) RUBBER BUFFER	Necessary	9.85 FS	*9.85 FS
78	1		*RH WATER CHANNEL	Necessary	37.95 FS	*37.95 FS
79	1		*REAR RH MOULDING	Necessary	74.10 FS	*74.10 FS
80	20		*BLIND RIVET AVIBVLB	Necessary	11.00 FS	*11.00 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	20,745.70	14,923.45
--------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE REAR BUMPER, REAR TAIL END PANEL, BOOT, REINFORCEMENT & ALL ATTACHMENT CAUSE BY THE ACCIDENT.	New	5,100.00	5,100.00
2	PAINTING ON REAR BUMPER, BOO, END PANEL & TRUNK FLOOR.	New	3,350.00	3,015.00
3	TO REPLACE REAR EXHAUST SILENCER INCLUDING ALIGNMENT SYSTEM AND CONDUCT CHECKS FOR LEAK.	New	531.00	451.00
4	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION.	New	177.00	0.00
5	TO TRANSFER LOCK MECHANISM FROM OLD TO NEW BOOTLID INCLUDING CONDCUT CHECKS ON NEW BOOTLID CENTRAL LOCKING SYSTEM FOR PROPER FUNCTION.	New	531.00	451.00
6	TO CARRY OUT BODY CAVITY PRESERVATION. (PER PANEL)	New	118.00	100.00
7	TO CARRY OUT BODY CAVITY PRESERVATION. (FOR CUT PANEL)	New	531.00	451.00
8	TO REPLACE BOOT LID SMART CORNER CONTROL UNIT AND TOP AND BOTTOM SENSOR LINE INCLUDE PROGRAMMING AND CONDUCTING CHECKS FOR PROPER FUNCTION.	New	562.00	562.00
9	TO MOUNT VEHICLE ON CELETTE BENCH TO FACILITATE RE-ALIGNMENT OF BODY / CHASSIS IN ACCORDANCE WITH BMW SPECIFICATION.	New	2,508.00	2,508.00
10	TO REMOVE AND INSTALL BOOT COMPARTMENT CARPETS AND GARNISH TO FACILITATE REPAIRS.	New	230.00	230.00
11	TO REMOVE & INSTALL ELECTRICAL WIRING CONTROL UNITS & BATTERY AT THE REAR SECTION TO FACILITATE REPAIRS.	New	451.00	451.00
Gross Labour Cost (S\$)			14,089.00	13,319.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >