

ASS. REC. BY:

REP:

CS/MSG/18012254/Krd3

n2

Special Instruction:

Survivor
meimen

Kenneth

ASSIGNMENT (Office)

From (Person):

Katherine Wong

of

MSG

Date/Time:

5/7/18 @ 10:39am

Estimated Cost:

Bill to:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLX 4637T

Insured:

8KQ 7583T

at Workshop no/:

Wei Lee Motor

Tel:

6456 9830

of

8KQ, Sin Ming Ind. Est # 01-32

Policy No:

A28866182 QMX

Claim No:

559602

Sum Insured:

Excess:

Make of Vch:

(Client's Record)

D.O.A. 26/05/2018

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

10:10pm @ 5/7/18

Person Contacted:

Karen

Vehicle ☒ IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SLX 4637T-x 5/7/18. Karen say she call Kenneth directly now

8KQ 7583T-x

Report from meimen

Confirmed with Karen \$600, 2-days (Est: \$1103.68, 65%.)

ASS. REC. BY:

REF: MSG /

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s Wei Lu

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 02 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SIX 46377 Tr Regn: 10,08Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or _____

Make: Honda Fit C.C. 1339Colour: M-Blue A/C: Insured / Std / Nil / NASp. Reading 217630 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: GEB 1108555Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orMod: Nil / SR / STD A/Rim orTyre Size: Precision 195/55R15R: Ediker

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

R/Bal. 4 mm RearL/Bal. 4 mm R/Bal. 9 mmD.O.A. 26/5/18 L/Bal. 9 mmD.O.I. 5/7/18

Survey held at _____

Des. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop orCLS Frnt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

6/7 File pass to Catherine
& Good

RECEIVED 8-1 AUG 2018

Date/Time, File Pass to?

1) typist

Date/Time, File Return to?

2) _____

☐ : Prel. Report☒ : Final ReportDays Of Repair: 2Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

\$ + RS. \$

Fees

Others

TOTAL

150

10

160

Report Format: TPLump Sum / I.B.I. (\$ 600)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 May 2018		05 Jul 2018 10:39 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	WONG KAH HENG, ID: S1135453Z, Tel: +6597960387, Email: NOEMAIL		
Main Claimant:	KH LEASING PTE. LTD., Co. Reg. No.: 201611813C		
Vehicle Reg. No.:	SLX4637T	Date of Loss:	26/05/2018 11:00 - :59 [114 Months and 26 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 559602	Policy/Cover Note No.:	A28866182QMX (Comprehensive) Coverage: 24/12/2017 - 23/12/2018
Vehicle Reg. No. (Insured):	SKQ7583T	Policy No. (Claimant):	
		Excess:	S\$500.00
Repairer:	Wei Lee Motor Works (HQ) BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32, 575644 Sin Ming - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 06/07/2018]		
Driver/Custodian (Insured):	WONG KAH HENG (62 / Male), NRIC: S1135453Z, Tel: +6597960387		
Adj Asg. Remarks:	ON WP. Car in at 1pm to 2.30pm, Liability 100% - Contact Person: Karen Seah: 6456 9830		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18012254/Krd3

16 RAFFLES QUAY

#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 05-07-2018



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKQ 7583T	Veh. Inspected	SLX 4637T
Policy No.	A28866182QMX	Coverage (\$)	0.00
Claim No.	559602	Excess (\$)	0.00
Assign From	MERIMEN (KATHERINE WONG)	Assign Date	05/07/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	26/05/2018	Inspection Date
Survey held at	WEI LEE MOTOR WORKS BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32 SINGAPORE 575644.	

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Katherine Wong Chew Shong

Date: 06 Jul 2018

Preliminary Advice

Insured Vehicle No	: SKQ7583T	Accident Date	: 26/05/2018
TP Vehicle No	: SLX4637T	Assignment Date	: 05/07/2018
Make	: HONDA FIT	Est. Duration of Repair	: 2.00
Date of Inspection	: 05/07/2018		
Inspection At	: WEI LEE MOTOR WORKS (HQ) BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32 SINGAPORE 575644		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	1,703.68
Revised Amount	:S\$	600.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	600.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

威利摩哆 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,
SINGAPORE 575644.
TEL: 6456 9830 • FAX: 6458 0128 • EMAIL: weileemotorworks@gmail.com
Business Regn No: 269436/00J

*Not Withheld
Resurvey After Paint
2 days*

03, July 2018

MSIG Insurance (S) PL
4 Shenton Way #21-01 SGX Centre 2
S 068807

Attn: Motor claim dept-3rd party claim
Claiming against your insured vehicle No: SKQ7583T
Accident involving vehicle No: SLX4637T/SKQ7583T
DOA: 26/05/2018 AT PIE Twds Sims Ave

Dear officer incharge
Re: Estimate cost of repair for vehicle No: SLX4637T
To supply--

Description	Qty	Amount
Front fender, Rh	1	266.20
Front bumper	1	523.50
Front bumper retainer, Rh	1	27.40
	Parts	817.10
	Parts less 20%	163.42
		653.68

To remove damaged parts and attachments.
Repair/reshape dented areas.
Replace/align above parts into position.
To spray paint.

550.00 *2001*
500.00 *4001*
1703.68

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18012254/KRD3N2

Date: 01/08/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A28866182QMX
Claimant Vehicle No :	SLX4637T	Insured Vehicle No :	SKQ7583T
Date of Loss:	26/05/2018	Nature of Claim:	TP
		Claim No:	559602

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLX4637T	Engine No:	L13A4116223
Make & Model:	HONDA FIT, 1.3 G (A)	Chassis No:	GE61104555
Reg. Date:	31/10/2008 (Man. Year: 2008)	Odometer:	217630 km
Colour:	Metallic Blue		
Engine Capacity:	1339 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/55R15	Rear Tyre Size:	195/55R15
Front Left Side:	Roadstone 4 mm	Rear Left Side:	Falken 9 mm
Front Right Side:	Roadstone 4 mm	Rear Right Side:	Falken 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	653.68	0.00	653.68	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,050.00	600.00	450.00	42.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	1,703.68	600.00	1,103.68	64.78

INSPECTION

Date of Assignment:	05/07/2018	
Date Inspected:	05/07/2018 Inspected At:	Wei Lee Motor Works (HQ) BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32 Singapore 575644

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 01 Aug 2018)
Parts: 144	HONDA FIT 1.3 G (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLX4637T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER,RH	Repair	266.20 FL	*- FL
2	1		*FRONT BUMPER	Repair	523.50 FL	*- FL
3	1		*FRONT BUMPER RETAINER,RH	Serviceable	27.40 FL	*- FL
				Sub Total (S\$)	817.10	0.00
				- List Item Discount on L Items 20.00/20.00% (S\$)	163.42	0.00
				Total Parts (S\$)	653.68	0.00

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE DAMAGED PARTS AND ATTACHMENTS.REPAIR/RESHAPE DENTED AREAS.REPLACE/ALIGN ABOVE PARTS INTO POSITION	New	550.00	200.00
2	TO SPRAY PAINT	New	500.00	400.00
Gross Labour Cost (S\$)			1,050.00	600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >