

ASS. REC. BY:

REF:

CS/EGJ18012280/Ktd3n2

Special Instruction:

Surveyor:

Kenneth

ASSIGNMENT (Office)

From (Person):

Yee Pei Li

of

FGI

Date/Time:

5/7/18 @ 11:11am

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHD 271 T

Insured:

XE 3301 B

at Workshop m/s:

Trans cab

Tel:

6287 6666

of

NO. 2 AMK st-63

Policy No:

Claim No:

XE 3301 B / RH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

04/07/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

'up'

H.O.D. Endorsement:

Date/Time:

11:17am @ 5/7/18

Person Contacted:

Candy

Vehicle:

IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SHD 271 T - X
	XE 3301 B - X

(08/11/13) wef

REF: EGI

ASS. REC. BY:

ASSIGNMENT

From: Date: 05/07/18

Estimated Cost:

On (TP) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SHD271T

at Workshop m/s Trans-cab

of No. 2 AMK St. 63

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR. Seen: Consistent? : Yes or No

Est. Repairs: 03 days Res.: Yes or No

Lum Sum: 1.8.1% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS up

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SHD 271T Yr Regn: 02 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Renault Latitude c.c. 1995

Colour: White / Red A/C: Insured / Std / NI / NA

Sp. Reading: 28195, T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: VF1AB215AUC 282420

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: M / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 8 mm

L/Bal. 8 mm

D.O.A. 4/7/18

Rear

R/Bal. 8 mm

L/Bal. 8 mm

D.O.I. 5/7/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Frt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

6/7 File pass to Carsten
8 8594.30 (Red. 35454.45; 80%)

RECEIVED 19 JUL 2018

Date/Time, File Pass to?

11/9/17 Typist

Date/Time, File Return to?

2)

Report Format: TP

Lump Sum / (B.): (\$ 8594.30)

☐ Preli. Report☒ Final Report

Days Of Repair: 3

Resurvey No. of Trip: -

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

350



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ERGO INSURANCE PTE LTD

Ref : CS/EGI18012280/Ktd3

5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
SINGAPORE 038985

Date : 05-07-2018



Code : EGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	XE 3301B	Veh. Inspected	SHD 271T
Policy No.		Coverage (\$)	0.00
Claim No.	XE3301B/RH	Excess (\$)	0.00
Assign From	YEE PEI LI	Assign Date	05/07/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	04/07/2018	Inspection Date	05/07/2018
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Nivitha (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Thursday, 5 July 2018 11:11 AM
To: 'admin-d@lkkauto.com'
Cc: 'ASSIGNMENTS@LKKAUTO.COM'
Subject: OI : XE3301B / TP : SHD271T/LKK / DOA : 04/07/2018
Attachments: SHD271T - ESTIMATE n SAS.pdf

Dear Catherine/Nivitha,

Please assist to conduct these surveys:-

NO	VEH TO BE SURVEY	W/SHOP NAME	PERSON TO CONTACT	OUR REF	OIC	REMARKS
1	SHD 271T	TRANS-CAB SERVICES PTE LTD @ 2 ANG MO KIO STREET 63	CANDY KONG @ 6287 6666	XE3301B/RH	ROHAINI	DOA: 04/07/2018 WP

Note: To survey on without prejudice basis. Please note that our insured/insured driver has yet to e-file their SAS for this accident. Please advise the consistency of damages to third party vehicle and inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop

Attached are estimate and TP's SAS (note: reports not to be released to any Third Party).

Kindly update of the survey status via Survey.Report@ergo.com.sg.

Kindly acknowledge receipt.

Regards,
Yee Pei Li
Claims Assistant (Motor)

ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-01 Suntec Tower Five
Singapore 038985
DID : +65 6829 9194
Tel : +65 6829 9199
Fax : +65 6829 9247
peili.yee@ergo.com.sg

ERGO

www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: XE3301B/RH
Our Ref: CS/EGI18012280/Kld3

Date: 19/7/2018

The Motor Claims Department
ERGO INSURANCE PTE LTD

Dear Sirs/Mdm


PRELIMINARY ADVICE OF VEHICLE NO. SHD 271T

Please be informed that we had conducted the inspection of the above-mentioned vehicle on 5/7/2018 at the premises of M/s Trans Cab and have the following to report:

Workshop Estimate Amount	: S\$ 44,048.75
Revised Estimate Amount	: S\$ 8,594.30
"Check" Items Amount	: S\$ -
Market Value	: S\$ -
LTA Reimbursement Value	: S\$ -
Nett Value	: S\$ -

Description of Damage:

The vehicle sustained damages
At o/s front portion.



Repair days: 3 Days

Comments/ Present Status:

Damages Consistent.

Yours faithfully
Kenneth
Automotive Assessor

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Thursday, 19 July 2018 9:40 AM
To: Admin-D (LKKAUTO); 'Survey Report (ERGO Insurance Pte. Ltd.); assignments
Cc: SUR
Subject: RE: XE3301B / TP : SHD271T/LKK / DOA : 04/07/2018
Attachments: PRELI ADVISED SHD 271T.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SHD 271T**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Thursday, 5 July 2018 11:25 AM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: XE3301B / TP : SHD271T/LKK / DOA : 04/07/2018

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Survey Report (ERGO Insurance Pte. Ltd.) [<mailto:Survey.Report@ergo.com.sg>]
Sent: Thursday, 5 July 2018 11:11 AM
To: 'admin-d@lkkauto.com' <admin-d@lkkauto.com>
Cc: 'ASSIGNMENTS@LKKAUTO.COM' <ASSIGNMENTS@LKKAUTO.COM>
Subject: OI : XE3301B / TP : SHD271T/LKK / DOA : 04/07/2018

Dear Catherine/Nivitha,

Please assist to conduct these surveys:-

NO	VEH TO BE SURVEY	W/SHOP NAME	PERSON TO CONTACT	OUR REF	OIC	REMARKS
----	---------------------	-------------	-------------------	---------	-----	---------

[-> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Company

Owner ID: 3878K

Vehicle Details

Vehicle No.: SHD271T

Vehicle to be Exported: Yes

Intended De-registration Date: 04 Jul 2018

Vehicle Make: RENAULT

Vehicle Model: LATITUDE 2.0L DCI AUTO D/AB 4DR

Primary Colour: Red

Manufacturing Year: 2015

Engine No.: M9R8839C002920

Chassis No.: VF1ABL15AUC282420

Maximum Power Output: 127.0 kW (170 bhp)

Open Market Value: \$19,998.00

Original Registration Date: 04 Feb 2016

First Registration Date: 04 Feb 2016

Transfer Count: 0

Actual ARF Paid: \$19,998.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 03 Feb 2024

PARF Rebate Amount: \$14,998.00

Intended COE Rebate Details

COE Expiry Date: 03 Feb 2024

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 8

PQP Paid: \$43,040.00

COE Rebate Amount: \$30,026.00

Total Rebate Amount: \$45,024.00**Message**

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 04 Jul 2018

OK

Trans-cab Auto Services Pte Ltd

AAD1807-035

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 271T

Not Notified
Penalty B4 part 88594.30

Vehicle No.:

SHD 271T

Chassis No.:

VF1ABL15AUC282420

Vehicle Make:

RENAULT

Vehicle Model:

LATITUDE

Date of Accident :

4.7.2018

Third Party Insurer :

ERGO

PART		LIST	
1	BUMPER COVER FRT	\$	CM 1,259.42 ✓
1	BUMPER SPOILER FRT	\$	CM 181.75 ✓
1	BUMPER ABSORBER FRT	\$	CM 394.68 ✓
1	BUMPER RETAINER FRT RH	\$	CM 150.77 ✓
1	BUMPER SUPPORT FRT	\$	D.I 123.88 ✓
1	BUMPER UNDERTRAY FRT	\$	SL 472.83 X
1	BUMPER GRILLE LOWER FRT	\$	CM 266.80 ✓
1	BUMPER FOG LAMP GRILLE RH	\$	SL 207.21 X
1	BUMPER BEAM FRT	\$	R 914.08 X
1	HEADLAMP RH	\$	MJCM 1,184.43 ✓
1	HEADLAMP PANEL FRT RH	\$	R 152.15 X
1	FENDER PANEL FRT RH	\$	B 783.83 ✓
1	WHEELARCH FRT RH	\$	CM 278.84 ✓
1	FENDER BRACKET LOWER RH	\$	Di 15.79 ✓
1	FENDER INSULATOR RH	\$	SL 130.84 X
1	DOOR PANEL FRT RH	\$	R 2,844.66 X
1	RADIATOR GRILLE	\$	MJCM 1,707.78 ✓
1	RADIATOR GRILLE BADGE 'RENAULT'	\$	CM 225.36 ✓
1	RADIATOR GRILLE FRAME	\$	CPA 1,353.75 ✓
1	RADIATOR FAN COWLING	\$	SL 820.54
1	RADIATOR FAN MOTOR LH	\$	SL 967.36
1	RADIATOR FAN MOTOR RH	\$	SL 1,479.46
1	FRAME FULL SUPPORT PANEL	\$	SL 615.90
1	FRAME FULL SUPPORT BRACKET	\$	R 89.79
1	DOOR MIRROR ASSY RH	\$	SL 1,483.40
1	DOOR PANEL FRT RH	\$	R 2,844.66
1	BONNET	\$	R 1,941.63
1	BONNET INSULATOR	\$	SL 405.73
1	BONNET STRUT LH	\$	SL 88.61
1	BONNET STRUT RH	\$	SL 88.61

Trans-cab Auto Services Pte Ltd**AAD1807-035**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 271T

1	BONNET HINGE LH	\$	348.31	}	X
1	BONNET HINGE RH	\$	348.31		
1	BONNET LOCK	\$	305.48		
1	BONNET CABLE	\$	119.19		
1	BONNET CABLE COVER	\$	161.03		
1	BONNET SEAL OUTER	\$	92.36		
1	BONNET SEAL INNER	\$	157.28		
1	SUBFRAME OUTER FRT	\$	2,652.45		
1	SUBFRAME BRACKET OUTER LH	\$	92.36		
1	SUBFRAME BRACKET OUTER RH	\$	92.36		
1	ENGINE UNDERTRAY	\$	564.98		
1	A/C CONDENSER	\$	2,020.37		
1	A/C CONDENSER GARNISH LH UPPER	\$	39.67		
1	A/C CONDENSER GARNISH RH UPPER	\$	39.67		
1	A/C CONDENSER GARNISH LH	\$	58.81		
1	A/C CONDENSER GARNISH RH	\$	59.60		
1	LOWER ARM RH	\$	685.76		
1	KUNCKLE ARM RH	\$	846.98		
1	ABSORBER FRT RH	\$	360.54		
1	STABILIZER BAR FRT	\$	604.65		
1	DRIVESHAFT RH	\$	1,747.45		
1	WIPER RESERVOIR	\$	348.25	✓	X
1	WIPER RESERVOIR NECK	\$	136.11		
1	WIPER RESERVOIR MOTOR	\$	270.06		

TOTAL	\$	35,626.53	57
10%	\$	3,562.65	
	\$	32,063.87	

Special Nett

1SET	BUMPER CLIP FRT	\$	66.00	✓
1	BUMPER BRACKET CLIP FRT RH	\$	12.00	X
1	BUMPER SUPPORT CLIP FRT RH	\$	10.50	λ
1SET	BUMPER GRILLE LOWER CLIP	\$	69.00	X
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	70.00	λ
2	FRAME FULL SUPPORT PANEL NUT	\$	20.00	X
2	FRAME FULL SUPPORT PANEL STUD	\$	30.00	X

Trans-cab Auto Services Pte Ltd**AAD1807-035**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 271T

1SET	WHEELARCH CLIP FRT RH	\$	30.50	✓
6	BONNET INSULATOR CLIP L70Y	\$	7.30	} X
2	BONNET STRUT L70Y	\$	88.61	
2	BONNET CABLE CLIP L70Y	\$	6.31	
2	BONNET CABLE COVER SCREW L70Y	\$	10.85	
1	WINDSCREEN SEALANT	\$	253.80	
1	FRONT WINDSCREEN MOULDING	\$	120.00	
1	FRONT WINDSCREEN INNER SPONGE SEAL	\$	100.00	

TOTAL	\$	894.88
--------------	-----------	---------------

TOTAL PARTS	\$	32,958.75
--------------------	-----------	------------------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	4,500.00	5 4000
Putty and spray painting of the affected portion.	\$	4,000.00	4000
To rust-proofing of the affected areas.	\$	170.00	300
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	X
To check steering geometry and computer wheel alignment	\$	220.00	600
To transfer of tire, rim and on wheel balancing.	\$	170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	200
To transfer of front fender fittings, attachment and perform water seepage test.	\$	380.00	X
To transfer of bonnet fittings, attachment and perform water seepage test.	\$	380.00	X

Trans-cab Auto Services Pte Ltd**AAD1807-035**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 271T

To vacuum, replace, refix and recharge air condenser	\$	380.00 X
To replace, refix and top up coolant for radiator	\$	170.00 X
To vacuum, replace, refix and recharge Air Intercooler	\$	170.00 X
To transfer of front windscreen fittings and conduct water seepage test	\$	170.00 X

TOTAL \$ 11,090.00**Over All Total \$ 44,048.75****PART-BY-PART (REPAIR DAY)****15 DAYS***3 days**44218.78*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD		Ref : CS/EGI18012280/Ktd3n2		
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 20-07-2018		
		Code : EGI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	XE 3301B	Veh. Inspected	SHD 271T	
Policy No.		Coverage (\$)	0.00	
Claim No.	XE3301B/RH	Excess (\$)	0.00	
Assign From	YEE PEI LI	Assign Date	05/07/2018	
2. Vehicle Particulars & Condition				
Make & Model	RENAULT LATITUDE (A)	c.c	1995	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	VF1ABL15AUC282420	Colour	WHITE / RED	
Odometer	281951	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	GITI	8 mm	
L/H Front Tyre	215/60 R16	GITI	8 mm	
R/H Rear Tyre	215/60 R16	GITI	8 mm	
L/H Rear Tyre	215/60 R16	GITI	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	04/07/2018	Inspection Date	05/07/2018	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 271T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BUMPER COVER FRT	CRACKED	1,259.42	1,259.42
1	BUMPER SPOILER FRT	CRACKED	181.75	181.75
1	BUMPER ABSORBER FRT	CRACKED	394.68	394.68
1	BUMPER RETAINER FRT RH	CRACKED	150.77	150.77
1	BUMPER SUPPORT FRT	DISTORTED	123.88	123.88
1	BUMPER UNDERTRAY FRT	SERVICEABLE	472.83	-
1	BUMPER GRILLE LOWER FRT	CRACKED	266.80	266.80
1	BUMPER FOG LAMP GRILLE RH	SERVICEABLE	207.21	-
1	BUMPER BEAM FRT	TO REPAIR SEE LABOUR	914.08	-
1	HEADLAMP RH	MTG CRACKED	1,184.43	1,184.43
1	HEADLAMP PANEL FRT RH	TO REPAIR SEE LABOUR	152.15	-
1	FENDER PANEL FRT RH	BENT	783.83	783.83
1	WHEELARCH FRT RH	CRACKED	278.84	278.84
1	FENDER BRACKET LOWER RH	DISTORTED	15.79	15.79
1	FENDER INSULATOR RH	SERVICEABLE	130.84	-
1	DOOR PANEL FRT RH	TO REPAIR SEE LABOUR	2,844.66	-
1	RADIATOR GRILLE	MTG CRACKED	1,707.78	1,707.78
1	RADIATOR GRILLE BADGE "RENAULT"	NECESSARY	225.36	225.36
1	RADIATOR GRILLE FRAME	CRACKED	1,353.75	1,353.75
1	RADIATOR FAN COWLING	SERVICEABLE	820.54	-
1	RADIATOR FAN MOTOR LH	SERVICEABLE	967.36	-
1	RADIATOR FAN MOTOR RH	SERVICEABLE	1,479.46	-
1	FRAME FULL SUPPORT PANEL	SERVICEABLE	615.90	-
1	FRAME FULL SUPPORT BRACKET	TO REPAIR SEE LABOUR	89.79	-
1	DOOR MIRROR ASSY RH	SERVICEABLE	1,483.40	-
1	DOOR PANEL FRT RH	TO REPAIR SEE LABOUR	2,844.66	-
1	BONNET	TO REPAIR SEE LABOUR	1,941.63	-

Report Ref No. CS/EGI18012280/Ktd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BONNET INSULATOR	SERVICEABLE	405.73	-
1	BONNET STRUT LH	SERVICEABLE	88.61	-
1	BONNET STRUT RH	SERVICEABLE	88.61	-
1	BONNET HINGE LH	TO REPAIR SEE LABOUR	348.31	-
1	BONNET HINGE RH	TO REPAIR SEE LABOUR	348.31	-
1	BONNET LOCK	TO REPAIR SEE LABOUR	305.48	-
1	BONNET CABLE	SERVICEABLE	119.19	-
1	BONNET CABLE COVER	SERVICEABLE	161.03	-
1	BONNET SEAL OUTER	SERVICEABLE	92.36	-
1	BONNET SEAL INNER	SERVICEABLE	157.28	-
1	SUBFRAME OUTER FRT	SERVICEABLE	2,652.45	-
1	SUBFRAME BRACKET OUTER LH	SERVICEABLE	92.36	-
1	SUBFRAME BRACKET OUTER RH	SERVICEABLE	92.36	-
1	ENGINE UNDERTRAY	SERVICEABLE	564.98	-
1	A/C CONDENSER	SERVICEABLE	2,020.37	-
1	A/C CONDENSER GARNISH LH UPPER	SERVICEABLE	39.67	-
1	A/C CONDENSER GARNISH RH UPPER	SERVICEABLE	39.67	-
1	A/C CONDENSER GARNISH LH	SERVICEABLE	58.81	-
1	A/C CONDENSER GARNISH RH	SERVICEABLE	59.60	-
1	LOWER ARM RH	SERVICEABLE	685.76	-
1	KNUCKLE ARM RH	SERVICEABLE	846.98	-
1	ABSORBER FRT RH	SERVICEABLE	360.54	-
1	STABILIZER BAR FRT	SERVICEABLE	604.65	-
1	DRIVESHAFT RH	TO REPAIR SEE LABOUR	1,747.45	-
1	WIPER RESERVOIR	DENTED	348.25	348.25
1	WIPER RESERVOIR NECK	SERVICEABLE	136.11	-
1	WIPER RESERVOIR MOTOR	SERVICEABLE	270.06	-
	LESS 10% DISCOUNT		-3,562.66	-827.53
			32,063.91	7,447.80

Report Ref No. CS/EGI18012280/Ktd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPECIAL NETT ITEMS			
1	SET BUMPER CLIP FRT (SN)	NECESSARY	66.00	66.00
1	BUMPER BRACKET CLIP FRT RH (SN)	NOT NECESSARY	12.00	-
1	BUMPER SUPPORT CLIP FRT RH (SN)	NOT NECESSARY	10.50	-
1	SET BUMPER GRILLE LOWER CLIP (SN)	NOT NECESSARY	69.00	-
1	SET FRAME FULL SUPPORT PANEL CLIP (SN)	NOT NECESSARY	70.00	-
2	FRAME FULL SUPPORT PANEL NUT (SN)	NOT NECESSARY	20.00	-
2	FRAME FULL SUPPORT PANEL STUD (SN)	NOT NECESSARY	30.00	-
1	SET WHEELARCH CLIP FRT RH (SN)	NECESSARY	30.50	30.50
6	BONNET INSULATOR CLIP L70Y (SN)	NOT NECESSARY	7.30	-
2	BONNET STRUT L70Y (SN)	SERVICEABLE	88.61	-
2	BONNET CABLE CLIP L70Y (SN)	NOT NECESSARY	6.31	-
2	BONNET CABLE COVER SCREW L70Y (SN)	SERVICEABLE	10.85	-
1	WINDSCREEN SEALANT (SN)	NOT NECESSARY	253.80	-
1	FRONT WINDSCREEN MOULDING (SN)	NOT NECESSARY	120.00	-
1	FRONT WINDSCREEN INNER SPONGE SEAL (SN)	NOT NECESSARY	100.00	-
			894.87	96.50
	LABOUR			
	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF BUMPER BEAM FRT,HEADLAMP PANEL FRT RH,DOOR PANEL FRT RH,FRAME FULL SUPPORT BRACKET,DOOR PANEL FRT RH,BONNET,BONNET HINGE LH,BONNET HINGE RH,BONNET LOCK, AND DRIVESHAFT RH.		4,500.00	500.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		4,000.00	440.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	30.00
	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.		220.00	60.00
	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-

Report Ref No. CS/EGI18012280/Ktd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
	TO TRANSFER OF FRONT FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF BONNET FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO VACUUM, REPLACE, REFILL AND RECHARGE AIR CONDENSER.	NOT NECESSARY	380.00	-
	TO REPLACE, REFILL AND TOP UP COOLANT FOR RADIATOR.	NOT NECESSARY	170.00	-
	TO VACUUM, REPLACE, REFILL AND RECHARGE AIR INTERCOOLER.	NOT NECESSARY	170.00	-
	TO TRANSFER OF FRONT WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
			11,260.00	1,050.00
	GRAND TOTAL		44,218.78	8,594.30
	RECOMMENDED COST OF REPAIRS			8,594.30

Report Ref No. CS/EG18012280/Ktd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.