

51 UBI AVE 1, #01/02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 6256 3561 FAX: (065) 6256 4315

Your Ref: D18005167MFSH Date: 01st October 2018

Our Ref : CS/FCI18012297/Kqd3n2

M/s First Capital Insurance Ltd 36 ROBINSON ROAD #16-01 CITY HOUSE Singapore 068877 (The Motor Claims Department)

Dear Sir / Madam,

INSPECTION REPORT OF VEHICLE NO: XD 3086C INSURED VEHICLE: SHC 7226J ACCIDENT DATE: 30/06/2018

We submit herewith our recommendation below:

Qty	Description of Parts	Estimate	Recommendation
1	One unit Truck-Mounted Attenuator (SN)	\$38,000.00	\$36,000.00
2	One Set Sticker (SN)	\$ 250.00	\$ 250.00
	Labour Charges		
	Strip/refit TMA & Crane Service & checking wiring.	\$1,000.00	\$ 800.00
	Touch-up Paint On Accident Affected Areas	\$ 600.00	\$ 450.00
		\$39,850.00	\$37,500.00
	Recommended Cost of Lump Sum Repair (To Its Pre-Accident Condition)		\$30,000.00

(SIN DOLLARS: Thirty Thousand Only)



51 UBI AVE 1, #01/02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 6256 3561 FAX: (065) 6256 4315

We recommend that the repairs of the entire damage require about <u>Seven</u> working days to complete.

Vehicle Inspected By:

KSC KONG SENG CHEONG Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.