



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18012297/Kqd3n2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 17-10-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

| | | | |
|--------------|----------------|----------------|------------|
| Insured Veh. | SHC 7226J | Veh. Inspected | XD 3086C |
| Policy No. | D-18088937MFSH | Coverage (\$) | 0.00 |
| Claim No. | D18005167MFSH | Excess (\$) | 0.00 |
| Assign From | LURENE | Assign Date | 05/07/2018 |

2. Vehicle Particulars & Condition

| | | | |
|--------------|---------------|--------------|--------------|
| Make & Model | mitsubishi FV | c.c | 12882 |
| Engine No. | HIDDEN | Year of Reg. | 2008 |
| Chassis No. | FV51JJA00355 | Colour | WHITE / BLUE |
| Odometer | 732379 | Steering | IN ORDER |
| Brakes | IN ORDER | Modification | NIL |
| General | GOOD | | |

3. Conditions of Tyres

| | Size | Make | Balance |
|----------------|--------------------|-----------|------------|
| R/H Front Tyre | 295/80 R22.5 | CHAO YANG | 7 mm |
| L/H Front Tyre | 295/80 R22.5 | CHAO YANG | 7 mm |
| R/H Rear Tyre | 295/80 R22.5 (D/D) | FIRESTONE | 6/6 3/3 mm |
| L/H Rear Tyre | 295/80 R22.5 (D/D) | FIRESTONE | 6/6 3/3 mm |

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

| | | | |
|----------------|--|-----------------|------------|
| Accident Date | 30/06/2018 | Inspection Date | 05/07/2018 |
| Survey held at | CHEONG CHEONG MOTOR SERVICE PL BLK 5032 ANG MO KIO INDUSTRIAL PARK 2 #01-293 SINGAPORE 569535 | | |

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT.
B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **7 Working Days**