

INS. CASE OWNER:

KC

CC4, Asm 180 12333, T. Wa 352

LKK

IDAC:

55663

ASSIGNMENT

Surveyor:

DOI:

6/11/18

Date / Time:

5/11/2018

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SKV 8720 G

Name of Insured:

Optima motor pte

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

30/6/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

TAY JIA T HWE DOUGLAS

Driver Tel No. : 97470771/64721313 (V/L: YES / NO)

Claim No.:

sgm0002a

Policy No.:

P1749542

Make / Model:

Porsche

Place of Accident:

PIE > CHANGI

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SKV 8720 G

SLP 48L

SKZ 3719Z



INSRS:

WSP:

Tel:

Liability:

RMKS:

on



INSRS:

WSP:

Tel:

Liability:

RMKS:

pmr

7P



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

10/11/18

SLP 48L - X, SKV 8720 G - X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

11/11/18

violation

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time: 21.9.18

Confirm with:

Confirm by: Mm

Repair Cost:

Plp

S\$ 18,404.76

(

9

days) Reduction:

4

%

Email

Call

FINAL SETTLEMENT

Date/Time: 25.02.19

Confirm with: CAROLINE

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

28

If NO or B 28, Ass. Lia:

100%

Repair Cost:

mlgst

S\$ 19,693.09

Loss of Rental (LOR):

S\$

(

days)

Loss of Use (LOU):

S\$

1,300

(\$

100

x

13

days)

Loss of Income (LOI):

S\$

-

(\$

x

days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

S\$

2,000

Medical:

S\$

-

Disbursement:

S\$

-

Legal Cost

S\$

-

(e.g. Tow/ Independent)

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

350

Total:

S\$ 20,995.09

Global Sum S\$:

FINAL PAYMENT

Date/Time: 25.02.19

Confirm with: CAROLINE

Email

Call

Payee 1:

S\$ 20,995.09

Name 1:

PERFORMANCE MOTORS LIMITED

Payee 2: (Strike if N.A.)

S\$

-

Name 2:

Payee 3: (Strike if N.A.)

S\$

-

Name 3:

(08/11/13) wef

ASS. REC. BY: TanpinREF: AXA12333/TW(w)**ASSIGNMENT**From: _____ Date: 6/7/18

Estimated Cost: _____

OD: ☒ TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SLP48Lat Workshop m/s Performanceof 303 Alexandra Road

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: \$230K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 9 days Res.: Yes or NoLum Sum: 2-B-2 % 3 Val.: Yes or NoCA / REV / REP. / 24 HRS up

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLP48L Yr Regn: 2016, MarchType: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BMW X6 c.c. 2479Colour: Red A/C: Insured / Std / NI / NASp. Reading: 22838 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBAKU220700P55472Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ Inorder / Jammed / Leaked / Burnt orBrake: ☒ Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 255/50R19R: 255/50R19BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / ☒ PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. _____ D.O.I. 6/2/18 @ 1550Survey held at PMLDes. of Damages: ☒ Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

27/9/18 Confirm 2-B-2 \$18404.76 with 9 working days(Red - \$15730.37)
45/-)

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee: _____

Transportation: _____

S + RS, SI

Photos

Others

TOTAL

Report Format : _____

Lump Sum / I.B.I. (\$) _____

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



In

GST REG. NO : M2 - 0020081 - X

05 JUL 2018

ESTIMATE

Estimate No. : b1 47569
Date Estimated : 05/07/2018
Prepared By : Kevin Leong Wai Kit

Page No. : 1 of 6

- ESTIMATE REPAIR FOR -
Rainbow Minerals Pte Ltd
8 Eu Tong Sen Street
#15-84
Singapore
Singapore 059818

- ACCOUNT - 238
AXA Insurance Pte Ltd
8 Shenton Way
#24-01 AXA Tower
Singapore 068811

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLP48L	OP55472	22/03/2016	X6 xDrive35i	0

DESCRIPTION

To replace rear bumper, tail gate, front bumper, front bonnet & all attachments cause by accident.

Painting on rear bumper, rear tail gate, front bumper & bonnet

To replace rear exhaust silencer including alignment system and conduct checks for leak.

To replace rear windscreen glass

To conduct water leak tests.

To supply and install rear windscreen solar film.

To check electrical wiring systems for proper function.

To transfer lock mechanism from old to new bootlid including conduct checks on new bootlid central locking system for proper function.

To carry out body cavity preservation.
(Per panel).

To supply front emboss number plate.

To tow accident vehicle to PML workshop.

Sundries.

Total Labour 1: 10,905.00

DESCRIPTION

CLAMP
REAR SILENCER BRACKET REAR

QTY	PRIC	VALUE
16	1.60	25.60
1	55.80	55.80

Handwritten notes and calculations:

- 4675 3825
- 4207.50 3400 4,250.00
- 2846 2244 3,690.00
- 2561.40
- un X 451? 531.00
- un X 488? 574.00
- un X ? 75.00
- un X 451? 531.00
- 135 / 150 177.00
- un X 451? 531.00
- 90 / 100 118.00
- / bt 83.00
- / / 195.00
- 100 / ? 150.00

Performance Motors Limited

A member of the Sime Darby Group
 Co. Reg. No. 197401559M GST Reg. No. M2-0020081-X



303, Alexandra Road
 Sime Darby Performance Centre
 Singapore 159941
 Tel. 63190100 (Sales & Admin)
 63190111 (AfterSales)
 Fax. 64747770

280, Kampong Arang Road
 East Coast Centre
 Singapore 438180
 Tel. 63190888 (AfterSales)
 Fax. 63449773

315, Alexandra Road
 Sime Darby Business Centre
 Singapore 159944
 Tel. 63190528 (AfterSales)
 63190533/530 (Motorrad)
 Fax. 64796601 (AfterSales)
 64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 47569
 Date Estimated : 05/07/2018
 Prepared By : Kevin Leong Wai Kit

Page No. : 2 of 6

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLP48L	0P55472	22/03/2016	X6 xDrive35i	0

DESCRIPTION	QTY	PRIC	VALUE
RUBBER MOUNTING	1	33.65	33.65
Tailpipe tip	2	130.55	261.10
REAR SILENCER WITH EXHAUST FLAP	1	2,371.55	2,371.55
BONNET	1	2,385.70	2,385.70
BOOTLID	1	1,987.90	1,987.90
GRILLE MIDDLE TOP OPEN	1	107.20	107.20
GRILLE MIDDLE BOTTOM OPEN	1	119.30	119.30
FRT SHOCK ABSORBER	1	85.20	85.20
GRILLE SIDE CLOSED LH	1	93.85	93.85
RH GRILLE SIDE CLOSED	1	93.90	93.90
LICENCE PLATE HOLDER ECE	1	67.60	67.60
FRT BUMPER CLADDING	1	225.75	225.75
FRT BUMPER COVER	1	161.25	161.25
HOLDER CAMERA SYSTEM (I-CAM)	1	32.75	32.75
FRT BUMPER PANEL PRIMED (SRA/PDC)	1	1,553.70	1,553.70
COVER TOWING LUG FRT PRIMED	1	46.45	46.45
RR BUMPER LH MOUNT	1	198.30	198.30
RR BUMPER RH MOUNT	1	198.30	198.30
COVER TOWING EYE REAR	1	40.20	40.20
REAR BOTTOM COVER	1	186.65	186.65
REAR BUMPER CARRIER	1	785.65	785.65
RR BUMPER LH CORNER MOUNT	1	142.55	142.55
RR BUMPER RH CORNER MOUNT	1	142.55	142.55
RR BUMPER CENTRE MOUNT	1	198.30	198.30
REAR BUMPER TRIM PANEL	1	1,436.50	1,436.50
REAR BUMPER CLADDING (PDC)	1	377.10	377.10
REAR BUMPER BOTTOM TRIM PANEL (V6)	1	404.95	404.95
LH ORNAMENTAL GRILLE BASIC	1	144.60	144.60
RH ORNAMENTAL GRILLE BASIC	1	144.60	144.60
RH ORNAMENTAL GRILLE BASIC	1	144.60	144.60
EMBLEM GROMMET	2	0.80	0.80
TRUNK LID BADGE	1	69.50	69.50
LETTERING X6	1	62.55	62.55
REAR WINDOW	1	1,174.80	1,174.80
COOLING AIR DUCT	1	308.95	308.95
BOOTLID GASKET	1	264.50	264.50
LH REAR FOG LIGHT/REFLECTOR	1	83.55	83.55
RH REAR FOG LIGHT/REFLECTOR	1	83.55	83.55
ULTRASONIC SENSOR BLACK REAR	3	248.70	746.10
DECOUPING RING PDC TORQUE CONVERTER	8	5.05	40.40
ULTRASONIC TRANSDUCER WC06 FRT	2	368.80	737.60
(DG) CLEANER R1 (100ML)	1	23.85	23.85
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	2	131.55	263.10
(DG/SL) ADHESIVE SET K6	1	53.05	53.05
(DG/SL) GLASS PRIMER 30ML (VP206)	1	27.85	27.85

Total Parts : 18,193.25

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 47569
Date Estimated : 05/07/2018
Prepared By : Kevin Leong Wai Kit

Page No. : 3 of 6

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLP48L	0P55472	22/03/2016	X6 xDrive35i	0

Claims OD / ☒ Survey / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 6/7/18 Excess \$ _____

Surveyor's Name Tan Jiah Sign [Signature]

Surveyor's Tel 97495749 Authorized Yes / No _____

Authorized Date _____ Time _____

PROCESSED BY: Tan Jiah / No PMU Yes / No _____

Surveyor's Email tan.jiah@pikanderson.com

No. of Working Days Recommended 9 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour 1	:	10,905.00
Parts	:	18,193.25
Labour 2	:	<u>29048.25</u> 0.00
Excess	:	0.00
Total GST @ 7%	:	2,036.88
Grand Total	:	<u>31,135.13</u>

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

31854.30

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 47569
Date Estimated : 05/07/2018
Prepared By : Kevin Leong Wai Kit

Page No. :

REPAIR FOR -
Rainbow Minerals Pte Ltd
8 Eu Tong Sen Street
#15-84
Singapore
Singapore 059818

- ACCOUNT - 238
AXA Insurance Pte Ltd
8 Shenton Way
#24-01 AXA Tower
Singapore 068811

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLP48L	0P55472	22/03/2016	X6 xDrive35i	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

# To replace charge air cooler include conducting checks for proper function and leaks	531.00	10.00	477.90 <i>net</i>
--	--------	-------	-------------------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
-------------	------------	-----	---------	------

# BLIND RIVET *	1.10	4.00	3.00	4.27 <i>net</i>
# CHARGE-AIR COOLER *	701.25	1.00	3.00	680.21 <i>bt</i>
# FRT BUMPER CARRIER *	516.65	1.00	3.00	501.15 <i>bt</i>
# FRT BUMPER LH INSERT (NIVI) *	80.85	1.00	3.00	78.42 <i>net</i>
# FRT BUMPER RH INSERT (NIVI) *	89.65	1.00	3.00	86.96 <i>net</i>
# LH HOLDER HEADLIGHT CLEANING SYSTEM *	20.60	1.00	3.00	19.98 <i>de</i>
# RH HOLDER HEADLIGHT CLEANING SYSTEM *	20.49	1.00	3.00	19.88 <i>de</i>
# LH BRAKE AIR DUCT *	54.10	1.00	3.00	52.48 <i>de</i>
# RH BRAKE AIR DUCT *	54.10	1.00	3.00	52.48 <i>de</i>
# EXPANDING RIVET *	1.35	20.00	3.00	26.19 <i>net</i>
# SENSOR LEAD SMART OPENER *	44.45	1.00	3.00	43.12 <i>de</i>
# CONTROL UNIT SMART OPENER *	468.85	1.00	3.00	454.78 <i>net</i>
# RH SPRAY NOZZLE *	179.30	1.00	3.00	173.92 <i>dis</i>

Total Labour :	477.90
Total Parts :	2,193.84
Total Labour & Parts :	2,671.74

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 47569
Date Estimated : 05/07/2018
Prepared By : Kevin Leong Wai Kit

Page No. :

REPAIR FOR -
Rainbow Minerals Pte Ltd
8 Eu Tong Sen Street
#15-84
Singapore
Singapore 059818

- ACCOUNT - 238
AXA Insurance Pte Ltd
8 Shenton Way
#24-01 AXA Tower
Singapore 068811

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLP48L	0P55472	22/03/2016	X6 xDrive35i	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
* To replace front/rear bumpers and attachments, bonnet, cooling air duct and attachments, RH spray nozzle include making good the boot lid, tail end panel and knocking out dents caused by the accident	4675.00	10.00	4,207.50	
* To spray paint boot lid, bonnet, front bumper, rear bumper and tail end panel	2846.00	10.00	2,561.40	
* To check electrical wiring systems at the front and rear for proper function	150.00	10.00	135.00	
To carry out body cavity preservation. (Per panel).	100.00	10.00	90.00	
To supply front emboss number plate.	83.00	0.00	83.00	
To tow accident vehicle to PML workshop.	195.00	0.00	195.00	
# To replace charge air cooler include conducting checks for proper function and leaks	✓ 531.00	10.00	477.90	
Sundries	150.00	0.00	150.00	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
CLAMP	3.20	10.00	3.00	31.04 ✓
# BLIND RIVET *	1.10	4.00	3.00	✓ 4.27
CLAMP	1.60	10.00	3.00	15.52 ✓
# CHARGE-AIR COOLER *	701.25	1.00	3.00	✓ 680.21
BONNET	2,385.70	1.00	3.00	✓ 2,314.13
# FRT BUMPER CARRIER *	516.65	1.00	3.00	✓ 501.15
SUPPORT INSERT LH *	14.90	1.00	3.00	14.45 ✓
GRILLE MIDDLE TOP OPEN	107.20	1.00	3.00	✓ 103.98
GRILLE MIDDLE BOTTOM OPEN	119.30	1.00	3.00	✓ 115.72
GRILLE SIDE CLOSED LH	93.85	1.00	3.00	✓ 91.03
RH GRILLE SIDE CLOSED	93.90	1.00	3.00	✓ 91.08
LICENCE PLATE HOLDER ECE	67.60	1.00	3.00	✓ 65.57
# FRT BUMPER LH INSERT (NIV) *	80.85	1.00	3.00	✓ 78.42

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X.



FINAL REPORT

# FRT BUMPER RH INSERT (NIVI) *	89.65	1.00	3.00	✓ 86.96
# LH HOLDER HEADLIGHT CLEANING SYSTEM *	20.60	1.00	3.00	✓ 19.98
# RH HOLDER HEADLIGHT CLEANING SYSTEM *	20.49	1.00	3.00	✓ 19.88
HOLDER CAMERA SYSTEM (I-CAM)	32.75	1.00	3.00	✓ 31.77
FRT BUMPER PANEL PRIMED (SRA/PDC)	1,553.70	1.00	3.00	✓ 1,507.09
COVER TOWING LUG FRT PRIMED	46.45	1.00	3.00	✓ 45.06
COVER TOWING EYE REAR	40.20	1.00	3.00	✓ 38.99
REAR BOTTOM COVER	186.65	1.00	3.00	✓ 181.05
RR BUMPER CENTRE MOUNT	198.30	1.00	3.00	✓ 192.35
REAR BUMPER TRIM PANEL	1,436.49	1.00	3.00	✓ 1,393.40
REAR BUMPER CLADDING (PDC)	377.10	1.00	3.00	✓ 365.79
REAR BUMPER BOTTOM TRIM PANEL (V6)	404.95	1.00	3.00	✓ 392.80
LH ORNAMENTAL GRILLE BASIC	144.60	1.00	3.00	✓ 140.26
RH ORNAMENTAL GRILLE BASIC	144.60	1.00	3.00	✓ 140.26
EMBLEM GROMMET	0.80	2.00	3.00	✓ 1.55
TRUNK LID BADGE	69.49	1.00	3.00	✓ 67.41
LETTERING X6	62.55	1.00	3.00	✓ 60.67
COOLING AIR DUCT	308.95	1.00	3.00	✓ 299.68
# LH BRAKE AIR DUCT *	54.10	1.00	3.00	✓ 52.48
# RH BRAKE AIR DUCT *	54.10	1.00	3.00	✓ 52.48
# EXPANDING RIVET *	1.35	20.00	3.00	✓ 26.19
# SENSOR LEAD SMART OPENER *	44.45	1.00	3.00	✓ 43.12
# CONTROL UNIT SMART OPENER *	468.85	1.00	3.00	✓ 454.78
# RH SPRAY NOZZLE *	179.30	1.00	3.00	✓ 173.92
LH REAR FOG LIGHT/REFLECTOR	83.55	1.00	3.00	✓ 81.04
RH REAR FOG LIGHT/REFLECTOR	83.55	1.00	3.00	✓ 81.04
DECOUPING RING PDC TORQUE CONVERTER	5.05	8.00	3.00	✓ 39.19
ULTRASONIC TRANSDUCER WC06 FLAMENCO	368.80	1.00	3.00	✓ 357.74
(DG/SL) ADHESIVE SET K6	53.05	1.00	3.00	✓ 51.46

SUPPLEMENTARY ITEMS

Total Labour :	7,899.80
Total Parts :	10,504.96
Total Labour & Parts :	18,404.76
Deduction for Excess :	0.00
Total Repair Costs less Excess:	18,404.76
GST @7%:	1,288.33
Grand Total :	19,693.09



FACSIMILE MESSAGE

DATE _____ TIME _____
 TO LKK FAX NO. _____
 ATTN Tausikh NO OF PAGES _____
 (INCLUSIVE OF THIS PAGE)
 CC _____
 ATTN _____ FAX NO. _____
 FROM Kevin Leong FAX NO. _____
 TEL NO. 9116 5600

If this fax is not received in order, please do call us. Thank you.

Dear Sirs,

Supplementary repair for BMW

X6

Vehicle Registration No.

SLP 481

Vehicle Chassis No.

OP 55472

Supplementary Parts to be replaced:		Price (nett)
①	Charge Air cooler	\$ 701.25 ✓
Supplementary Labour		
①	To replace Charge Air Cooler	\$ 531.00 ✓
②	To repair on rear End panel	\$ 850.00 ✓
③	Painting on End panel.	\$ 632.00 (nett) ✓
Kindly add on additional 2 day on no. of days.		



Service Request Details

Claim

S8M00MZQ

Reference

None 

Loss Date

June 30, 2018

Request Date

July 5, 2018

Due Date

July 12, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

05072018 @ 4:50pm
Caroline veh in

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SLP48L

Make

TPVD BMW

Model

X6 XDRIVE35I SR LED NAV HUD

Service Address

...

Primary Contact/Insured

OPTIMA WERKZ PTE. LTD.

6 KUNG CHONG ROAD, ALEXANDRA INDUSTRIAL ESTATE, 159143, Singapore
64721313

roylim@ow.sg;adeline@ow.sg;angel@ow.sg

Claim Handler

CHAN Kian Chuan

6568804269

kianchuan.chan@axa.com.sg

Additional Instructions

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)



Re:RE: Re:S8M00MZQ-mandate approval

Type

🔔 Question

Message

LOR @ 13 DAY OTHERS AS PROPOSED

Reply

Asher Sng (LKKAUTO)

From: PBSP <pml-pbsp@simedarby.com.sg>
Sent: Friday, 22 February 2019 3:21 PM
To: Kevin Leong Wai Kit; Asher Sng (LKKAUTO)
Subject: Re: PRE-SIGNED DV - SLP48L & SKV8720G ON 30.06.2018

Follow Up Flag: Flag for follow up
Flag Status: Completed

Dear Asher

Please proceed with the payment.

Our CSA has confirmed with our client and agreed with the proposed settlement.

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

From: PBSP
Sent: Friday, 22 February 2019 1:11 PM
To: Kevin Leong Wai Kit
Cc: Asher Sng (LKK Auto)
Subject: Re: PRE-SIGNED DV - SLP48L & SKV8720G ON 30.06.2018

Dear Kevin

Please advise ASAP.

Thank you.

Regards,
Caroline

From: PBSP
Sent: Monday, 18 February 2019 3:19:56 PM
To: Kevin Leong Wai Kit
Subject: Re: PRE-SIGNED DV - SLP48L & SKV8720G ON 30.06.2018

Dear Kevin

Please let us have your decision asap.

Thanks
Caroline

From: PBSP
Sent: Monday, 7 January 2019 6:40:18 PM
To: Kevin Leong Wai Kit
Subject: Re: PRE-SIGNED DV - SLP48L & SKV8720G ON 30.06.2018

Dear Kevin

Surveyor recommended 9 days repair. However, your customer is claiming for 17 days loss of use.

Please confirm with your customer if we may proceed to settle as per offer below - \$100 x 13 days = \$1300.

Thank you.

Regards,
Caroline

From: PBSP
Sent: Wednesday, 12 December 2018 5:04 PM
To: Vivian Lau (LKKAUTO)
Cc: 甯珺 ©
Subject: Re: PRE-SIGNED DV - SLP48L & SKV8720G ON 30.06.2018

Dear Kevin

Surveyor recommended 9 days repair. However, your customer is claiming for 17 days loss of use. Please see attached invoice.

Please confirm with your customer if we may proceed to settle as per offer below - \$100 x 13 days = \$1300.

Thank you.

Regards,
Caroline

From: Vivian Lau (LKKAUTO) <vivianlau@lkkauto.com>
Sent: Wednesday, 12 December 2018 4:09:00 PM
To: PBSP
Cc: 甯珺 ©
Subject: RE: PRE-SIGNED DV - SLP48L & SKV8720G ON 30.06.2018

WITHOUT PREJUDICE'

SAVE AS TO COSTS

Dear Sir/Madam,

Accident involving Vehicle SLP 48L & SKV 8720G on 30/06/2018

We refer to the above matter

On a without prejudice basis, our principal propose settlement as follow:

COST OF REPAIR	\$ 19,693.09
Loss of RENTAL (\$ 100.00 x 13day)	\$ 1,300.00
GIA SEARCH	\$ 2.00
	\$ 20,995.09

Kindly confirm acceptance

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement.

Thank you

Best Regards,

Vivian Lau | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-8625 | email: Vivianlau@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP [mailto:pml-pbsp@simedarby.com.sg]
Sent: Wednesday, 14 November, 2018 5:24 PM
To: Vivian Lau (LKKAuto) <vivianlau@lkkauto.com>; CS A Team <cs-a@lkkauto.com>
Subject: Re: PRE-SIGNED DV - SLP48L & SKV8720G ON 30.06.2018

From: PBSP
Sent: Wednesday, 14 November 2018 4:50:13 PM
To: Vivian Lau; CS A Team
Subject: PRE-SIGNED DV - SLP48L & SKV8720G ON 30.06.2018

Dear Sirs

Payment reminder (pre-signed dv enclosed).

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKV 8720G (Insd veh)	Model:	B.M.W. X6
	SLP 48L (TP veh)		
Date of Accident:	30/06/2018		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	34,089.45
Final Repair Cost	:	\$	19,693.09
Loss of Use	:	\$	1,300.00
Rental (if any)	:	\$	
LTA / GIA Search Fee	:	\$	2.00

Others:	:	\$	
---------	---	----	--

	:	\$	
Final Settlement Sum	:	\$	20,995.09

Is Third Party Workshop GIA Registered?	☒ YES	☐ NO	(Kindly indicate below)
---	---	-----------------------------	-------------------------

A) For Non GIA Registered Workshop:	Agreed Liability _____ (%)
B) For GIA Registered Workshop:	BOLA Applicable: Yes/ No BOLA Scenario No: _____
BOLA Liability: _____ 100 _____ (%)	Assessed Liability (*): _____ 100 _____ (%)
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.	

Remarks	_____
---------	-------

Payment Instruction: Payee's Breakdown			
1)	PERFORMANCE MOTORS LTD	:	\$ 20,995.09

NUR SHAQILAH BTE ABDOL
WAHAB

06/03/2019

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CC4/ASM18012333/T1ea3s2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: KIAN CHUAN			Date : 06-03-2019	
			Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKV 8720G	Veh. Inspected	SLP 48L	
Policy No.	P1749542	Coverage (\$)	0.00	
Claim No.	S8M00MZQ	Excess (\$)	0.00	
Assign From	KIAN CHUAN	Assign Date	05/07/2018	
2. Vehicle Particulars & Condition				
Make & Model	B.M.W. X6	c.c	2979	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	WBAKU220700P55472	Colour	RED	
Odometer	22838	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	255/50R19	PIRELLI	6 mm	
L/H Front Tyre	255/50R19	PIRELLI	6 mm	
R/H Rear Tyre	255/50R19	PIRELLI	6 mm	
L/H Rear Tyre	255/50R19	PIRELLI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	30/06/2018	Inspection Date	06/07/2018	
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		9 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLP 48L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
10	CLAMP (SN) (CONSISTENT)	NECESSARY	31.04	31.04
1	REAR SILENCER BRACKET REAR (SN) (CONSISTENT)	NOT NECESSARY	55.80	-
1	RUBBER MOUNTING (SN) (CONSISTENT)	NOT NECESSARY	33.65	-
2	TAILPIPE TIP (SN) (CONSISTENT)	NOT NECESSARY	261.10	-
1	REAR SILENCER WITH EXHAUST FLAP (SN) (CONSISTENT)	NOT NECESSARY	2,371.55	-
1	BONNET (SN) (CONSISTENT)	BENT	2,385.70	2,314.13
1	BOOTLID (SN) (CONSISTENT)	TO REPAIR SEE LABOUR	1,987.90	-
1	GRILLE MODULE TOP OPEN (SN) (CONSISTENT)	DEFORMED	107.20	103.98
1	GRILLE MIDDLE BOTTOM OPEN (SN) (CONSISTENT)	DEFORMED	119.30	115.72
1	FRT SHOCK ABSORBER (SN) (CONSISTENT)	NOT NECESSARY	85.20	-
1	GRILLE SIDE CLOSED LH (SN) (CONSISTENT)	CUT	93.85	91.03
1	RH GRILLE SIDE CLOSED (SN) (CONSISTENT)	CRACKED	93.90	91.08
1	LICENCE PLATE HOLDER ECE (SN) (CONSISTENT)	DEFORMED	67.60	65.57
1	FRT BUMPER CLADDING (SN) (CONSISTENT)	NOT NECESSARY	225.75	-
1	FRT BUMPER COVER (SN) (CONSISTENT)	NOT NECESSARY	161.25	-
1	HOLDER CAMERA SYSTEM (I-CAM) (SN) (CONSISTENT)	DISTORTED	32.75	31.77
1	FRT BUMPER PANEL PRIMED (SRA/PDC) (SN) (CONSISTENT)	DEFORMED	1,553.70	1,507.09
1	COVER TOWING LUG FRT PRIMED (SN) (CONSISTENT)	DEFORMED	46.45	45.06
1	RR BUMPER LH MOUNT (SN) (CONSISTENT)	NOT NECESSARY	198.30	-
1	RR BUMPER RH MOUNT (SN) (CONSISTENT)	NOT NECESSARY	198.30	-
1	COVER TOWING EYE REAR (SN) (CONSISTENT)	DEFORMED	40.20	38.99
1	REAR BOTTOM COVER (SN) (CONSISTENT)	MISSING	186.65	181.05
1	REAR BUMPER CARRIER (SN) (CONSISTENT)	NOT NECESSARY	785.65	-
1	RR BUMPER LH CORNER MOUNT (SN) (CONSISTENT)	NOT NECESSARY	142.55	-
1	RR BUMPER RH CORNER MOUNT (SN) (CONSISTENT)	NOT NECESSARY	142.55	-
1	RR BUMPER CENTRE MOUNT (SN) (CONSISTENT)	DEFORMED	198.30	192.35
1	REAR BUMPER TRIM PANEL (SN) (CONSISTENT)	DEFORMED	1,436.50	1,393.40
1	REAR BUMPER CLADDING (PDC) (SN) (CONSISTENT)	DEFORMED	377.10	365.79

Report Ref No. CC4/ASM18012333/T1ea3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BUMPER BOTTOM TRIM PANEL (V6) (SN) (CONSISTENT)	MISSING	404.95	392.80
1	LH ORNAMENTAL GRILLE BASIC (SN) (CONSISTENT)	DEFORMED	144.60	140.26
1	RH ORNAMENTAL GRILLE BASIC (SN) (CONSISTENT)	DEFORMED	144.60	140.26
1	RH ORNAMENTAL GRILLE BASIC (SN) (CONSISTENT)	NOT NECESSARY	144.60	-
2	EMBLEM GROMMET (SN) (CONSISTENT)	NECESSARY	1.60	1.55
1	TRUNK LID BADGE (SN) (CONSISTENT)	NECESSARY	69.50	67.41
1	LETTERING X6 (SN) (CONSISTENT)	NECESSARY	62.55	60.67
1	REAR WINDOW (SN) (CONSISTENT)	NOT NECESSARY	1,174.80	-
1	COOLING AIR DUCT (SN) (CONSISTENT)	DEFORMED	308.95	299.68
1	BOOTLID GASKET (SN) (CONSISTENT)	NOT NECESSARY	264.50	-
1	LH REAR FOG LIGHT / REFLECTOR (SN) (CONSISTENT)	CRACKED	83.55	81.04
1	RH REAR FOG LIGHT / REFLECTOR (SN) (CONSISTENT)	CRACKED	83.55	81.04
3	ULTRASONIC SENSOR BLACK REAR (SN) (CONSISTENT)	NOT NECESSARY	746.10	-
8	DECOUPING RING PDC TORQUE CONVERTER (SN) (CONSISTENT)	NECESSARY	40.40	39.19
2	ULTRASONIC TRANSDUCER WC06 FRT (SN) (CONSISTENT)	DISTORTED	737.60	357.74
1	(DG) CLEANER R1 (100ML) (SN) (CONSISTENT)	NOT NECESSARY	23.85	-
2	(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR) (SN) (CONSISTENT)	NOT NECESSARY	263.10	-
1	(DG/SL) ADHESIVE SET K6 (SN) (CONSISTENT)	NECESSARY	53.05	51.46
1	(DG/SL) GLASS PRIMER 30ML (VP206) (SN) (CONSISTENT)	NOT NECESSARY	27.85	-
1	REAR WINDSCREEN SOLAR FILM (SN) (CONSISTENT)	NOT NECESSARY	531.00	-
1	FRONT EMBOSS NUMBER PLATE (SN) (CONSISTENT)	BENT	83.00	83.00
1	SUNDRIES (SN) (CONSISTENT)	NECESSARY	150.00	150.00
4	BLIND RIVET (SN) (CONSISTENT) (ADDITIONAL)	NECESSARY	4.27	4.27
1	CHARGE-AIR COOLER (SN) (CONSISTENT) (ADDITIONAL)	BENT	680.21	680.21
1	FRT BUMPER CARRIER (SN) (CONSISTENT) (ADDITIONAL)	BENT	501.15	501.15
1	FRT BUMPER LH INSERT (NIVI) (SN) (CONSISTENT) (ADDITIONAL)	NECESSARY	78.42	78.42
1	FRT BUMPER RH INSERT (NIVI) (SN) (CONSISTENT) (ADDITIONAL)	NECESSARY	86.96	86.96

Report Ref No. CC4/ASM18012333/T1ea3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	LH HOLDER HEADLIGHT CLEANING SYSTEM (SN) (CONSISTENT) (ADDITIONAL)	DEFORMED	19.98	19.98
1	RH HOLDER HEADLIGHT CLEANING SYSTEM (SN) (CONSISTENT) (ADDITIONAL)	DEFORMED	19.88	19.88
1	LH BRAKE AIR DUCT (SN) (CONSISTENT) (ADDITIONAL)	DEFORMED	52.48	52.48
1	RH BRAKE AIR DUCT (SN) (CONSISTENT) (ADDITIONAL)	DEFORMED	52.48	52.48
20	EXPANDING RIVET (SN) (CONSISTENT) (ADDITIONAL)	NECESSARY	26.19	26.19
1	SENSOR LEAD SMART OPENER (SN) (CONSISTENT) (ADDITIONAL)	DISTORTED	43.12	43.12
1	CONTROL UNIT SMART OPENER (SN) (CONSISTENT) (ADDITIONAL)	CRACKED	454.78	454.78
1	RH SPRAY NOZZLE (SN) (CONSISTENT) (ADDITIONAL)	DISTORTED	173.92	173.92
10	CLAMP (SN) (CONSISTENT) (ADDITIONAL)	NECESSARY	15.52	15.52
1	SUPPORT INSERT LH (SN) (CONSISTENT) (ADDITIONAL)	NECESSARY	14.45	14.45
			21,187.30	10,737.96
	LABOUR			
	TO REPLACE REAR BUMPER, TAIL GATE, FRONT BUMPER, FRONT BONNET & ALL ATTACHMENTS CAUSE BY ACCIDENT. INCLUSIVE OF THE REPAIR OF BOOTLID.		4,250.00	4,207.50
	PAINTING ON REAR BUMPER, REAR TAIL GATE, FRONT BUMPER & BONNET.		3,690.00	2,561.40
	TO REPLACE REAR EXHAUST SILENCER INCLUDING ALIGNMENT SYSTEM AND CONDUCT CHECKS FOR LEAK.	NOT NECESSARY	531.00	-
	TO REPLACE REAR WINDSCREEN GLASS.	NOT NECESSARY	574.00	-
	TO CONDUCT WATER LEAK TESTS.	NOT NECESSARY	75.00	-
	TO CHECK ELECTRICAL WIRING SYSTEMS FOR PROPER FUNCTION.		177.00	135.00
	TO TRANSFER LOCK MECHANISM FROM OLD TO NEW BOOTLID INCLUDING CONDUCT CHECKS ON NEW BOOTLID CENTRAL LOCKING SYSTEM FOR PROPER FUNCTION.	NOT NECESSARY	531.00	-
	TO CARRY OUT BODY CAVITY PRESERVATION. (PER PANEL)		118.00	90.00
	TO TOW ACCIDENT VEHICLE TO PML WORKSHOP.		195.00	195.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REPLACE CHARGE AIR COOLER INCLUDE CONDUCTING CHECKS FOR PROPER FUNCTION AND LEAKS. (ADDITIONAL)		531.00	477.90
			10,672.00	7,666.80
GRAND TOTAL			31,859.30	18,404.76
RECOMMENDED COST OF REPAIRS				18,404.76

Report Ref No. CC4/ASM18012333/T1ea3s2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.