

15/02/2010

INS. CASE OWNER:

Lynethia

CC 4 ASM
AXA1801

YME0 / Kpb3

LKK:
IDAC:

Surveyor:

Kenneth

DOI:

ASSIGNMENT

9/7/18

Date / Time:

6/7/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SCT 3019J

Name of Insured:

CHUNG YAN YH VINCENT

Insured Tel No.:

HP:

82783393

Excess Sec II :SS

D.O.A:

2/7/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age: SKINNER CHUNY YEE HUNG

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

S8m 60N15 / 55708

Policy No.:

GA11111

Make / Model:

VOLVO XC60

Place of Accident:

TIP WORK STILL RD EXT.

INSRS:
WSP:
Tel:
Liability:
RMKS:LOH
HENGINSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

a/7/18
WT

SCT 3019J - 7

SCT 3019J - 7

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(Agreed / Assessed)

BOLA S/N No.:

22 (2cc 01 last)

or B 28, Ass. Lia:

100%

Repair Cost:

SS

1200.00

Loss of Rental (LOR):

SS

(days)

Loss of Use (LOU):

SS

1400.00

x 16 days)

Loss of Income (LOI):

SS

(S x days)

LOR only

LOU only

LOR + LOU

LOR + LO

[Tick only one]

GIA/LTA Search

SS

Medical:

SS

Disbursement:

SS

(e.g. Tow/ Independent)

Legal Cost

SS

Total:

SS

13440.00

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

13440.00

Name 1:

LOH HENG

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

RECEIVED 16 NOV 2018

COPY SENT

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$350.00

ASS. REC. BY:

REF: *AM /**Kennerth*

ASSIGNMENT

From: _____

Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: *885k*

IDAC Accident Report: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: *14* days

Res.: Yes or No

Lum Sum: *20* %

3 Val.: Yes or No

CA / REV / REP, / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Date / Time

Action / Instruction

*17 File pass to Catherine**US # 12K Cred # 269.15 / 374.1*Veh No: *SKP 5789K*Yr Regn: *10, 12*Type: ☒ Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or _____

Make: *Bmw 328i*c.c. *1997*Colour: *M. Black*A/C: ☐ Insured / ☐ Std / ☐ NI / ☐ NASp. Reading: *104012*T/Radio: ☐ Insured / ☐ Std / ☐ NI / ☐ NA

Eng/No: _____

C/No: *WBA 3A 520 30F 253831*Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orModl: ☐ Nil / ☐ S/Rim / ☒ STD / ☐ RIM or

Tyre Size: F: _____

R: *225 145 BR18*BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal. *6* mm

Rear

R/Bal. *7* mmL/Bal. *6* mmL/Bal. *7* mmD.O.A. *3/7/18*D.O.I. *9/7/18*

Survey held at _____

Des. of Damages: ☐ Frt / ☒ Rear / ☐ O/S / ☐ N/S / ☐ UIC / ☐ Rooftop or
2131

The UIC / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

Date/Time, File Return to?

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS. \$ _____

Fixturs _____

Others _____

TOTAL

Add Fee: ☐

: Site Insp (\$ _____)

☐

: Interview (\$ _____)

☐

Tech Invs (\$ _____)

☐

Weekend (\$ _____)

Report Format: _____

Lump Sum / I.B.I. (\$) _____



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CC4/ASM18012340/pb3	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811			Date : 06-07-2018	
			Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SCK 3019J	Veh. Inspected	SKP 5789K
	Policy No.		Coverage (\$)	0.00
	Claim No.		Excess (\$)	0.00
	Assign From		Assign Date	06/07/2018
2. Vehicle Particulars & Condition				
	Make & Model		c.c	0
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.		Colour	
	Odometer	-	Steering	
	Brakes		Modification	
	General			
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm
4. Description of Damages				
5. General Information				
	Accident Date	03/07/2018	Inspection Date	
	Survey held at	LOH HENG BLK 176 #03-08 SIN MING DRIVE SINGAPORE 575721		
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

LOH HENG

Automotive Repair Services
Accident Insurance Claims

7-Jun-18

AXA Insurance Pte Ltd

Singapore

Attn. : Motor Claim Department

Re : Estimated Quotation

Vehicle No. ~~SCK3010J (BMW 328i)~~

SLCP 5789K.

S/N		Amount (\$S)
A	PART REPLACEMENT	
	Front bumper	\$ 1,124.00
	Front bonnet	\$ 1,435.00
	Front bumper grille, right	\$ 138.00
	Front bumper grille, left	\$ 138.00
		\$ 78.00
	Rear bumper	\$ 1,321.00
	Rear bumper lower moulding chrome	\$ 98.00
	Rear bumper reinforcement	\$ 457.00
	Rear bumper bracket retainer left	\$ 113.00
	Rear boot Lib	\$ 1,323.00
	Rear lib lock	\$ 178.00
	Rear boot Lib hinge right	\$ 75.00
	Rear boot Lib hinge left	\$ 75.00
	Rear bumper park sensor \$298x2	\$ 792.00
	Rear bumper reflector (x2) @76x2	\$ 154.00
	Rear bumper garnish central	\$ 89.00
	Rear lower left garnish cover	\$ 87.00
	Rear bumper top garnish moulding	\$ 189.00
	Rear tow cover cover	\$ 32.00
	Head restraint sensor left and right \$245x2	\$ 490.00
	No. plate and casing front and rear	\$ 110.00
	Tail lamp left	\$ 398.00
	Rear boot lid weather stripe	\$ 165.00
	Tail panel garnish	\$ 187.00
	Tail end panel	\$ 869.00
	Rear exhaust shield	\$ 192.00
	Rear exhaust box	\$ 1,960.00
	Sensor holder set	\$ 154.00
	Exhaust hanger	\$ 59.00
	Exhaust actuator	\$ 378.00
	Smart sensor control	\$ 658.00
	PDC wiring sensor	\$ 327.00
	Truck floor panel	\$ 1,452.00
	Right lower arm cover	\$ 95.00

Not Notarized
11 Sep 81 \$21,000
Remy Abu Paim
14 days

[illegible]

Block 176 #03-08 Sin Ming Autocare
Sin Ming Drive
Singapore 575721
Tel : 64532237 / 64530797
Fax : 64556384

LOH HENG

Automotive Repair Services
Accident Insurance Claims

		\$ 15,388.00
less 5%		\$ 14,618.60
	PARTS:	
B	LABOUR CHARGES	
	To change rear damaged parts and refix. Knock out tail panel, readjust and cut and reweld floor panel etc:	\$ 2,000.00
	Tow to workshop	\$ 80.00
	To remove all sockets, wiring, and testing components.	\$ 200.00
	To do sealant and rustproof on affected area	\$ 150.00
	Respraying front and rear accident area	\$ 1,200.00
	GRAND TOTAL OF A & B	\$ 18,248.60

15312
14546.40

1800

501

1501

901

11001

18176.40

101096.95

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Block 176 #03-08 Sin Ming Autocare
Sin Ming Drive
Singapore 575721
Tel : 64532237 / 64530797
Fax : 64556384

LOH HENG

Automotive Repair Services
Accident Insurance Claims

28-Jul-18

AXA Insurance Co.

Singapore

Attn : Motor Claim Department

Re : Estimated Quotation (Supplymentary)

Vehicle No. SKP5789K (BMW 328)

S/N		Amount (S\$)
A	PART REPLACEMENT	
	Lock sencor	<i>Net</i> \$397.00 ✓
	Floor panel top cover	<i>Net</i> \$ 572.00 ✓
	less 5%	\$ 969.00
		\$ 920.55

19169.15

Block 176 #03-08 Sin Ming Autocare
Sin Ming Drive
Singapore 575721
Tel 64532237 / 64530797
Fax 64556384

7-Jun-18

AXA Insurance Pte Ltd

Singapore

Attn. : Motor Claim Department

Re : Estimated Quotation

Vehicle No. ~~SCK3019J (BMW 328i)~~

S/N		Amount (\$S)
A	PART REPLACEMENT	
	Front bumper Bu	\$ 1,124.00
	Front bonnet R	\$ 1,435.00
	Front bumper grille, right CM	\$ 138.00
	Front bumper grille, left	\$ 138.00
		\$ 76.00
	Rear bumper Ry	\$ 1,321.00
	Rear bumper lower moulding chrome	\$ 98.00
	Rear bumper reinforcement Ry	\$ 457.00
	Rear bumper bracket retainer left D.I	\$ 113.00
	Rear boot Lib Ry	\$ 1,323.00
	Rear lib lock Ry	\$ 178.00
	Rear boot Lib hinge right R	\$ 75.00
	Rear boot Lib hinge left R	\$ 75.00
	Rear bumper park sensor \$298x2 Jher	\$ 792.00
	Rear bumper reflector (x2) @76x2 Ry	\$ 154.00
	Rear bumper garnish central Ry	\$ 89.00
	Rear lower rleft garnish cover Ry	\$ 87.00
	Rear bumper top garnish moulding	\$ 189.00
	Rear tow cover cover	\$ 32.00
	Head restraint sensor left and right \$245x2 NSP	\$ 490.00
	No. plate and casing front and rear Ry Ry	\$ 110.00
	Tail lamp left CM	\$ 398.00
	Rear boot lid weather stripe D.I Ry	\$ 165.00
	Tail panel garnish	\$ 187.00
	Tail end panel Ry	\$ 869.00
	Rear exhaust shield Ry	\$ 192.00
	Rear exhaust box Ry	\$ 1,960.00
	Sensor holder set	\$ 154.00
	Exhaust hanger	\$ 59.00
	Exhaust actuator	\$ 378.00
	Smart sensor control	\$ 658.00
	PDC wiring sensor	\$ 327.00
	Truck floor panel Ry Bu	\$ 1,452.00
	Right lower arm cover	\$ 95.00

LOH HENG

Automotive Repair Services
Accident Insurance Claims

		\$ 15,388.00
	less 5%	\$ 14,618.60
	PARTS:	
	B LABOUR CHARGES	
	To change rear damaged parts and refix. Knock out tail panel, readjust and cut and reweld floor panel etc.	\$ 2,000.00
	Tow to workshop	\$ 80.00
	To remove all sockets, wiring and testing components.	\$ 200.00
	To do sealant and rustproof on affected area	\$ 150.00
	Respraying front and rear accident area	\$ 1,200.00
	GRAND TOTAL OF A & B	\$ 18,248.60

1800

501

1501

901

11001

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Block 176 #03-08 Sin Ming Autocare
Sin Ming Drive
Singapore 575721
Tel : 64532237 / 64530797
Fax : 64556384

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 10/07/2018

Survey Details:

Date of loss	3-Jul-18
Date of appointment	6-Jul-18
Date of survey	9-Jul-18
Location of survey	LOH HENG

Vehicle Details:

Claim Type:	Third party
Vehicle number	SKP 5789K
Make and Model	B.M.W.328i 2.0 AT D/AB 4DR ABS HID NAV
Date of registration	31/10/2012
Excess	
Market Value	\$85,000
Part Rebate	\$70,623
Nett Loss	\$14,377

Repair details:

Initial Estimate	\$ 18,248.60
------------------	--------------

Proposed/Revised repair cost:

Parts	\$ 10,288.97
Check items (estimate)	\$ 2,001.65
Labour	\$ 3,190.00
Total	\$ 15,480.62
Lump Sum(if applicable)	\$ -

Number of days for repair	14
---------------------------	-----------



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

We have not authorized repairs.

Mandate:

Liability(TP)		%
Proposed repair cost	\$	
Loss of use	\$	no. of days
Loss of rental	\$	no. of days
Loss of income	\$	no. of days
LTA search fees	\$	
Others	\$	
Proposed Total		



Service Request Details

V.In → fenneth

Claim

S8MOONIS

Reference

None

Loss Date

July 3, 2018

Request Date

July 6, 2018

Due Date

July 13, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SKP5789K

Make

TPVD BMW

Model

328

Service Address

Primary Contact/Insured

CHUNG YAU YU VINCENT

68 BAYSHORE ROAD, #13-01, COSTA DEL SOL, 469986, Singapore

YYCHUNG168@GMAIL.COM

Claim Handler

LOH Cynthia

6568804843

cynthia.loh@axa.com.sg

Additional Instructions:

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)



<SEEK MANDATE> - S8M00NIS [ACCIDENT INVOLVING SCK 3019J(OI) & SKP 5789K(TP) & OTHERS ON 03/07/2018]

Type

🔔 Question

Message

Liability: 3 vehicles chain collision. Our insured was last car. Inform insured third party claim, agreed to settle and aware NCD(if any) is affected. We seek your mandate from \$16,084.49 - \$ 17,104.49. *IA with mandate uploaded in Smartclaims. **14days recommendation for repair. For your approval/ instruction please. Hsiao Tong - 13 July 2018

Reply



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

STURIAVE L 202-25 PAYA LEBU INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 13.07.2018

Survey Details:

Date of loss	03.07.2018
Date of appointment	06.07.2018
Date of survey	09.07.2018
Location of survey	LOH HENG

Vehicle Details:

Claim Type:	Third party
Vehicle number	SKP 5789K
Make and Model	B.M.W.328I 2.0 AT D/AB 4DR ABS HID NAV
Date of registration	31.10.2012
Excess	
Market Value	\$ 85,000.00
Parf/COE Rebate	\$ 70,623.00
Nett Loss	\$ 14,377.00

Repair details:

Initial Estimate	\$ 18,248.60
------------------	--------------

Proposed/Revised repair cost:

Parts	\$ 10,288.97
Check items (estimate)	\$ 2,001.65
Labour	\$ 3,190.00
Total	\$ 15,480.62
Lump Sum(if applicable)	

Number of days for repair	<u>14</u>
---------------------------	-----------



Airto
Consultants
Pte Ltd

Company Registration No. 199607196R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Date: 13.07.2018

Remarks:

--

Mandate:

Liability(TP)	100%	
Proposed repair cost	\$ 14,377.00	\$ 14,377.00
Loss of use	(17days x \$100) \$ 1,700.00	
Loss of rental		(17days x \$180) 2,720.00
Loss of income		
LTA search fees	\$ 7.49	\$ 7.49
Others		
Proposed Total	\$16,084.49	\$ 17,104.49

« Re:<SEEK MANDATE> - S8M00NIS [ACCIDENT INVOLVING SCK 3019J(OI) & SKP 5789K(TP) & OTHERS ON 03/07/2018]

Type

🔗 Question

Message

TP's AVF showed that did not hit into the front veh hence is not 3VCC and we should not allow their claim on front portion as it shouldn't have any damage at all. Please re-confirm with the surveyor why allowed TP claim on front portion repair.

Reply

◀ Service Request Details

Claim

S8MOONIS

Reference

CC4/ASM18012340/pb3 

Loss Date

3 July 2018

Request Date

6 July 2018

Due Date

6 July 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Actions

Next Step

Finish the work

Complete Work

More: ▾

Vehicle Information

Incident Vehicle Registration #

SKP5789K

Make

TPVD BMW

Model

328

Service Address

...

Primary Contact/Insured

CHUNG YAU YU VINCENT

68 BAYSHORE ROAD, #13-01, COSTA DEL SOL, 469986, Singapore

YYCHUNG168@GMAIL.COM

Claim Handler

LOH Cynthia

6568804843

cynthia.loh@axa.com.sg

Additional Instructions

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

New Message

TYPE



SENT

15/8/18 6:34 PM

FROM

LOH Cynthia

SUBJECT

Re:<SEEK MANDATE> - S8M00NIS [ACCIDENT INVOLVING SCK
3019J(OI) & SKP 5789K(TP) & OTHERS ON 03/07/2018]

BODY

TP's veh (Yr2012) > 5yrs. Mandate approved lump su...



TYPE



SENT

15/8/18 6:23 PM

FROM

LOH Cynthia

SUBJECT Re:<SEEK MANDATE> - S8M00NIS [ACCIDENT INVOLVING SCK 3019J(OI) & SKP 5789K(TP) & OTHERS ON 03/07/2018]

BODY TP's AVF showed that did not hit into the front ve...



TYPE



SENT 13/7/18 12:43 PM

FROM LKK AUTO CONSULTANTS PTE LTD (TP)

SUBJECT <SEEK MANDATE> - S8M00NIS [ACCIDENT INVOLVING SCK 3019J(OI) & SKP 5789K(TP) & OTHERS ON 03/07/2018]

BODY Liability: 3 vehicles chain collision. Our insured...



TYPE



SENT 10/7/18 3:30 PM

FROM LOH Cynthia

SUBJECT SCK3019J (INSD) > SKP5789K (TP) > SLZ1382L

BODY PROCEED DS





Re:<SEEK MANDATE> - S8M00NIS [ACCIDENT INVOLVING SCK 3019J(OI) & SKP 5789K(TP) & OTHERS ON 03/07/2018]

Type

🔍 Question

Message

TP's veh (Yr2012) > 5yrs. Mandate approved lump sum \$15000 (All in)

Reply

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Saturday, 18 August 2018 1:34 PM
To: 'lohheng0308@yahoo.com.sg'
Subject: Your Ref: SKP 5789K *Our Ref: CC4/ASM18012340/Kpb3 [ACCIDENT INVOLVING SCK 3019J(AXA) /SKP 5789K/ OTHERS ON 03/07/2018]

Your Ref: **SKP 5789K** Without Prejudice
Our Ref: CC4/ASM18012340/Kpb3

Dear Sirs,

ACCIDENT INVOLVING SCK 3019J(AXA) /SKP 5789K/ OTHERS ON 03/07/2018

We refer to the above matter.

We would like to request a copy of video footage as stated in your client accident report for our necessary action.

Appreciate an early reply.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Hsiao Tong (LKKAUTO)

From: Danny Loh <loh heng0308@yahoo.com.sg>
Sent: Monday, 17 September 2018 9:59 AM
To: Hsiao Tong (LKKAUTO)
Subject: Fw: Danny - front video accident SKP5789K Jay's cousin
Attachments: accident front 1vid.mp4

Hi Hsiao Tong, attached video clips

Sent from Yahoo Mail on Android

Hsiao Tong (LKKAUTO)

From: Danny Loh <loh heng0308@yahoo.com.sg>
Sent: Friday, 7 September 2018 2:27 PM
To: Hsiao Tong (LKKAUTO)
Subject: LOD for SKP5789K
Attachments: CCI09072018.pdf

Hi Hsiao Tong,

I forward you the LOD for SKP5789K with attachment for your perusal.

Kind regards,

Loh Heng

Danny

Hsiao Tong (LKKAUTO)

From: Danny Loh <loh heng0308@yahoo.com.sg>
Sent: Tuesday, 30 October 2018 2:00 PM
To: Hsiao Tong (LKKAUTO)
Subject: RE: LOD for SKP5789K *LKK REF: CC4/ASM18012340/Kpb3

Hi Hsiao Tong,

we accept the sum settlement offer for the case.

Thanks
Danny

Sent from Yahoo Mail on Android

On Sat, 27 Oct 2018 at 14:15, Hsiao Tong (LKKAUTO)
<chewht@lkkauto.com> wrote:

Without Prejudice

Hi Danny,

We refer to the above matter.

We have our principal instruction to offer at a global sum of **\$13,440.00(all-in)**.

Please confirm.

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Danny Loh <loh heng0308@yahoo.com.sg>

Sent: Friday, 7 September 2018 2:27 PM

To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Subject: LOD for SKP5789K

Hi Hsiao Tong,

I forward you the LOD for SKP5789K with attachment for your perusal.

Kind regards,

Loh Heng

Danny

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SCK 3019J (Insd veh)	Model:	B.M.W. 328i (A)
	SKP 5789K (TP veh)		
Date of Accident:	03/07/2018		

Global Sum Settlement	:	☐ Yes	☒ No	
Repair Estimate	:	\$		19,096.95
Final Repair Cost	:	\$		12,000.00
Loss of Use	:	\$		1,440.00
Rental (if any)	:	\$		16 days at \$90.00 per day
LTA / GIA Search Fee	:	\$		days

Others:	:	\$	
---------	---	----	--

	:	\$	
Final Settlement Sum	:	\$	13,440.00

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)			
A) For Non GIA Registered Workshop:	Agreed Liability	100	(%)
B) For GIA Registered Workshop:	BOLA Applicable: Yes/ No BOLA Scenario No:		
BOLA Liability: _____(%)	Assessed Liability (*): 100(%)		
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks			

Payment Instruction: Payee's Breakdown			
1)	LOH HENG	:	\$ 13,440.00

NUR SHAQILAH BTE ABDOL
WAHAB

22/11/2018
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CC4/ASM18012340/Kpb3s2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: CYNTHIA LOH		Date : 22-11-2018 Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SCK 3019J	Veh. Inspected	SKP 5789K
Policy No.	GA191131	Coverage (\$)	0.00
Claim No.	S8M00NIS	Excess (\$)	0.00
Assign From	CYNTHIA LOH	Assign Date	06/07/2018
2. Vehicle Particulars & Condition			
Make & Model	B.M.W. 328i (A)	c.c	1997
Engine No.	HIDDEN	Year of Reg.	2012
Chassis No.	WBA3A52030F253831	Colour	METALLIC BLACK
Odometer	104012	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/45ZR18	MICHELIN	6 mm
L/H Front Tyre	225/45ZR18	MICHELIN	6 mm
R/H Rear Tyre	225/45ZR18	MICHELIN	7 mm
L/H Rear Tyre	225/45ZR18	MICHELIN	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	03/07/2018	Inspection Date	09/07/2018
Survey held at	LOH HENG BLK 176 #03-08 SIN MING DRIVE SINGAPORE 575721		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		14 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKP 5789K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER (CONSISTENT)	BUCKLED	1,124.00	1,124.00
1	FRONT BONNET (CONSISTENT)	TO REPAIR SEE LABOUR	1,435.00	-
1	FRONT BUMPER GRILLE, RIGHT (CONSISTENT)	CRACKED	138.00	138.00
1	FRONT BUMPER GRILLE, LEFT (CONSISTENT)	DENTED	138.00	138.00
1	REAR BUMPER (CONSISTENT)	BENT	1,321.00	1,321.00
1	REAR BUMPER LOWER MOULDING CHROME (CONSISTENT)	MISSING	98.00	98.00
1	REAR BUMPER REINFORCEMENT (CONSISTENT)	BENT	457.00	457.00
1	REAR BUMPER BRACKET RETAINER LEFT (CONSISTENT)	DISTORTED	113.00	113.00
1	REAR BOOT LIB (CONSISTENT)	BENT	1,323.00	1,323.00
1	REAR LIB LOCK (CONSISTENT)	DENTED	178.00	178.00
1	REAR BOOT LIB HINGE RIGHT (CONSISTENT)	TO REPAIR SEE LABOUR	75.00	-
1	REAR BOOT LIB HINGE LEFT (CONSISTENT)	TO REPAIR SEE LABOUR	75.00	-
2	REAR BUMPER PARK SENSOR @ \$298.00 (CONSISTENT)	SHORTED	792.00	596.00
2	REAR BUMPER REFLECTOR @ \$76.00 (CONSISTENT)	MISSING	154.00	154.00
1	REAR BUMPER GARNISH CENTRAL (CONSISTENT)	MISSING	89.00	89.00
1	REAR LOWER LEFT GARNISH COVER (CONSISTENT)	MISSING	87.00	87.00
1	REAR BUMPER TOP GARNISH MOULDING (CONSISTENT)	SERVICEABLE	189.00	-
1	REAR TOW COVER COVER (CONSISTENT)	SERVICEABLE	32.00	-
2	HEAD RESTRAINT SENSOR LEFT AND RIGHT @ \$245.00 (CONSISTENT)	NO SUCH PARTS	490.00	-
1	TAIL LAMP LEFT (CONSISTENT)	CRACKED	398.00	398.00
1	TAIL PANEL GARNISH (CONSISTENT)	DENTED	187.00	187.00
1	TAIL END PANEL (CONSISTENT)	BENT	869.00	869.00
1	REAR EXHAUST SHIELD (CONSISTENT)	BENT	192.00	192.00
1	REAR EXHAUST BOX (CONSISTENT)	BENT	1,960.00	1,960.00
1	SET SENSOR HOLDER (CONSISTENT)	SERVICEABLE	154.00	-
1	EXHAUST HANGER (CONSISTENT)	TORN	59.00	59.00

Report Ref No. CC4/ASM18012340/Kpb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	EXHAUST ACTUATOR (CONSISTENT)	SERVICEABLE	378.00	-
1	SMART SESNOR CONTROL (CONSISTENT)	CRACKED	658.00	658.00
1	PDC WIRING SENSOR (CONSISTENT)	SHORTED	327.00	327.00
1	TRUCK FLOOR PANEL (CONSISTENT)	BENT / BUCKLED	1,452.00	1,452.00
1	RIGHT LOWER ARM COVER (CONSISTENT)	BUCKLED	95.00	95.00
1	LOCK SENSOR (CONSISTENT) (ADDITIONAL)	DENTED	397.00	397.00
1	FLOOR PANEL TOP COVER (CONSISTENT) (ADDITIONAL)	DEFORMED	572.00	572.00
	LESS 5% DISCOUNT		-800.30	-649.10
			15,205.70	12,332.90
1	NO. PLATE AND CASING FRONT AND REAR (FRONT) (SN) (CONSISTENT)	DENTED	110.00	45.00
1	REAR BOOT LID WEATHER STRIPE (50%) (SN) (CONSISTENT)	DISTORTED / DENTED	165.00	82.50
	LESS 5% DISOCUNT		-13.75	-
			261.25	127.50
	LABOUR			
	TO CHANGE REAR DAMAGED PARTS AND REFIX. KNOCK OUT TAIL PANEL, READJUST AND CUT AND REWELD FLOOR PANEL ETC. INCLUSIVE OF THE REPAIR OF FRONT BONNET, REAR BOOT LIB HINGE RIGHT AND REAR BOOT LIB HINGE LEFT.		2,000.00	1,800.00
	TOW TO WORKSHOP.		80.00	50.00
	TO REMOVE ALL SOCKETS, WIRING AND TESTING COMPONENTS.		200.00	150.00
	TO DO SEALANT AND RUSTPROOF ON AFFECTED AREA.		150.00	90.00
	RESPRAYING FRONT AND REAR ACCIDENT AREA.		1,200.00	1,100.00
			-	-
			-	-
			-	-
			3,630.00	3,190.00
GRAND TOTAL			19,096.95	15,650.40

Report Ref No. CC4/ASM18012340/Kpb3s2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			12,000.00
---	--	--	-----------

Report Ref No. CC4/ASM18012340/Kpb3s2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.