



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLU 8645J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER (WCP) (CONSISTENT)	DEFORMED / DENTED	960.00	960.00
1	FRT BUMPER CLAMP KIT (WCP) (CONSISTENT)	NECESSARY	45.00	45.00
1	L/F BUMPER BRACKET (WCP) (CONSISTENT)	NOT NECESSARY	13.00	-
1	MANUFACTURER BADGE (WCP) (CONSISTENT)	NECESSARY	20.00	20.00
1	R/F BUMPER BRACKET (WCP) (CONSISTENT)	NOT NECESSARY	13.00	-
	COST PLUS 15%		157.65	153.75
			1,208.65	1,178.75
SPECIAL NETT ITEMS				
1	SUNDRY PARTS (NPA) (SN) (CONSISTENT)	NOT NECESSARY	-	-
1	AUDATEX FEE (SN) (CONSISTENT)		42.00	-
			42.00	-
LABOUR				
	LABOUR: TOTAL PANEL / MECHANICAL.		67.50	67.50
	LABOUR: TOTAL PAINTWORK.		180.00	180.00
	TOTAL PAINT / MATERIAL COSTS.	NOT NECESSARY	99.01	-
			346.51	247.50
GRAND TOTAL			1,597.16	1,426.25
RECOMMENDED COST OF REPAIRS				1,426.25

Report Ref No. CC4/ASM18012342/Uea3s2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.