

ASS. REC. BY:

REF CS3/MSG18012343/G24d3e

Special Instruction:

SURVEYOR
MEMBER

Good Orange

ASSIGNMENT (Office)

From (Person):

Irene fan

of

MSG

Date/Time:

6/7/18 @ 9:32am

Estimated Cost:

Bill to:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLB 2013Y

Insured:

SG X 3592D

at Workshop m/s

Ann joo Motor

Tel:

61550747

of

Blk 176, Sin Ming Drive # 02-17

Policy No:

A288781467MP

Claim No:

563352

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

04/07/2018

CA / REV / REP. / REV 24 HRS

1up

H.O.D. Endorsement:

Date/Time:

12:49pm @ 6/7/18

Person Contacted:

Yiwen

Vehicle

IN/OUT

Date/Time	Action/Instruction	(+) Estimate
	SLB 2013Y - NA/MSG 18012186/24	DOA: 4/7/2018
	SG X 3592D - NA/MSG 18012186/24	DOA: 4/7/2018
9/7/18	dimmed.	

PK-
Kme

REF: MSIG

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Ann Joe Motor

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum-Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLB 2013Y Yr Regn: 19 Jan 2016

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota ~~Alphard~~ Alphard C.C. 2493

Colour: ~~Black~~ Black A/C: Insured / Std / NI / NA

Sp. Reading: 82269 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: AGH 30000 7277

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 235/50 R18

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIO / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. _____ D.O.I. 06-07-18

Survey held at W/S 5:20pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	\$ 5000 - \$ 6000 \$ 7000 - \$ 8000
<u>11/1/18</u>	<u>submit PRS report</u>

Date/Time, File Pass to? : Preli. Report

1) : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: 120

Transportation: 50

Add Fee: : Site Insp (\$)

: Interview (\$)

: Tech. Invs (\$)

: Weekend (\$)

) S + RS, SI

) Photos 10

) Others

TOTAL

180

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	04 Jul 2018		06 Jul 2018 09:32 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	KOH CHAI KIM , ID: S1771472D, Tel: +6597565621								
Main Claimant:	ST CARZ LEASING PTE LTD , Co. Reg. No.: 201535819E								
Vehicle Reg. No.:	SLB2013Y	Date of Loss:	04/07/2018 08:00 - :59 [29 Months and 15 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 563352	Policy/Cover Note No.:	A28878146TMP (Third Party Only) Coverage: 21/02/2018 - 20/02/2019						
Vehicle Reg. No. (Insured):	SGX3592D	Policy No. (Claimant):							
		Excess:							
Repairer:	Ann Joo Motor Pte Ltd (HQ) Blk 176 Sin Ming Drive #02-17, Singapore 575721, 575721 Sin Ming - Tel: 64510747								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 07/07/2018]								
Driver/Custodian (Insured):	QUEK BOON SING (52 / Male), NRIC: S1711605C, Tel: +6596283830								
Adj Asg. Remarks:	SJE : DISAGREED Kindly appoint LKK AUTO to conduct the survey .Please contact YIWEN @ 6455 0747 to arrange for survey . Liability : 100%								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	04 Jul 2018		06 Jul 2018 09:32 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]
Insured:	KOH CHAI KIM , ID: S1771472D, Tel: +6597565621	
Main Claimant:	ST CARZ LEASING PTE LTD , Co. Reg. No.: 201535819E	
Vehicle Reg. No.:	SLB2013Y	Date of Loss: 04/07/2018 08:00 - :59 [29 Months and 15 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 563352	Policy/Cover Note No.: A28878146TMP (Third Party Only) Coverage: 21/02/2018 - 20/02/2019
Vehicle Reg. No. (Insured):	SGX3592D	Policy No. (Claimant): Excess:
Repairer:	Ann Joo Motor Pte Ltd (HQ) Blk 176 Sin Ming Drive #02-17, Singapore 575721, 575721 Sin Ming - Tel: 64510747	
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Imm.Advice due 07/07/2018]	
Driver/Custodian (Insured):	QUEK BOON SING (52 / Male), NRIC: S1711605C, Tel: +6596283830	
Adj Asg. Remarks:	SJE : DISAGREED Kindly appoint LKK AUTO to conduct the survey .Please contact YIWEN @ 6455 0747 to arrange for survey . Liability : 100%	

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

Claim Documents

*SLB2013Y (563352)
 [SGX3592D]
 TP
 ST CARZ LEASING PTE LTD
 Jul 4 2018 8:00AM
 [KOH CHAI KIM]
 Ann Joo Motor Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		View	View in Browser <input type="checkbox"/>	
Assessment Reports							1 per page <input type="checkbox"/>	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)				Thumbnail	Print	
1	05/07/18 14:14	Accident Statement From: SC - Reg. No: SGX3592D, Claimant: KOH CHAI KIM				 Load HTM	<input type="checkbox"/>	
Photos/Images							3 per page <input type="checkbox"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)				Thumbnail	Print	
1	11/07/18 19:39	General View				 Load JPG	<input checked="" type="checkbox"/>	
2	11/07/18 19:39	General View				 Load JPG	<input checked="" type="checkbox"/>	
3	11/07/18 19:39	General View				 Load JPG	<input checked="" type="checkbox"/>	
4	11/07/18 19:39	General View				 Load JPG	<input checked="" type="checkbox"/>	
5	11/07/18 19:39	General View				 Load JPG	<input checked="" type="checkbox"/>	
6	11/07/18 19:39	General View				 Load JPG	<input checked="" type="checkbox"/>	
7	11/07/18 19:39	General View				 Load JPG	<input checked="" type="checkbox"/>	
8	11/07/18 19:39	General View				 Load JPG	<input checked="" type="checkbox"/>	
9	11/07/18 19:39	General View				 Load JPG	<input checked="" type="checkbox"/>	
10	11/07/18 19:39	General View				 Load JPG	<input checked="" type="checkbox"/>	
11	11/07/18 19:40	General View				 Load JPG	<input checked="" type="checkbox"/>	
12	11/07/18 19:40	General View				 Load JPG	<input checked="" type="checkbox"/>	
13	11/07/18 19:40	General View				 Load JPG	<input checked="" type="checkbox"/>	
14	11/07/18 19:40	General View				 Load JPG	<input checked="" type="checkbox"/>	
15	11/07/18 19:40	General View				 Load JPG	<input checked="" type="checkbox"/>	
16	11/07/18 19:40	General View				 Load JPG	<input checked="" type="checkbox"/>	
17	11/07/18 19:40	General View				 Load JPG	<input checked="" type="checkbox"/>	
18	11/07/18 19:40	General View				 Load JPG	<input checked="" type="checkbox"/>	
19	11/07/18 19:40	General View				 Load JPG	<input checked="" type="checkbox"/>	
20	11/07/18 19:40	General View				 Load JPG	<input checked="" type="checkbox"/>	
21	11/07/18 19:40	General View				 Load JPG	<input checked="" type="checkbox"/>	
22	11/07/18 19:40	General View				 Load JPG	<input checked="" type="checkbox"/>	
23	11/07/18 19:40	General View				 Load JPG	<input checked="" type="checkbox"/>	
24	11/07/18 19:40	General View				 Load JPG	<input checked="" type="checkbox"/>	
25	11/07/18 19:40	General View				 Load JPG	<input checked="" type="checkbox"/>	
26	11/07/18 19:40	General View				 Load JPG	<input checked="" type="checkbox"/>	
27	11/07/18 19:40	General View				 Load JPG	<input checked="" type="checkbox"/>	
28	11/07/18 19:40	General View				 Load JPG	<input checked="" type="checkbox"/>	
29	11/07/18 19:40	General View				 Load JPG	<input checked="" type="checkbox"/>	
30	11/07/18 19:40	General View				 Load JPG	<input checked="" type="checkbox"/>	
31	11/07/18 19:40	General View				 Load JPG	<input checked="" type="checkbox"/>	
32	11/07/18 19:40	General View				 Load JPG	<input checked="" type="checkbox"/>	
33	11/07/18 19:40	General View				 Load JPG	<input checked="" type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
34	11/07/18 19:40	General View	 Load JPG	<input checked="" type="checkbox"/>
35	11/07/18 19:40	General View	 Load JPG	<input checked="" type="checkbox"/>
36	11/07/18 19:40	General View	 Load JPG	<input checked="" type="checkbox"/>
37	11/07/18 19:40	General View	 Load JPG	<input checked="" type="checkbox"/>
38	11/07/18 19:40	General View	 Load JPG	<input checked="" type="checkbox"/>
39	11/07/18 19:40	General View	 Load JPG	<input checked="" type="checkbox"/>
40	11/07/18 19:40	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
41	11/07/18 19:40	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
42	11/07/18 19:40	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
43	11/07/18 19:40	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
44	11/07/18 19:40	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
45	11/07/18 19:40	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
46	11/07/18 19:40	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
47	11/07/18 19:40	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
48	11/07/18 19:40	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
49	11/07/18 19:40	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
50	11/07/18 19:40	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
51	11/07/18 19:40	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
52	11/07/18 19:40	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
53	11/07/18 19:40	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
54	11/07/18 19:40	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
55	11/07/18 19:40	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
56	11/07/18 19:40	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
57	11/07/18 19:40	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
58	11/07/18 19:40	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
59	11/07/18 19:40	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
60	11/07/18 19:40	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
61	11/07/18 19:40	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
62	11/07/18 19:40	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
63	11/07/18 19:40	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
64	11/07/18 19:40	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
65	11/07/18 19:40	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
66	11/07/18 19:40	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
67	11/07/18 19:40	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
68	11/07/18 19:40	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
69	11/07/18 19:40	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
70	11/07/18 19:40	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
71	11/07/18 19:40	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
72	11/07/18 19:40	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
73	11/07/18 19:40	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
74	11/07/18 19:40	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
75	11/07/18 19:40	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
76	11/07/18 19:40	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
77	11/07/18 19:40	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
78	11/07/18 19:40	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
79	11/07/18 19:40	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
80	11/07/18 19:40	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
81	11/07/18 19:40	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
82	11/07/18 19:40	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
83	11/07/18 19:40	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
84	11/07/18 19:40	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
85	11/07/18 19:40	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
86	11/07/18 19:40	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
87	11/07/18 19:40	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
88	11/07/18 19:40	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
89	11/07/18 19:40	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
90	11/07/18 19:40	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
91	11/07/18 19:40	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
92	11/07/18 19:40	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
93	11/07/18 19:40	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
94	11/07/18 19:40	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
95	11/07/18 19:40	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
96	11/07/18 19:40	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
97	11/07/18 19:40	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
98	11/07/18 19:40	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
99	11/07/18 19:40	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
100	11/07/18 19:40	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
101	11/07/18 19:40	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
102	11/07/18 19:40	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
103	11/07/18 19:40	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
104	11/07/18 19:40	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	05/07/18 14:14	TPD SLB2013Y GIA REPORT <small>From: SC - Reg. No: SGX3592D, Claimant: KOH CHAI KIM</small>	Load PDF	
2	05/07/18 14:15	TPD SLB2013Y - SURVEY LISITING	Load PDF	
3	05/07/18 14:15	FAX FOR REJECT TPD SURVEY NAME LISTING - SLB2013Y	Load PDF	
4	05/07/18 16:59	TPD SLB2013Y - PRI	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18012343/GZ4D3E2

Date: 12/07/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No: A28878146TMP
Claimant Vehicle No : SLB2013Y	Insured Vehicle No : SGX3592D
Date of Loss: 04/07/2018	Nature of Claim: TP
	Claim No: 563352

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLB2013Y		
Make & Model:	TOYOTA ALPHARD, 2.5 S CVT ABS D/AIRBAG 2WD 5DR (A)	Engine No:	2ARH541679
Reg. Date:	19/01/2016 (Man. Year: 2015)	Chassis No:	AGH300007277
Colour:	Black	Odometer:	82269 km
Engine Capacity:	2493 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/50 R18	Rear Tyre Size:	235/50 R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	06/07/2018	
Date Inspected:	06/07/2018 Inspected At:	Ann Joo Motor Pte Ltd (HQ) Blk 176 Sin Ming Drive #02-17, Singapore 575721 Singapore 575721
Estimated Period of Repair:	0.0 days	

Adjuster: XING GUO QIANG**Manager:** Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$7,000.00 -\$8,000.00

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 Jul 2018)
Parts:	M1-MPV	TOYOTA ALPHARD 2.5 S CVT ABS D/AIRBAG 2WD 5DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLB2013Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >