

ASS. REC. BY:

REF:

CS3/IC818012366/G24d367

Special Instruction:

Surveyor

MURIMEN

ASSIGNMENT (Office)

From (Person):

Jenice Goh

of

ECICS

Date/Time:

6/7/18 @ 3:08pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBG 9505R

Insured:

GBA 3962A

at Workshop m/s

Motor Intel

Tel:

G2810087

of

13 Kaki Bukit Rd 4 # 01-20

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

D.O.A.

05/07/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

1up

117/18

H.O.D. Endorsement:

Date/Time:

4:10pm @ 6/7/18

Person Contacted:

Tinnie

Vehicle IN / OUT

Date/Time	Action/Instruction (X) Estimate
	GBG 9505R - X
	GBA 3962A - CCG / AIG 10023557 / Ujpdq2 DOA: 19/11/2010
9/7/18	Dismantled
13/7/18	After repair

(08/11/13) wef

ASS. REC. BY: XBL

REF:

JCS

## ASSIGNMENT

From: \_\_\_\_\_ Date: 9/7/2018

Estimated Cost: \_\_\_\_\_

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: GBG 9505Dat Workshop m/s Motor Intel  
of 13 kaki Bukit Rd 4 #01-20

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_


Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: wilson @ 8838 3318

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or NoCA / REV / REP. / 24 HRS up

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: GBG 9505D Regn: 14 Dec 2017

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Dyna 150cc 2982Colour: silver A/C: Insured / Std / NI / NASp. Reading: 19192 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JTFAT35Y 90K 209454Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: ☒ M / S/Rim / STD A/Rim orTyre Size: F: 195/75 R15R: 155 R12☒ BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mmL/Bal. 6 mm

D.O.A. \_\_\_\_\_

Rear

R/Bal. 6 mmL/Bal. 6 mmD.O.I. 09-07-18Survey held at W/SDes. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

\$3000 - \$4000.13/7/18 submit PRS report

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Report Format : \_\_\_\_\_

Lump Sum / I.B.I.: (\$ \_\_\_\_\_)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee:

☐ : Site Insp (\$ \_\_\_\_\_)☐ : Interview (\$ \_\_\_\_\_)☐ : Tech. Invs (\$ \_\_\_\_\_)☐ : Weekend (\$ \_\_\_\_\_)

Survey Fee:

Transportation:

\_\_\_\_ S + RS \_\_\_\_ SI

Photos

Others

TOTAL

100100+10010210

## Nivitha (LKK Auto)

---

**From:** ECICS Claims <claims@ecics.com.sg>  
**Sent:** Friday, 6 July 2018 3:08 PM  
**To:** Sales MIA; assignments@lkkauto.com  
**Cc:** ECICS Claims  
**Subject:** RE: OUR REF : TD GBG9505R ( MIA ) PRE-REPAIR SURVEY REQUEST & YOUR REF : GBA3962A  
**Attachments:** GBG9505R PRI.PDF

Dear Tinie

Thank you for your email.  
We will appoint LKK for the PRS.

Aside to LKK

Please assist to arrange TP PRS.

Thank you.

Regards,  
Janice Goh  
**Claims Division**  
DID: +65 6303 0182  
FAX: +65 6338 9267

**ECICS Limited**  
7 Temasek Boulevard, #10-01 Suntec Tower One, Singapore 038987

**WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to [motorsurvey@ecics.com.sg](mailto:motorsurvey@ecics.com.sg) directly.**

***\*\*Please bear with us should we take longer to response as we are currently experiencing a high volume of claims. Thank you for your kind patience and understanding.\*\****

**From:** Sales MIA [mailto:sales@mia.com.sg]  
**Sent:** Friday, 6 July, 2018 12:27 PM  
**To:** ECICS Claims  
**Subject:** OUR REF : TD GBG9505R ( MIA ) PRE-REPAIR SURVEY REQUEST & YOUR REF : GBA3962A

Without Prejudice

Dear Sir / Mdm ,

We refer to the above matter.

Please find enclosed documents for your necessary action.

Kindly assist to arrange the Pre-Repair Survey as per attachment details.

Thks & Regards  
Tinie  
Motor Intel Automo Pte Ltd

This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.



## Motor Intel Automo Pte. Ltd.

13 Kaki Bukit Road 4 @ Bartley Biz Centre

#01-20 Singapore 147807

Tel: 6281-0087 Fax: 6281-0187

Our Ref : TD GBG9505R ( MIA )

Your Ref : VEHICLE GBA3962A

Date: 06 JULY 2018

ECICS LIMITED

Email : claims@ecics.com.sg

Attn: Motor Claims Department

Dear Sirs,

**ACCIDENT INVOLVING** GBG9505R & GBA3962A AT CTE TOWARDS AYE ( BEFORE BRADDELL EXIT ) ON 05/072018 @ 1015HOURS

(NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 6.2 OF PRE-ACTION PROTOCOL FOR NIMA CASES)

We act for YONG XIN (2008 ) CONSTRUCTION PTE LTD who has appointed the undermentioned workshop to repair his/her motor vehicle no. GBG9505R.

Please be informed that the said vehicle can be inspected at:

Name : Motor Intel Automo Pte Ltd  
Address : Bartley Biz Centre  
13 Kaki Bukit Road 4 #01-20  
Singapore 417807  
Person to contact : Mr Wilson Ong  
Tel : 6281 0087 / 8838 3318

If you failed to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully



Motor Intel Automo Pte. Ltd.  
Email : sales@mia.com.sg

For Surveyor  
Please initial here after completion  
of pre-repair inspection. Thank you.

Appointed surveyor :  
(Name & Signature)

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	05/07/2018 17:03
Date Of Accident	05/07/2018 10:15
Exact Location Of Accident	CTE TOWARDS AYE(BEFORE BRADELL EXIT)
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBG9505R
<b>Insured/Policyholder</b>	
Name Of Registered Owner	YONG XIN (2008) CONSTRUCTION PTE LTD
Co Reg No	201100248N
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90275218
Alternative Phone No	OFFICE-90275218

### Vehicle Particulars

Manufacturer	TOYOTA
Model	DYNA 1.5T-3.0 (M)
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5096678193
Cover Note Number	PREFERRED WORKSHOP PLAN

### Driver

Name of Driver	YANG GUOXIN
NRIC No	S2751196A
Date Of Birth	18/09/1965
Occupation	OUTDOOR
Date Of Driving Pass	10/10/2016
Driving Experience	1 YEAR AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96275218
Fax Number	
Contact Number	
Email Address	YANG96418353@GMAIL.COM

Address	BLK 312 SEMBAWANG DRIVE #10-490
Postcode	750312
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	5
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : YANG YONG GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	EUNOS NEIGHBOURHOOD POLICE POST
Police Station Address	ROAD: BLK 629 BEDOK RESERVOIR ROAD #01-1620 , POSTCODE: 470629 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-4439999 - FAX NO: 62444376
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

AS PER POLICE REPORT No.T/20180705/2057.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBA3962A
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	

Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number GN8588L  
Vehicle Make/Model/Colour  
Details Of Properties  
Vehicle Category COMMERCIAL VEHICLE  
Name of Driver  
NRIC/Passport Number  
Contact Number  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

#### DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number GY4135D  
Vehicle Make/Model/Colour  
Details Of Properties  
Vehicle Category COMMERCIAL VEHICLE  
Name of Driver  
NRIC/Passport Number  
Contact Number  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

#### DETAILS OF OTHER VEHICLE PROPERTY 4

Vehicle Registration Number YP1820M  
Vehicle Make/Model/Colour  
Details Of Properties  
Vehicle Category COMMERCIAL VEHICLE  
Name of Driver  
NRIC/Passport Number  
Contact Number  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

#### DETAILS OF INJURED PERSON 1

Name •YANG YONG  
Approximate Age  
Injuries Sustain  
Injured person in which vehicle? GBG9505R  
Were seat belts worn? YES  
Was this injured conveyed to hospital by ambulance? NO



Address  
Postcode

BLK 312 SEMBAWANG DRIVE #10-490  
750312

# Accident Sketch Plan Pg. 1



**SINGAPORE  
POLICE FORCE**



T/20180705/2057

Police Station Of Origin:  
Eunos NPP  
629 Bedok Reservoir Road #01-1620  
SINGAPORE 470629  
Tel No: 1800-4439999

1 of 4

Report No. T/20180705/2057

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 05/07/2018 12:54		Vide Report No.: F/20180705/0102		Station Diary No.: 15	
<b>Informant's Particulars</b>					
Name of Informant: YANG GUOXIN			Address: APT BLK 312 SEMBAWANG DRIVE #16-490 SINGAPORE 750312		
ID Type / ID No.: NRIC NO / S2751196A			Contact No.: Home/Office: Mobile: 96275218		
Nationality: CHINESE			Email:		
Sex: Male	Age: 52	Date of Birth: 18/09/1965	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: Self-Employed			Driving Licence Information: Class: 3 Date of Expiry:		

## General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 05/07/2018 10:10	Type of Location: Bend
Location: Along Road 1 CENTRAL EXPRESSWAY				
CTE towards AYE (Before Bradell Exit) at PIE Exit (Changi)				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: Yes

## Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBA3962A	Van	TOYOTA	Hiace Manual	Silver	Seriously Damaged	1
GBG9505R	Lorry	TOYOTA	Dyna	Silver	Slightly Damaged	2
GN8588L	Van	TOYOTA	Hiace Diesel	Green	Seriously Damaged	5
GY4135D	Lorry	ISUZU		Blue	Seriously Damaged	1
YP1820M	Lorry	ISUZU		White	Slightly Damaged	1



**SINGAPORE  
POLICE FORCE**



T/20180705/2057

Police Station Of Origin:  
Eunos NPP  
629 Bedok Reservoir Road #01-1620  
SINGAPORE 470629  
Tel No: 1800-4439999

2 of 4

Report No. T/20180705/2057

**CONTINUATION OF REPORT**

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No.	Effective	Expiry Date
GBG9505R	NTUC Income Insurance Co-Operative Limited			

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	YANG GUOXIN	ID No.	S2751196A
Related Vehicle	GBG9505R (Lorry)	Contact No.	96275218
Hospital/Clinic	NIL	Glass of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Passenger			
Name	Yang Yong	ID No.	S8874788G
Related Vehicle	GBG9505R (Lorry)	Contact No.	96418353
Hospital/Clinic	NIL	Glass of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	Slight

**Brief Details.**

On 05/07/2018 at about 10:10am, I was driving my company lorry bearing registration number GBG9505R along CTE (towards AYE before Bradell Road), along the lane to PIE (Changi) exit with a heavy and slow-moving traffic. Just before exiting the CTE, my lorry was hit from behind and heard a loud sound. I stopped my vehicle and my front seat passenger who is my son namely Yang Yong told me that he felt pain on his back due to the impact. I got out of my vehicle to make a check as it felt as though something had dropped onto my lorry as the impact felt very strong.

One silver van bearing registration number GBA3962A had collided head on to the rear of my lorry, and there was a chain collision involving 5 vehicles. Behind the silver van is another metallic green van bearing registration number GN8588L, and the next vehicle is one blue lorry GY4135D. The last vehicle in the collision is one white big lorry bearing registration number YP1820M. I am not sure exactly what had happened and no witness came forward. The damages to my lorry were badly dented and the other 3 vehicles were also very badly damaged front and rear. There is no in-vehicle camera in my lorry and I did not noticed any CCTV at the said location.



**SINGAPORE  
POLICE FORCE**



T/20180705/2057

Police Station Of Origin:

Eunos NPP

629 Bedok Reservoir Road #01-1620

SINGAPORE 470629

Tel No: 1800-4439999

3 of 4

Report No. T/20180705/2057

**CONTINUATION OF REPORT**

The two said vans and the blue lorry were damaged badly. Subsequently ambulance and police came to scene. My passenger was conveyed to Tan Tock Seng Hospital in an ambulance. The driver from van GBA3962A, the driver and a few passengers from van GN8588L and the driver of blue lorry GY4135D were conveyed. Emas towing crews came and towed away the two vans and blue lorry. Traffic Police officers were at scene and gave me a Traffic Police Case Card and told me to lodge a traffic police report. I do not feel any injury at the moment however I am still feeling shocked about what had happened.

[➤ Back to OneMotoring](#)

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	0248N
Vehicle Details	
Vehicle No.:	GBG9505R
Vehicle to be Exported:	No
Intended De-registration Date:	12 Jul 2019
Vehicle Make:	TOYOTA
Vehicle Model:	DYNA 150 5MT
Primary Colour:	Silver
Manufacturing Year:	2017
Engine No.:	1KD2762746
Chassis No.:	JTFAT35Y90K209454
Maximum Power Output:	-
Open Market Value:	\$27,084.00
Original Registration Date:	14 Dec 2017
First Registration Date:	14 Dec 2017
Transfer Count:	0
Actual ARF Paid:	\$1,355.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	13 Dec 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$41,918.00
COE Rebate Amount:	\$35,292.00
<b>Total Rebate Amount:</b>	<b>\$35,292.00</b>

The information contained herein is correct as at 12 Jul 2018

OK

### ...CLAIM SUBFOLDER...(Pending for Survey Report)






































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	16 Jul 2018 08:35 <a href="#">Edit Reg</a>		06 Jul 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured: -, Co. Reg. No.: -, Email: EMAIL@EMAIL.COM									
Main Claimant: <b>YONG XIN (2008) CONSTRUCTION PTE LTD</b> , Co. Reg. No.: 201100248N									
Vehicle Reg. No.: <b>GBG9505R</b>		Date of Loss: 05/07/2018 10:00 - :59 [6 Months and 21 Days From LTA Reg Date (Man Yr)]							
Claim Type: <b>TP</b>		Policy/Cover Note No.:							
Vehicle Reg. No. (Insured): <b>GBA3962A</b>		Policy No. (Claimant):							
		Excess:							
Repairer: <b>Motor Intel Automo Pte Ltd - Kaki Bukit (HQ)</b> 13 Kaki Bukit Road 4, #01-20 Bartley Biz Centre, 417807 Kaki Bukit - Tel:									
Handling Insurer: <b>ECICS Limited (HQ)</b> - Tel: 63374779 /6303 0178									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>XING GUO QIANG</b> ] ... <b>[Final Rpt due 23/07/2018]</b>									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*GBG9505R  
[GBA3962A]  
TP  
YONG XIN (2008) CONSTRUCTION PTE LTD  
Jul 5 2018 10:00AM  
[-]  
Motor Intel Automo Pte Ltd - Kaki Bukit

<a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a>			<b>View</b> <a href="#">View in Browser</a>	
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	13/07/18 11:48	General View	 Load JPG	<input checked="" type="checkbox"/>
2	13/07/18 11:48	General View	 Load JPG	<input checked="" type="checkbox"/>
3	13/07/18 11:48	General View	 Load JPG	<input checked="" type="checkbox"/>
4	13/07/18 11:48	General View	 Load JPG	<input checked="" type="checkbox"/>
5	13/07/18 11:48	General View	 Load JPG	<input checked="" type="checkbox"/>
6	13/07/18 11:48	General View	 Load JPG	<input checked="" type="checkbox"/>
7	13/07/18 11:48	General View	 Load JPG	<input checked="" type="checkbox"/>
8	13/07/18 11:48	General View	 Load JPG	<input checked="" type="checkbox"/>
9	13/07/18 11:48	General View	 Load JPG	<input checked="" type="checkbox"/>
10	13/07/18 11:48	General View	 Load JPG	<input checked="" type="checkbox"/>
11	13/07/18 11:48	General View	 Load JPG	<input checked="" type="checkbox"/>
12	13/07/18 11:48	General View	 Load JPG	<input checked="" type="checkbox"/>
13	13/07/18 11:48	General View	 Load JPG	<input checked="" type="checkbox"/>
14	13/07/18 11:48	General View	 Load JPG	<input checked="" type="checkbox"/>
15	13/07/18 11:48	General View	 Load JPG	<input checked="" type="checkbox"/>
16	13/07/18 11:48	General View	 Load JPG	<input checked="" type="checkbox"/>
17	13/07/18 11:48	General View	 Load JPG	<input checked="" type="checkbox"/>
18	13/07/18 11:48	General View	 Load JPG	<input checked="" type="checkbox"/>
19	13/07/18 11:48	General View	 Load JPG	<input checked="" type="checkbox"/>
20	13/07/18 11:48	General View	 Load JPG	<input checked="" type="checkbox"/>
21	13/07/18 11:48	General View	 Load JPG	<input checked="" type="checkbox"/>
22	13/07/18 11:48	General View	 Load JPG	<input checked="" type="checkbox"/>
23	13/07/18 11:48	General View	 Load JPG	<input checked="" type="checkbox"/>
24	13/07/18 11:48	General View	 Load JPG	<input checked="" type="checkbox"/>
25	13/07/18 11:48	General View	 Load JPG	<input checked="" type="checkbox"/>
26	13/07/18 11:48	General View	 Load JPG	<input checked="" type="checkbox"/>
27	13/07/18 11:48	General View	 Load JPG	<input checked="" type="checkbox"/>
28	13/07/18 11:48	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
29	13/07/18 11:48	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
30	13/07/18 11:48	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
31	13/07/18 11:48	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
32	13/07/18 11:48	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
33	13/07/18 11:48	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
34	13/07/18 11:48	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
35	13/07/18 11:48	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
36	13/07/18 11:48	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
37	13/07/18 11:48	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	14/07/18 21:09	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
39	14/07/18 21:09	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
40	14/07/18 21:09	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
41	14/07/18 21:09	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
42	14/07/18 21:09	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
43	14/07/18 21:09	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
44	14/07/18 21:09	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
45	14/07/18 21:09	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
46	14/07/18 21:09	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
47	14/07/18 21:09	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
48	14/07/18 21:09	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
49	14/07/18 21:09	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:

☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.



## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/ICS18012366/GZ4D3E2

Date: 17/07/2018

## REFERENCE

Handling Insurer: ECICS Limited

Policy No:

Claimant Vehicle No : GBG9505R

Insured Vehicle No :

GBA3962A

Date of Loss: 05/07/2018

Nature of Claim:

TP

Claim No:

N/A

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: GBG9505R

Make &amp; Model: TOYOTA DYNA 150, 3.0 D (M)

Engine No: 1KD2762746

Reg. Date: 14/12/2017 (Man. Year: 2017)

Chassis No: JTFAT35Y90K209454

Colour: Silver

Odometer: 19192 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 195/75 R15

Rear Tyre Size:

155 R12

Front Left Side: Bridgestone 6 mm

Rear Left Side:

Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side:

Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 06/07/2018

Date Inspected: 09/07/2018 Inspected At:

Motor Intel Automo Pte Ltd - Kaki Bukit (HQ)

13 Kaki Bukit Road 4, #01-20 Bartley Biz Centre

Singapore 417807

Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000.00 -\$4,000.00

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 16 Jul 2018)	
<b>Parts:</b>	N/A	TOYOTA DYNA 150 3.0 D (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBG9505R)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >