

Survivor

CWS

Kenneth

ASSIGNMENT (Office)

From (Person)

Kuren Tan

of

FCI

Date/Time

6/7/18 @ 4:34pm

Estimated Cost

Bill to

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.

SLU 4780C

Insured:

SHC 8046E

at Workshop in/

Hui Yang Motor

Tel:

64515752

of

Blk 176 Sin Ming Drive # 04-02

Policy No.

Claim No.

DI800 5228 MPST

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

04/07/2018

CA / REV / REP. / REV 24 HRS (DS)

H.O.D. Endorsement

Date/Time:

9:09am @ 9/7/18

Person Contacted:

Belle

Vehicle (IN) OUT

Date/Time

Action/Instruction (✓) Estimate

SLU 4780C-X

SHC8046E- cs/FCI17011237/MHbn2

DOA: 5/6/2017

10/7/18

Revert via email preli

16/10

11 Lm 8 good email & call from (Red. 6067.71, 42%)

ASS. REC. BY:

REF: FC21

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

QD / TP / WS / TP RES / QD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: \$106k

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 10 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLU 47806 Yr Regn: 12, 17

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Toy CHA c.c. 1797

Colour: M. D. Gray A/C: Insured / Std / NI / NA

Sp. Reading: 61250 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 24X10 2074016

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal. 3 mm

L/Bal. 3 mm

D.O.A. 6/7/18

Rear

R/Bal. 3 mm

L/Bal. 3 mm

D.O.I. 6/7/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

9/7 File pass to Catherine

RECEIVED 19 OCT 2018

Date/Time, File Pass to?

1) 19/10 Typist

Date/Time, File Return to?

2)

☐: Prell. Report
☒: Final Report

Days Of Repair: 10

Resurvey No. of Trip: 1+1

Survey Fee:

Transportation:

S + RS \$1

Fees

Others

TOTAL

Add Fee: ☐: Site Insp (\$)☐: Interview (\$)☐: Tech Invs (\$)☐: Weekend (\$)

Report Format: TP

Lump Sum / I.B.I. (\$)

81007-

4x15=60

170+60

50

50+50

33

413

MOTOR SURVEY ASSIGNMENT

Date	05-07-2018	Our Ref No. D18005228MFSH
Accident Date	04-07-2018	Claim Type. Third Party
Insured Vehicle	SHC8046E	Third Party Vehicle. SLU4780C
Survey Location	BLK 176 SIN MING DRIVE #04-02 SIN MING AUTOCARE	
Contact Person.	BEL	
Contact No.	64515752/ 90473466	Fax No. 64514658
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	HUI YANG MOTOR PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/242111)



PRI Documents



Close



PRI Header Details

Claim No	D18005228MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & HUI YANG
Workshop Name	HUI YANG MOTOR PTE LTD (Contact Person : BEL)	Survey Location & Contact Details	BLK 176 SIN MING DRIVE #04-02 SIN MING AUTOCARE Mobile: 90473466 , Phone: 64515752 , Fax: 64514651 EmailId: HUI_YANG_MOTOR@HOTMAIL.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHC8046E	TP Vehicle No	SLU4780C
PRI Recieved Date	05-07-2018 09:43:12 PM	Surveyor Appointed Date	06-07-2018 04:33:25 PM	Surveyor Accept Date	09-07-2018 1

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	09-07-2018	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18012406/Ktd3

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 09-07-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 8046E	Veh. Inspected	SLU 4780C
Policy No.		Coverage (\$)	0.00
Claim No.	D18005228MFSH	Excess (\$)	0.00
Assign From	CWS (KAREN TAN)	Assign Date	09/07/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	04/07/2018	Inspection Date	06/07/2018
Survey held at	HUI YANG MOTOR PTE LTD BLOCK 176 SIN MING DRIVE #04-02 SIN MING AUTOCARE SINGAPORE 575721		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18005228MFSH

Date: 10/7/2018

Our Ref: CS/FCI18012406/Ktd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLU 4780C

Please be informed that we had conducted the inspection of the abovementioned vehicle 6/7/2018 at the premises of M/s Hui Yang and have the following to report: -

Workshop Estimate Amount	: <u>S\$ 14,167.71</u>
Revised Estimate Amount	: <u>S\$ 9,734.26</u>
"Check" Items Amount	: <u>S\$ 3,088.59</u>
LTA Reimbursement Value	: <u>S\$</u>
Nett Value	: <u>S\$</u>

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/ Present Status:

Damages Consistent.

Yours faithfully

Kennth

Automotive Assessor

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Tuesday, 10 July 2018 4:36 PM
To: Admin-D (LKKAUTO); 'Claim Workflow System'; assignments
Cc: KARENTAN@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18005228MFSH/1
Attachments: PRELI ADVISED SLU 4780C.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SLU 4780C**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Monday, 9 July 2018 10:01 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: KARENTAN@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18005228MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Friday, 6 July 2018 4:34 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; KARENTAN@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18005228MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team
Claim Workflow System

輝陽汽車有限公司

HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

Reg No. 201629438M

04/07/2018

Owner: FAVORIDE PTE LTD

ESTIMATE TO REPAIR TOYOTA C-HR 1.8 - SLU4780C

1pc	rear tailgate	Bj	\$	981.45	✓
1pc	rear tailgate outer garnish	Mjmr	\$	882.20	✓
1pc	rear tailgate "C-HR" emblem	ru	\$	83.20	—
1pc	rear tailgate "HYBRID" emblem	ru	\$	71.00	—
1pc	rear tailgate "TOYOTA" logo	ru	\$	68.80	—
2pcs	rear tailgate refector @\$353.50	lu	\$	707.00	✓
1pc	rear tailgate inner lock	nu	\$	374.45	✓
1pc	rear tailgate inner rubber	Dis/nu	\$	374.85	✓
1pc	rear tailgate inner garnish	lu	\$	588.85	✗
2pcs	rear taillamp @\$374.50	lu	\$	749.00	✗
2pcs	rear taillamp lower bracket @\$171.45	ru	\$	342.90	✗
1pc	rear bumper	Bj	\$	972.45	✓
2pcs	rear bumper side retainer @\$141.45	nu	\$	282.90	—
2pcs	rear bumper refector @\$172.25	lu	\$	344.50	✗
2pcs	rear bumper refector garnish @\$281.90	nu lu ru	\$	563.80	✓
1pc	rear bumper diffuser	nu	\$	581.45	—
8pcs	rear bumper diffuser clip @\$5.50	ru	\$	44.00	—
1pc	rear bumper diffuser centre cover	nu	\$	74.85	✓
1pc	rear bumper reinforcement	Bj	\$	782.10	✓
1pc	rear end panel	Bj	\$	781.45	✓
1pc	rear end panel inner garnish	Bu	\$	378.85	✓
1pc	rear floor panel	Bu/Bu	\$	785.85	✓
1pc	rear floor panel sponge	CM	\$	285.85	✓
1pc	rear exhaust box 1592.70	Bj	\$	1,850.00	✓
1pc	rear exhaust box top cover	Bj	\$	181.50	✓
3pcs	rear exhaust mounting @\$58.50	ru	\$	175.50	✓
2pcs	rear fender protector @\$258.85	nu/ru	\$	517.70	✓
1pc	rear LH lower arm	lu	\$	485.58	✗
1pc	rear LH absorber	lu	\$	450.25	✗
				\$14,762.28	
	less 25%			\$ 3,690.57	
	balance c/f			\$11,071.71	



1st first cop
2K
Not Author
1/1/18 @ 8100h
Resony After Rain
10 days

輝 陽 汽 車 有 限 公 司

HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

Reg No. 201629438M

04/07/2018

Owner: FAVORIDE PTE LTD

ESTIMATE TO REPAIR TOYOTA C-HR 1.8 - SLU4780C

	balance b/f			\$ 11,071.71
1pc	rear end panel outer sensor	nett	\$ 240.00	X
			\$ 240.00	
	less 10%		\$ 24.00	
			\$ 216.00	
1set	parking sensor	N/P s.nett	\$ 280.00	X
	remove & refit rear windscreen glass		\$ 120.00	✓
	sealant		\$ 80.00	405m
	wiring		\$ 80.00	201
	tuffkote		\$ 120.00	901
	spray painting		\$ 1,000.00	90d
	labour charges		\$ 1,200.00	110d
	Total		\$ 14,167.71	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18012406/Ktd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 24-10-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 8046E	Veh. Inspected	SLU 4780C	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18005228MFSH	Excess (\$)	0.00	
Assign From	KARENT	Assign Date	06/07/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA C-HR (A)	c.c	1797	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	ZYX102074016	Colour	METALLID DARK GREY	
Odometer	61250	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R17	DUNLOP	3 mm	
L/H Front Tyre	215/60 R17	DUNLOP	3 mm	
R/H Rear Tyre	215/60 R17	DUNLOP	3 mm	
L/H Rear Tyre	215/60 R17	DUNLOP	3 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	04/07/2018	Inspection Date	06/07/2018	
Survey held at	HUI YANG MOTOR PTE LTD BLOCK 176 SIN MING DRIVE #04-02 SIN MING AUTOCARE SINGAPORE 575721			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		10 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLU 4780C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR TAILGATE	BENT	981.45	981.45
1	REAR TAILGATE OUTER GARNISH	MTG CRACKED	882.20	882.20
1	REAR TAILGATE "C-HR" EMBLEM	NECESSARY	83.20	83.20
1	REAR TAILGATE "HYBRID" EMBLEM	NECESSARY	71.00	71.00
1	REAR TAILGATE "TOYOTA" LOGO	NECESSARY	68.80	68.80
2	REAR TAILGATE REFLECTOR @\$353.50	SERVICEABLE	707.00	-
1	REAR TAILGATE INNER LOCK	DENTED	374.45	374.45
1	REAR TAILGATE INNER RUBBER	DISTORTED / DENTED	374.85	374.85
1	REAR TAILGATE INNER GARNISH	SERVICEABLE	588.85	-
2	REAR TAILLAMP @\$374.50	SERVICEABLE	749.00	-
2	REAR TAILLAMP LOWER BRACKET @\$171.45	TO REPAIR SEE LABOUR	342.90	-
1	REAR BUMPER	BENT	972.45	972.45
2	REAR BUMPER SIDE RETAINER @\$141.45	DISTORTED	282.90	282.90
2	REAR BUMPER REFLECTOR @\$172.25	SERVICEABLE	344.50	-
2	REAR BUMPER REFLECTOR GARNISH @\$281.90	CUT	563.80	563.80
1	REAR BUMPER DIFFUSER	MISSING	581.45	581.45
8	REAR BUMPER DIFFUSER CLIP @\$5.50	NECESSARY	44.00	44.00
1	REAR BUMPER DIFFUSER CENTRE COVER	MISSING	74.85	74.85
1	REAR BUMPER REINFORCEMENT	BENT	782.10	782.10
1	REAR END PANEL	BENT	781.45	781.45
1	REAR END PANEL INNER GARNISH	BUCKLED	378.85	378.85
1	REAR FLOOR PANEL	BENT / BUCKLED	785.85	785.85
1	REAR FLOOR PANEL SPONGE	CRACKED	285.85	285.85
1	REAR EXHAUST BOX	BENT	1,850.00	1,592.70
1	REAR EXHAUST BOX TOP COVER	BENT	181.50	181.50
3	REAR EXHAUST MOUNTING @\$58.50	TORN	175.50	175.50
2	REAR FENDER PROTECTOR @\$258.85	N/S DISTORTED	517.70	258.85
1	REAR LH LOWER ARM	SERVICEABLE	485.58	-
1	REAR LH ABSORBER	SERVICEABLE	450.25	-

Report Ref No. CS/FCI18012406/Ktd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 25% DISCOUNT		-3,690.57	-2,644.51
			11,071.71	7,933.54
	NETT ITEMS			
1	REAR END PANEL OUTER SENSOR (N)	SERVICEABLE	240.00	-
	LESS 10% DISCOUNT		-24.00	-
			216.00	-
	SPECIAL NETT ITEMS			
1	SET PARKING SENSOR (SN)	NO SUCH PARTS	280.00	-
1	SEALANT (SN)	NECESSARY	80.00	40.00
			360.00	40.00
	LABOUR			
	REMOVE & REFIT REAR WINDSCREEN GLASS.		120.00	120.00
	WIRING.		80.00	20.00
	TUFFKOTE.		120.00	90.00
	SPRAY PAINTING.		1,000.00	900.00
	LABOUR CHARGES. INCLUSIVE OF THE REPAIR OF REAR TAILLAMP LOWER BRACKET.		1,200.00	1,100.00
			2,520.00	2,230.00
	GRAND TOTAL		14,167.71	10,203.54
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			8,100.00

Report Ref No. CS/FCI18012406/Ktd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.