

INS. CASE OWNER:

CC 3 / EOI 180

12435, Kea3sz

LKK:

IDAC:

ASSIGNMENT

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II : SS

Is driver the owner?

If NO, Driver Name / Age:

Driver Tel No.:

HP:

D.O.A.:

Nature of Accident:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

23/7/18

ASW

27-7-18 @ 3:55pm

27/9/18

1:10:13

SHE 5542J - X

CALLED OLD NO RESPONSE.

- RTM

FILE PASS TO TYPST TO PREPARE REPORT.

RECEIVED 22 NOV 2018

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher: (NO NEED)

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time: 27.9.18

Confirm with: JASMINE

Confirm by: KSK

Repair Cost:

4% S\$ 7,500.00

(1 days)

Reduction:

81 %

Email

Call

FINAL SETTLEMENT

Date/Time: 22.11.18

Confirm with: JASMINE

Email

Call

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.:

9

If NO or B 28, Ass. Lia:

Repair Cost:

W/EST: S\$ 8,025.00

OLD TURN RH INTO THE MAIN ROAD.

Loss of Rental (LOR):

S\$ 811.68

(8 days)

x \$101.46

Loss of Use (LOU):

S\$ -

(\$ x days)

Loss of Income (LOI):

S\$ 400.00

(\$30 x 8 days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☒

[Tick only one]

GIA/LTA Search

S\$ 7.45

Medical:

S\$ -

Disbursement:

S\$ -

(e.g. Tow/Independent)

Legal Cost

S\$ -

Total:

S\$ 9,244.13

Global Sum SS:

FINAL PAYMENT

Date/Time: 22.11.18

Confirm with: JASMINE

Email

Call

Payee 1:

S\$ 9,244.13

Name 1:

TRANS-CAB AUTO SERVICES PTE LTD

Payee 2: (Strike if N.A.)

S\$ -

Name 2:

Payee 3: (Strike if N.A.)

S\$ -

Name 3:

ASS. REC. BY:

REF: EG 1

ASSIGNMENT

From: _____

Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: 07 days

Res.: Yes or No

Lum Sum: 20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHC 55427Yr Regn: 08, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry (Taxi) / Prime Mover /

Truck / Traller or _____

Make: Renault Latitudec.g. 1995Colour: M. White / R

A/C: Insured / Std / NI / NA

Sp. Reading: 394868

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: V1-1 ABL 15 AUC 278894Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: NI / S/Rim / STD A/Rim orTyre Size: F: 215/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Giti

Front

Rear

R/Bal. 9 mmR/Bal. 5 mmL/Bal. 9 mmL/Bal. 5 mmD.O.A. 3/7/18D.O.I. 6/7/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

9/7 File pass to Catherine1719 1/1 Sup 8 7500 Confirmed Jarmine (7X+1X101.46+400)

(RED: 31/05/21 8:17)

Date/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + R.S. \$

Fees

Others

TOTAL

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

Report Format :

Lump Sum / I.B.I: (\$)

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5542J**AAD1807-039***Not Notified**1/1/18*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHC 5542J

VF1ABL15AUC278894

RENAULT

LATITUDE

5.7.2018

EQ

PART		LIST	
1	FENDER PANEL FRT RH	\$	<i>R</i> 783.83 ✓
1	WHEELARCH FRT RH	\$	<i>SL</i> 278.84 X
1	FENDER BRACKET LOWER RH	\$	<i>SL</i> 15.79 X
1	FENDER INSULATOR RH	\$	<i>SL</i> 130.84 ✓
1	DOOR PANEL FRT RH	\$	<i>R</i> 2,844.66 ✓
1	DOOR HINGE UPPER RH	\$	<i>R</i> 261.28
1	DOOR HINGE LOWER RH	\$	<i>R</i> 300.55
1	DOOR CHECK FRT RH	\$	<i>SL</i> 194.77
1	DOOR LOCK FRT RH	\$	<i>R</i> 908.75
1	DOOR CATCH FRT RH	\$	<i>SL</i> 131.23
1	DOOR HANDLE OUTER FRT RH	\$	<i>SL</i> 477.76
1	DOOR HANDLE COVER FRT RH	\$	<i>SL</i> 13.22
1	DOOR HANDLE MODULE FRT RH	\$	<i>SL</i> 133.60
1	DOOR REGULATOR FRT RH	\$	<i>SL</i> 505.19
1	DOOR REGULATOR MOTOR FRT RH	\$	<i>SL</i> 796.46
1	DOOR REGULATOR GUIDE FRT RH	\$	<i>SL</i> 120.97
1	DOOR PANEL REAR RH	\$	<i>R</i> 2,844.66 ✓
1	DOOR GUIDE REAR RH	\$	<i>SL</i> 176.82
1	DOOR HINGE UPPER RH	\$	<i>R</i> 274.50
1	DOOR HINGE LOWER RH	\$	<i>R</i> 300.55
1	DOOR CHECK REAR LH/RH L70Y	\$	<i>SL</i> 203.06
1	DOOR LOCK REAR RH	\$	<i>R</i> 908.75
1	DOOR HANDLE OUTER REAR RH	\$	<i>SL</i> 126.49
1	DOOR HANDLE CAP REAR RH	\$	<i>SL</i> 35.52
1	DOOR HANDLE SEAL REAR RH	\$	<i>SL</i> 7.89
1	DOOR HANDLE COVER REAR RH	\$	<i>SL</i> 13.22
1	DOOR HANDLE MODULE REAR RH	\$	<i>SL</i> 133.60
1	DOOR REGULATOR REAR RH	\$	<i>R</i> 1,135.10
1	DOOR REGULATOR MOTOR REAR RH	\$	<i>SL</i> 893.75
1	DOOR REGULATOR NUT REAR L70Y	\$	<i>SL</i> 12.43

Trans-cab Auto Services Pte Ltd**AAD1807-039**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5542J

1	DOOR REGUALTOR MOTOR SCREW REAR L70Y	\$	6.31	}
1	DOOR FINISHER REAR RH	\$	423.10	
1	DOOR MOULDING REAR RH	\$	176.82	
1	DOOR MOULDING CLIP L70Y	\$	5.92	
1	DOOR MOULDING SCREW L70Y	\$	6.91	
1	DOOR CASING REAR RH	\$	1,509.06	
1	DOOR WATER SHIELD REAR RH	\$	30.39	
1	DOOR CASING CLIP	\$	12.63	
1	DOOR CASING LIGHT L70Y	\$	48.74	
1	DOOR FINISHER INNER REAR RH	\$	323.44	
1	DOOR FINISHER BRACKET INNER REAR RH	\$	46.97	
1	DOOR FINISHER BRACKET INNER REAR RH	\$	20.33	
1	DOOR FINISHER BRACKET INNER REAR RH	\$	20.33	
1	DOOR FINISHER BRACKET INNER REAR RH	\$	20.33	
1	DOOR GRAB HANDLE REAR RH	\$	210.96	
1	DOOR BLIND REAR RH	\$	741.80	
1	DOOR WHEATHESTRIIP REAR RH	\$	410.66	
1	DOOR SEAL REAR RH	\$	162.02	
1	DOOR GLASS RUNNER SEAL REAR RH	\$	229.31	
1	DOOR WAIST SEAL OUTER REAR RH	\$	334.69	
1	DOOR WAIST SEAL INNER REAR RH	\$	115.64	
1	FENDER PANEL REAR RH	\$	3,299.13	}
1	FENDER PANEL INNER TRIM REAR	\$	671.45	
1	WHEELARCH REAR RH	\$	543.47	
1	DOOR MIRROR ASSY RH	\$	1,483.40	
1	ROCKER PANEL INNER GARNISH RH	\$	466.51	
1	ROCKER PANEL INNER RH	\$	1,024.79	}
1	ROCKER PANEL CENTER RH	\$	990.25	
1	BUMPER COVER REAR	\$	1,108.46	

\$	29,407.90
----	------------------

10% \$	2,940.79
--------	-----------------

\$	26,467.11
----	------------------

Specical Nett

1SET	FRAME FULL SUPPORT PANEL CLIP	\$	70.00	X
2	FRAME FULL SUPPORT PANEL NUT	\$	20.00	X
2	FRAME FULL SUPPORT PANEL STUD	\$	30.00	X

Trans-cab Auto Services Pte Ltd**AAD1807-039**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5542J

1SET	WHEELARCH CLIP FRT LH	\$	nn	30.50	X
1	FRONT DOOR STICKER 'Trans-cab'	\$	nn	80.00	— 60sn
1	FRONT DOOR STICKER 'Chassis'	\$	nn	50.00	— 15sn
1	REAR DOOR STICKER '6555 3333'	\$	nn	80.00	— 60sn
1	DOOR CHECK BOLT	\$	sn	22.69	} X
1	DOOR GUIDE SCREW	\$	sn	10.85	
1	DOOR HINGE BOLT	\$	sn	10.85	
1	DOOR HINGE NUT RH	\$	sn	14.60	
1	DOOR CHECK BOLT	\$	sn	22.69	
1	DOOR CHECK NUT	\$	sn	3.75	
1	DOOR LOCK SCREW L70Y	\$	sn	6.12	
1	DOOR CATCH SCREW L70Y	\$	sn	10.06	

TOTAL \$ 462.13**TOTAL PARTS** \$ 26,929.24**LABOUR**

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	4,500.00	800
Putty and spray painting of the affected portion.	\$	4,200.00	1320
To rust-proofing of the affected areas.	\$	170.00	120
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	80
To check steering geometry and computer wheel alignment	\$	220.00	60
To transfer of tire, rim and on wheel balancing.	\$	170.00	20
To Check Electrical Lighting Concerned.	\$	170.00	20

Trans-cab Auto Services Pte Ltd**AAD1807-039**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5542J

To transfer of front fender fittings, attachment and perform water seepage test.

\$ *nn* 380.00 *X*

To transfer of front door fittings, attachment and perform water seepage test.

\$ 380.00 *60%*

To transfer of Rear door fittings, attachment and perform water seepage test.

\$ 380.00 *60%*

Towing Fees.

\$ *nn* 120.00 *X*

To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.

\$ *nn* 380.00 *X*

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.

\$ *nn* 380.00 *X***TOTAL \$ 11,830.00****Over All Total \$ 38,759.24 *2*****LUMP SUM (REPAIR DAY)*****15* DAYS***7 days***LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Mei Kwan (LKKAUTO)

From: Joel Goh <joel.goh@eqinsurance.com.sg>
Sent: Friday, 20 July, 2018 8:59 AM
To: Mei Kwan (LKKAUTO)
Cc: Asher Sng (LKKAUTO); Joy Irene (LKKAUTO); Hsiao Tong (LKKAUTO); Admin A
Subject: RE: Direct Settlement - Accident Involving SGZ3514U (OI : EQI - DM18HO01762-JG) AND SHC5542J (TP : LKK REF - CC3/EQI18012435/Kea3) on 05/07/2018
Attachments: SGZ3514U.PDF
Follow Up Flag: Follow up
Flag Status: Completed
Categories: HMK

Dear Mei Kwan

Attached insured's GIA report for your attention.

Best Regards,

Joel Goh
Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190
www.eqinsurance.com.sg



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the

From: Joel Goh
Sent: Thursday, July 12, 2018 4:56 PM
To: 'Mei Kwan (LKKAUTO)'
Cc: Asher Sng (LKKAUTO); Joy Irene (LKKAUTO); Hsiao Tong (LKKAUTO); Admin A
Subject: RE: Direct Settlement - Accident Involving SGZ3514U (OI : EQI - TBA) AND SHC5542J (TP : LKK REF - CC3/EQI18012435/Kea3) on 05/07/2018

Dear Mei Kwan

Our insured has not reported the accident.

Best Regards,

Joel Goh
Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110

did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190

www.eqinsurance.com.sg



A Member of Citystate

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the

From: Mei Kwan (LKKAUTO) [mailto:Meikwan@lkkauto.com]

Sent: Thursday, July 12, 2018 11:07 AM

To: Janet Tan; Joel Goh

Cc: Asher Sng (LKKAUTO); Joy Irene (LKKAUTO); Hsiao Tong (LKKAUTO); Admin A

Subject: Direct Settlement - Accident Involving SGZ3514U (OI : EQI - TBA) AND SHC5542J (TP : LKK REF - CC3/EQI18012435/Kea3) on 05/07/2018

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

This is a TP direct settlement case. We had inspected TP vehicle SHC 5542J at M/s Trans-cab Auto Services Pte Ltd - Ang Mo Kio.

Enclosed for your perusal is:

- Estimated cost of repair
- Preliminary advice
- TP GIA report
- Photographs of TP vehicle in its damaged condition

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Asher and she can be contacted at DID: 6841 6051.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD

Ref : CC3/EQ18012435/Kea3s2

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEXSINGAPORE 069110

Date : 26-11-2018



Code : EQ1

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGZ 3514U	Veh. Inspected	SHC 5542J
Policy No.	DMPPHQ17-005610	Coverage (\$)	0.00
Claim No.	DM18HO01762-JG	Excess (\$)	0.00
Assign From		Assign Date	06/07/2018

2. Vehicle Particulars & Condition

Make & Model	RENAULT LATITUDE (A)	c.c	1995
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	VF1ABL15AUC278894	Colour	METALLIC WHITE / RED
Odometer	394868	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60R16	GITI	9 mm
L/H Front Tyre	215/60R16	GITI	9 mm
R/H Rear Tyre	215/60R16	GITI	5 mm
L/H Rear Tyre	215/60R16	GITI	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	05/07/2018	Inspection Date	06/07/2018
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	7 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 5

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 5542J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FENDER PANEL FRT RH	BENT	783.83	783.83
1	WHEELARCH FRT RH	SERVICEABLE	278.84	-
1	FENDER BRACKET LOWER RH	SERVICEABLE	15.79	-
1	FENDER INSULATOR RH	SERVICEABLE	130.84	-
1	DOOR PANEL FRT RH	BENT	2,844.66	2,844.66
1	DOOR HINGE UPPER RH	TO REPAIR SEE LABOUR	261.28	-
1	DOOR HINGE LOWER RH	TO REPAIR SEE LABOUR	300.55	-
1	DOOR CHECK FRT RH	SERVICEABLE	194.77	-
1	DOOR LOCK FRT RH	TO REPAIR SEE LABOUR	908.75	-
1	DOOR CATCH FRT RH	SERVICEABLE	131.23	-
1	DOOR HANDLE OUTER FRT RH	SERVICEABLE	477.76	-
1	DOOR HANDLE COVER FRT RH	SERVICEABLE	13.22	-
1	DOOR HANDLE MODULE FRT RH	SERVICEABLE	133.60	-
1	DOOR REGULATOR FRT RH	SERVICEABLE	505.19	-
1	DOOR REGULATOR MOTOR FRT RH	SERVICEABLE	796.46	-
1	DOOR REGULATOR GUIDE FRT RH	SERVICEABLE	120.97	-
1	DOOR PANEL REAR RH	BENT	2,844.66	2,844.66
1	DOOR GUIDE REAR RH	SERVICEABLE	176.82	-
1	DOOR HINGE UPPER RH	TO REPAIR SEE LABOUR	274.50	-
1	DOOR HINGE LOWER RH	TO REPAIR SEE LABOUR	300.55	-
1	DOOR CHECK REAR LH/RH L70Y	SERVICEABLE	203.06	-
1	DOOR LOCK REAR RH	TO REPAIR SEE LABOUR	908.75	-
1	DOOR HANDLE OUTER REAR RH	SERVICEABLE	126.49	-
1	DOOR HANDLE CAP REAR RH	SERVICEABLE	35.52	-
1	DOOR HANDLE SEAL REAR RH	SERVICEABLE	7.89	-
1	DOOR HANDLE COVER REAR RH	SERVICEABLE	13.22	-
1	DOOR HANDLE MODULE REAR RH	SERVICEABLE	133.60	-

Report Ref No. CC3/EQ18012435/Kea3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	DOOR REGULATOR REAR RH	TO REPAIR SEE LABOUR	1,135.10	-
1	DOOR REGULATOR MOTOR REAR RH	SERVICEABLE	893.75	-
1	DOOR REGULATOR NUT REAR L70Y	SERVICEABLE	12.43	-
1	DOOR REGULATOR MOTOR SCREW REAR L70Y	SERVICEABLE	6.31	-
1	DOOR FINISHER REAR RH	SERVICEABLE	423.10	-
1	DOOR MOULDING REAR RH	SERVICEABLE	176.82	-
1	DOOR MOULDING CLIP L70Y	SERVICEABLE	5.92	-
1	DOOR MOULDING SCREW L70Y	SERVICEABLE	6.91	-
1	DOOR CASING REAR RH	SERVICEABLE	1,509.06	-
1	DOOR WATER SHIELD REAR RH	SERVICEABLE	30.39	-
1	DOOR CASING CLIP	NOT NECESSARY	12.63	-
1	DOOR CASING LIGHT L70Y	SERVICEABLE	48.74	-
1	DOOR FINISHER INNER REAR RH	SERVICEABLE	323.44	-
1	DOOR FINISHER BRACKET INNER REAR RH	TO REPAIR SEE LABOUR	46.97	-
1	DOOR FINISHER BRACKET INNER REAR RH	TO REPAIR SEE LABOUR	20.33	-
1	DOOR FINISHER BRACKET INNER REAR RH	TO REPAIR SEE LABOUR	20.33	-
1	DOOR FINISHER BRACKET INNER REAR RH	TO REPAIR SEE LABOUR	20.33	-
1	DOOR GRAB HANDLE REAR RH	SERVICEABLE	210.96	-
1	DOOR BLIND REAR RH	SERVICEABLE	741.80	-
1	DOOR WEATHERSTRIP REAR RH	SERVICEABLE	410.66	-
1	DOOR SEAL REAR RH	SERVICEABLE	162.02	-
1	DOOR GLASS RUNNER SEAL REAR RH	SERVICEABLE	229.31	-
1	DOOR WAIST SEAL OUTER REAR RH	SERVICEABLE	334.69	-
1	DOOR WAIST SEAL INNER REAR RH	SERVICEABLE	115.64	-
1	FENDER PANEL REAR RH	TO REPAIR SEE LABOUR	3,299.13	-
1	FENDER PANEL INNER TRIM REAR	SERVICEABLE	671.45	-
1	WHEELARCH REAR RH	SERVICEABLE	543.47	-
1	DOOR MIRROR ASSY RH	SERVICEABLE	1,483.40	-
1	ROCKER PANEL INNER GARNISH RH	SERVICEABLE	466.51	-

Report Ref No. CC3/EQI18012435/Kea3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	ROCKER PANEL INNER RH	TO REPAIR SEE LABOUR	1,024.79	-
1	ROCKER PANEL CENTER RH	BENT	990.25	990.25
1	BUMPER COVER REAR	TO REPAIR SEE LABOUR	1,108.46	-
	LESS 10% DISCOUNT		-2,940.79	-746.34
			26,467.11	6,717.06
	SPECIAL NETT ITEMS			
1	SET FRAME FULL SUPPORT PANEL CLIP (SN)	NOT NECESSARY	70.00	-
2	FRAME FULL SUPPORT PANEL NUT (SN)	NOT NECESSARY	20.00	-
2	FRAME FULL SUPPORT PANEL STUD (SN)	NOT NECESSARY	30.00	-
1	SET WHEELARCH CLIP FRT LH (SN)	NOT NECESSARY	30.50	-
1	FRONT DOOR STICKER 'TRANS-CAB' (SN)	NECESSARY	80.00	60.00
1	FRONT DOOR STICKER 'CHASSIS' (SN)	NECESSARY	50.00	15.00
1	REAR DOOR STICKER '6555-3333' (SN)	NECESSARY	80.00	60.00
1	DOOR CHECK BOLT (SN)	SERVICEABLE	22.69	-
1	DOOR GUIDE SCREW (SN)	SERVICEABLE	10.85	-
1	DOOR HINGE BOLT (SN)	SERVICEABLE	10.85	-
1	DOOR HINGE NUT RH (SN)	SERVICEABLE	14.60	-
1	DOOR CHECK BOLT (SN)	SERVICEABLE	22.69	-
1	DOOR CHECK NUT (SN)	SERVICEABLE	3.75	-
1	DOOR LOCK SCREW L70Y (SN)	SERVICEABLE	6.12	-
1	DOOR CATCH SCREW L70Y (SN)	SERVICEABLE	10.06	-
			462.11	135.00

Report Ref No. CC3/EQ118012435/Kea3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 4 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY, PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF DOOR HINGE UPPER RH, DOOR HINGE LOWER RH, DOOR LOCK FRT RH, DOOR HINGE UPPER RH, DOOR HINGE LOWER RH, DOOR LOCK REAR RH, DOOR REGULATOR REAR RH, DOOR FINISHER BRACKET INNER REAR RH, DOOR FINISHER BRACKET INNER REAR RH, DOOR FINISHER BRACKET INNER REAR RH, DOOR FINISHER BRACKET INNER REAR RH, FENDER PANEL REAR RH, ROCKER PANEL INNER RH AND }		4,500.00	800.00
	BUMPER COVER REAR. }		-	-
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		4,200.00	1,320.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	120.00
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.		380.00	80.00
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.		220.00	60.00
	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.		170.00	20.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
	TO TRANSFER OF FRONT FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF FRONT DOOR FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.		380.00	60.00
	TO TRANSFER OF REAR DOOR FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.		380.00	60.00
	TOWING FEES.	NOT NECESSARY	120.00	-
	TO PULL AND JACK OUT CHASSIS FRAME AND CORRECT IT TO SYMMETRICAL POSITION WITH THE AID OF HYDRAULIC PNEUMATIC JACK.	NOT NECESSARY	380.00	-
	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR.	NOT NECESSARY	380.00	-
			11,830.00	2,540.00
	GRAND TOTAL		38,759.22	9,392.06

Report Ref No. CC3/EQ18012435/Kea3s2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			7,500.00
---	--	--	----------

Report Ref No. CC3/EQ118012435/Kea3s2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.