



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:STACEY NG			Ref: CC4/ASM18012444/Uea3q2 Date: 05/08/2021 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	TRC 5195J	Veh. Inspected	GZ 3253Y	
Policy No.	P1569374	Coverage (\$)	0.00	
Claim No.	S8M00PP4	Excess (\$)	0.00	
Assign From		Assign Date	06/07/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA DYNA (M)	c.c	2986	
Engine No.	HIDDEN	Year of Reg.	2006	
Chassis No.	JTFUF34Y603011639	Colour	WHITE	
Odometer	541526 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185 R14	TRIANGLE	6 mm	
L/H Front Tyre	185 R14	TRIANGLE	6 mm	
R/H Rear Tyre	155 R12 (D)	WEST LAKE	6/6 mm	
L/H Rear Tyre	155 R12 (D)	WEST LAKE	6/6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION AND N/S BODY & FRONT WINDSCREEN CRACKED. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	06/07/2018	Inspection Date	09/07/2018	
Survey held at	LIU'S BROTHER AUTO ENGINEERING WORKSHOP 1 KAKI BUKIT AVENUE 6 #01-01 AUTOBAY @ KAKI BUKIT SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			8 Working Days	