



TPAYA.
Acher.

Jm6BL1021A0152544

ESTIMATE

DATE OF ACCIDENT : 22/06/2018
VEHICLE : SJZ3737H
MAKE & MODEL : MAZDA
INSURANCE : AXA INSURANCE
SURVEYOR : LKK AUTO

PARTS		CONDITION	COST
1.	FRONT BUMPER <i>Repaired</i>		966.70
2.	FRONT RIGHT FENDER <i>Dented</i>	637.20	485.20
3.	FRONT RIGHT SIDE MIRROR COVER <i>Repaired</i>	509.76	152
SPECIAL NETT			
1.	FRONT RIGHT RIM <i>cut</i>	380	\$ 350
2.	CLIPS <i>new</i>		\$ 80
LABOUR			
1.	TO PUTTY & SPRAY PAINT OF AFFECTED AREA		\$ 600
2.	TO PANEL BEAT & RENEWAL OF ALL NECESSARY DAMAGED BODY PARTS	750	\$ 900
3.	TO REMOVE & INSTALL FRONT BUMPER		\$ 220
PARTS - 20% :		\$	
SPECIAL NETT :		\$ 430	
LABOUR :		\$ 1,720	
LUMP SUM - 20% :		\$	
TOTAL :		\$	
7% GST :		\$	
GRAND TOTAL :		\$	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lj
2/5 16/07/18
04 days

total: 1639.76
L/S: 1.3K.