

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Elaine Cheong

Date: 11 Jul 2018

Preliminary Advice

Vehicle No	: WC6725P	Accident Date	: 13/06/2018
Make	: ISUZU CYH52S	Policy No.	: DMCVSN1806861800
Assignment Date	: 11/07/2018	Excess	: S\$1,500.00
Date of Inspection	: 10/07/2018	Est. Duration of Repair	: 25 days
Inspection At	: Fook Heng Motor Service (HQ) 100 BEDOK NORTH AVENUE 4 PEARL GARDENS, #13-1922 Singapore 460100		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front, o/s and n/s portion and the u/c, chassis frame and body structure affected due to collision parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	57,884.45
Revised Amount	:S\$	47,532.95
Check Items (Estimated)	:S\$	6,680.00
Total	:S\$	54,212.95
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	98,000.00
COE / PARF Rebate	:S\$	37,447.00
Salvage Value	:S\$	
Margin for Repair	:S\$	60,553.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.
Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :