

ASS. REC. BY:

REF: CS/FCL18012502 / Dvbnz

Special Instruction:

Surveyor

Bryan

ASSIGNMENT (Office)

From (Person):

WGN Eileen Lee

of

FCL

Date/Time:

04/07/2018 3:18pm

Estimated Cost:

Bill to:

OD /  TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKX 6738J

Insured:

SHA 6208D

at Workshop m/s

Teamwork

Tel:

6844 2475

of

Blk 53 Ubi Ave 1 #01-211

Policy No:

Claim No:

D18005149MFSH

Sum Insured:

Excess:

Make of Veh:  
(Client's Record)

D.O.A.

30062018

CA / REV / REP. / REV 24 HRS 'DS'

H.O.D. Endorsement:

Date/Time:

10/07/2018 11:59am

Person Contacted:

Darren

Vehicle  IN  OUT

| Date/Time | Action/Instruction ( <input checked="" type="checkbox"/> ) Estimate |
|-----------|---|
|           | SKX 6738J - NA / INCL 801928/13 DA: 30062018                        |
|           | SHA 6208D - CS/FCL16021464 / Ugh3m DA: 21.11.2016                   |
| 7/12/18   | Email preli revised to FCI  |


REF:

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No: \_\_\_\_\_  
 Claims No: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

Veh No: **8KX 6738 J** Yr Regn: **2015 / Dec**  
 Type:  M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: **Toyota Corolla Altis** C.C. **1598**  
 Colour: **Silver** A/C: Insured / Std / NI / NA  
 Sp. Reading: **147159** T/Radio: Insured / Std / NI / NA  
 Eng/No: **1ZR X525986**  
 C/No: **MAR053REH104537262**  
 Gen. Cond:  Good / Fair / Poor / Burnt  
 Steering:  In order / Jammed / Leaked / Burnt or  
 Brake:  In order / Jammed / Leaked / Burnt or  
 Modl:  Nil / SRim / STD A/Rim or  
 Tyre Size: F: **205/55 R 14**  
 R: **— " —**

(Policy Condition)  
 Remark: **The veh had commenced its repair at the time of inspection.**



BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or **Triangle**  
 Front \_\_\_\_\_ Rear \_\_\_\_\_  
 R/Bal. **5** mm L/Bal. **5** mm  
 L/Bal. **5** mm R/Bal. **5** mm  
 D.O.A. **30/06/2018** D.O.I. **05/07/2018**  
 Survey held at **Teamwork Page 4bi**  
 Des. of Damages: Frt /  Rear O/S / N/S / U/C / Rooftop or  
**Rear**  
 The U/C / Chassis frame / Body Structure affected due to collision.

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: **6** days Res.: Yes or No  
 Lum Sum: **20** % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

| Date / Time     | Action / Instruction  |
|-----------------|---|
|                 | <b>First Capital SHA 62087</b>                                    |
| <b>07/12/18</b> | <b>Final 2/5 62501 - with 6 days of rep (Red 12,500.57, 6790)</b> |

RECEIVED 07 DEC 2018

Date/Time, File Pass to?  : Preli. Report  
 : Final Report

Days Of Repair: **6**  
 Resurvey No. of Trip: **2**

Date/Time, File Return to?  
 2) **7/12 - typist**

Add Fee:  : Site Insp (\$)  
 : Interview (\$)  
 : Tech. Invs (\$)  
 : Weekend (\$)

|                 |           |
|-----------------|-----------|
| Survey Fee:     | 170 + 120 |
| Transportation: | 50        |
| S + RS, SI      | 50 + 50   |
| Photos          | 122       |
| Others          |           |
| TOTAL           | 562       |

Report Format: **aws**  
 Lump Sum / I.B.I. (\$) **62501/2**

8x15 = 120



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18005149MFSH

Our ref: CS/FCI18012502/Dvb

Date: 7/12/2018

The Motor Claims Department  
MS FIRST CAPITAL INSURANCE LTD

Without Prejudice

Dear Sir/Madam,

**INITIAL INSPECTION REPORT OF VEHICLE NO. SKX 6738J**


We thank you for your instruction on 4/7/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 5/7/2018 at the premises of M/s TEAMWORK GARAGE PTE LTD and have the following to report:-

|                          |                          |
|--------------------------|--------------------------|
| Workshop Estimate Amount | : S\$18,750.57           |
| Revised Estimate Amount  | : S\$6,250.00 (LUMP SUM) |
| "Check" Items Amount     | : S\$                    |
| Book Value               | : S\$                    |
| LTA Reimbursement Value  | : S\$                    |
| Nett Value               | : S\$                    |

Description of Damage:

The vehicle sustained damages at the rear portion



Comments/Present Status:  
Damages Consistent

Yours faithfully,

Bryan Ang  
Motor Surveyor / Investigator

**MOTOR SURVEY ASSIGNMENT**

|                           |   |                                      |
|---------------------------|---|--------------------------------------|
| <b>Date</b>               | 02-07-2018  | <b>Our Ref No.</b> D18005149MFSH     |
| <b>Accident Date</b>      | 30-06-2018  | <b>Claim Type.</b> Third Party       |
| <b>Insured Vehicle</b>    | SHA6208D  | <b>Third Party Vehicle.</b> SKX6738J |
| <b>Survey Location</b>    | BLK 53 UBI AVE 1 #01-24 PAYA UBI INDUSTRIAL PARK            |                                      |
| <b>Contact Person.</b>    | DARREN NG   |                                      |
| <b>Contact No.</b>        | 68442475/ 0   | <b>Fax No.</b> 68442474              |
| <b>Survey Type</b>        | WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED: |                                      |
| <b>Appointed Surveyor</b> | LKK AUTO CONSULTANTS PTE LTD                                |                                      |
| <b>Contact Person</b>     | NA  | <b>Fax No.</b> 68416315              |
| <b>Contact Number.</b>    | NA  |                                      |

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**THIRD PARTY SURVEY REQUEST**

|                          |                            |                                |
|--------------------------|----------------------------|--------------------------------|
| <b>Cc : Workshop</b>     | TEAMWORK GARAGE<br>PTE LTD | <b>Attention.</b> NIL          |
| <b>Cc : TP Solicitor</b> | NA                         | <b>TP Solicitor Fax No.</b> NA |
| <b>Officer Incharge</b>  | EILEEN LEE                 |                                |

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

## Veron Chen (LKKAuto)

---

**From:** Veron Chen (LKKAuto)  
**Sent:** Friday, 7 December 2018 3:27 PM  
**To:** SUR; 'CWS Motor Claims'  
**Cc:** 'Eileen Lee'  
**Subject:** RE: SURVEY ASSESSMENT - D18005149MFSH/1, SKX 6738J  
**Attachments:** SKX 6738J PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SKX 6738J  
Date of survey: 5/7/2018  
Number of days : 6 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]  
**Sent:** Wednesday, 4 July, 2018 3:18 PM  
**To:** [ASSIGNMENTS@LKKAUTO.COM](mailto:ASSIGNMENTS@LKKAUTO.COM)  
**Cc:** [CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG](mailto:CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG); [EILEENLEE@MSFIRSTCAPITAL.COM.SG](mailto:EILEENLEE@MSFIRSTCAPITAL.COM.SG)  
**Subject:** PRI: SURVEY ASSESSMENT - D18005149MFSH/1

Dear Sir/Mdm,

We refer to the above reference.  
Please find attached the necessary documents for survey.  
Kindly submit your report via CWS within the next 14 days.

Best Regards,  
Admin Team  
Claim Workflow System  
Motor Claims Department  
MS First Capital Insurance Limited  
Tel : 6507 3848  
Fax : 6507 3849

**PS: This is a system generated mail. Please do not reply to this mail.**



Teamwork Garage Pte Ltd  
 53 Ubi Avenue 1 #01-23/24 Spore 408934  
 Paya Ubi Industrial Park  
 Tel : 6844 2475  
 E-mail : claims@teamworkgarage.com  
 Register number : 201015366H

First Capital Insurance Ltd  
 #16-01 City House  
 Singapore 068877

3RD PARTY CLAIM ESTIMATION

|                |                   |
|----------------|-------------------|
| Vehicle number | SKC6738J          |
| Make / Model   | TOYOTA/ALTIS      |
| Chassis number | mr053reh104537262 |
| Accident date  | 30 June 2018      |
| Reference      | 1806-33           |

Qty Particulars Unit Price - SGD \$

| Qty                                   | Particulars                                   | Unit Price - SGD \$         |
|---------------------------------------|---|-----------------------------|
| <u>PARTS REPLACEMENT - LIST ITEMS</u> |   |                             |
|                                       |   | <b>772.50</b>               |
| 1                                     | BOOTLID <i>bst</i>                            | 906.52 ✓                    |
| 1                                     | BOOTLID LOGO <i>hlc</i>                       | 72.09 ✓                     |
| 1                                     | BOOTLID EMBLEM COROLLA <i>hlc</i>             | 58.37 ✓                     |
| 1                                     | BOOTLID EMBLEM ALTIS <i>hlc</i>               | 58.92 ✓                     |
| 1                                     | BOOTLID CHROME GARNISH <i>hh</i>              | 280.80 X                    |
| 1                                     | BOOTLID LICENCE PLATE LAMP <i>hh</i>          | 69.60 X                     |
| 2                                     | BOOTLID LAMP <i>crack mounty</i>              | 624.40 <del>804.00</del> ✓  |
| 2                                     | BOOTLID INNER SEAL <i>svc</i>                 | 222.81 X                    |
| 1                                     | BOOTLID LOCK <i>bst</i>                       | 132.20 <del>462.43</del> ✓  |
| 1                                     | BOOTLID LOCK COVER <i>hh</i>                  | 43.30 X                     |
| 1                                     | BOOTLID LOCK CATCH <i>hh</i>                  | 54.03 X                     |
| 2                                     | BOOTLID HINGE <i>hh</i>                       | 163.20 X                    |
| 1                                     | BOOTLID INNER TRIM <i>hh</i>                  | 515.40 X                    |
| 2                                     | BOOTLID STOPPER <i>svc</i>                    | 40.00 X                     |
| 1                                     | REAR BUMPER <i>Rental</i>                     | 685.32 ✓                    |
| 2                                     | BUMPER REFLECTOR <i>mounty crack</i>          | 139.20 ✓                    |
| 2                                     | REAR BUMPER BRACKET <i>svc</i>                | 163.20 X                    |
| 2                                     | REAR BUMPER RETAINER <i>svc</i>               | 288.30 X                    |
| 4                                     | REAR BUMPER PDC SENSOR <i>Down</i>            | 780.00 ✓                    |
| 1                                     | REAR BUMPER PDC SENSOR WIRE HARNESS <i>hh</i> | 342.40 X                    |
| 1                                     | REAR BUMPER REINFORCEMENT <i>svc</i>          | 474.42 ✓                    |
| 1                                     | REAR WINDSCREEN <i>hh</i>                     | 1460.40 X                   |
| 2                                     | REAR FENDER INNER TRIM <i>hh</i>              | 759.02 ✓                    |
| 1                                     | REAR END PANEL <i>svc</i>                     | 571.40 <del>749.80</del> ✓  |
| 1                                     | REAR END PANEL GARNISH <i>deformed mounty</i> | 282.80 ✓                    |
| 2                                     | REAR TAILLAMP <i>mounty crack</i>             | 843.20 <del>963.80</del> ✓  |
| 2                                     | REAR TAILLAMP PANEL <i>hh</i>                 | 261.08 X                    |
| 2                                     | REAR TAILLAMP INNER SEAL <i>svc</i>           | 70.34 X                     |
| 1                                     | REAR FLOOR PANEL <i>Rental</i>                | 802.90 <del>973.34</del> ✓  |
| 1                                     | REAR SPARE TYRE TOP BOARD <i>bst</i>          | 259.10 <del>309.88</del> ✓  |
| 1                                     | REAR EXHAUST SILENCER <i>bst</i>              | 794.50 <del>1145.58</del> ✓ |
| 1                                     | REAR EXHAUST MID PIPE <i>hh</i>               | 3409.90 X                   |
| 1                                     | REAR EXHAUST HEAT SHIELD <i>hh</i>            | 189.10 X                    |
| 2                                     | REAR EXHAUST MOUNTING <i>hh</i>               | 60.00 X                     |
| 2                                     | SPARE TYRE EXTENSION PANEL <i>hh</i>          | 451.40 X                    |
|                                       |   | 17680.75                    |
|                                       | Less 25 %                                     | 4420.18                     |
|                                       | Subtotal                                      | 13260.57                    |
|                                       | Balance C/F                                   | 13260.57                    |

220.5H

7330.34

5497.75

| <u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u> |   |               |
|---|---|---------------|
| 1 SET   | REAR BUMPER CLIP H/c                                | 60.00 30/-    |
| 1 SET   | REAR FENDER INNER TRIM CLIP H/c                     | 40.00 20/-    |
| 1 SET   | REAR FENDER INNER SHIELD CLIP H/H                   | 40.00 x       |
| 1 SET   | REAR BOOTLID INNER TRIM CLIP S/c                    | 40.00 x       |
| 1   | REAR JOINT SEALANT H/c                              | 150.00 40/-   |
| 1   | REAR FLOOR INSULATOR H/c                            | 150.00 50/-   |
| 1   | REAR REVERSE CAMERA H/H                             | 500.00 x      |
|   | Subtotal  | 980.00        |
|   | Balance C/F   | 14240.57      |
| <u>LABOUR AND MISCELLANEOUS CHARGES</u>       |   |               |
| S/No  |   |               |
| 1   | CHECK REAR WIRING AND LIGHTNING SYSTEM              | 60.00 30/-    |
| 2   | REMOVE AND REFIT REAR LINING, TRIM AND GARNISH      | 400.00 80/-   |
| 3   | REMOVE AND RENEW REAR REVERSE SENSOR                | 150.00 40/-   |
| 4   | REMOVE AND REFIT FUEL TANK                          | 150.00 H/H    |
| 5   | REMOVE AND RENEW REAR EXHAUST ASSY                  | 150.00 60/-   |
| 6   | REMOVE AND RENEW FLOOR INSULATOR                    | 150.00 50/-   |
| 7   | TRANSFER PARTS, ATTACHEMENT FROM OLD BOOTLID TO NEW | 200.00 60/-   |
| 8   | PANEL BEATING ON AFFECTED AREAS                     | 1600.00 800/- |
| 9   | SPRAY PAINTING ON AFFECTED AREAS                    | 1500.00 800/- |
| 10  | APPLY ANTI RUST ON AFFECTED AREAS                   | 150.00 40/-   |
|   | Subtotal  | 4510.00       |
|   | Grand total   | 18750.57      |
|   |   | 7817.75       |
|   |   | 456250/-      |

360.00

1960.00

05/07/2018 @ 1145 hrs

at Archard

L15mm 6 days

Ryan

LKK Auto

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile  |   |                            |   |
|--|---|----------------------------|---|
| MS FIRST CAPITAL INSURANCE LTD   |   | Ref : CS/FCI18012502/Dvbn2 |   |
| 36 ROBINSON ROAD<br>#16-01 CITY HOUSESINGAPORE 068877  |   | Date : 10-12-2018          |  |
|  |   | Code : FCI2                |   |
| 1. Policy Particulars :- THIRD PARTY CLAIM   |   |                            |   |
| Insured Veh.   | SHA 6208D   | Veh. Inspected             | SKX 6738J   |
| Policy No.   |   | Coverage (\$)              | 0.00  |
| Claim No.  | D18005149MFSH   | Excess (\$)                | 0.00  |
| Assign From  | EILEEN  | Assign Date                | 04/07/2018  |
| 2. Vehicle Particulars & Condition   |   |                            |   |
| Make & Model   | TOYOTA COROLLA ALTIS  | c.c                        | 1598  |
| Engine No.   | HIDDEN  | Year of Reg.               | 2015  |
| Chassis No.  | MR053REH104537262   | Colour                     | SILVER  |
| Odometer   | 147159  | Steering                   | IN ORDER  |
| Brakes   | IN ORDER  | Modification               | SPORTS RIM  |
| General  | GOOD  |                            |   |
| 3. Conditions of Tyres   |   |                            |   |
|  | Size  | Make                       | Balance   |
| R/H Front Tyre   | 205/55 R16  | TRIANGLE                   | 5 mm  |
| L/H Front Tyre   | 205/55 R16  | TRIANGLE                   | 5 mm  |
| R/H Rear Tyre  | 205/55 R16  | TRIANGLE                   | 5 mm  |
| L/H Rear Tyre  | 205/55 R16  | TRIANGLE                   | 5 mm  |
| 4. Description of Damages  |   |                            |   |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.<br>DAMAGES SEE DETAILS.   |   |                            |   |
| 5. General Information   |   |                            |   |
| Accident Date  | 30/06/2018  | Inspection Date            | 05/07/2018  |
| Survey held at   | TEAMWORK GARAGE PTE LTD<br>53 UBI AVENUE 1<br>#01-24<br>SINGAPORE 408934. |                            |   |
| 5a. Remarks  |   |                            |   |
| A)DAMAGES CONSISTENT TO ACCIDENT REPORT.<br>B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |   |                            |   |
| 5b. Estimate Days of Repair  |   |                            |   |
| ESTIMATED NORMAL PERIOD FOR REPAIR:  |   | 6 Working Days             |   |



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKX 6738J

| Qty                         | Description of Parts                | Condition               | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----------------------------|-------------------------------------|-------------------------|---------------------------|-------------------|
| <b>REPLACEMENT OF PARTS</b> |                                     |                         |                           |                   |
| 1                           | BOOTLID                             | BENT                    | 906.52                    | 772.50            |
| 1                           | BOOTLID LOGO                        | NECESSARY               | 72.09                     | 72.09             |
| 1                           | BOOTLID EMBLEM COROLLA              | NECESSARY               | 58.37                     | 58.37             |
| 1                           | BOOTLID EMBLEM ALTIS                | NECESSARY               | 58.92                     | 58.92             |
| 1                           | BOOTLID CHROME GARNISH              | NOT NECESSARY           | 280.80                    | -                 |
| 1                           | BOOTLID LICENCE PLATE LAMP          | NOT NECESSARY           | 69.60                     | -                 |
| 2                           | BOOTLID LAMP                        | MOUNTING<br>CRACKED     | 804.00                    | 624.40            |
| 2                           | BOOTLID INNER SEAL                  | SERVICEABLE             | 222.81                    | -                 |
| 1                           | BOOTLID LOCK                        | BENT                    | 462.43                    | 132.20            |
| 1                           | BOOTLID LOCK COVER                  | NOT NECESSARY           | 43.30                     | -                 |
| 1                           | BOOTLID LOCK CATCH                  | TO REPAIR SEE<br>LABOUR | 54.03                     | -                 |
| 2                           | BOOTLID HINGE                       | TO REPAIR SEE<br>LABOUR | 163.20                    | -                 |
| 1                           | BOOTLID INNER TRIM                  | NOT NECESSARY           | 515.40                    | -                 |
| 2                           | BOOTLID STOPPER                     | SERVICEABLE             | 40.00                     | -                 |
| 1                           | REAR BUMPER                         | DENTED                  | 685.32                    | 685.32            |
| 2                           | BUMPER REFLECTOR                    | MOUNTING<br>CRACKED     | 139.20                    | 139.20            |
| 2                           | REAR BUMPER BRACKET                 | SERVICEABLE             | 163.20                    | -                 |
| 2                           | REAR BUMPER RETAINER                | SERVICEABLE             | 288.30                    | -                 |
| 1                           | REAR BUMPER PDC SENSOR WIRE HARNESS | NOT NECESSARY           | 342.40                    | -                 |
| 1                           | REAR BUMPER REINFORCEMENT           | BUCKLED                 | 474.42                    | 474.42            |
| 1                           | REAR WINDSCREEN                     | NOT NECESSARY           | 1,460.40                  | -                 |
| 2                           | REAR FENDER INNER TRIM              | TORN                    | 759.02                    | 759.02            |
| 1                           | REAR END PANEL                      | BUCKLED                 | 719.80                    | 571.40            |
| 1                           | REAR END PANEL GARNISH              | MOUNTING<br>DEFORMED    | 282.80                    | 282.80            |
| 2                           | REAR TAILLAMP                       | MOUNTING<br>CRACKED     | 963.80                    | 843.20            |
| 2                           | REAR TAILLAMP PANEL                 | TO REPAIR SEE<br>LABOUR | 261.08                    | -                 |

Report Ref No. CS/FCI18012502/Dvbn2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

| Qty | Description of Parts                                | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|---|---------------|---------------------------|-------------------|
| 2   | REAR TAILLAMP INNER SEAL                            | SERVICEABLE   | 70.34                     | -                 |
| 1   | REAR FLOOR PANEL                                    | DENTED        | 973.34                    | 802.90            |
| 1   | REAR SPARE TYRE TOP BOARD                           | BENT          | 309.88                    | 259.10            |
| 1   | REAR EXHAUST SILENCER                               | BENT          | 1,145.58                  | 794.50            |
| 1   | REAR EXHAUST MID PIPE                               | NOT NECESSARY | 3,409.90                  | -                 |
| 1   | REAR EXHAUST HEAT SHIELD                            | NOT NECESSARY | 189.10                    | -                 |
| 2   | REAR EXHAUST MOUNTING                               | NOT NECESSARY | 60.00                     | -                 |
| 2   | SPARE TYRE EXTENSION PANEL                          | NOT NECESSARY | 451.40                    | -                 |
|     | LESS 25% DISCOUNT                                   |               | -4,225.18                 | -1,832.58         |
|     |   |               | 12,675.57                 | 5,497.76          |
| 4   | REAR BUMPER PDC SENSOR (SN)                         | DAMAGED       | 780.00                    | 220.00            |
|     | LESS 25% DISCOUNT                                   |               | -195.00                   | -                 |
|     |   |               | 585.00                    | 220.00            |
|     | <b>SPECIAL NETT ITEMS</b>                           |               |                           |                   |
| 1   | SET REAR BUMPER CLIP (SN)                           | NECESSARY     | 60.00                     | 30.00             |
| 1   | SET REAR FENDER INNER TRIM CLIP (SN)                | NECESSARY     | 40.00                     | 20.00             |
| 1   | SET REAR FENDER INNER SHIELD CLIP (SN)              | NOT NECESSARY | 40.00                     | -                 |
| 1   | SET REAR BOOTLID INNER TRIM CLIP (SN)               | SERVICEABLE   | 40.00                     | -                 |
| 1   | REAR JOINT SEALANT (SN)                             | NECESSARY     | 150.00                    | 40.00             |
| 1   | REAR FLOOR INSULATOR (SN)                           | NECESSARY     | 150.00                    | 50.00             |
| 1   | REAR REVERSE CAMERA (SN)                            | NOT NECESSARY | 500.00                    | -                 |
|     |   |               | 980.00                    | 140.00            |
|     | <b>LABOUR</b>                                       |               |                           |                   |
|     | CHECK REAR WIRING AND LIGHTING SYSTEM.              |               | 60.00                     | 30.00             |
|     | REMOVE AND REFIT REAR LINING, TRIM AND GARNISH.     |               | 400.00                    | 80.00             |
|     | REMOVE AND RENEW REAR REVERSE SENSOR.               |               | 150.00                    | 40.00             |
|     | REMOVE AND REFIT FUEL TANK.                         | NOT NECESSARY | 150.00                    | -                 |
|     | REMOVE AND RENEW REAR EXHAUST ASSY.                 |               | 150.00                    | 60.00             |
|     | REMOVE AND RENEW FLOOR INSULATOR.                   |               | 150.00                    | 50.00             |
|     | TRANSFER PARTS, ATTACHMENT FROM OLD BOOTLID TO NEW. |               | 200.00                    | 60.00             |

Report Ref No. CS/FCI18012502/Dvbn2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

| Qty | Description of Parts   | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|--|-----------|---------------------------|-------------------|
|     | PANEL BEATING ON AFFECTED AREAS.INCLUSIVE OF THE REPAIR OF BOOTLID LOCK CATCH,BOOTLID HINGE AND REAR TAILLAMP PANEL. |           | 1,600.00                  | 800.00            |
|     | SPRAY PAINTING ON AFFECTED AREAS.  |           | 1,500.00                  | 800.00            |
|     | APPLY ANTI RUST ON AFFECTED AREAS.   |           | 150.00                    | 40.00             |
|     |  |           | 4,510.00                  | 1,960.00          |
|     | <b>GRAND TOTAL</b>   |           | <b>18,750.57</b>          | <b>7,817.76</b>   |
|     | <b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>  |           |                           | <b>6,250.00</b>   |

Report Ref No. CS/FC118012502/Dvbn2

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.