

ASS. REC. BY:

REP: CS/CTU18012540/Kvb2

Special Instruction:

Surveyor
merimen

ASSIGNMENT (Office)

From (Person): Hwang Shiang Yi of CT Date/Time: 10072018 12:18pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJM 1149L Insured:

at Workshop m/s: S & H Motor Tel: 6453 1730

of: 160 Sin Ming Drive #07-02

Policy No: DMP CSN 3007151801 Claim No: SNM13003351001

Sum Insured: Excess: Waived

Make of Veh: D.O.A. 05072018

(Client's Record)

CA / REV / REP. / REV 24 HRS 11.072018 H.O.D. Endorsement:

Date/Time: 10072018 1:07pm Person Contacted: Cynthia Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SJM 1149L - CS/CTU18012540 / J03 DUA: 00072018
11/7/18	Revert via merimen, pending repair cost from repairer
12/7/18	@ 349pm Doris request LS \$3500/-
12/7/18	Revert via merimen, repairer request LS \$3500
16/7/18	Rec approved from Susan by merimen

ASSIGNMENT

From: _____ Date: 11/7/2018

Estimated Cost: _____

☒ OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SJM 1149Lat Workshop m/s S & H Motorof 160 Sin Ming Drive #07-02

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: Waived

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$812K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 14 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA ☒ REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Date / Time Action / Instruction

12/7 File pass to Coroner16/7/18 Informed Doris clA on LS not exceeding \$3500 by email10/8/18 @455pm LS \$3500 confirmed with Doris (Reel 9719-55, 73B)

RECEIVED 23 AUG 2018

Veh No: SJM 1149L Yr Regn: 12, 08Type: ☒ M. Car / ☐ M. Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover / ☐ Truck / ☐ Trailer orMake: NIS Latio C.C. 1498Colour: M. Black A/C: ☐ Insured / ☐ Std / ☐ NI / ☐ NASp. Reading: 208392 T/Radio: ☐ Insured / ☐ Std / ☐ NI / ☐ NA

Eng/No: _____

C/No: JN1FAA C117 0010055Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orModi: ☐ Nil / ☐ S/Rim / ☒ STD / ☐ Rim orTyre Size: F: Dun 195/60R15R: Nil

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal. 65 mmL/Bal. 65 mmD.O.A. 5/7/18

Survey held at _____

Rear

R/Bal. 6 mmL/Bal. 6 mmD.O.I. 11/7/18Des. of Damages: ☐ Frt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop orFrnt O/S, N/S & Acc

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

1) 21/8 - typistDays Of Repair: 14Resurvey No. of Trip: 1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

____ \$ + RS. ____ \$

Photos

Others

TOTAL

220220

Report Format:

merimen

ump Sum / I.B.I. (\$

3500/-)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	09 Jul 2018 Sendback Est	09 Jul 2018 17:08 S\$13,219.55	10 Jul 2018 12:18 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:	ONG YOKE MIN, ID: 56815520G, Tel: +6596363879, Email: NOEMAIL								
Vehicle Reg. No.:	SJM1149L	Date of Loss:	05/07/2018 16:00 - :59 [114 Months and 13 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / SNM18D03351C01	Policy/Cover Note No.:	DMPCSN3007151801 (Comprehensive)						
		Excess:	S\$0.00						
Repairer:	S & H Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #07-02, Sin Ming AutoCity, 575722 Sin Ming - Tel: 6453 4730								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Hwang Shiang Yi - 63896541]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 19/07/2018]								
Driver/Custodian:	ONG YOKE MIN (50 / Male), NRIC: 56815520G, Tel: +6596363879								
Adj Asg. Remarks:	PLEASE SURVEY INSURED VEHICLE AND REVERT. EXCESS WAIVED.								
ASSOCIATED MAIL RECEIVED			View All	Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Monday, 16 July 2018 10:21 AM
To: 'Enquiry'; SUR; Doris
Subject: RE: Surveyor marking for SJM1149L

Dear Doris,

As instructed by our client , please proceed to repair the insured vehicle **SJM 1149L on Lump Sum basis not exceeding S\$3500/- (Excess S\$0/-).**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Enquiry [mailto:enquiry@sh-motor.com]
Sent: Wednesday, 11 July 2018 1:47 PM
To: SUR <sur@lkkauto.com>
Subject: Surveyor marking for SJM1149L

Hi,

Kindly see as per attached for your reference.

Thank you & Best Regards,

Cynthia

S&H MOTOR PTE LTD

160 Sin Ming Drive #07-02
Sing Ming AutoCity Singapore 575722
Tel: 6453 4730 Fax: 64571931

View Received Message

This mail is associated with :

SJM1149L (SNM18D03351C01)

OD

Jul 5 2018 4:00PM

[ONG YOKE MIN]

S & H Motor Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA_TAIPING), sent on 16/07/2018 09:35 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$3500.00) - SJM1149L - Claim Handler: Hwang Shiang Yi

Approved:3500.00.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd. 3 Anson Road #16-00 Springleaf Tower Singapore 079909	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Hwang Shiang Yi	Date: 12 Jul 2018
<u>Preliminary Advice</u>	

Vehicle No	: SJM1149L	Accident Date	: 05/07/2018
Make	: NISSAN LATIO	Policy No.	: DMPCSN3007151801
Assignment Date	: 10/07/2018	Excess	: S\$0.00
Date of Inspection	: 11/07/2018	Est. Duration of Repair	: 14.00
Inspection At	: S & H MOTOR PTE LTD (SIN MING) 160 SIN MING DRIVE #07-02, SIN MING AUTOCITY SINGAPORE 575722		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion, rear portion and n/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,219.55
Revised Amount	:S\$	8,473.60
Check Items (Estimated)	:S\$	3,773.83
Total	:S\$	12,247.43
Lump Sum Repair	:S\$	
Total Loss Consideration		
New for Old Value	:S\$	
Pre-Accident Value	:S\$	12,000.00
COE / PARF Rebate	:S\$	8,702.00
Salvage Value	:S\$	
Margin for Repair	:S\$	3,298.00

Remarks

☐	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
☐	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
☒	Other comments :Repairer asking for Lump Sum \$3500/-

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To:	China Taiping Insurance (Singapore) Pte. Ltd. 3 Anson Road #16-00 Springleaf Tower Singapore 079909	From:	LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn:	Hwang Shiang Yi	Date:	11 Jul 2018
<u>Preliminary Advice</u>			

Vehicle No	: SJM1149L	Accident Date	: 05/07/2018
Make	: NISSAN LATIO	Policy No.	: DMPCSN3007151801
Assignment Date	: 10/07/2018	Excess	: S\$0.00
Date of Inspection	: 11/07/2018	Est. Duration of Repair	: 14.00
Inspection At	: S & H MOTOR PTE LTD (SIN MING) 160 SIN MING DRIVE #07-02, SIN MING AUTOCITY SINGAPORE 575722		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion, rear portion and n/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,219.55
Revised Amount	:S\$	8,473.60
Check Items (Estimated)	:S\$	3,773.83
Total	:S\$	12,247.43
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	12,000.00
COE / PARF Rebate	:S\$	8,702.00
Salvage Value	:S\$	
Margin for Repair	:S\$	3,298.00

Remarks

☐	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
☐	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
☒	Other comments :Pending repair cost from repairer

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5520G
Vehicle Details	
Vehicle No.:	SJM1149L
Vehicle to be Exported:	No
Intended De-registration Date:	10 Jul 2018
Vehicle Make:	NISSAN
Vehicle Model:	LATIO CVT 1.5L ABS D/AIRBAG 2WD 5DR
Primary Colour:	Black
Manufacturing Year:	2008
Engine No.:	HR15399570A
Chassis No.:	JN1FAAC11Z0010055
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$16,716.00
Original Registration Date:	22 Dec 2008
First Registration Date:	22 Dec 2008
Transfer Count:	2
Actual ARF Paid:	\$16,716.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	21 Dec 2018
PARF Rebate Amount:	\$8,358.00
Intended COE Rebate Details	
COE Expiry Date:	21 Dec 2018
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$7,721.00
COE Rebate Amount:	\$344.00
Total Rebate Amount:	\$8,702.00

The information contained herein is correct as at 10 Jul 2018.

OK

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5520G
Vehicle Details	
Vehicle No.:	SJM1149L
Vehicle to be Exported:	Yes
Intended De-registration Date:	15 Jul 2018
Vehicle Make:	NISSAN
Vehicle Model:	LATIO CVT 1.5L ABS D/AIRBAG 2WD 5DR
Primary Colour:	Black
Manufacturing Year:	2008
Engine No.:	HR15399570A
Chassis No.:	JN1FAAC11Z0010055
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$16,716.00
Original Registration Date:	22 Dec 2008
First Registration Date:	22 Dec 2008
Transfer Count:	2
Actual ARF Paid:	\$16,716.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	21 Dec 2018
PARF Rebate Amount:	\$8,358.00
Intended COE Rebate Details	
COE Expiry Date:	21 Dec 2018
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$7,721.00
COE Rebate Amount:	\$334.00
Total Rebate Amount:	\$8,692.00

The information contained herein is correct as at 11 Jul 2018

OK

[> Back to OneMotoring](#)

Enquire Transfer Fee

Vehicle Details

Vehicle No.:	SJM1149L
Vehicle Type:	P10 - Passenger Motor Car
Vehicle Attachment 1:	No Attachment
Vehicle Scheme:	Normal
Vehicle Make:	NISSAN
Vehicle Model:	LATIO CVT 1.5L ABS D/AIRBAG 2WD 5DR
Chassis No.:	JN1FAAC11Z0010055
Propellant:	Petrol
Engine No.:	HR15399570A
Engine Capacity:	1498 cc
Maximum Power Output:	80.0 kW (107 bhp)
Maximum Laden Weight:	1435 kg
Unladen Weight:	1130 kg
Year Of Manufacture:	2008
Original Registration Date:	22 Dec 2008
Lifespan Expiry Date:	-
COE Category:	A - Car (1600cc & below)
Quota Premium:	\$7,721.00
COE Expiry Date:	21 Dec 2018
Road Tax Expiry Date:	21 Dec 2018
PARF Eligibility Expiry Date:	21 Dec 2018
Inspection Due Date:	21 Dec 2019
Intended Transfer Date:	06 Jul 2018
CO2 Emission:	-
CO Emission:	-
HC Emission:	-
NOx Emission:	-
PM Emission:	-

Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Total Amount Payable:			25.00

You may print this page for reference.

[OK](#)

[Print](#)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	06/07/2018 15:46
Date Of Accident	05/07/2018 16:05
Exact Location Of Accident	PIE TO CHANGI AIRPORT NEAR TP AFT THOMSON FLYOVER
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJM1149L
Insured/Policyholder	
Name Of Registered Owner	ONG YOKE MIN
NRIC No	S6815520G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96363879
Alternative Phone No	OFFICE-96363879

Vehicle Particulars

Manufacturer	NISSAN
Model	-

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPCSN3007151801
Cover Note Number	

Driver

Name of Driver	ONG YOKE MIN
NRIC No	S6815520G
Date Of Birth	24/05/1968
Occupation	INDOOR
Date Of Driving Pass	15/11/1985
Driving Experience	32 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96363879
Fax Number	
Contact Number	OFFICE-96363879
Email Address	NOEMAIL

Address -
 Postcode -
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident CHAIN COLLISION
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name JURONG WEST NEIGHBOURHOOD POLICE CENTRE
 Police Station Address ROAD: 700 CORPORATION ROAD , POSTCODE: 649818 , COUNTRY: SINGAPORE
 Police Station Contact TEL NO: 1800-2689999 - FAX NO: 62672438
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

refer attached police report.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKS4425D
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SKP338L
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number FBM7358E
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category MOTORCYCLE
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 4

Vehicle Registration Number SGS9686D
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name
Approximate Age
Injuries Sustain
Injured person in which vehicle? FBM7358E
Were seat belts worn?
Was this injured conveyed to hospital by ambulance? NO
Address
Postcode


SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims, (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



⑤ SGS 9686D

④ CTS 4425D

③ SJM 1149L

② FBM 7358E

① SKP 338L

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer attached police report.


DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature

Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:


**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Sering West S.P.C.
700 Corporation Road SINGAPORE 848118
Tel No: 1800-2551999



130180062157

1 of 4

Report No: K200000000157


Statement of a Roadside Accident

Driver's Name Report Made		Victim Report No.		Station Query No.	
05/07/2018 20:24				2113	
Accident Details					
Name of Informant		Address			
Ong Yock MIN		APT BLK 142 BRUNT MATOK STREET 11 #15-13 SINGAPORE			
ID Type (SG No.)		Contact No.			
SPRING 400 888159290		M. Min 90303878			
Nationality		Home/Office			
SINGAPORE CITIZEN		Estate			
Sex		Date of Birth		Type of Informant	
Male		24/05/1988		Driver	
Name		Language		Registration / School Name	
Chenue					
Occupation		Driving License Information		Date of Expiry	
SELF EMPLOYED		Class 3			

Details of the Accident

Type of Accident	Non-Injury	Others	Drink Drive	Other Time of Accident	Type of Location
			No	05/07/2018 18:00	Along Road
Location					
Along Road 1					
PAN ISLAND EXPRESSWAY					
PAN ISLAND EXPRESSWAY NEAR TOA PAYOH AFTER THOMSON FLYOVER TOWARDS CHANGI					
Road Surface					
Dry					
Road Speed Limit					
80 km/h					
Traffic Flow					
Traffic Control					
Not Controlled					
Type of Vehicle					
PST TWO VEHICLE ON THE FRONT AND TO THE LEFT					
Anyone conveyed by ambulance					
No					

Report No.	Station	Vehicle	Make	Color	Condition	No. of Passenger
PST07388	Motorcycle				Slightly Damaged	0
PST07389	Car				Slightly Damaged	0
PST07390	Car	NISSAN	LATIO CVT 1.8L ABS, CHAIRING 2ND SORT	Black	Slightly Damaged	0



Major Offices Of Origin
 Irving West N. H. C.
 100 Corporate Road Singapore 648116
 Tel: 1600-216009

CONTRIBUTORS: FROM OUR SPONSOR

Overall condition	Model	Year	Condition	No. of Passengers
Good	Car	1971-1980	Slightly Damaged	0
Good	Car	1981-1990	Slightly Damaged	0
Good	Car	1991-2000	Slightly Damaged	0
Good	Car	2001-2010	Slightly Damaged	0
Good	Car	2011-2020	Slightly Damaged	0
Good	Car	2021-2030	Slightly Damaged	0
Good	Car	2031-2040	Slightly Damaged	0
Good	Car	2041-2050	Slightly Damaged	0
Good	Car	2051-2060	Slightly Damaged	0
Good	Car	2061-2070	Slightly Damaged	0
Good	Car	2071-2080	Slightly Damaged	0
Good	Car	2081-2090	Slightly Damaged	0
Good	Car	2091-2100	Slightly Damaged	0
Good	Car	2101-2110	Slightly Damaged	0
Good	Car	2111-2120	Slightly Damaged	0
Good	Car	2121-2130	Slightly Damaged	0
Good	Car	2131-2140	Slightly Damaged	0
Good	Car	2141-2150	Slightly Damaged	0
Good	Car	2151-2160	Slightly Damaged	0
Good	Car	2161-2170	Slightly Damaged	0
Good	Car	2171-2180	Slightly Damaged	0
Good	Car	2181-2190	Slightly Damaged	0
Good	Car	2191-2200	Slightly Damaged	0
Good	Car	2201-2210	Slightly Damaged	0
Good	Car	2211-2220	Slightly Damaged	0
Good	Car	2221-2230	Slightly Damaged	0
Good	Car	2231-2240	Slightly Damaged	0
Good	Car	2241-2250	Slightly Damaged	0
Good	Car	2251-2260	Slightly Damaged	0
Good	Car	2261-2270	Slightly Damaged	0
Good	Car	2271-2280	Slightly Damaged	0
Good	Car	2281-2290	Slightly Damaged	0
Good	Car	2291-2300	Slightly Damaged	0
Good	Car	2301-2310	Slightly Damaged	0
Good	Car	2311-2320	Slightly Damaged	0
Good	Car	2321-2330	Slightly Damaged	0
Good	Car	2331-2340	Slightly Damaged	0
Good	Car	2341-2350	Slightly Damaged	0
Good	Car	2351-2360	Slightly Damaged	0
Good	Car	2361-2370	Slightly Damaged	0
Good	Car	2371-2380	Slightly Damaged	0
Good	Car	2381-2390	Slightly Damaged	0
Good	Car	2391-2400	Slightly Damaged	0
Good	Car	2401-2410	Slightly Damaged	0
Good	Car	2411-2420	Slightly Damaged	0
Good	Car	2421-2430	Slightly Damaged	0
Good	Car	2431-2440	Slightly Damaged	0
Good	Car	2441-2450	Slightly Damaged	0
Good	Car	2451-2460	Slightly Damaged	0
Good	Car	2461-2470	Slightly Damaged	0
Good	Car	2471-2480	Slightly Damaged	0
Good	Car	2481-2490	Slightly Damaged	0
Good	Car	2491-2500	Slightly Damaged	0
Good	Car	2501-2510	Slightly Damaged	0
Good	Car	2511-2520	Slightly Damaged	0
Good	Car	2521-2530	Slightly Damaged	0
Good	Car	2531-2540	Slightly Damaged	0
Good	Car	2541-2550	Slightly Damaged	0
Good	Car	2551-2560	Slightly Damaged	0
Good	Car	2561-2570	Slightly Damaged	0
Good	Car	2571-2580	Slightly Damaged	0
Good	Car	2581-2590	Slightly Damaged	0
Good	Car	2591-2600	Slightly Damaged	0
Good	Car	2601-2610	Slightly Damaged	0
Good	Car	2611-2620	Slightly Damaged	0
Good	Car	2621-2630	Slightly Damaged	0
Good	Car	2631-2640	Slightly Damaged	0
Good	Car	2641-2650	Slightly Damaged	0
Good	Car	2651-2660	Slightly Damaged	0
Good	Car	2661-2670	Slightly Damaged	0
Good	Car	2671-2680	Slightly Damaged	0
Good	Car	2681-2690	Slightly Damaged	0
Good	Car	2691-2700	Slightly Damaged	0
Good	Car	2701-2710	Slightly Damaged	0
Good	Car	2711-2720	Slightly Damaged	0
Good	Car	2721-2730	Slightly Damaged	0
Good	Car	2731-2740	Slightly Damaged	0
Good	Car	2741-2750	Slightly Damaged	0

Line of Work & Insurance	Insurance No.	Effective	Expiry Date
Line of Work & Insurance	DMACRIN0071818	17/01/2016	16/01/2019
Line of Work & Insurance	CHINA FOREIGN INSURANCE (OVERSEAS) PTE LTD	01	

Is/are all persons involved Any Pedestrian Involved Yes		List of Pedestrian Crossing N/A	
Event			
Name	ONG TOUR M/N	ID No	566165300
Rescued Victims	N/A	Contact No	96383879
Hospital/Clinic	N/A	Class of Driving License & Expiry Date	Class: 3 Date of Expiry: Nil
Date/Treatment Nil No. of Days granted Medical Leave Nil		Date Discharge Nil Expiry of Injury Nil	

United Details:

On 08/07/2018 at about 1600hrs, I was driving my vehicle, EJ3114AL, along I94 towards Changi. While on the PSE, shortly after Thomson Flyover, I was driving at a speed of 80km/h when another vehicle, SKS442SDU ran off an E-Bridge causing me to perform an E-Bridge as well. However as I expected that I could not stop in time, I immediately swerved to the left to avoid a head on collision with EJ344283. While swerving to the left, I also collided with SKS442SDU on its rear left bumper, as well as EF3286, which was on the left of SKS442SDU. I hit the side of SKS442SDU on the right side of the vehicle and the motorcycle, FEM7358E flew into my rear

After the accident, I put off my vehicle to assess the situation. The driver of 5K554425D claimed that he had hit another vehicle, 6S359486D due to my vehicle hitting him, however I have doubts about his claims. I did not manage to take their particulars as I was in shock and not thinking well, however the other drivers and motorcyclist took my particulars.

I wish to state that there was another gentleman, SL R027E who saw the accident and claimed he was part a Workshop, and proceeded to assist the other vehicles. However I have a feeling that he is helping due to me-conceal secrets. The gentleman who drove SL R027E, drove SK0443SD away from the accident zone. I did wish to state that I did not consume nor take any intoxicating substances before and during the drive.

Accident Sketch Plan

**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Jurong West N.P.C.
700 Corporation Road SINGAPORE 649118
Tel No: 1800 2688889

Report No: T07060000155

3 of 4

COMPLETION OF REPORT

130306 0500157

Accident Sketch Plan

SINGAPORE POLICE FORCE
 Police Station: 04-0101
 Joo Koon Road, Singapore 640001
 Tel No: 1100-0000

Accident Report Form
 Report No: 04-0101-00000000

CONNECTIONS OF REPORT

Sketch Plan
 Attached is a set of sketches to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 6547 4000 using the report number as reference.

Signature Of Officer Recording The Report
 S/P 3 CHENG WEE TONG

Signature Of Intervenor
 Not applicable

Signature Of Injured
 [Signature]

Date/Time
 05/07/2018 20:24

Classification Of Case

Officer In Charge Of Case
 SP 1 GUA /
 SP 1 SGT WONG SIEU LUE
 Contact No: 6547 0000

Authorisation Stamp
 [Stamp]

S & H Motor Pte Ltd
Blk 106 Sin Ming Drive
#07-02
Sin Ming Autocity
Singapore 575722

Claim Reference:
Assessment Number: SH000245
Version: S&HMOTOR/1
Date Calculated: 09/07/2018 10:07

Full Report - V1
Registration: SJM1149L
Printed: 09/07/2018 17:08

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	SH Motor	Date of Incident:	05/07/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	China Taiping Insurance (S) Pt	Repairs Authorised:	TBA
Claim Reference:		Estimated Repair Time:	
Policy Number:	DMPCSN3007151801	Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	NISSAN
Model:	Latio
Sub Model:	BASE MODEL
Model Sheet Number:	Z76 19
Registration:	SJM1149L
Registration Month:	
Registration Year:	
VIN Number:	
Odometer:	Not Known
Colour:	
Engine Number:	
Fuel Level:	%

Model Specs

FROM 07/2008	AIR CONDITIONING
FOG LAMPS	1.5 LTR 80KW
CVT AUTO GEARBOX	ANTI LOCK BRAKES
5-DOOR	TWO COAT METALLIC
PREPARE OFF VEHICLE	



For oil, n/s body
& Acc

Not Authorized
11/7/87
Pushing After Repair
Ex NL

Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Severity of Impact:	
Steering:	Vehicle Status on Inspection:	
Brakes Pedal Travel:	Date of Inspection:	09/07/2018
Place of Inspection:		
Pre-Accident Damage:		
Tyres Condition:		
Tread Depth LHF:	Tread Depth RHF:	
Tread Depth LHR:	Tread Depth RHR:	
Damage Areas:	Direction of Impact:	

14 days
Fax: 62564315

Claim Reference:

Assessment Number: SH000245



Version: S&HMOTOR/1

Date Calculated: 09/07/2018 10:07

Full Report - V1

Registration: SJM1149L

Printed: 09/07/2018 17:08



Addresses

Cost Summary

Total Labour	\$3,256.80
Total Paint/Material	\$392.92
Total Parts	\$9,244.83
Total of Additional Costs	\$325.00
Excess:	TBA
Grand Total Exc GST:	\$13,219.55
7 % GST:	\$925.37
Grand Total Inc GST:	\$14,144.92

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$46.00/HR

Price/Dent = \$46.00/HR

Repair /

Guide Number	Repair Details	WU	Cost Price (\$)
NO NUMBER	JOB ALLOWANCE	5.0	23.00
2991A1	ADJUST FRONT TOE	7.0	32.20
1262A1	RENEW L/F WING, L/F FRONT PANEL AND FRONT UPPER CROSSMEMBER INCLUDES: R + R FRONT BUMPER, R/F WING, RADIATOR, CONDENSER AND ALL ATTACHED PARTS IN THE REPAIR SECTION, DRAIN + REFILL AIR CONDITIONING	45.0	207.00
1651A1	RENEW RIGHT FRONT WHEELHOUSE (COMPOSITE WORK) INCLUDES: EXPOSE REPAIR AREA	36.0	165.60
CD30A1	R + R LOWER ENGINE COMPARTMENT PANELLING	3.0	13.80
1420A1)	R + R FRONT LOWER CROSSMEMBER	9.0	41.40
1243A1	RENEW RIGHT FRONT PANEL INCLUDES: R + R RADIATOR, FRONT BUMPER, FRONT WING, RIGHT HEADLAMP AND ALL NECESSARY ATTACHED PARTS	48.0	220.80
UA10A2)	RENEW FRONT BUMPER (BUMPER REMOVED) INCLUDES: R + R BUMPER REINFORCEMENTS	3.0	13.80
2211A1	RENEW L/F FOG LAMP (REMOVED)	1.0	4.60
2211A1	RENEW R/F FOG LAMP (REMOVED)	1.0	4.60
1150A1	R + R RADIATOR GRILLE BADGE	1.0	4.60
1350A1	RENEW R/HEADLAMP (REMOVED)	1.0	4.60
2990A1	ADJUST HEADLAMPS	2.0	9.20

S & H Motor Pte Ltd

Claim Reference:

Assessment Number: SH000245

Version: S&HMOTOR/1

Date Calculated: 09/07/2018 10:07

Full Report - V1

Registration: SJM1149L

Printed: 09/07/2018 17:08

1231A1	ADDITIONAL WORK FOR RENEW RIGHT WING (BUMPER REMOVED) INCLUDES: R + R INNER WING PROTECTION AND INDICATOR LAMP	9.0	41.40
UE26A2	RENEW BONNET INCLUDES: CONVERT ALL ATTACHED PARTS AND ADJUST BONNET, APPLY PROTECTIVE WAX	4.0	18.40
2921A1	RENEW LEFT BONNET HINGE (BONNET REMOVED)	1.0	4.60
2922A1	RENEW RIGHT BONNET HINGE (BONNET REMOVED)	1.0	4.60
UE24A2	R + R AIR INLET COVER	3.0	13.80
VB14A2)	R + R R/UPPER A-PILLAR TRIM	1.0	4.60
VB15A1)	R + R L/- AND R/A-PILLAR TRIM	1.0	4.60
UH40A2	R + R LEFT FRONT DOOR TRIM	2.0	9.20
4192A1	R + R LEFT FRONT DOOR WINDOW GLASS AND WINDOW LIFTER (DOOR TRIM REMOVED)	4.0	18.40
8004A1)	R + R RIGHT FRONT QTR WINDOW GLASS	1.0	4.60
UK36A2	R + R LEFT REAR DOOR TRIM	2.0	9.20
4212A1	R + R LEFT REAR DOOR WINDOW GLASS AND WINDOW LIFTER (DOOR TRIM REMOVED)	5.0	23.00
740441	DISM/ASS STEERING BOX (REMOVED)	2.0	9.20
PW10A1)	R + R LEFT FRONT WHEEL	2.0	9.20
PW10A1)	R + R RIGHT FRONT WHEEL	2.0	9.20
PW10A1)	FIT/BALANCE RIGHT FRONT TYRE (WHEEL REMOVED)	3.0	13.80
7200A1 ZAX	R + R RIGHT FRONT STRUT (WHEEL REMOVED)	1.0	4.60
7228A1)	DETACH + REFIT L/- AND R/DRIVE SHAFT	1.0	4.60
7225B1)	R + R RIGHT FRONT DRIVE SHAFT	2.0	9.20
7202A1)	DISS/ASS R/F SUSPENSION STRUT	3.0	13.80
7204A1)	R + R RIGHT FRONT STEERING KNUCKLE (WHEEL REMOVED) INCLUDES: R + R BRAKE DISC AND BRAKE DISC PROTECTION PLATE	4.0	18.40
7204A1)	R + R RIGHT FRONT WHEEL HUB	3.0	13.80
7205A1)	RENEW STEERING KNUCKLE/WHEEL BEARG/SEAL	2.0	9.20
7200A1 ZAX	DET + REF SPR-LEG TUBES AND WH-BEAR HOUS	3.0	13.80
7212A1)	DETACH/REFIT L/FRT CONTROL ARM	2.0	9.20
7212A1)	DETACH/REFIT R/FRT CONTROL ARM	2.0	9.20
7224A1)	RENEW FRONT AXLE BODY (BOTH AXLE LINK MOULDINGS AND WHEELS REMOVED) INCLUDES: R + R STEERING, FRONT STABILIZER AND BOTH AXLE LINKS	14.0	64.40
NO NUMBER	ADD/WORK FOR AIR CONDITIONING	10.0	46.00
NN	AIR CON COOLANT R&R / NEW PARTS	20.0*	92.00
1276	REPAIR R/S-MEMB COVER PANEL	15 30.0*	138.00
1481	REPAIR LEFT FRONT DOOR	30 50.0*	230.00
1482	REPAIR RIGHT FRONT DOOR	10.0* ✓	46.00
1781	REPAIR L/R DOOR	15 40.0*	184.00

S & H Motor Pte Ltd

Claim Reference:

Assessment Number: SH000245

Version: S&HMOTOR/1

Date Calculated: 09/07/2018 10:07

Full Report - V1

Registration: SJM1149L

Printed: 09/07/2018 17:08

2085	REPAIR L/SIDE FRAME CPL	20 40:0*	184.00
2102	REPAIR R/OUTER DOOR SILL	15 40:0*	184.00
LABOUR COST			
	Total Work Units	482.0	
	Panel / Mechanical Labour	47.5HRS	\$2,185.00
	Visual Alignment Labour	0.7HRS	\$32.20
	Corrosion Protection External Labour	0.0HRS	0.00
	Corrosion Protection Internal Labour	0.0HRS	0.00
	Sub Total	48.2HRS	\$2,217.20
	Paint Labour	22.6HRS	\$1,039.60
	Total Labour	70.8HRS	\$3,256.80

PAINT WORK		Time Basis 10 WU = 1 HR. Price = \$46.00/HR	
Guide Number	Description	WU	Cost Price (\$)
	- TWO COAT METALLIC		
	- PREPARE OFF VEHICLE		
340	FRT BUMPER SUPPORT SURFACE PAINT	4.0	
471	BONNET NEW PART PAINTING	19.0	
741	L/F WING NEW PART PAINTING	10.0	
742	R/F WING NEW PART PAINTING	10.0	
1001	LOWER CROSSMEMBER SURFACE PAINT	5.0	
1007	L/UPP RADIATOR BRKT SURFACE PAINT	4.0	
1008	R/UPP RADIATOR BRKT SURFACE PAINT	4.0	
1017	FRT UPP CROSSMEMBER SURFACE PAINT	4.0	
1118	R/F WHEELHOUSE CPL SURFACE PAINT	6.0	
283	FRONT BUMPER NEW PART PAINT K1R	10.0	
651	L/FOG LAMP COVER NEW PART PAINT K1R	3.0	
652	R/FOG LAMP COVER NEW PART PAINT K1R	3.0	
1737	L/DOOR MIRROR NEW PART PAINT K1R	4.0	
2208	R/SILL EXTENSION NEW PART PAINT K1R	5.0	
1481	LEFT FRONT DOOR REPAIR PAINTING <50%	17.0	
1482	RIGHT FRONT DOOR REPAIR PAINTING <50%	17.0	
1781	L/R DOOR REPAIR PAINTING <50%	15.0	
2101	L/OUTER DOOR SILL REPAIR PAINTING <50%	10.0	
2102	R/OUTER DOOR SILL REPAIR PAINTING <50%	10.0	
2229	LEFT A-PILLAR REPAIR PAINTING <50%	8.0	
2291	LEFT B-PILLAR REPAIR PAINTING <50%	9.0	
2351	ROOF CPL SURFACE PAINT	13.0	
3481	L/R WING SURFACE PAINT	6.0	
LABOUR COST - PAINT			
	TIME(PAINT)	196.0	
	Preparation Main Work Plastic	5.0	
	Preparation Main Work Metal	25.0	
	Preparation Work Multi Layer Paint	0.0	
	Total Work Units (10WU/HR)	226.0	
	Total Paintwork Labour	22.6HRS	\$1,039.60
MATERIAL COST - PAINT			
	New Part Painting		\$92.88
	New Part Painting - Plastic K1R		\$63.97
	Material-Constant Main Work Metal		\$28.60
	Surface-/Blend Paint		\$88.65
	Repair Painting		\$109.82

S & H Motor Pte Ltd

Claim Reference:

Assessment Number: SH000245

Version: S&HMOTOR/1

Date Calculated: 09/07/2018 10:07

Full Report - V1

Registration: SJM1149L

Printed: 09/07/2018 17:08

Material-Const Main Work Plastic
Total Excluding Pearlescent Uplift
Pearlescent Uplift @ 0.0%
Total Paint Material Cost

\$9.00
\$392.92
\$0.00
\$392.92

PARTS

Price Valid: 01/06/2015

Guide No.	Qty	Description	Part Number	Supplier	Bet.	Price (\$)	
257	1	FRONT NUMBER PLATE	KNPL3		0%	217 45.00*	—
283	1	FRONT BUMPER	62022 1JY0J		0%	217 290.00*	—
299	1	FRT UPP BUMPER COVER	62322 ED000		0%	217 120.00*	—
333	1	FRT BUMPER S-ABSORB	62090 1JY0A		0%	217 180.00*	—
340	1	FRT BUMPER SUPPORT	62030 1JY0A		0%	217 260.00*	—
350	6	FRT BUMPER CLAMP KIT	01553 09321		0%	217 22.00*	✓
413	1	RADIATOR SHROUD	62310 1JY0B		0%	217 280.00*	X
431	1	BONNET EMBLEM	62890 9Y000		0%	217 60.00*	—
471	1	BONNET	F510M ED0MA		0%	217 390.00*	—
475	1	LEFT BONNET HINGE	65401 ED00A		0%	217 40.00*	—
476	1	RIGHT BONNET HINGE	65400 ED00A		0%	217 40.00*	—
562	1	RIGHT HEADLAMP ASSY	26010 1JY1A		0%	217 380.00*	—
637	1	L/F FOG LAMP	SEE GUIDE NO. 0639		0%	217 120.00*	—
638	1	R/F FOG LAMP	SEE GUIDE NO. 0639		0%	217 120.00*	—
651	1	L/FOG LAMP COVER	62050 CY000		0%	217 55.00*	—
652	1	R/FOG LAMP COVER	62050 CY000		0%	217 55.00*	—
707	1	L/SIDE REPEATER LAMP	26160 AX00A		0%	217 45.00*	—
708	1	R/SIDE REPEATER LAMP	26160 AX00A		0%	217 45.00*	X
741	1	L/F WING	63101 ED0MA		0%	217 260.00*	—
742	1	R/F WING	63100 ED0MA		0%	217 260.00*	—
748	1	R/F WING BRACKET	62224 ED000		0%	217 18.00*	—
789	13	L/F WING CLAMP KIT	08146 6122G		0%	217 18.00*	—
790	13	R/F WING CLAMP KIT	08146 6122G		0%	217 18.00*	—
841	1	L/F WHEELHOUSE COVER	63843 ED05D		0%	217 80.00*	—
842	1	R/F WHEELHOUSE COVER	63842 ED05D		0%	217 80.00*	—
1001	1	LOWER CROSSMEMBER	62530 ED00A		0%	217 180.00*	X
1007	1	L/UPP RADIATOR BRKT	62513 ED000		0%	217 80.00*	X
1008	1	R/UPP RADIATOR BRKT	62512 ED000		0%	217 80.00*	X
1017	1	FRT UPP CROSSMEMBER	62511 ED000		0%	217 180.00*	X
1118	1	R/F WHEELHOUSE CPL	64120 ED000		0%	217 290.00*	X
1166	1	R/UPP W-HOUSE REINF	64190 ED500		0%	217 80.00*	X
1168	1	R/UPP W-HOUSE REINF	64180 ED000		0%	217 260.00*	X
1435	1	W-WASHER BOTTLE	28910 ED00A		0%	217 90.00*	—
1518	1	R/F QTR WINDOW	76820 ED500		0%	217 240.00*	—
1741	1	QTR WINDOW SEAL KIT	G289A 89925		0%	217 40.00*	—
2208	1	R/SILL EXTENSION	76850 ED000		0%	217 120.00*	—
7011	1	FRONT AXLE BEAM	54400 EW00B		0%	217 380.00*	—
7036	1	R/DRIVE SHAFT CPL	39100 1V10A		0%	217 750.00*	—
7054	1	R/F LOWER AXLE ARM	54500 1FU0B		0%	217 180.00*	—
7056	1	R/F C/ARM MNTG KIT	USE SINGLE PARTS		0%	217 0.00	X
7062	1	SCREW	54459 AX02E		0%	217 6.18U	X
7064	2	NUT	08918 6421A		0%	217 5.14U	X
7066	1	SCREW	54459 ED04A		0%	217 17.51U	X
7078	1	R/F STRUT	E4302 EU51A		0%	217 190.00*	✓

S & H Motor Pte Ltd

Claim Reference:

Assessment Number: SH000245

Version: S&HMOTOR/1

Date Calculated: 09/07/2018 10:07

Full Report - V1

Registration: SJM1149L

Printed: 09/07/2018 17:08

7082	1	R/F STEERING KNUCKLE	40014 ED000	0%	By	360.00*	✓
7096	1	R/UPP SPRING SEAT	54320 1FE0A	0%	Sm	65.00*	X
7132	1	R/F WHEEL HUB	40202 EE90A	0%	By	260.00*	X
7228	1	R/F TYRE	185/65 R 15 .. H	0%	Cur	145.00*	401
7261	1	FRONT STABILISER	54611 EW01A	0%	Sm	290.00*	8
7269	1	L/F STABILISER BUSH	54613 ED001	0%	Sm	20.00*	2
7270	1	R/F STABILISER BUSH	54613 ED001	0%	Sm	20.00*	2
7271	1	L/STABI CLAMP	54614 AX400	0%	Sm	45.00*	2
7272	1	R/STABI CLAMP	54614 AX400	0%	Sm	45.00*	X
7274	1	R/LOWER TOWING STRUT	54618 ED00A	0%	Sm	95.00*	2
7302	1	POWER STEERING	48010 ED01A	0%	Attn	1,200.00*	2
7311	1	L/TIE ROD BALL JOINT	48640 3U025	0%	Sm	95.00*	X
7312	1	R/TIE ROD BALL JOINT	48520 3U025	0%	Sm	95.00*	2
9986	1	AIR CON COOLANT	NO NUMBER	0%	Sm	60.00*	201
f: OEM Parts				Sub Total		\$9,244.83	
g: Original				Total Parts		\$9,244.83	
h: Secondhand							
p: Parallel							
x: Exchange							

THIS ASSESSMENT CONTAINS UNPRICED PARTS

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description	Betterment	Price	
TOWING SPECIALIST	0%	\$90.00	X
ELECTRICAL WORK SPECIALIST		\$50.00	201
WHEEL ALIGNMENT SPECIALIST	0%	\$65.00	✓
ECU DIAGNOSTIC SPECIALIST		\$120.00	X
Total Extras		\$325.00	

Final Calculation

Total Parts	\$9,244.83
Labour	
Total Panel/Mechanical	\$2,185.00
Total Paintwork	\$1,039.60
Total Visual Alignment work	\$32.20
Total Labour	\$3,256.80
Additional Costs	
Corr Prot Materials External	\$0.00
Corr Prot Materials Internal	\$0.00
Cost of Specialist	\$325.00
Total of Additional Costs	\$325.00
Total Paint/Material Costs	\$392.92
Grand Total Excludes GST	\$13,219.55
GST @ 7 %	\$925.37
Grand Total Includes GST	\$14,144.92

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Assessment Notes

Claim Reference:

Assessment Number: SH000245

Version: S&HMOTOR/1

Date Calculated: 09/07/2018 10:07

Full Report - V1

Registration: SJM1149L

Printed: 09/07/2018 17:08

51 Ubi Avenue 1, #01-25
Paya Ubi Industrial Park
Singapore
408933

Revert

Claim Reference: 18/3351
Assessment Number: SH000245
Version: S&HMOTOR/2
Date Calculated: 11/07/2018 08:22

Full Report - V1
Registration: SJM1149L
Printed: 11/07/2018 15:23

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	LKK AUTO	Date of Incident:	05/07/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	China Taiping Insurance (S) Pt	Repairs Authorised:	TBA
Claim Reference:	18/3351	Estimated Repair Time:	
Policy Number:	DMPCSN3007151801	Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	NISSAN
Model:	Latio
Sub Model:	BASE MODEL
Model Sheet Number:	Z76 19
Registration:	SJM1149L
Registration Month:	
Registration Year:	
VIN Number:	
Odometer:	Not Known
Colour:	
Engine Number:	
Fuel Level:	%



Model Specs

FROM 07/2008	AIR CONDITIONING
FOG LAMPS	1.5 LTR 80KW
CVT AUTO GEARBOX	ANTI LOCK BRAKES
5-DOOR	TWO COAT METALLIC
PREPARE OFF VEHICLE	

Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Severity of Impact:
Steering:	Vehicle Status on Inspection:
	Date of Inspection: 09/07/2018
Brakes Pedal Travel:	
Place of Inspection:	
Pre-Accident Damage:	
Tyres Condition:	Tread Depth RHF:
Tread Depth LHF:	Tread Depth RHR:
Tread Depth LHR:	Direction of Impact:
Damage Areas:	



Addresses

Cost Summary

Total Labour	\$2,709.40
Total Paint/Material	\$386.20
Total Parts	\$8,856.83
Total of Additional Costs	\$295.00
Excess:	- \$0.00
Grand Total Exc GST:	\$12,247.43
7 % GST:	\$857.32
Grand Total Inc GST:	\$13,104.75

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$46.00/HR
Price/Dent = \$46.00/HR

Repair / Guide Number	Repair Details	WU	Cost Price (\$)
NO NUMBER	JOB ALLOWANCE	5.0	23.00
2991A1	ADJUST FRONT TOE	7.0	32.20
1262A1	RENEW L/F WING, L/FRONT PANEL AND FRONT UPPER CROSSMEMBER INCLUDES: R + R FRONT BUMPER, R/F WING, RADIATOR, CONDENSER AND ALL ATTACHED PARTS IN THE REPAIR SECTION, DRAIN + REFILL AIR CONDITIONING	45.0	207.00
CD30A1	R + R LOWER ENGINE COMPARTMENT PANELLING	3.0	13.80
1751A1	RENEW R/FRONT WHEELHOUSE REINFORCEMENT	20.0	92.00
1420A1)	R + R FRONT LOWER CROSSMEMBER	9.0	41.40
1243A1	RENEW RIGHT FRONT PANEL INCLUDES: R + R RADIATOR, FRONT BUMPER, FRONT WING, RIGHT HEADLAMP AND ALL NECESSARY ATTACHED PARTS	48.0	220.80
UA10A2)	RENEW FRONT BUMPER (BUMPER REMOVED) INCLUDES: R + R BUMPER REINFORCEMENTS	3.0	13.80
2211A1	RENEW L/F FOG LAMP (REMOVED)	1.0	4.60
2211A1	RENEW R/F FOG LAMP (REMOVED)	1.0	4.60
1150A1	R + R RADIATOR GRILLE BADGE	1.0	4.60
1350A1	RENEW R/HEADLAMP (REMOVED)	1.0	4.60
2990A1	ADJUST HEADLAMPS	2.0	9.20
1231A1	ADDITIONAL WORK FOR RENEW RIGHT WING (BUMPER REMOVED) INCLUDES: R + R INNER WING PROTECTION	9.0	41.40

UE26A2	AND INDICATOR LAMP RENEW BONNET INCLUDES: CONVERT ALL ATTACHED PARTS AND ADJUST BONNET, APPLY PROTECTIVE WAX	4.0	18.40
2921A1	RENEW LEFT BONNET HINGE (BONNET REMOVED)	1.0	4.60
2922A1	RENEW RIGHT BONNET HINGE (BONNET REMOVED)	1.0	4.60
UE24A2	R + R AIR INLET COVER	3.0	13.80
VB14A2)	R + R R/UPPER A-PILLAR TRIM	1.0	4.60
VB15A1)	R + R L/- AND R/A-PILLAR TRIM	1.0	4.60
UH40A2	R + R LEFT FRONT DOOR TRIM	2.0	9.20
4192A1	R + R LEFT FRONT DOOR WINDOW GLASS AND WINDOW LIFTER (DOOR TRIM REMOVED)	4.0	18.40
8004A1)	R + R RIGHT FRONT QTR WINDOW GLASS	1.0	4.60
UK36A2	R + R LEFT REAR DOOR TRIM	2.0	9.20
4212A1	R + R LEFT REAR DOOR WINDOW GLASS AND WINDOW LIFTER (DOOR TRIM REMOVED)	5.0	23.00
740441	DISM/ASS STEERING BOX (REMOVED)	2.0	9.20
PW10A1)	R + R LEFT FRONT WHEEL	2.0	9.20
PW10A1)	R + R RIGHT FRONT WHEEL	2.0	9.20
PW10A1)	FIT/BALANCE RIGHT FRONT TYRE (WHEEL REMOVED)	3.0	13.80
7200A1 ZAX	R + R RIGHT FRONT STRUT (WHEEL REMOVED)	1.0	4.60
7228A1)	DETACH + REFIT L/- AND R/DRIVE SHAFT	1.0	4.60
7225B1)	R + R RIGHT FRONT DRIVE SHAFT	2.0	9.20
7202A1)	DISS/ASS R/F SUSPENSION STRUT	3.0	13.80
7204A1)	R + R RIGHT FRONT STEERING KNUCKLE (WHEEL REMOVED)	4.0	18.40
7204A1)	INCLUDES: R + R BRAKE DISC AND BRAKE DISC PROTECTION PLATE	3.0	13.80
7205A1)	R + R RIGHT FRONT WHEEL HUB	2.0	9.20
7200A1 ZAX	RENEW STEERING KNUCKLE/WHEEL BEARG/SEAL	3.0	13.80
7212A1)	DET + REF SPR-LEG TUBES AND WH-BEAR HOUS	3.0	13.80
7212A1)	DETACH/REFIT L/FRT CONTROL ARM	2.0	9.20
7212A1)	DETACH/REFIT R/FRT CONTROL ARM	2.0	9.20
7224A1)	RENEW FRONT AXLE BODY (BOTH AXLE LINK MOULDINGS AND WHEELS REMOVED)	14.0	64.40
NO NUMBER	INCLUDES: R + R STEERING, FRONT STABILIZER AND BOTH AXLE LINKS	10.0	46.00
NN	ADD/WORK FOR AIR CONDITIONING	20.0*	92.00
1276	AIR CON COOLANT R&R / NEW PARTS	15.0*	69.00
1481	REPAIR R/S-MEMB COVER PANEL	30.0*	138.00
1482	REPAIR LEFT FRONT DOOR	10.0*	46.00
1781	REPAIR RIGHT FRONT DOOR	15.0*	69.00
2085	REPAIR L/R DOOR	20.0*	92.00
	REPAIR L/SIDE FRAME CPL		

2102	REPAIR R/OUTER DOOR SILL	15.0*	69.00
	LABOUR COST	361.0	
	Total Work Units	35.4HRS	\$1,628.40
	Panel / Mechanical Labour	0.7HRS	\$32.20
	Visual Alignment Labour	0.0HRS	0.00
	Corrosion Protection External Labour	0.0HRS	0.00
	Corrosion Protection Internal Labour	36.1HRS	\$1,660.60
	Sub Total	22.8HRS	\$1,048.80
	Paint Labour	58.9HRS	\$2,709.40
	Total Labour		

PAINT WORK		Time Basis 10 WU = 1 HR. Price = \$46.00/HR	
Guide Number	Description	WU	Cost Price (\$)
	- TWO COAT METALLIC		
	- PREPARE OFF VEHICLE		
340	FRT BUMPER SUPPORT SURFACE PAINT	4.0	
471	BONNET NEW PART PAINTING	19.0	
741	L/F WING NEW PART PAINTING	10.0	
742	R/F WING NEW PART PAINTING	10.0	
1001	LOWER CROSSMEMBER SURFACE PAINT	5.0	
1007	L/UPP RADIATOR BRKT SURFACE PAINT	4.0	
1008	R/UPP RADIATOR BRKT SURFACE PAINT	4.0	
1017	FRT UPP CROSSMEMBER SURFACE PAINT	4.0	
1168	R/UPP W-HOUSE REINF SURFACE PAINT	4.0	
283	FRONT BUMPER NEW PART PAINT K1R	10.0	
651	L/FOG LAMP COVER NEW PART PAINT K1R	3.0	
652	R/FOG LAMP COVER NEW PART PAINT K1R	3.0	
1737	L/DOOR MIRROR NEW PART PAINT K1R	4.0	
2208	R/SILL EXTENSION NEW PART PAINT K1R	5.0	
1481	LEFT FRONT DOOR REPAIR PAINTING <50%	17.0	
1482	RIGHT FRONT DOOR REPAIR PAINTING <50%	17.0	
1781	L/R DOOR REPAIR PAINTING <50%	15.0	
2101	L/OUTER DOOR SILL REPAIR PAINTING <50%	10.0	
2102	R/OUTER DOOR SILL REPAIR PAINTING <50%	10.0	
2229	LEFT A-PILLAR REPAIR PAINTING <50%	8.0	
2291	LEFT B-PILLAR REPAIR PAINTING <50%	9.0	
1276	R/S-MEMB COVER PANELSURFACE PAINT	4.0	
2351	ROOF CPL SURFACE PAINT	13.0	
3481	L/R WING SURFACE PAINT	6.0	
	LABOUR COST - PAINT	198.0	
	TIME(PAINT)	5.0	
	Preparation Main Work Plastic	25.0	
	Preparation Main Work Metal	0.0	
	Preparation Work Multi Layer Paint	228.0	
	Total Work Units (10WU/HR)	22.8HRS	\$1,048.80
	Total Paintwork Labour		Cost Price
	MATERIAL COST - PAINT		\$92.88
	New Part Painting		\$63.97
	New Part Painting - Plastic K1R		\$28.60
	Material-Constant Main Work Metal		\$81.93
	Surface-/Blend Paint		

Repair Painting	\$109.82
Material-Const Main Work Plastic	\$9.00
Total Excluding Pearlescent Uplift	\$386.20
Pearlescent Uplift @ 0.0%	\$0.00
Total Paint Material Cost	\$386.20

PARTS

Price Valid: 01/06/2015

Guide No.	Qty	Description	Part Number	Supplier	Bet.	Price (\$)
9986	1	AIR CON COOLANT	NO NUMBER		0%	20.00*
471	1	BONNET	F510M ED0MA		0%	390.00*
431	1	BONNET EMBLEM	62890 9Y000		0%	60.00*
7011	1	FRONT AXLE BEAM	54400 EW00B		0%	380.00*
283	1	FRONT BUMPER	62022 1JY0J		0%	290.00*
257	1	FRONT NUMBER PLATE	KNPL3		0%	45.00*
7261	1	FRONT STABILISER	54611 EW01A		0%	290.00*
350	6	FRT BUMPER CLAMP KIT	01553 09321		0%	22.00*
333	1	FRT BUMPER S-ABSORB	62090 1JY0A		0%	180.00*
340	1	FRT BUMPER SUPPORT	62030 1JY0A		0%	260.00*
299	1	FRT UPP BUMPER COVER	62322 ED000		0%	120.00*
1017	1	FRT UPP CROSSMEMBER	62511 ED000		0%	180.00*
637	1	L/F FOG LAMP	SEE GUIDE NO.		0%	120.00*
			0639			
7269	1	L/F STABILISER BUSH	54613 ED001		0%	20.00*
841	1	L/F WHEELHOUSE COVER	63843 ED05D		0%	80.00*
741	1	L/F WING	63101 ED0MA		0%	260.00*
789	13	L/F WING CLAMP KIT	08146 6122G		0%	18.00*
651	1	L/FOG LAMP COVER	62050 CY000		0%	55.00*
707	1	L/SIDE REPEATER LAMP	26160 AX00A		0%	45.00*
7271	1	L/STABI CLAMP	54614 AX400		0%	45.00*
7311	1	L/TIE ROD BALL JOINT	48640 3U025		0%	95.00*
1007	1	L/UPP RADIATOR BRKT	62513 ED000		0%	80.00*
475	1	LEFT BONNET HINGE	65401 ED00A		0%	40.00*
1001	1	LOWER CROSSMEMBER	62530 ED00A		0%	180.00*
7064	2	NUT	08918 6421A		0%	5.14U
7302	1	POWER STEERING	48010 ED01A		0%	1,200.00*
1741	1	QTR WINDOW SEAL KIT	G289A 89925		0%	40.00*
7036	1	R/DRIVE SHAFT CPL	39100 1V10A		0%	750.00*
7056	1	R/F C/ARM MNTG KIT	USE SINGLE PARTS		0%	0.00
638	1	R/F FOG LAMP	SEE GUIDE NO.		0%	120.00*
			0639			
7054	1	R/F LOWER AXLE ARM	54500 1FU0B		0%	180.00*
1518	1	R/F QTR WINDOW	76820 ED500		0%	240.00*
7270	1	R/F STABILISER BUSH	54613 ED001		0%	20.00*
7082	1	R/F STEERING KNUCKLE	40014 ED000		0%	360.00*
7078	1	R/F STRUT	E4302 EU51A		0%	190.00*
7228	1	R/F TYRE	185/65 R 15 .. H		0%	87.00*
7132	1	R/F WHEEL HUB	40202 EE90A		0%	260.00*
842	1	R/F WHEELHOUSE COVER	63842 ED05D		0%	80.00*
742	1	R/F WING	63100 ED0MA		0%	260.00*
748	1	R/F WING BRACKET	62224 ED000		0%	18.00*
790	13	R/F WING CLAMP KIT	08146 6122G		0%	18.00*
652	1	R/FOG LAMP COVER	62050 CY000		0%	55.00*

7274	1	R/LOWER TOWING STRUT	54618 ED00A	0%	95.00*
708	1	R/SIDE REPEATER LAMP	26160 AX00A	0%	45.00*
2208	1	R/SILL EXTENSION	76850 ED000	0%	120.00*
7272	1	R/STABI CLAMP	54614 AX400	0%	45.00*
7312	1	R/TIE ROD BALL JOINT	48520 3U025	0%	95.00*
1008	1	R/UPP RADIATOR BRKT	62512 ED000	0%	80.00*
7096	1	R/UPP SPRING SEAT	54320 1FE0A	0%	65.00*
1166	1	R/UPP W-HOUSE REINF	64190 ED500	0%	80.00*
1168	1	R/UPP W-HOUSE REINF	64180 ED000	0%	260.00*
413	1	RADIATOR SHROUD	62310 1JY0B	0%	280.00*
476	1	RIGHT BONNET HINGE	65400 ED00A	0%	40.00*
562	1	RIGHT HEADLAMP ASSY	26010 1JY1A	0%	380.00*
7062	1	SCREW	54459 AX02E	0%	6.18U
7066	1	SCREW	54459 ED04A	0%	17.51U
1435	1	W-WASHER BOTTLE	28910 ED00A	0%	90.00*
f: OEM Parts				Sub Total	\$8,856.83
g: Original				Total Parts	\$8,856.83
h: Secondhand					
p: Parallel					
x: Exchange					

THIS ASSESSMENT CONTAINS UNPRICED PARTS
NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras	Description	Betterment	Price
	TOWING SPECIALIST	0%	\$90.00
	ELECTRICAL WORK SPECIALIST		\$20.00
	WHEEL ALIGNMENT SPECIALIST	0%	\$65.00
	ECU DIAGNOSTIC SPECIALIST		\$120.00
	Total Extras		\$295.00

Final Calculation

Total Parts		\$8,856.83
Labour		
Total Panel/Mechanical	\$1,628.40	
Total Paintwork	\$1,048.80	
Total Visual Alignment work	\$32.20	
Total Labour		\$2,709.40
Additional Costs		
Corr Prot Materials External	\$0.00	
Corr Prot Materials Internal	\$0.00	
Cost of Specialist	\$295.00	
Total of Additional Costs		\$295.00
Total Paint/Material Costs		\$386.20
Grand Total Excludes GST		\$12,247.43
GST @ 7 %		\$857.32
Grand Total Includes GST		\$13,104.75

Assessment Notes

51 Ubi Avenue 1, #01-25 Paya Ubi Industrial Park Singapore

Claim Reference: 18/3351

Assessment Number: SH000245

Version: S&HMOTOR/2

Date Calculated: 11/07/2018 08:03

Full Report - V1

Registration: SJM1149L

Printed: 11/07/2018 15:03

51 Ubi Avenue 1, #01-25
Paya Ubi Industrial Park
Singapore
408933

Finalised

Claim Reference: 18/3351
Assessment Number: SH000245
Version: LKKAUTOC/2
Date Calculated: 21/08/2018 08:08

Full Report - V1
Registration: SJM1149L
Printed: 21/08/2018 15:09

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	LKK AUTO	Date of Incident:	05/07/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	China Taiping Insurance (S) Pt	Repairs Authorised:	TBA
Claim Reference:	18/3351	Estimated Repair Time:	
Policy Number:	DMPCSN3007151801	Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	NISSAN
Model:	Latio
Sub Model:	BASE MODEL
Model Sheet Number:	Z76 19
Registration:	SJM1149L
Registration Month:	
Registration Year:	
VIN Number:	
Odometer:	Not Known
Colour:	
Engine Number:	
Fuel Level:	%



Model Specs

FROM 07/2008	AIR CONDITIONING
FOG LAMPS	1.5 LTR 80KW
CVT AUTO GEARBOX	ANTI LOCK BRAKES
5-DOOR	TWO COAT METALLIC
PREPARE OFF VEHICLE	

Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Severity of Impact:	
Steering:	Vehicle Status on Inspection:	
Brakes Pedal Travel:	Date of Inspection:	09/07/2018
Place of Inspection:		
Pre-Accident Damage:		
Tyres Condition:		
Tread Depth LHF:	Tread Depth RHF:	
Tread Depth LHR:	Tread Depth RHR:	
Damage Areas:	Direction of Impact:	



Addresses

Cost Summary

Total Labour	\$2,074.60
Total Paint/Material	\$372.49
Total Parts	\$6,939.00
Total of Additional Costs	\$85.00
Excess: •	- \$0.00
Grand Total Exc GST:	\$9,471.09
7 % GST:	\$662.98
Grand Total Inc GST:	\$10,134.07

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$46.00/HR

Price/Dent = \$46.00/HR

Repair /

Guide Number	Repair Details	WU	Cost Price (\$)
NO NUMBER	JOB ALLOWANCE	5.0	23.00
2991A1	ADJUST FRONT TOE	7.0	32.20
UE10A2	RENEW L/F WING	13.0	59.80
	INCLUDES: R + R BUMPER, INNER WING PROTECTION, HEADLAMP AND ALL NECESSARY ATTACHED PARTS		
UA10A2)	RENEW FRONT BUMPER (BUMPER REMOVED)	3.0	13.80
	INCLUDES: R + R BUMPER REINFORCEMENTS		
2810A1)	R + R FRONT BUMPER REINFORCEMENT	5.0	23.00
2211A1	RENEW L/F FOG LAMP (REMOVED)	1.0	4.60
2211A1	RENEW R/F FOG LAMP (REMOVED)	1.0	4.60
1150A1	R + R RADIATOR GRILLE BADGE	1.0	4.60
1350A1	RENEW R/HEADLAMP (REMOVED)	1.0	4.60
2990A1	ADJUST HEADLAMPS	2.0	9.20
1231A1	ADDITIONAL WORK FOR RENEW RIGHT WING (BUMPER REMOVED)	9.0	41.40
	INCLUDES: R + R INNER WING PROTECTION AND INDICATOR LAMP		
UE26A2	RENEW BONNET	4.0	18.40
	INCLUDES: CONVERT ALL ATTACHED PARTS AND		
	ADJUST BONNET, APPLY PROTECTIVE WAX		
2921A1	RENEW LEFT BONNET HINGE (BONNET REMOVED)	1.0	4.60
2922A1	RENEW RIGHT BONNET HINGE (BONNET REMOVED)	1.0	4.60
UE24A2	R + R AIR INLET COVER	3.0	13.80

VB14A2)	R + R R/UPPER A-PILLAR TRIM	1.0	4.60
VB15A1)	R + R L/- AND R/A-PILLAR TRIM	1.0	4.60
UH40A2	R + R LEFT FRONT DOOR TRIM	2.0	9.20
4192A1	R + R LEFT FRONT DOOR WINDOW GLASS AND WINDOW LIFTER (DOOR TRIM REMOVED)	4.0	18.40
8004A1)	R + R RIGHT FRONT QTR WINDOW GLASS	1.0	4.60
UK36A2	R + R LEFT REAR DOOR TRIM	2.0	9.20
4212A1	R + R LEFT REAR DOOR WINDOW GLASS AND WINDOW LIFTER (DOOR TRIM REMOVED)	5.0	23.00
740441	DISM/ASS STEERING BOX (REMOVED)	2.0	9.20
PW10A1)	R + R LEFT FRONT WHEEL	2.0	9.20
PW10A1)	R + R RIGHT FRONT WHEEL	2.0	9.20
PW10A1)	FIT/BALANCE RIGHT FRONT TYRE (WHEEL REMOVED)	3.0	13.80
7200A1 ZAX	R + R RIGHT FRONT STRUT (WHEEL REMOVED)	1.0	4.60
7228A1)	DETACH + REFIT L/- AND R/DRIVE SHAFT	1.0	4.60
7225B1)	R + R RIGHT FRONT DRIVE SHAFT	2.0	9.20
7202A1)	DISS/ASS R/F SUSPENSION STRUT	3.0	13.80
7204A1)	R + R RIGHT FRONT STEERING KNUCKLE (WHEEL REMOVED)	4.0	18.40
	INCLUDES: R + R BRAKE DISC AND BRAKE DISC PROTECTION PLATE		
7204A1)	R + R RIGHT FRONT WHEEL HUB	3.0	13.80
7205A1)	RENEW STEERING KNUCKLE/WHEEL BEARG/SEAL	2.0	9.20
7200A1 ZAX	DET + REF SPR-LEG TUBES AND WH-BEAR HOUS	3.0	13.80
7212A1)	DETACH/REFIT L/FRT CONTROL ARM	2.0	9.20
7212A1)	DETACH/REFIT R/FRT CONTROL ARM	2.0	9.20
7224A1)	RENEW FRONT AXLE BODY (BOTH AXLE LINK MOULDINGS AND WHEELS REMOVED)	14.0	64.40
	INCLUDES: R + R STEERING, FRONT STABILIZER AND BOTH AXLE LINKS		
NN	AIR CON COOLANT R&R / NEW PARTS	20.0*	92.00
1276	REPAIR R/S-MEMB COVER PANEL	15.0*	69.00
1481	REPAIR LEFT FRONT DOOR	30.0*	138.00
1482	REPAIR RIGHT FRONT DOOR	10.0*	46.00
1781	REPAIR L/R DOOR	15.0*	69.00
2085	REPAIR L/SIDE FRAME CPL	20.0*	92.00
2102	REPAIR R/OUTER DOOR SILL	15.0*	69.00
LABOUR COST			
	Total Work Units	244.0	
	Panel / Mechanical Labour	23.7HRS	\$1,090.20
	Visual Alignment Labour	0.7HRS	\$32.20
	Corrosion Protection External Labour	0.0HRS	0.00
	Corrosion Protection Internal Labour	0.0HRS	0.00
	Sub Total	24.4HRS	\$1,122.40
	Paint Labour	20.7HRS	\$952.20
	Total Labour	45.1HRS	\$2,074.60

PAINT WORK		Time Basis 10 WU = 1 HR. Price = \$46.00/HR	
Guide Number	Description	WU	Cost Price (\$)
	- TWO COAT METALLIC		
	- PREPARE OFF VEHICLE		
340	FRT BUMPER SUPPORT SURFACE PAINT	4.0	
471	BONNET NEW PART PAINTING	19.0	
741	L/F WING NEW PART PAINTING	10.0	
742	R/F WING NEW PART PAINTING	10.0	
283	FRONT BUMPER NEW PART PAINT K1R	10.0	
651	L/FOG LAMP COVER NEW PART PAINT K1R	3.0	
652	R/FOG LAMP COVER NEW PART PAINT K1R	3.0	
1737	L/DOOR MIRROR NEW PART PAINT K1R	4.0	
2208	R/SILL EXTENSION NEW PART PAINT K1R	5.0	
1481	LEFT FRONT DOOR REPAIR PAINTING <50%	17.0	
1482	RIGHT FRONT DOOR REPAIR PAINTING <50%	17.0	
1781	L/R DOOR REPAIR PAINTING <50%	15.0	
2101	L/OUTER DOOR SILL REPAIR PAINTING <50%	10.0	
2102	R/OUTER DOOR SILL REPAIR PAINTING <50%	10.0	
2229	LEFT A-PILLAR REPAIR PAINTING <50%	8.0	
2291	LEFT B-PILLAR REPAIR PAINTING <50%	9.0	
1276	R/S-MEMB COVER PANELSURFACE PAINT	4.0	
2351	ROOF CPL SURFACE PAINT	13.0	
3481	L/R WING SURFACE PAINT	6.0	
LABOUR COST - PAINT			
	TIME(PAINT)	177.0	
	Preparation Main Work Plastic	5.0	
	Preparation Main Work Metal	25.0	
	Preparation Work Multi Layer Paint	0.0	
	Total Work Units (10WU/HR)	207.0	
	Total Paintwork Labour	20.7HRS	\$952.20
MATERIAL COST - PAINT			Cost Price
	New Part Painting		\$92.88
	New Part Painting - Plastic K1R		\$63.97
	Material-Constant Main Work Metal		\$28.60
	Surface-/Blend Paint		\$68.22
	Repair Painting		\$109.82
	Material-Const Main Work Plastic		\$9.00
	Total Excluding Pearlescent Uplift		\$372.49
	Pearlescent Uplift @ 0.0%		\$0.00
	Total Paint Material Cost		\$372.49

PARTS

				Price Valid: 01/06/2015	
Guide No.	Qty	Description	Part Number	Supplier	Price (\$)
9986	1	AIR CON COOLANT	NO NUMBER		20.00*
471	1	BONNET	F510M ED0MA		390.00*
431	1	BONNET EMBLEM	62890 9Y000		60.00*
7011	1	FRONT AXLE BEAM	54400 EW00B		380.00*
283	1	FRONT BUMPER	62022 1JY0J		290.00*
257	1	FRONT NUMBER PLATE	KNPL3		45.00*
350	6	FRT BUMPER CLAMP KIT	01553 09321		22.00*
333	1	FRT BUMPER S-ABSORB	62090 1JY0A		180.00*

51 Ubi Avenue 1, #01-25 Paya Ubi Industrial Park Singapore

Claim Reference: 18/3351

Assessment Number: SH000245

Version: LKKAUTOC/2

Date Calculated: 21/08/2018 08:08

Full Report - V1

Registration: SJM1149L

Printed: 21/08/2018 15:09

340	1	FRT BUMPER SUPPORT	62030 1JY0A	0%	260.00*
299	1	FRT UPP BUMPER COVER	62322 ED000	0%	120.00*
637	1	L/F FOG LAMP	SEE GUIDE NO. 0639	0%	120.00*
841	1	L/F WHEELHOUSE COVER	63843 ED05D	0%	80.00*
741	1	L/F WING	63101 ED0MA	0%	260.00*
789	13	L/F WING CLAMP KIT	08146 6122G	0%	18.00
651	1	L/FOG LAMP COVER	62050 CY000	0%	55.00*
707	1	L/SIDE REPEATER LAMP	26160 AX00A	0%	45.00*
475	1	LEFT BONNET HINGE	65401 ED00A	0%	40.00*
7064	2	NUT	08918 6421A	0%	0.00F
7302	1	POWER STEERING	48010 ED01A	0%	1,200.00*
1741	1	QTR WINDOW SEAL KIT	G289A 89925	0%	40.00*
7036	1	R/DRIVE SHAFT CPL	39100 1V10A	0%	750.00*
7056	1	R/F C/ARM MNTG KIT	USE SINGLE PARTS	0%	0.00F
638	1	R/F FOG LAMP	SEE GUIDE NO. 0639	0%	120.00*
7054	1	R/F LOWER AXLE ARM	54500 1FU0B	0%	180.00*
1518	1	R/F QTR WINDOW	76820 ED500	0%	240.00*
7082	1	R/F STEERING KNUCKLE	40014 ED000	0%	360.00*
7078	1	R/F STRUT	E4302 EU51A	0%	190.00*
7228	1	R/F TYRE	185/65 R 15 .. H	0%	58.00*
7132	1	R/F WHEEL HUB	40202 EE90A	0%	260.00*
842	1	R/F WHEELHOUSE COVER	63842 ED05D	0%	80.00*
742	1	R/F WING	63100 ED0MA	0%	260.00*
748	1	R/F WING BRACKET	62224 ED000	0%	18.00*
790	13	R/F WING CLAMP KIT	08146 6122G	0%	18.00*
652	1	R/FOG LAMP COVER	62050 CY000	0%	55.00*
2208	1	R/SILL EXTENSION	76850 ED000	0%	120.00*
7312	1	R/TIE ROD BALL JOINT	48520 3U025	0%	95.00*
476	1	RIGHT BONNET HINGE	65400 ED00A	0%	40.00*
562	1	RIGHT HEADLAMP ASSY	26010 1JY1A	0%	380.00*
7066	1	SCREW	54459 ED04A	0%	0.00F
7062	1	SCREW	54459 AX02E	0%	0.00F
1435	1	W-WASHER BOTTLE	28910 ED00A	0%	90.00*
f: OEM Parts			Saving	\$28.83	
g: Original			Sub Total	\$6,939.00	
h: Secondhand			Total Parts	\$6,939.00	
p: Parallel					
x: Exchange					

THIS ASSESSMENT CONTAINS UNPRICED PARTS
NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description		Betterment	Price
TOWING	SPECIALIST	0%	\$0.00
ELECTRICAL WORK	SPECIALIST		\$20.00
WHEEL ALIGNMENT	SPECIALIST	0%	\$65.00
Total Extras			\$85.00

Final Calculation

Total Parts	\$6,939.00
Labour	
Total Panel/Mechanical	\$1,090.20

Total Paintwork	\$952.20	
Total Visual Alignment work	\$32.20	
Total Labour		\$2,074.60
Additional Costs		
Corr Prot Materials External	\$0.00	
Corr Prot Materials Internal	\$0.00	
Cost of Specialist	\$85.00	
Total of Additional Costs		\$85.00
Total Paint/Material Costs		\$372.49
Grand Total Excludes GST		\$9,471.09
GST @ 7 %		\$662.98
Grand Total Includes GST		\$10,134.07

Assessment Notes

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Iris Auth'd	Status
Main	09 Jul 2018 Sendback Est	09 Jul 2018 17:08 \$13,219.55	10 Jul 2018 12:18 Edit Adj Rpt	\$3,500.00 Edit Estimates	\$3,500.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured: ONG YOKE MIN , ID: S6815520G, Tel: +6596363879, Email: NOEMAIL									
Vehicle Reg. No.: SJM1149L		Date of Loss: 05/07/2018 16:00 - :59 [114 Months and 13 Days From LTA Reg Date (Man Yr)]							
Claim Type: OD / SNM18D03351C01		Policy/Cover Note No.: DMPCSN3007151801 (Comprehensive)							
		Excess: \$0.00							
Repairer: S & H Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #07-02, Sin Ming AutoCity, 575722 Sin Ming - Tel: 6453 4730									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Hwang Shiang Yi - 63896541]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 19/07/2018]									
Driver/Custodian: ONG YOKE MIN (50 / Male), NRIC: S6815520G, Tel: +6596363879									
Adj Asg. Remarks: PLEASE SURVEY INSURED VEHICLE AND REVERT. EXCESS WAIVED.									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• CHINA_TAIPIING (16/07/2018): Alert - Adj Mandate Approved (\$3500.00) - SJM1149L - Claim Handler: Hwang Shian...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SJM1149L (SNM18D03351C01)

OD

Jul 5 2018 4:00PM

[ONG YOKE MIN]

S & H Motor Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View [View in Browser](#)

Assessment Reports				1 per page	☒
No	Finalized On			Thumbnail	Print
S & H Motor Pte Ltd (Sin Ming)					
1	06/07/18 16:50	Accident Statement		Load HTM	
2	09/07/18 17:08	Repairer Estimates		Load HTM	
LKK Auto Consultants Pte Ltd (HQ)					
1	11/07/18 16:38	Adjuster Immediate Advice		Load HTM	
2	11/07/18 16:45	Adjuster Immediate Advice		Load HTM	
3	12/07/18 15:59	Adjuster Immediate Advice		Load HTM	

Photos/Images				3 per page	☒
No	Finalized On			Thumbnail	Print
S & H Motor Pte Ltd (Sin Ming)					
1	06/07/18 16:26	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
2	06/07/18 16:26	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
3	06/07/18 16:26	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
4	06/07/18 16:26	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
5	06/07/18 16:26	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
6	06/07/18 16:26	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
7	06/07/18 16:26	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
8	06/07/18 16:26	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
9	06/07/18 16:26	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
10	06/07/18 16:26	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
LKK Auto Consultants Pte Ltd (HQ)					
No	Relabel/Reorder			Thumbnail	Print
1	12/07/18 09:13	General View		Load JPG	☒
2	12/07/18 09:13	General View		Load JPG	☒
3	12/07/18 09:13	General View		Load JPG	☒
4	12/07/18 09:13	General View		Load JPG	☒
5	12/07/18 09:13	General View		Load JPG	☒
6	12/07/18 09:13	General View		Load JPG	☒
7	12/07/18 09:13	General View		Load JPG	☒
8	12/07/18 09:13	General View		Load JPG	☒
9	12/07/18 09:13	General View		Load JPG	☒
10	12/07/18 09:13	General View		Load JPG	☒
11	12/07/18 09:13	General View		Load JPG	☒
12	12/07/18 09:13	General View		Load JPG	☒
13	12/07/18 09:13	General View		Load JPG	☒
14	12/07/18 09:13	General View		Load JPG	☒
15	12/07/18 09:13	General View		Load JPG	☒
16	12/07/18 09:13	General View		Load JPG	☒
17	12/07/18 09:13	General View		Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)	Thumbnail	Print
18	12/07/18 09:13	General View	 Load JPG	☒
19	12/07/18 09:13	General View	 Load JPG	☒
20	12/07/18 09:13	General View	 Load JPG	☒
21	12/07/18 09:13	General View	 Load JPG	☒
22	12/07/18 09:13	General View	 Load JPG	☒
23	12/07/18 09:13	General View	 Load JPG	☒
24	12/07/18 09:13	General View	 Load JPG	☒
25	12/07/18 09:13	General View	 Load JPG	☒
26	12/07/18 09:13	General View	 Load JPG	☒
27	12/07/18 09:13	General View	 Load JPG	☒
28	12/07/18 09:13	General View	 Load JPG	☒
29	12/07/18 09:13	General View	 Load JPG	☒
30	12/07/18 09:13	General View	 Load JPG	☒
31	12/07/18 09:13	General View	 Load JPG	☒
32	12/07/18 09:13	General View	 Load JPG	☒
33	12/07/18 09:13	General View	 Load JPG	☒
34	21/08/18 15:44	Reinspection Photo	 Load JPG	☒
35	21/08/18 15:44	Reinspection Photo	 Load JPG	☒
36	21/08/18 15:44	Reinspection Photo	 Load JPG	☒
37	21/08/18 15:44	Reinspection Photo	 Load JPG	☒
38	21/08/18 15:44	Reinspection Photo	 Load JPG	☒
39	21/08/18 15:44	Reinspection Photo	 Load JPG	☒
40	21/08/18 15:44	Reinspection Photo	 Load JPG	☒
41	21/08/18 15:44	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	06/07/18 16:27	Sketch Plan [Linked Accident Report Documents]	 Load TIF	
2	06/07/18 16:27	Sketch Plan #2 [Linked Accident Report Documents]	 Load TIF	
3	06/07/18 16:27	Sketch Plan #3 [Linked Accident Report Documents]	 Load JPG	☒
4	06/07/18 16:27	Sketch Plan #4 [Linked Accident Report Documents]	 Load JPG	☒
5	06/07/18 16:46	Accident Sketch Plan [Linked Accident Report Documents]	 Load JPG	☒
6	06/07/18 16:48	Accident Sketch Plan [Linked Accident Report Documents]	 Load JPG	☒
7	06/07/18 16:48	Accident Sketch Plan [Linked Accident Report Documents]	 Load TIF	
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	10/07/18 12:16	SKP338L	 Load PDF	
2	10/07/18 12:16	SKS4425B	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	11/07/18 16:45	MARK ESTIMATE	 Load PDF	
2	11/07/18 16:45	AUDATEX	 Load PDF	

Linked Accident Report Documents

Assessment Reports			View	View in Browser
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	06/07/18 16:50	Accident Statement	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)	Thumbnail	Print

Assessment Reports				1 per page	☒
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)		Thumbnail	Print
1	06/07/18 16:26	Accident Photo		Load JPG	☒
2	06/07/18 16:26	Accident Photo		Load JPG	☒
3	06/07/18 16:26	Accident Photo		Load JPG	☒
4	06/07/18 16:26	Accident Photo		Load JPG	☒
5	06/07/18 16:26	Accident Photo		Load JPG	☒
6	06/07/18 16:26	Accident Photo		Load JPG	☒
7	06/07/18 16:26	Accident Photo		Load JPG	☒
8	06/07/18 16:26	Accident Photo		Load JPG	☒
9	06/07/18 16:26	Accident Photo		Load JPG	☒
10	06/07/18 16:26	Accident Photo		Load JPG	☒

Documentation				1 per page	☒
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)		Thumbnail	Print
1	06/07/18 16:27	Sketch Plan		Load TIF	
2	06/07/18 16:27	Sketch Plan #2		Load TIF	
3	06/07/18 16:27	Sketch Plan #3		Load JPG	☒
4	06/07/18 16:27	Sketch Plan #4		Load JPG	☒
5	06/07/18 16:46	Accident Sketch Plan		Load JPG	☒
6	06/07/18 16:48	Accident Sketch Plan		Load JPG	☒
7	06/07/18 16:48	Accident Sketch Plan		Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) 			
Show Remarks To: ☐ Repairer ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CT118012540/KVBE2

Date: 10/09/2018

REFERENCE

Insured/Claimant: ONG YOKE MIN Policy No: DMPCSN3007151801
Date of Loss: 05/07/2018 Nature of Claim: OD Claim No: SNM18D03351C01

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJM1149L**
Make & Model: NISSAN LATIO, 1.5 (A) Engine No: HR15399570A
Reg. Date: 22/12/2008 (Man. Year: 2008) Chassis No: JN1FAAC11Z0010055
Colour: Metallic Black Odometer: 208392 km
Engine Capacity: 1498 cc
Market Value/New Car Price: S\$12,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/60 R15 Rear Tyre Size: 195/60 R15
Front Left Side: Dunlop 5 mm Rear Left Side: Michelin 6 mm
Front Right Side: Dunlop 5 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,954.83	6,776.00	2,178.83	24.33
Miscellaneous Items	525.00	248.00	277.00	52.76
Labour	3,649.72	2,447.09	1,202.63	32.95
Paintwork Labour	0.00	0.00	0.00	
Towing	90.00	0.00	90.00	100.00
Calculated Gross Total (S\$)	13,219.55	9,471.09	3,748.46	28.36
Approved Total (Overridden) (S\$)		3,500.00		
(S\$)	13,219.55	3,500.00	9,719.55	73.52
+ GST 7.00/7.00% (S\$)	925.37	245.00	680.37	73.52
Nett Amount (S\$)	14,144.92	3,745.00	10,399.92	73.52

INSPECTION

Date of Assignment: 10/07/2018 Present Location: S & H Motor Pte Ltd (Sin Ming)
Date Inspected: 11/07/2018 Inspected At: S & H Motor Pte Ltd (Sin Ming)
160 Sin Ming Drive #07-02, Sin Ming
AutoCity
Singapore 575722

Estimated Period of Repair: 14.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 10 Sep 2018)
Parts: 144	NISSAN LATIO 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJM1149L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	NA	*BONNET	Bent	390.00 F	*390.00 F
2	1	NA	*BONNET EMBLEM	Necessary	60.00 F	*60.00 F
3	1	NA	*FRONT AXLE BEAM	Bent	380.00 F	*380.00 F
4	1	NA	*FRONT BUMPER	Missing	290.00 F	*290.00 F
5	1	NA	*FRONT STABILISER	Serviceable	290.00 F	*- F
6	1	NA	*FRT BUMPER CLAMP KIT	Necessary	22.00 F	*22.00 F
7	1	NA	*FRT BUMPER S-ABSORB	Broken	180.00 F	*180.00 F
8	1	NA	*FRT BUMPER SUPPORT	Bent	260.00 F	*260.00 F
9	1	NA	*FRT UPP BUMPER COVER	Missing	120.00 F	*120.00 F
10	1	NA	*FRT UPP CROSSMEMBER	Repair	180.00 F	*- F
11	1	NA	*L/F FOG LAMP	Missing	120.00 F	*120.00 F
12	1	NA	*L/F STABILISER BUSH	Serviceable	20.00 F	*- F
13	1	NA	*L/F WHEELHOUSE COVER	Cracked	80.00 F	*80.00 F
14	1	NA	*L/F WING	Bent	260.00 F	*260.00 F
15	1	NA	*L/F WING CLAMP KIT	Necessary	18.00 F	*18.00 F
16	1	NA	*L/FOG LAMP COVER	Missing	55.00 F	*55.00 F
17	1	NA	*L/SIDE REPEATER LAMP	Missing	45.00 F	*45.00 F
18	1	NA	*L/STABI CLAMP	Serviceable	45.00 F	*- F
19	1	NA	*L/TIE ROD BALL JOINT	Serviceable	95.00 F	*- F
20	1	NA	*L/UPP RADIATOR BRKT	Repair	80.00 F	*- F
21	1	NA	*LEFT BONNET HINGE	Distorted	40.00 F	*40.00 F
22	1	NA	*LOWER CROSSMEMBER	Repair	180.00 F	*- F
23	1	NA	*NUT	Serviceable	5.14 F	*- F
24	1	NA	*POWER STEERING	Bent / Jammed	1,200.00 F	*1,200.00 F
25	1	NA	*R/DRIVE SHAFT CPL	Bent	750.00 F	*750.00 F
26	1	NA	*R/F C/ARM MNTG KIT (WCP)	Serviceable	0.00 F	*- F
27	1	NA	*R/F FOG LAMP	Missing	120.00 F	*120.00 F
28	1	NA	*R/F LOWER AXLE ARM	Bent	180.00 F	*180.00 F
29	1	NA	*R/F QTR WINDOW	Distorted	240.00 F	*240.00 F
30	1	NA	*R/F STABILISER BUSH	Serviceable	20.00 F	*- F
31	1	NA	*R/F STEERING KNUCKLE	Bent	360.00 F	*360.00 F
32	1	NA	*R/F STRUT	Bent	190.00 F	*190.00 F
33	1	NA	*R/F WHEEL HUB	Bent	260.00 F	*260.00 F
34	1	NA	*R/F WHEELHOUSE COVER	Missing	80.00 F	*80.00 F
35	1	NA	*R/F WHEELHOUSE CPL	Repair	290.00 F	*- F
36	1	NA	*R/F WING	Bent	260.00 F	*260.00 F
37	1	NA	*R/F WING BRACKET	Bent	18.00 F	*18.00 F
38	1	NA	*R/F WING CLAMP KIT	Necessary	18.00 F	*18.00 F
39	1	NA	*R/FOG LAMP COVER	Missing	55.00 F	*55.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1	NA	*R/LOWER TOWING STRUT	Repair	95.00 F	*- F
41	1	NA	*R/SIDE REPEATER LAMP	Serviceable	45.00 F	*- F
42	1	NA	*R/SILL EXTENSION	Cracked	120.00 F	*120.00 F
43	1	NA	*R/STABI CLAMP	Repair	45.00 F	*- F
44	1	NA	*R/TIE ROD BALL JOINT	Distorted	95.00 F	*95.00 F
45	1	NA	*R/UPP RADIATOR BRKT	Repair	80.00 F	*- F
46	1	NA	*R/UPP SPRING SEAT	Serviceable	65.00 F	*- F
47	1	NA	*R/UPP W-HOUSE REINF	Repair	80.00 F	*- F
48	1	NA	*R/UPP W-HOUSE REINF	Repair	260.00 F	*- F
49	1	NA	*RADIATOR SHROUD	Serviceable	280.00 F	*- F
50	1	NA	*RIGHT BONNET HINGE	Distorted	40.00 F	*40.00 F
51	1	NA	*RIGHT HEADLAMP ASSY	Broken	380.00 F	*380.00 F
52	1	NA	*SCREW	Serviceable	6.18 F	*- F
53	1	NA	*SCREW	Serviceable	17.51 F	*- F
54	1	NA	*SUNDRY PARTS (NPA)	Not Necessary	0.00 F	*- F
55	1	NA	*W-WASHER BOTTLE	Missing	90.00 F	*90.00 F
Total Parts (S\$)					8,954.83	6,776.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	AC refrigerant (NECESSARY)	60.00	20.00
2	1	ECU diagnostic (NOT NECESSARY)	120.00	0.00
3	1	Electrical work	50.00	20.00
4	1	Front number plate (MISSING)	45.00	45.00
5	1	RH front Qtr window seal kit (NECESSARY)	40.00	40.00
6	1	RH front tyre (CUT) (40%)	145.00	58.00
7	1	Wheel alignment	65.00	65.00
Sub Total (S\$)			525.00	248.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	Total Paint Labour	New	1,039.60	952.20
2	Total Paint Materials	New	392.92	372.49
3	Total Panel/Mechanical Labour	New	2,217.20	1,122.40
Gross Labour Cost (S\$)			3,649.72	2,447.09

Report was unsubmitted during this print-out.

< END OF ESTIMATES >