

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 4992U

MAKE :

MODEL : HYUNDAI i40

China Taiping - US

DATE 9/7/2018

IS

LKK - Kalvin

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover <i>X repair</i>			\$ 562.30
	Front Bumper Grille (LH) <i>X see</i>			\$ 40.30
	Front Bumper Bracket Top (LH) <i>X see</i>			\$ 22.40
	Front Bumper Retainer Mounting <i>X see</i>			\$ 9.20
	Front Fender (LH) <i>— flat</i>			\$ 619.00
	Front Fender Shield (LH) <i>X see</i>			\$ 169.80
	Front Fender Retainer <i>X see</i>			\$ 9.20
	Frt Wheel Hub Cap, LH <i>— hatched</i>			\$ 150.70
	SUB TOTAL			\$ 1,582.90
	LESS 20%			\$ 316.58
	DISCOUNTED TOTAL			\$ 1,266.32
	Labour Charge			
	Panel Beating			\$ 500.00 ²⁰⁰
	Spray Painting Charge			\$ 400 500.00
	Tuff Kote			\$ 20 50.00
	Frt Wheel Alignment			\$ 80.00
	TOTAL LABOUR			\$ 1,190.00
	ESTIMATE TOTAL			\$ 2,456.32

Kalvin (LKK)
9/7/18 1140 hrs.
2 Day
US
After Repair photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) may be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.