

7PA16
Xiao Tong

SMA1140M.

Toyota Uios. 1497cc
MR053HY9305125531

Rear Number Plate	2	30(SW) X
Rear Number Plate Holder	Not New	30(SW) X
Rear Bumper Distorted		481.90 ✓
Rear Bumper Clips. New		30 ✓
Rear Bumper Side Holder x 02	New	$46.5 \times 2 = 93$ ✓
Rear Bumper Reflector x 02	Crushed	$95.6 \times 2 = 191.20$ ✓
Rear Bumper Bracket x 02	Bent	$68.2 \times 2 = 136.40$ ✓
Reverse Sensor Damaged		220(SW) 220(SW)
Rear End Panel Distorted		689 ✓
Rear End Panel Top Garnish.	Behind	185.60 -
Rear End Panel Sealant. New		60(SW) -
Taillamp x 02	Crushed	$324.6 \times 2 = 649.20$ ✓
Taillamp Sponge Gasket x 02	New	$20 \times 2 = 40$ ✓
Taillamp Panel x 02	Dented	$111.6 \times 2 = 223.20$ ✓
Bootlid.	Dented	655.20 -
Bootlid Lock	Damaged	92.60 -
Bootlid Weatherstripe. Cut		184.70 ✓
Bootlid Outer Garnish	Behind	185.10 ✓
Bootlid Hinge x 02	Bent	$68.5 \times 2 = 137$ ✓

SMA1140M.

Toyota Logo	45.60 /
E Emblem	47.80 /
Vios Emblem	50.40 /
Spare Tyre Panel Repair	769.60 x
Spare Tyre Panel Top Cover	169.20 /
Spare Tyre Panel Side Sponge x 02	216.9 x 2 = 433.80 /
Rear Fenders x 02 Repair	845.1 x 2 = 1690.20 x
Rear Fender Inner Trim x 02	256.1 x 2 = 512.20 x
Rear Fender Inner Trim Clips	60 x
Rear Windscreen Moulding	132.10 x
Rear Windscreen Sealant	60(SN) x
Rear Exhaust Pipe	569 x
Rear Exhaust Mounting	30.90 x
Spare Tyre Panel Centre Sponge	213.60 /
Spare Tyre Lock Screw	39.20 /

SMA 1140M.

Panel Beating

Spray Painting.

Wiring.

To undersoul.

To remove reverse sensor

To remove upholstery

To transfer bootlid fittings.

To remove rear windscreen.

To remove exhaust pipe.

2000 1400.

~~1800~~ 1400

~~50~~ 30

~~150~~ 50

~~100~~ 50

~~150~~ 60

~~150~~ 60

180 x

~~150 x~~ 80

hist 4973.70

len 25% 3730.27

S.N: 260

Labour: 3130

total: 7120.27

H/S: 5.7K

OT Pays.

5.7K.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: