

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

SMRT Accident Vehicle Repair Estimates

Guy

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No

SHB5518K

Ref. No

TAX/07/18/2006

Reg. Date

25/07/2012

Vehicle Type

TAXI

Make

SSANGYONG

Model

RODIUS-SV270

Name of Driver

JEFFREY TEO XIANG MING

Type of Accident

SIDE SWIPE

Date / Time of Accident

02/07/2018 10:21:00 AM

Accident Reported Date / Time:

03/07/2018 12:00:00 AM

Surveyor is Required?

Yes

Survey by

Vehicle is Towed Back?

No

Towed Back Date/Time

Replacement Vehicle issued? :

Accident Repair Job Card No :

000024096904

Special Instruction to ARC, if any :

TOS / PC7005K

Prepared Date

09/07/2018 08:33:50 AM

Satura Sai 98072012

- Lump Sum Repair - Photo after paint

LKK Auto Consultants hence notify

the Repairer of the following:

- · To resurvey before/after spray painting
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- · No illegal modification(s) is allowed
- · Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No: KPTV0B1FSCP066735

Mileage

0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

Quotation from ARC

Adjusted by Surveyor, if applicable

Total Labout Charges

338.00

0.00

Total Spray Painting Charges

473.00

0.00

Total Material Charges

890.64

Other Charges

140.00

890.64 0.00

TOTAL

1,841.64

0.00

Lum Sum Total

1,850.00

0.00

No. of Repair Days

3.00

2000

Prepared / Adjusted By

Arc / Surveyor Sing Off Date

: 09/07/2018 10:02:52 AM

01/01/1900 12:00:00 AM

Prepared / Adjusted Date

Remarks

Prepared Date : 09/07/2018 10:02:44 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No

Invoice No

Quotation Date

Invoice Date :

Invoice Amount : 0.00

Prepared Date:

7/9/2018 10:03:20 AM

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable		
TO REPAIR FRONT PORTION	338.00	0.00 200		
Total Labour	338.00			

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable			
TO REPSRAY FRONT BUMPER	473.00	19:00 200			
Total Spray Painting & Panel Beating	473.00	0.00			

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Total Other Costs	140.00	0.00			
TO WASH AND VACUUM	60.00	0.00 🗶			
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	10.00 40			
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable			

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommen d	Surveyor Approved	Photos Attached	
7871A21 000	FRONT		FRT BUMPER ASSY R	. 1	1,187.50	10.00	1,068.75	Replace	Replace	No	
	FRONT		FRT BUMPER CLIP	6	8.25	10.00	44.55	Replace	Replace	No	
		Т	TOTAL MATERIALS				1,113.30 1,113.30				
TOTAL MATERIALS(Discounted)							890.64 890.64				

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

Page: