

REF: RM(Ax9)

Surveyor

ASSIGNMENT

From:

Date: 16/7/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

YM39A

at Workshop m/s

Kun Fook Sing
61 Defu Lane 12

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

morning

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

62k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

YM39A

Yr Regn:

10 / 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

HINO X2u710R

C.C

4009

Colour:

white

A/C:

Insured / Std / NI / NA

Sp. Reading

102531

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JHMUCI3H80K01438

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Order / Jammed / Leaked / Burnt or

Brake: Order / Jammed / Leaked / Burnt or

Modi: Air / S/Rim / STD A/Rim or

Tyre Size:

F:

215/85R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6/6

mm

L/Bal.

6

mm

L/Bal.

6/6

mm

D.O.A.

9/7/18

D.O.I.

16/7/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear ALS.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Reg 9k.

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

) \$ + RS. SI

) Photos

) Others

Report Format :

Lump Sum / I.B.I. (\$))

TOTAL