

22/03/2002

ASS. REC. BY:

REF: CS3/SMO18000481/Bsd3^{er}

Special Instruction: Paul & daip

Signature: Paul

ASSIGNMENT (Office)

From (Person): Thelma Choo

of SMO

Date/Time: 11/07/2018

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBD8833R

Insured: GBD4877R

at Workshop m/s

Paul Hoe Buffonies & Motor Services

9623 5068

of 7 Kaki, Bkt Ave G #01-109 Autobay

Policy No:

Claim No: CMTD1800134 / THE

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 05/01/2018

CA / REV / REP. / REV 24 HRS 'wp'

Date/Time: 8:58am 09/01/18

Person Contacted: paul

H.O.D. Endorsement:

Vehicle IN OUT

Date/Time	Action/Instruction (X) Estimate	
	<u>GBD8833R - NA / EGT 18000361/h1</u>	<u>NOA 05/01/2018</u>
	<u>GBD4877R - NA / EGT 18000364/h1</u>	<u>NOA 05/01/2018</u>
	<u>After repair 29.01.2018.</u>	
<u>07/09/18</u>	<u>Submit HS \$ 12,950/- @ 16 days, checked by Simon</u>	
	<u>C\$ 17,750.00 Red - 18%</u>	

RECEIVED 10 SEP 2018

TGLim

450-160=29

6/9/18

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	8651N
Vehicle Details	
Vehicle No.:	GBD8833R
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Sep 2018
Vehicle Make:	NISSAN
Vehicle Model:	CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5
Primary Colour:	Gold
Manufacturing Year:	2014
Engine No.:	ZD30336400K
Chassis No.:	JN1SC2F24Z0855603
Maximum Power Output:	-
Open Market Value:	\$25,799.00
Original Registration Date:	10 Mar 2014
First Registration Date:	10 Mar 2014
Transfer Count:	0
Actual ARF Paid:	\$1,290.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	09 Mar 2024
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$50,001.00
COE Rebate Amount:	\$27,463.00
Total Rebate Amount:	\$27,463.00

The information contained herein is correct as at 07 Sep 2018

OK

Nivitha (LKK Auto)

From: Choo, Thelma <thelma.choo@sompo.com.sg>
Sent: Wednesday, 11 July 2018 4:10 PM
To: Nivitha (LKK Auto); assignments@lkkauto.com
Cc: Henry, Irene James; 'SUR'
Subject: RE: CMTD1800134/THE - LKK Ref: CS3/SMO18000481/R1d3e2; ACCIDENT INVOLVING GBD4877R & GBD8833R ON 05.01.2018
1377_001.pdf; 1378_001.pdf; 1379_001.pdf; 1380_001.pdf
Attachments:
Importance: High

Dear Nivitha,

We refer to your reference CS3/SMO18000481/R1d3e2

Please assist to get your surveyor to conduct a paper re-survey on an urgent basis

Let us have the paper re-survey report within the next 10 days.

Best Regards
Thelma Choo
Claims Divisions
D: 6322 4681 | T: 6461 6555 | F: 6221 3147

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG



¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy.

From: Nivitha (LKK Auto) [mailto:admin-d@lkkauto.com]
Sent: Tuesday, January 09, 2018 9:00 AM
To: Teo, Grace <grace.teo@sompo.com.sg>; assignments@lkkauto.com
Cc: Choo, Thelma <thelma.choo@sompo.com.sg>; Henry, Irene James <irene.henry@sompo.com.sg>; 'SUR' <sur@lkkauto.com>
Subject: RE: CMTD1800134/THE - ACCIDENT INVOLVING GBD4877R & GBD8833R ON 05.01.2018

Dear Sir/Mdm,

Thank you for the assignment.

G.Niyitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Teo, Grace [<mailto:grace.teo@sompo.com.sg>]

Sent: Monday, 8 January 2018 5:38 PM

To: Kelly Cheng <kelly.cheng@ksteoptr.com>; admin-d@lkkauto.com; assignments@lkkauto.com

Cc: Choo, Thelma <thelma.choo@sompo.com.sg>; Henry, Irene James <irene.henry@sompo.com.sg>

Subject: CMTD1800134/THE - ACCIDENT INVOLVING GBD4877R & GBD8833R ON 05.01.2018

Our Reference: CMTD1800134/THE

Your Reference: TKS/P566-ACC-39605.18/kc

Without Prejudice

Date: 8th January 2018

Attention:

M/S TEO KENG SIANG LLC

Dear Kelly,

ACCIDENT INVOLVING GBD4877R & GBD8833R ON 05.01.2018

We refer to your email reply dated 08/01/2018.

We do not agree to your list of surveyors.

As such, we will be appointing our motor surveyor, **LKK AUTO CONSULTANTS** to conduct the pre-repair survey of your client's vehicle.

The pre-repair survey will include a survey of the vehicle when its damaged parts are being dismantled prior to the commencement of repairs.

We would like our motor surveyor to conduct a post repair inspection once your client's vehicle has been repaired.

The survey is conducted on a without Prejudice basis and without any admission of liability.

Yours faithfully,

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Kelly Cheng [<mailto:kelly.cheng@ksteoptr.com>]

Sent: Monday, January 08, 2018 5:18 PM

To: Teo, Grace

Subject: Re: CMTD1800134/THE - ACCIDENT INVOLVING GBD4877R & GBD8833R ON 05.01.2018

WITHOUT PREJUDICE

Dear Grace,

We refer to the above matter and to your email dated 8 January 2018.

We have our client's instructions to reject your proposal on your Single Joint Expert.

We enclosed herewith the list of our client's proposal on single joint expert for your necessary action.

Kindly let us hear from you within the stipulated time frame as per the new NIMA protocol failing which we will proceed with the necessary.

Thank you.

On Mon, Jan 8, 2018 at 3:23 PM, Teo, Grace <grace.teo@sompo.com.sg> wrote:

Our Reference: CMTD1800134/THE

Your Reference: TKS/P566-ACC-39605.18/kc

Without Prejudice

Date: 8th January 2018

EMAIL ONLY

Attention:

M/S TEO KENG SIANG LLC

Dear Kelly,

ACCIDENT INVOLVING GBD4877R & GBD8833R ON 05.01.2018

We refer to your Notice of Accident dated 08/01/2018.

Please be informed that Thelma Choo the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffery Ong	
4	JP Knights Adjusters & Surveyors	Jason Lek	
5	In House surveyor	Teo See Ling	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Yours faithfully,

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

--

Best Regards,

Kelly Cheng
Tel: 6333 4222 ext 72
Fax: 6333 5675

Teo Keng Siang LLC
111 North Bridge Road
Peninsula Plaza, #29-07/08
Singapore 179098

PRO-OPTION SERVICES

Mailing address: Blk 189B Rivervale Drive, #04-1004, Singapore 542189
Tel: 6315 1239, Fax: 6315 3298, Mobile: 9061 0543, Email: mirage1195@gmail.com

ACCIDENT VEHICLE INSPECTION REPORT

Report no : 15M0118.PH
Vehicle no : GBD8833R

1 REFERENCE

Date of inspection : 9 January 2018
Requested by : SC Integrated Engineering Pte Ltd
15 Yishun Industrial Street 1
#09-12 Win 5
Singapore 768091
Type of survey : Independent
Repairer : Paul Hoe Batteries & Motor Services
Blk 1 Kaki Bukit Ave 6, #01-109 AutoBay @ Kaki Bukit, Singapore 417883
Date of accident : 5 January 2018

2 VEHICLE DATA

Make/model : Nissan CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5
Chassis no : JN1SC2F24Z0855603
Engine no : ZD30336400K
Date of registration : 10 March 2014
Engine capacity : 2953 cc
Odometer Reading :
Colour : Golden

3 STATIC CONDITION CHECK

Steering : Serviceable
Foot brakes : Serviceable
Hand brakes : Serviceable
Paintwork : Good
General Condition : Good

4 TIRE CONDITION CHECK

	<u>RH/MAKE</u>	<u>LH/MAKE</u>	<u>SIZE</u>
Front tread	7 mm/Yokohama	7 mm/Yokohama	195/80R15
Rear tread	6 mm/Cheng shin	6 mm/Cheng shin	165R13

5 BRIEF DESCRIPTION OF DAMAGE

Floor board panel crumpled, RH front door squashed/distorted, RH front suspension parts damaged, front bumper grazed/bent/deformed, RH headlamp broken, front windscreen cracked, front RH door glass shattered, tailgate dented/bent, etc. Please see para. 8 of this report for more details.

6 REMARKS

This inspection is carried out on a "WITHOUT PREJUDICE" basis and I have not authorized any repairs.

7 RECOMMENDATION

Cost of repairs : \$30,700.00 (lump sum)
No. of days taken : Twenty-one (21)

8 ASSESSMENT OF DAMAGE AND COSTS

Report no: 15M0118.PH

Vehicle no: GBD8833R

A SPARE PARTS

Description	Qty	Assessed Condition	Repairer's Amount	Revised Amount
(Nett Items)				
Front windscreen glass	1	cracked	991.00	991.00 CR ✓
Front windscreen inner seal	1	necessary	205.00	80.00 205.00 NEC
Front panel	1	buckled/distorted	NCX 1,412.70	1,412.70
Front panel "CABSTAR" emblem	1	necessary	NCX 35.30	35.30
Front grille	1	warped/distorted	578.60	438.40 578.60 DD ✓
Front grille logo	1	necessary	48.10	48.10 NEC ✓
RH side mirror	1	missing	171.70	171.70
RH side mirror arm	1	missing	191.90	191.90 } Mis ✓
RH side mirror arm base cover	1	missing	111.30	111.30
Front wiper panel	1	to repair	494.60	0.00 RX
Front wiper linkage	1	to reuse	151.50	0.00 NNX
Front wiper motor	1	serviceable	542.10	0.00 SVCX
RH front corner panel	1	crumpled	389.90	389.90 CRU ✓
RH headlamp assy	1	broken	473.40	473.40 BR ✓
LH headlamp assy	1	casing bent/tab fractured	473.40	-473.40 NNX
RH headlamp lower garnish	1	bent/distorted	28.60	28.60 BT ✓
Front bumper	1	grazed/bent/distorted	945.10	945.10 DD ✓
Front bumper bracket RH	1	bent	91.50	91.50 BT ✓
RH front door	1	squashed/distorted	1,396.50	1,396.50 DD ✓
RH front door hinge – upper	1	bent	61.10	61.10 BT ✓
RH front door hinge – lower	1	bent	61.10	61.10 BT ✓
RH front door check	1	bent	39.50	39.50 BT ✓
RH front door weatherstrip	1	squashed/deformed	151.10	151.10 DIS ✓
RH front door indicator lamp	1	to reuse	57.10	0.00 NNX
RH front door trim board	1	bent/deformed	722.50	722.50 BT ✓
RH front door trim board clip	10	necessary	85.00	85.00 NEC ✓
RH front door power window motor	1	seized	Δ NNX 524.40	524.40
RH front door glass regulator	1	bent	112.00	112.00 BT
RH front door glass outer moulding	1	torn	136.20	136.20 CUT ✓
RH front door 1/4 garnish	1	bent/deformed	55.30	55.30 BT ✓
RH front door inner lock	1	distorted	190.60	190.60 BT ✓
RH front door hand bezel	1	warped	101.20	101.20 BT ✓
RH front door inner handle	1	to reuse	57.00	0.00 NNX
RH front door glass rubber channel	1	deformed	185.20	185.20 DIS ✓
RH front door lock channel	1	bent	48.90	48.90 BT ✓
RH front door arc weatherstrip	1	deformed	85.10	85.10 CUT ✓
RH front door frame	1	bent/distorted	1,646.40	1000.00 1,646.40 BT ✓
RH front door frame beading	1	squashed/deformed	151.10	151.10 BT ✓
RH front door frame inner top cover RH	1	warped/distorted	114.70	114.70 BT ✓
RH front wheelhouse inner panel	1	bent/distorted	485.60	485.60 DIS ✓
RH front wheelhouse top sill garnish	1	bent/deformed	78.40	78.40 BT ✓
RH front step panel board	1	broken	139.40	139.40 BR ✓
Dashboard assy (complete)	1	side bent/cut	1,329.00	1123.00 1,329.00 CUT ✓
Dashboard underside support beam	1	bent	Δ R X 869.60	869.60
Meter assy	1	Leg & casing bent/deformed	Δ NNX 1,178.20	1,178.20
Instrumental cover	1	warped/distorted	Δ SVCX 257.90	257.90
Centre console box	1	warped/distorted	443.40	180.00 443.40 DIS ✓

Report no: 15M0118.PH
 Vehicle no: GBD8833R

ABS brake pipe	1 bent	60.20	60.20	
Steering column assy	1 bent	1,162.80	1,162.80	
Steering column base cover	1 torn	115.50	115.50	
Steering column top cover	1 buckled/deformed	151.20	151.20	NN
Steering column lower cover	1 buckled/deformed	135.60	135.60	
Steering box	1 shaft bent/jammed	881.60	881.60	
Wiper washer tank c/motor	1 squashed/distorted	206.40	206.40	
Brake vacuum tank	1 squashed	225.60	225.60	
Tailgate assy	1 dented/bent	1,399.70	1,399.70	Δ ✓
Taillamp assy RH/RH	2 broken	497.20	497.20	BRV
RH front lower arm	1 bent	489.00	489.00	
RH front upper arm	1 bent	480.00	480.00	NN
RH front suspension ball joint	1 bent/jammed	87.50	87.50	
RH front steering tie rod	1 bent	34.80	34.80	
RH steering ball joint	1 bent/jammed	124.00	124.00	
Subtotal of the above		24,150.30	22,848.00	
Discount	10% / 10%	2,415.03	2,284.80	
Subtotal 1:		21,735.27	20,563.20	

(Special nett)

ERP bracket	1 necessary	26.40	26.40	
Front windscreen sealant	1 necessary	80.00	80.00	50 80.00 NEC
Co. registration sticker	1 necessary	35.00	35.00	25 35.00
RH front door glass	1 shattered	760.00	760.00	613 760.00 BRV
ABS pump assy	1 seized	4,500.00	4,500.00	
ABS wheel speed sensor wire RH	1 shorted	525.30	525.30	
Brake booster c/w bracket	1 bent	310.60	310.60	
Brake /clutch pedal bracket	1 bent	208.80	208.80	NK
Aircon evaporator unit	1 mounting arm bent	1,310.60	1,310.60	
RH front shock absorber	1 bent	180.40	180.40	
LH front shock absorber	1 Necessary (50%)	180.40	90.20	
RH front knuckle arm	1 bent/distorted	857.80	857.80	
RH front wheel bearing	1 notchy/rattled	73.20	73.20	
Tailgate "70 km/h" sticker	1 necessary	15.00	15.00	
Tailgate "13 pax" sticker	1 necessary	15.00	15.00	NEC
Tailgate aluminum back plate	1 bent	200.00	200.00	150 200.00 BTv
Rear step bar	1 bent	125.00	125.00	100 125.00 BTv
Rear step bar aluminum cover	1 bent	50.00	50.00	BTv
RH front door artwork sticker set	1 necessary	150.00	150.00	120 150.00 NEC
Rear number plate	1 bent	35.00	35.00	BT
Brake oil	1 necessary	40.00	40.00	NN X
Subtotal 2:		9,678.50	9,588.30	1556

Total cost of parts:

31,413.77 30,151.50

B LABOUR

FRONT PORTION

To check wiring.	120.00	60.00	30
To refocus headlamp beams to specifications.	80.00	60.00	
To re-apply rustproofing for the affected portion.	200.00	150.00	60.00

Report no: 15M0118.PH
 Vehicle no: GBD8833R

Labour charges to remove and replace, to cut and weld, to panel beat and reshape damaged body parts & panels.	3,600.00	3,000.00	1600
Spray painting charges to putty and spray all affected parts and body panels.	1,500.00	1,250.00	800.00
To remove and replace front windscreen glass.	150.00	120.00	
To remove and replace front dashboard and support beam.	450.00	360.00	200.00
To remove and replace aircon evaporator, vacuum and charge up aircon gas.	120.00	90.00	NNX
To remove and replace front RHS undercarriage parts.	600.00	450.00	X
To remove and replace ABS pump, pipe, sensing wire and test for safe operating condition.	800.00	600.00	X
To remove and replace steering column, steering pump, brake/clutch bracket, brake booster, etc. To bleed brake system of airlock and test for safe operating condition.	450.00	300.00	X
To realign wheels by computerised wheel alignment.	90.00	90.00	NNX
To supply front door artwork stickers and affix after the repairs.	150.00	150.00	X
REAR PORTION			
To check wiring.	45.00	30.00	
To re-apply rustproofing for the affected portion.	120.00	60.00	40
Labour charges to remove and replace, to cut and weld, to panel beat and reshape damaged body parts & panels.	900.00	600.00	400.00
Spray painting charges to putty and spray all affected parts and body panels.	750.00	500.00	200.00
To supply tailgate artwork/information stickers and affix after the repairs.	300.00	300.00	100.00

Total cost of labour:	10,425.00	8,170.00
-----------------------	-----------	----------

Total cost of repair:	41,838.77	38,321.50
-----------------------	-----------	-----------

9 CONCLUSION

Report no: 15M0118.PH
Vehicle no: GBD8833R

The actual damage sustained by the vehicle was carefully inspected and assessed during the inspection and the assessment is appended in para. 8 of this report. The degree of damage sustained by individual part(s) is/are carefully assessed before the part(s) is/are recommended to be either replaced or repaired.

The revised or adjusted cost of repairs to restore the vehicle is \$38,321.50.


However, after considering the age and condition of the vehicle and the availability of good second hand parts in the market, the repairs are therefore recommended to be undertaken on a contract lump sum basis of \$30,700.00 and the repairs had taken Twenty-one (21) days to complete.

The above recommendations in my view are fair and reasonable for the restoration of the vehicle to its pre-accident condition.

Note: By accepting to carry out the repairs on a contract lump sum basis, the repairer has the discretion to replace the damaged part(s) with used, reconditioned or new part(s), or to repair the part(s) to a roadworthy condition.

We have not authorised any repairs and would like to revert the recommendations for your consideration and decision.

Yours faithfully



.....
Liaw Leong San
Licensed Automotive Appraiser

Repair days 16



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL		Ref : CS3/SMO18000481/Bsd3e2-1		
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623		Date : 10-09-2018		
		Code : SMO		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBD 4877R	Veh. Inspected	GBD 8833R	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD1800134/THE	Excess (\$)	0.00	
Assign From	THELMA CHOO	Assign Date	11/07/2018	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN CABSTAR	c.c	2953	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	JN1SC2F24Z0855603	Colour	GOLD	
Odometer	145171	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/80 R15	YOKOHAMA	7 mm	
L/H Front Tyre	195/80 R15	YOKOHAMA	7 mm	
R/H Rear Tyre	155 R15C (D)	YOKOHAMA	6/6 mm	
L/H Rear Tyre	155 R15C (D)	YOKOHAMA	6/6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	05/01/2018	Inspection Date	09/01/2018	
Survey held at	PAUL HOE BATTERIES & MOTOR SERVICES BLK 1 KAKI BUKIT AVE 6 #01-109 AUTOBAY SINGAPORE 417833			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		16 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBD 8833R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT WINDSCREEN GLASS	CRACKED	991.00	991.00
1	FRONT WINDSCREEN INNER SEAL	NECESSARY	205.00	80.00
1	FRONT PANEL (BUCKLED / DISTORTED)	NOT CONSISTENT WITH THE IMPACT	1,412.70	-
1	FRONT PANEL "CABSTAR" EMBLEM (NECESSARY)	NOT CONSISTENT WITH THE IMPACT	35.30	-
1	FRONT GRILLE	DENTED	578.60	438.40
1	FRONT GRILLE LOGO	NECESSARY	48.10	48.10
1	RH SIDE MIRROR	MISSING	171.70	171.70
1	RH SIDE MIRROR ARM	MISSING	191.90	191.90
1	RH SIDE MIRROR ARM BASE COVER	MISSING	111.30	111.30
1	FRONT WIPER PANEL	TO REPAIR SEE LABOUR	494.60	-
1	FRONT WIPER LINKAGE	NOT NECESSARY	151.50	-
1	FRONT WIPER MOTOR	SERVICEABLE	542.10	-
1	RH FRONT CORNER PANEL	CRUSHED	389.90	389.90
1	RH HEADLAMP ASSY	BROKEN	473.40	473.40
1	LH HEADLAMP ASSY	NOT NECESSARY	473.40	-
1	RH HEADLAMP LOWER GARNISH	BENT	28.60	28.60
1	FRONT BUMPER	DENTED	945.10	945.10
1	FRONT BUMPER BRACKET RH	BENT	91.50	91.50
1	RH FRONT DOOR	DENTED	1,396.50	1,396.50
1	RH FRONT DOOR HINGE - UPPER	BENT	61.10	61.10
1	RH FRONT DOOR HINGE - LOWER	BENT	61.10	61.10
1	RH FRONT DOOR CHECK	BENT	39.50	39.50
1	RH FRONT DOOR WEATHERSTRIP	DISTORTED	151.10	151.10
1	RH FRONT DOOR INDICATOR LAMP	NOT NECESSARY	57.10	-
1	RH FRONT DOOR TRIM BOARD	BENT	722.50	722.50
10	RH FRONT DOOR TRIM BOARD CLIP	NECESSARY	85.00	85.00
1	RH FRONT DOOR POWER WINDOW MOTOR	NOT NECESSARY	524.40	-
1	RH FRONT DOOR GLASS REGULATOR	BENT	112.00	112.00
1	RH FRONT DOOR GLASS OUTER MOULDING	CUT	136.20	136.20
1	RH FRONT DOOR 1/4 GARNISH	BENT	55.30	55.30
1	RH FRONT DOOR INNER LOCK	BENT	190.60	190.60
1	RH FRONT DOOR HAND BEZEL	BENT	101.20	101.20

Report Ref No. CS3/SMO18000481/Bsd3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	RH FRONT DOOR INNER HANDLE	NOT NECESSARY	57.00	-
1	RH FRONT DOOR GLASS RUBBER CHANNEL	DISTORTED	185.20	185.20
1	RH FRONT DOOR LOCK CHANNEL	BENT	48.90	48.90
1	RH FRONT DOOR ARC WEATHERSTRIP	CUT	85.10	85.10
1	RH FRONT DOOR FRAME	BENT	1,646.40	1,000.00
1	RH FRONT DOOR FRAME BEADING	BENT	151.10	151.10
1	RH FRONT DOOR FRAME INNER TOP COVER RH	BENT	114.70	114.70
1	RH FRONT WHEELHOUSE INNER PANEL	DISTORTED	485.60	485.60
1	RH FRONT WHEELHOUSE TOP SILL GARNISH	BENT	78.40	78.40
1	RH FRONT STEP PANEL BOARD	BROKEN	139.40	139.40
1	DASHBOARD ASSY (COMPLETE)	CUT	1,329.00	1,123.00
1	DASHBOARD UNDERSIDE SUPPORT BEAM	TO REPAIR SEE LABOUR	869.60	-
1	METER ASSY	NOT NECESSARY	1,178.20	-
1	INSTRUMENTAL COVER	SERVICEABLE	257.90	-
1	CENTRE CONSOLE BOX	DISTORTED	443.40	180.00
1	ABS BRAKE PIPE	NOT NECESSARY	60.20	-
1	STEERING COLUMN ASSY	NOT NECESSARY	1,162.80	-
1	STEERING COLUMN BASE COVER	NOT NECESSARY	115.50	-
1	STEERING COLUMN TOP COVER	NOT NECESSARY	151.20	-
1	STEERING COLUMN LOWER COVER	NOT NECESSARY	135.60	-
1	STEERING BOX	NOT NECESSARY	881.60	-
1	WIPER WASHER TANK C/MOTOR	NOT NECESSARY	206.40	-
1	BRAKE VACUUM TANK	NOT NECESSARY	225.60	-
1	TAILGATE ASSY	DENTED / BENT	1,399.70	1,399.70
2	TAILLAMP ASSY RH / LH	BROKEN	497.20	497.20
1	RH FRONT LOWER ARM	NOT NECESSARY	489.00	-
1	RH FRONT UPPER ARM	NOT NECESSARY	480.00	-
1	RH FRONT SUSPENSION BALL JOINT	NOT NECESSARY	87.50	-
1	RH FRONT STEERING TIE ROD	NOT NECESSARY	34.80	-
1	RH STEERING BALL JOINT	NOT NECESSARY	124.00	-
	LESS 10% DISCOUNT		-2,415.03	-1,256.13
			21,735.27	11,305.17
	<u>SPECIAL NETT ITEMS</u>			
1	ERP BRACKET (SN)	NECESSARY	26.40	26.40
1	FRONT WINDSCREEN SEALANT (SN)	NECESSARY	80.00	50.00

Report Ref No. CS3/SMO18000481/Bsd3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	CO . REGISTRATION STICKER (SN)	NECESSARY	35.00	25.00
1	RH FRONT DOOR GLASS (SN)	BROKEN	760.00	613.00
1	ABS PUMP ASSY (SN)	NOT NECESSARY	4,500.00	-
1	ABS WHEEL SPEED SENSOR WIRE RH (SN)	NOT NECESSARY	525.30	-
1	BRAKE BOOSTER C/W BRACKET (SN)	NOT NECESSARY	310.60	-
1	BRAKE / CLUTCH PEDAL BRACKET (SN)	NOT NECESSARY	208.80	-
1	AIRCON EVAPORATOR UNIT (SN)	NOT NECESSARY	1,310.60	-
1	RH FRONT SHOCK ABSORBER (SN)	NOT NECESSARY	180.40	-
1	LH FRONT SHOCK ABSORBER (SN)	NOT NECESSARY	180.40	-
1	RH FRONT KNUCKLE ARM (SN)	NOT NECESSARY	857.80	-
1	RH FRONT WHEEL BEARING (SN)	NOT NECESSARY	73.20	-
1	TAILGATE "70KM/H" STICKER (SN)	NECESSARY	15.00	15.00
1	TAILGATE "13 PAX" STICKER (SN)	NECESSARY	15.00	15.00
1	TAILGATE ALUMINIUM BACK PLATE (SN)	BENT	200.00	150.00
1	REAR STEP BAR (SN)	BENT	125.00	100.00
1	REAR STEP BAR ALUMINIUM COVER (SN)	BENT	50.00	50.00
1	SET RH FRONT DOOR ARTWORK STICKER (SN)	NECESSARY	150.00	120.00
1	REAR NUMBER PLATE (SN)	BENT	35.00	35.00
1	BRAKE OIL (SN)	NOT NECESSARY	40.00	-
			9,678.50	1,199.40
	LABOUR			
	TO CHECK WIRING. }		120.00	30.00
	TO REFOCUS HEADLAMP BEAMS TO SPECIFICATIONS. }		80.00	-
	TO RE-APPLY RUSTPROOFING FOR THE AFFECTED PORTION.		200.00	60.00
	LABOUR CHARGES TO REMOVE AND REPLACE, TO CUT AND WELD, TO PANEL BEAT AND RESHAPE DAMAGED BODY PARTS & PANELS. INCLUSIVE OF THE REPAIR OF FRONT WIPER PANEL AND DASHBOARD UNDERSIDE SUPPORT BEAM.		3,600.00	1,600.00
	SPRAY PAINTING CHARGES TO PUTTY AND SPRAY ALL AFFECTED PARTS AND BODY PANELS.		1,500.00	800.00
	TO REMOVE AND REPLACE FRONT WINDSCREEN GLASS.		150.00	120.00
	TO REMOVE AND REPLACE FRONT DASHBOARD AND SUPPORT BEAM.		450.00	200.00
	TO REMOVE AND REPLACE AIRCON EVAPORATOR, VACUUM AND CHARGE UP AIRCON GAS.	NOT NECESSARY	120.00	-

Report Ref No. CS3/SMO18000481/Bsd3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND REPLACE FRONT RHS UNDERCARRIAGE PARTS.	NOT NECESSARY	600.00	-
	TO REMOVE AND REPLACE ABS PUMP, PIPE, SENSING WIRE AND TEST FOR SAFE OPERATING CONDITION.	NOT NECESSARY	800.00	-
	TO REMOVE AND REPLACE STEERING COLUMN, STEERING PUMP, BRAKE / CLUTCH BRACKET, BRAKE BOOSTER, ETC. TO BLEED BRAKE SYSTEM OF AIRLOCK AND TEST FOR SAFE OPERATING CONDITION.	NOT NECESSARY	450.00	-
	TO REALIGN WHEELS BY COMPUTERISED WHEEL ALIGNMENT.	NOT NECESSARY	90.00	-
	TO SUPPLY FRONT DOOR ARTWORK STICKERS AND AFFIX AFTER THE REPAIRS.	NOT NECESSARY	150.00	-
	TO CHECK WIRING.		45.00	30.00
	TO RE-APPLY RUSTPROOFING FOR THE AFFECTED PORTION.		120.00	40.00
	LABOUR CHARGES TO REMOVE AND REPLACE, TO CUT AND WELD, TO PANEL BEAT AND RESHAPE DAMAGED BODY PARTS & PANELS.		900.00	400.00
	SPRAY PAINTING CHARGES TO PUTTY AND SPRAY ALL AFFECTED PARTS AND BODY PANELS.		750.00	300.00
	TO SUPPLY TAILGATE ARTWORK / INFORMATION STICKERS AND AFFIX AFTER THE REPAIRS.		300.00	100.00
			10,425.00	3,680.00
GRAND TOTAL			41,838.77	16,184.57
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				12,950.00

Report Ref No. CS3/SMO18000481/Bsd3e2-1

LIM TEOW GUAN

Asst. Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.