

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC6/III18012641/KPA3Q2

**Date:** 13/05/2020

### REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
<b>Claimant</b>		
<b>Vehicle No :</b> SGF8686D	<b>Insured Vehicle No :</b>	SHC8953L
Date of Loss: 05/07/2018	Nature of Claim: TP	Claim No: MCT18070335

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGF8686D		
Make & Model:	TOYOTA WISH, 1.8 CVT (A)	Engine No:	2ZR1830916
Reg. Date:	28/09/2016 (Man. Year: 2016)	Chassis No:	JTDGG20W00J005039
Colour:	Metallic Grey	Odometer:	38324 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Michelin 9 mm	Rear Left Side:	Michelin 9 mm
Front Right Side:	Michelin 9 mm	Rear Right Side:	Michelin 9 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,557.15	368.92	1,188.23	76.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,830.00	400.00	1,430.00	78.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>3,387.15</b>	<b>768.92</b>	<b>2,618.23</b>	<b>77.30</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	237.10	53.82	183.28	77.30
<b>Nett Amount (\$\$)</b>	<b>3,624.25</b>	<b>822.74</b>	<b>2,801.51</b>	<b>77.30</b>
<b>Global Sum Settlement (\$\$)</b>		<b>0.00</b>		

### INSPECTION

Date of Assignment:	10/07/2018	
Date Inspected:	10/07/2018 Inspected At:	Alan's United Auto Pte Ltd (HQ) Blk 7 Sin Ming Industrial Estate, #01-76 Singapore 575642
Estimated Period of Repair:	5.0 days	

**Adjuster:** KENNETH KONG

**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 13 May 2020)
<b>Parts:</b>	M1-MPV	TOYOTA WISH 1.8 CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SGF8686D)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER FASCIA	Buckled	491.90 FL	*491.90 FL
2	2		*REAR BUMPER BRACKET	Repair	97.40 FL	*- FL
3	2		*REAR BUMPER SIDE RETAINER	Serviceable	179.80 FL	*- FL
4	1		*REAR END PANEL INNER	Repair	199.50 FL	*- FL
5	1		*REAR END PANEL OUTER	*Check	453.90 FL	*- FL
6	1		*END PANEL TOP GARNISH	Serviceable	253.70 FL	*- FL
7	1		*SET REAR BUMPER REVERSE SENSOR	*Check	300.00 FS	*- FS
					<b>Sub Total (S\$)</b>	<b>1,976.20 491.90</b>
					<b>- List Item Discount on L Items 25.00/25.00% (S\$)</b>	<b>419.05 122.98</b>
					<b>Total Parts (S\$)</b>	<b>1,557.15 368.92</b>

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO REMOVE ROOF LINING ,FRONT AND REAR SEATS ,TRIM BOARD AND CARPET (*Check)	New	120.00	0.00
2	TO APPLY UNDERSEALING (*Check)	New	60.00	0.00
3	TO PUTTY AND SPRAY REPLACED PARTS	New	800.00	400.00
4	TO REMOVE, CUT -OUT DAMAGED PARTS, PANEL BEATING ,WELDING ,ALIGN,REFIX AND TO RENEW ABOVE PARTS (*Check)	New	850.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,830.00</b>	<b>400.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >