

## CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD **EUNOS LINK SERVICE CENTRE**



330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

## **ESTIMATE**

Invoice Name & Address	Owner Name & Vehicle Info				
Mr PREM KUMAR S/O JAYABALAN	Cust No/Name	/Mr Prem Kumar S/O Jayabalan			
10A Canberra Drive	Reg No/Reg Date	SLK2412G / 11/01/2017			
#07-20	Date In/Mileage	10/07/2018/ 0			
Singapore 768143	Chassis No KNAPH81BMH5299723 Engine No D4HBGH302266				
	Colour/Trim	ABP / WK			

Acc	ount No	Terms	Date/Time Pr	inted	CSE	Operator	84 6 T S 180	WIP No	THE WAR	
CSM	00001	Cash	12/07/2018/	10:44	DS	218 / MarsLer		61002		
			Description	of Goods	s / Services		Qty	Unit Price	Disc%	Amount
М	SUNDRY							sec		35.0
	C & C LO	GO						,	.	
	MIPNT8808							6	0	80.0
		LIGHTING	& WIRING SY	STEM ON	REAR ACCI	DENT AFFECTED		0		
	AREAS	00							-	250 0
	MIPNT8808		INTAC							250.0
	DIAGNOST:		INING					3	_	600.0
_			ATE COMPONET	8. MECH	MICH DADT	2		3	00	000.0
	MIPNT880		IATE COMPONET	a PILCHI	MIDH FAKT	3				300.0
9	TO REPLA		TE GLASS			П	_			
S	MIPNT880				277		247	· · · ·		100.0
			ILGATE GLASS	(	511		⊒   ( <u>←</u>	1 rue		
S	MIPNT880			7	0) [		2115	7 11	X	220.0
	TO INSTA	LL RIKE C	COOL SOLAR FI	LM ON TA	AILGATE GL	ASS				
S	MIPNT880							_	300	600.
			INSTALL REAR							
			ON REAR ACC	IDENT A	FFECTED AR	EAS		16	20-	2600
S	MIPNT880		TE DD CDOTLE	D DEAD !	NIMPED DET	NEODOCHENE ETO		10	200	3600.
					SUMPER, REI	NFORCEMENT, ETC				
			AR END PANEL 1,ALIGN ON RE		DENT AFFEC	TED ADEAS				
2	MIPNT880		, ALIGN ON KE	AK ACCII	JENI AFFEC	IEU AREAS		/	50	300.
			KIT ON REAR	ACCIDEN.	AFFECTED	AREAS			70	
S	MIPNT980							16	an	2940.
	SPRAY PA	INTING ON	REAR ACCIDE	NT AFFE	CTED AREAS			10	00	
S	MIPNT880	88						Se	W -	50.0
			WITH CASING						`	
P	KS 86611				R BUMPER,			696.00	25.5 (1.00)	696.
P		C5 020			R BUMPER	De	1.00	650.00		650.0
Ρ.		C5 010			- REAR BU	741		103.00		
M		C5 000		RR HOOK	CVET ACCV	11	1.00	22.00	1.	22.
Μ	KS 86661	C5 000	LH S	INF RKW	CKET ASSY	Sul	1.00	25.00	0.00	25.

Confirm & accepted by

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimated results on our initial inspection and does not include any additional parts or labour which may be required after repair work has recommenced of the work has started and needed for repairs or replacement. However, is bould this about 1820 Set 1930. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Signature:

Page 1 of 2



## CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD **EUNOS LINK SERVICE CENTRE**



330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

## **ESTIMATE**

Invoice Name & Address	Owner Name & Vehicle Info				
M. DDEM WIMAD C /O JAVADALAN	Cust No/Name	/Mr Prem Kumar S/O Jayabalan			
Mr PREM KUMAR S/O JAYABALAN 10A Canberra Drive	Reg No/Reg Date	SLK2412G / 11/01/2017			
#07-20	Date In/Mileage	10/07/2018/ 0			
Singapore 768143	Chassis No	KNAPH81BMH5299723			
	Engine No	D4HBGH302266			
Contact No Mobile: 90698787	Make/Model	KIA/SORENTO UM 2.2 A DIESEL 2WD AB			
	Colour/Trim	ABP / WK			

Account N	o Terms	Date/Time Printed	CSE	Operato	r		WIP No	<b>多数的</b>		
CSM00001	Cash	12/07/2018/ 10:44	DS	218 / M	arsLer		61002			
		Description of Good	s / Services			Qty	Unit Price	Disc%	Ar	nount
M KS 866	62 C5 000	RH SIDE BRA	CKET ASSY		Bul 1	1.00	25.00	0.00	_	25.00
M KS 968	390 C5 100	ULTRASONIC	SENSOR -		Sulto	4.00	215.00	0.00	2715	860.00
M KS 918	380 C5 030	WIRING HARM	IESS - REA			1.00	248.00	0.00	3.	248.00
P KS OGO	32 50 037	CLIP- BUMPE	R		ne	10.00	2.00	0.00	_	20.00
M KS 924	106 C5 100	RHR FOG LAN	MP ASSY		11	1.00	129.00	0.00	X	129.00
M KS 924	105 C5 100	LHR FOG LAN	MP ASSY		11	1.00	129.00	0.00	X	129.00
M KS 86	530 C5 010	RAIL ASSY-F	REAR BUMPE			1.00	392.00	0.00	?	392.00
M KS 954	120 C5 500	ANTENNA ASS	Y-SMARTKE			1.00	53.00	0.00	?	53.00
M KS 659	910 C5 000	PANEL ASSY-	-BACK		12	1.00	526.00	0.00	+	526.00
M KS 95	760 C5 000	RR CAMERA 8	TRUND LI		11	1.00	804.00	0.00	Ĭ.	804.00
M KS 95	766 C5 000	CAMERA ASS	-BACK-VI			□1.00	635.00	0.00	7	635.00
M KS 95	710 C5 000	BUZZER_ASS)	EPIEZO > F	IFOX	200	5 7.00	50.00	0.00	?	50.00
M KS 73	700 C5 121	TAIL GATE	ANEL ASSY	1111	Sa 1750	1.00	1445.00	0.00	_	1445.00
M KS 92	501 3K 000	LISENCE PL	TE-LAMP 4		11401	(8.60	7 33.00	0.00	?	66.00
	403 C5 110	LH TAIL LAN			11	1.00	751.00	0.00	X	751.00
	404 C5 110	RH TAIL LAM	MP ASSY-RE		11		751.00	0.00	مر	751.00
M KS 92	401 C5 112	LH OTR LAM	ASSY-REA		cro		687.00	0.00	_	687.00
M KS 92	402 C5 112	RH OTR LAM	ASSY - R			1.00	687.00	0.00	?	687.00
M KS 86	320 C5 100	EMBLEM-KIA			n	1.00	69.00	0.00	_	69.00
P KS 86	310 C5 010	EMBLEM-SORE	ENTO		re	€ 1.00	28.00	0.00	_	28.00
	333 C5 000		CO DYNAMIC		re	1.00	37.00	0.00		37.00
	210 C5 000		REAR		1	1.00	915.00	0.00	2	915.00
M KS 87	110 C5 000	GLASS ASSY	- TAILGAT		+₹≪	1.00	690.00	0.00	X	690,00
M KS 86	114 2L 000	PAD - WINDS	SHIELD		n	4.00	17.00	0.00		68.00
M KS 86	114 3D 000	PAD-W/SHLD	GLASS		re	6.00	2.00	0.00	?	12.00
M KS 81	230 C5 100					1.00	652.00	0.00		652.00
M KS 81	770 C5 100	LH POWER TA	AIL GATE A			1.00	760.00	0.00		760.00
M KS 87	321 C5 000	W/STRIP TA	ILGATE		nec	1.00	128.00	0.00		128.00
Z NOTES		,								
	ENT ON 05/	07/2018 ALONG JUNCTIO	ON OF YISHUN	AVE 7 &	AVENUE 2					
		THIRD PARTY			/					
	RED REPLAC		alat	Dell.	. pl					
TP :	GZ7707D	TP INS : EQ	Not	ngu	41					
			d	the		Daniela				12 112 0
Confirm	& accepted	by		12/1		Parts				13,113.0
			251	1/18		Labour	lonu			0.0
			(	/		Standard M				9,040.00
			. 6	dy.		Specialist				0.0
			76.1	111	/	Others (Lub	,etc)			35.0
			ane ja	· sepo	how	Sundry Total (w/o	CST)			22,188.0
		ry and company stamp			1	TOTAL(W/O	431)			22,200.0

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.