

ASS. REC. BY:

REF: CS/FCI18012673/Kqd3⁷²

Special Instruction:

Surveyor:
CWS

Kenneth

ASSIGNMENT (Office)

From (Person):

Lurene juw

of

FCI

Date/Time: 11/07/18 @ 5.59pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHD 9202J

Insured:

SHC 7639B

at Workshop m/s

Trans-cab

Tel:

6287 6666

of

No. 2 AMK 8f-63

Policy No:

Claim No:

D18005349 MFSH

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A.

06/07/2018

CA / REV / REP. / REV 24 HRS

lup

H.O.D. Endorsement:

Date/Time:

8:45am @ 12/7/18

Person Contacted:

Cendy

Vehicle

IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SHD 9202J - CC3/FCI16018256/Kqbe2

DOA: 26/09/2016

SHC 7639B - CC3/TMI17023862/K/vbn2

DOA: 15/12/2017

13/7/18 @ 5.27pm revised to Lurene by email.

11 Sep 83450/ Cred @ 2236.98, 87%.)

(08/11/13) wef

ASS. REC. BY:

REF:

FCI

ASSIGNMENT

From: _____ Date: 12/07/18

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SHD 9202Jat Workshop m/s Trans-Cabof No. 2 AMK St. 63

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____


Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or NoCA / REV / REP. / 24 HRS up

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHD 9202J Yr Regn: 101 11Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi Prime Mover /

Truck / Trailer or

Make: Chevrolet Epica c.c. 1991Colour White / Red A/C: Insured / Std / NI / NASp. Reading 771663 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KL11A69RJBB 058554Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Giti

Front

R/Bal. 9 mmL/Bal. 9 mmD.O.A. 8/7/18

Rear

R/Bal. 8 mmL/Bal. 8 mmD.O.I. 12/7/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or N/S body

The U/C / Chassis frame / Body Structure affected due to collision.

RECEIVED 9 OCT 2018

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report1) 09/10 10:55

Date/Time, File Return to?

2) _____

Days Of Repair: 4

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

\$ + RS. \$ _____

Photos OSPOthers 10/10/18

TOTAL

15X15 = 225

170 + 225

50

20

(465)

Report Format: TPLump Sum / I.B.I. (\$) 3450



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18012673/Kqd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 12-07-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 7639B	Veh. Inspected	SHD 9202J
Policy No.		Coverage (\$)	0.00
Claim No.	D18005349MFSH	Excess (\$)	0.00
Assign From	CWS (LURENE JAW)	Assign Date	12/07/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	06/07/2018	Inspection Date	12/07/2018
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18005349MFSH

Date: 13 July 2018

Our Ref: CS/FCI18012673/Kqd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SHD 9202J .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 12/07/2018 at the premises of M/s TRANS-CAB, and have the following to report:-

Workshop Estimate Amount	: S\$ 25,819.89 .
Revised Estimate Amount	: S\$ 4,284.66 .
"Check" Items Amount	: S\$ 463.10 .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:

The vehicle sustained damages
at the n/s body.



Yours faithfully

KONG SENG CHEONG
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	11-07-2018	Our Ref No. D18005349MFSH
Accident Date	06-07-2018	Claim Type. Third Party
Insured Vehicle	SHC7639B	Third Party Vehicle. SHD9202J
Survey Location	NO. 2 ANG MO KIO STREET 63	
Contact Person.	CANDY KONG	
Contact No.	62876666/ 0	Fax No. 62571330
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TRANS-CAB AUTO SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/242275)



PRI Documents



Close



PRI Header Details

Claim No	D18005349MFSH	Policy No	D-18088937MFSH	Claimant S.No & Name	1 & TRANS-C/
Workshop Name	TRANS-CAB AUTO SERVICES PTE LTD (Contact Person : CANDY KONG)	Survey Location & Contact Details	NO. 2 ANG MO KIO STREET 63 Mobile: 0 , Phone: 62876666 , Fax: 62571330 EmailId: CANDY.KONG@TRANSCAB.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHC7639B	TP Vehicle No	SHD9202J
PRI Recieved Date	11-07-2018 07:57:39 PM	Surveyor Appointed Date	11-07-2018 05:58:15 PM	Surveyor Accept Date	12-07-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	12-07-2018	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

Upload Multiple Documents	
File Name	Action

Surveyor Job Remarks

Remarks		Save
---------	----------------------	-------------------------------------

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Friday, 13 July 2018 5:17 PM
To: 'Claim Workflow System'; assignments
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18005349MFSH/1
Attachments: CSFCI18012673Kqd3.pdf

Dear Lurene,

Enclosed herewith preliminary advice of SHD 9202J.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sjewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Thursday, 12 July 2018 9:11 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18005349MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 11 July 2018 5:59 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; LURENEJAW@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18005349MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

[-> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	3878K

Vehicle Details

Vehicle No.:	SHD9202J
Vehicle to be Exported:	Yes
Intended De-registration Date:	09 Jul 2018
Vehicle Make:	CHEVROLET
Vehicle Model:	EPICA 2.0DSL AT ABS D/AB 2WD 4DR TURBO
Primary Colour:	Red
Manufacturing Year:	2011
Engine No.:	Z20S1443353K
Chassis No.:	KL1LA69RJB058554
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$14,052.00
Original Registration Date:	14 Oct 2011
First Registration Date:	14 Oct 2011
Transfer Count:	0
Actual ARF Paid:	\$14,052.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 Oct 2019
PARF Rebate Amount:	\$9,133.00

Intended COE Rebate Details

COE Expiry Date:	13 Oct 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	8
QP Paid:	\$35,200.00
COE Rebate Amount:	\$5,547.00
Total Rebate Amount:	\$14,680.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 09 Jul 2018

OK

Trans-Cab Services Pte Ltd

APPLICATION FOR RELIEF DRIVER

Name : ONG NAY NANG
NRIC No. : S0738455F
Address : BLK 535 JURONG WEST STREET 52
#03-467
Singapore, 640535
SINGAPORE

Contact No. Home :
Handphone : 97439251
Other :

Signature of Relief Driver

11. July 2018

Date

I, Hirer PUA JACK LAI of NRIC No. S1195918J of Taxi Number SHC5448Z ("The Taxi") wish to engage the above mentioned Applicant's as my relief driver.

Signature of Hirer

11. July 2018

Date

Please see enclosed Terms and Conditions

Entered By: TRANSCAB\ANNE.TOH on 11/07/18 01:26 PM

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9202J**AAD1807-076***Not Authored
L1 Imp 834501*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD 9202J

LK1LA69RJB058554

CHEVROLET

EPICA 2.0

6.7.2018

FCIL**PART****LIST**

1	1	Front Fender LH	\$	<i>R</i>	837.60	X
2	1	Front Fender Liner LH	\$	<i>Sm</i>	47.00	X
3	1	Front Fender Inner Wheel House Panel LH	\$	<i>R</i>	1,437.00	X
4	1	Front Shock Absorber Assy LH	\$	<i>Sm</i>	216.17	X
5	1	Front Shock Absorber Top Mounting LH	\$	<i>Sm</i>	48.32	X
6	1	Front Lower Arm LH	\$	<i>Sm</i>	283.00	X
7	1	Front Knuckle Arm LH	\$	<i>Sm</i>	230.00	X
8	1	Front Door LH	\$	<i>R</i>	1,133.00	✓
9	1	Front Door Glass Guide RH Chrome Moulding	\$	<i>Sm</i>	60.00	X
10	1	Front Door Outer Moulding	\$	<i>Sm</i>	220.00	X
11	1	Front Door Outer Handle	\$	<i>Sm</i>	125.00	✓
12	1	Front Door Handle Support	\$	<i>Sm</i>	3.00	} X
13	1	Front Door outer handle inner seal	\$	<i>Sm</i>	89.15	
14	1	Front Door outer key lock	\$	<i>Sm</i>	25.00	
15	1	Front Door Hinge Upper	\$	<i>R</i>	65.00	
16	1	Front Door Hinge Lower	\$	<i>R</i>	65.00	
17	1	Front Door inner lock	\$	<i>R</i>	586.00	
18	1	Front Door Inner Lock Latch LH	\$	<i>R</i>	206.00	
19	1	Front Door Check / Arrestor	\$	<i>Sm</i>	67.50	
20	1	Front Door Weatherstrip LH	\$	<i>Sm</i>	138.79	
21	1	Front Door glass channel weatherstrip	\$	<i>Sm</i>	160.00	
22	1	Front Door inner trim board	\$	<i>Sm</i>	455.69	} X
23	1	Front Door window glass	\$	<i>Sm</i>	456.12	
24	1	Front Door Power Window Motor (Master) LH	\$	<i>Sm</i>	284.97	X
25	1	Front Door power window motor switch	\$	<i>Sm</i>	145.00	X
26	1	Front Door Window Regulator Gear LH	\$	<i>Sm</i>	84.58	X
27	1	Front Door Outer Pillar Panel LH	\$	<i>R</i>	715.00	X

Trans-cab Auto Services Pte Ltd**AAD1807-076**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9202J

28	1	Front Door Pillar Inner Panel LH	\$	<i>N</i>	850.00	X
29	1	Front Door Center Pillar Panel LH	\$	<i>N</i>	698.15	X
30	1	Front Side View Mirror Assy LH	\$	<i>Sn</i>	1,191.00	X
31	1	Rear Door LH (Panel A-RR DR LH)	\$	<i>N</i>	1,133.00	✓
32	1	Rear door weatherstrip - Inner	\$	<i>Sn</i>	41.40	X
33	1	Rear door weatherstrip - 2nd Frame	\$	<i>Sn</i>	25.90	X
34	1	Rear door top hinge	\$	<i>N</i>	35.00	X
35	1	Rear door bottom hinge	\$	<i>N</i>	35.00	X
36	1	Rear door inner lock	\$	<i>N</i>	425.00	X
37	1	Rear door check / arrestor	\$	<i>N</i>	65.00	X
38	1	Rear door lock striker / latch	\$	<i>N</i>	120.00	X
39	1	Rear door outer weatherstrip moulding	\$	<i>Sn</i>	85.00	X
40	1	Side Rocker Panel Garnish LH	\$	<i>Nu / Nu</i>	236.40	✓
41	1	Rear Fender LH	\$	<i>N</i>	1,145.00	X
42	1	Rear Fender Inner Trim LH	\$	<i>Sn</i>	418.44	X
43	1	Front Side Rocker Panel Garnish LH	\$	<i>Sn</i>	236.40	X
44	1	Front Side Rocker Panel Outer LH	\$	<i>N</i>	600.00	X
45	1	Front Side Rocker Panel Inner LH	\$	<i>N</i>	519.30	X

TOTAL	\$	16,043.88
10%	\$	1,604.39
	\$	14,439.49

Special Nett

1 Set	Front Bumper Fastener Clip	\$	<i>Nu</i>	24.00	} X
1 Set	Front licence plate with holder	\$	<i>Sn</i>	192.00	
1 Set	Radiator Grille clip	\$	<i>Nu</i>	35.00	
1 Set	Front Fender Liner clip	\$	<i>Nu</i>	30.00	
1	Front Fender RR Bracket LH	\$	<i>N</i>	7.10	
1	Front Wheel Rim Hub Cap LH	\$	<i>Sn</i>	166.30	
1	Front Tyre LH	\$	<i>Sn</i>	180.00	} X
1	Front Tyre Rim LH	\$	<i>Sn</i>	126.00	
1	Front left door sticker 'Trans-cab'	\$	<i>Nu</i>	80.00	<i>basu</i>
1	Rear rear door sticker '6555-3333'	\$	<i>Nu</i>	80.00	<i>basu</i>

Trans-cab Auto Services Pte Ltd

AAD1807-076

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9202J

TOTAL	\$	920.40
--------------	-----------	---------------

TOTAL PARTS	\$	15,359.89
--------------------	-----------	------------------

LABOUR

To Check Electrical Lighting Concerned.	\$	170.00	201
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	4,500.00	604
Putty and spray painting of the affected portion.	\$	4,000.00	10001
Towing Fees.	\$	~ 120.00	X
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	~ 380.00	X
To check steering geometry and computer wheel alignment	\$	~ 220.00	X
To transfer of tire, rim and on wheel balancing.	\$	~ 170.00	X
To rust-proofing of the affected areas.	\$	170.00	601
To check steering geometry and computer wheel alignment	\$	~ 220.00	X
To transfer of tire, rim and on wheel balancing.	\$	~ 170.00	X
To transfer of door fittings, attachment and perform water seepage test.	\$	170.00	1201

Trans-cab Auto Services Pte Ltd

AAD1807-076

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9202J

To transfer of fender fittings, attachment and
perform water seepage test.

\$ *nn* 170.00 X**TOTAL** \$ 10,460.00**Over All Total** \$ 25,819.89**Repair Days (Lump Sum)**~~15 days~~*4 days*



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18012673/Kqd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 18-10-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 7639B	Veh. Inspected	SHD 9202J	
Policy No.	D-18088937MFSH	Coverage (\$)	0.00	
Claim No.	D18005349MFSH	Excess (\$)	0.00	
Assign From	LURENE	Assign Date	11/07/2018	
2. Vehicle Particulars & Condition				
Make & Model	CHEVROLET EPICA (A)	c.c	1991	
Engine No.	HIDDEN	Year of Reg.	2011	
Chassis No.	KL1LA69RJBB058554	Colour	WHITE / RED	
Odometer	771663	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	GITI	9 mm	
L/H Front Tyre	195/65 R15	GITI	9 mm	
R/H Rear Tyre	195/65 R15	GITI	8 mm	
L/H Rear Tyre	195/65 R15	GITI	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	06/07/2018	Inspection Date	12/07/2018	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 9202J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT FENDER LH	TO REPAIR SEE LABOUR	837.60	-
1	FRONT FENDER LINER LH	SERVICEABLE	47.00	-
1	FRONT FENDER INNER WHEEL HOUSE PANEL LH	TO REPAIR SEE LABOUR	1,437.00	-
1	FRONT SHOCK ABSORBER ASSY LH	SERVICEABLE	216.17	-
1	FRONT SHOCK ABSORBER TOP MOUNTING LH	SERVICEABLE	48.32	-
1	FRONT LOWER ARM LH	SERVICEABLE	283.00	-
1	FRONT KNUCKLE ARM LH	SERVICEABLE	230.00	-
1	FRONT DOOR LH	BENT	1,133.00	1,133.00
1	FRONT DOOR GLASS GUIDE RH CHROME MOULDING	SERVICEABLE	60.00	-
1	FRONT DOOR OUTER MOULDING	SERVICEABLE	220.00	-
1	FRONT DOOR OUTER HANDLE	DENTED	125.00	125.00
1	FRONT DOOR HANDLE SUPPORT	SERVICEABLE	3.00	-
1	FRONT DOOR OUTER HANDLE INNER SEAL	SERVICEABLE	89.15	-
1	FRONT DOOR OUTER KEY LOCK	SERVICEABLE	25.00	-
1	FRONT DOOR HINGE UPPER	TO REPAIR SEE LABOUR	65.00	-
1	FRONT DOOR HINGE LOWER	TO REPAIR SEE LABOUR	65.00	-
1	FRONT DOOR INNER LOCK	TO REPAIR SEE LABOUR	586.00	-
1	FRONT DOOR INNER LOCK LATCH LH	TO REPAIR SEE LABOUR	206.00	-
1	FRONT DOOR CHECK/ARRESTOR	SERVICEABLE	67.50	-
1	FRONT DOOR WEATHERSTRIP LH	SERVICEABLE	138.79	-
1	FRONT DOOR GLASS CHANNEL WEATHERSTRIP	SERVICEABLE	160.00	-
1	FRONT DOOR INNER TRIM BOARD	SERVICEABLE	455.69	-
1	FRONT DOOR WINDOW GLASS	SERVICEABLE	456.12	-
1	FRONT DOOR POWER WINDOW MOTOR (MASTER) LH	SERVICEABLE	284.97	-
1	FRONT DOOR POWER WINDOW MOTOR SWITCH	SERVICEABLE	145.00	-
1	FRONT DOOR WINDOW REGULATOR GEAR LH	SERVICEABLE	84.58	-

Report Ref No. CS/FCI18012673/Kqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT DOOR OUTER PILLAR PANEL LH	TO REPAIR SEE LABOUR	715.00	-
1	FRONT DOOR PILLAR INNER PANEL LH	TO REPAIR SEE LABOUR	850.00	-
1	FRONT DOOR CENTER PILLAR PANEL LH	TO REPAIR SEE LABOUR	698.15	-
1	FRONT SIDE VIEW MIRROR ASSY LH	SERVICEABLE	1,191.00	-
1	REAR DOOR LH (PANEL A-RR DR LH)	BENT	1,133.00	1,133.00
1	REAR DOOR WEATHERSTRIP-INNER	SERVICEABLE	41.40	-
1	REAR DOOR WEATHERSTRIP-2ND FRAME	SERVICEABLE	25.90	-
1	REAR DOOR TOP HINGE	TO REPAIR SEE LABOUR	35.00	-
1	REAR DOOR BOTTOM HINGE	TO REPAIR SEE LABOUR	35.00	-
1	REAR DOOR INNER LOCK	TO REPAIR SEE LABOUR	425.00	-
1	REAR DOOR CHECK/ARRESTOR	TO REPAIR SEE LABOUR	65.00	-
1	REAR DOOR LOCK STRIKER-LATCH	TO REPAIR SEE LABOUR	120.00	-
1	REAR DOOR OUTER WEATHERSTRIP MOULDING	SERVICEABLE	85.00	-
1	SIDE ROCKER PANEL GARNISH LH	BUCKLED / DENTED	236.40	236.40
1	REAR FENDER LH	TO REPAIR SEE LABOUR	1,145.00	-
1	REAR FENDER INNER TRIM LH	SERVICEABLE	418.44	-
1	FRONT SIDE ROCKER PANEL GARNISH LH	SERVICEABLE	236.40	-
1	FRONT SIDE ROCKER PANEL OUTER LH	TO REPAIR SEE LABOUR	600.00	-
1	FRONT SIDE ROCKER PANEL INNER LH	TO REPAIR SEE LABOUR	519.30	-
	LESS 10% DISCOUNT		-1,604.39	-262.74
			14,439.49	2,364.66
	SPECIAL NETT ITEMS			
1	SET FRONT BUMPER FASTENER CLIP (SN)	NOT NECESSARY	24.00	-
1	SET FRONT LICENCE PLATE WITH HOLDER (SN)	SERVICEABLE	192.00	-
1	SET RADIATOR GRILLE CLIP (SN)	NOT NECESSARY	35.00	-

Report Ref No. CS/FCI18012673/Kqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET FRONT FENDER LINER CLIP (SN)	NOT NECESSARY	30.00	-
1	FRONT FENDER RR BRACKET LH (SN)	TO REPAIR SEE LABOUR	7.10	-
1	FRONT WHEEL RIM HUB CAP LH (SN)	SERVICEABLE	166.30	-
1	FRONT TYRE LH (SN)	SERVICEABLE	180.00	-
1	FRONT TYRE RIM LH (SN)	SERVICEABLE	126.00	-
1	FRONT LEFT DOOR STICKER "TRANS-CAB" (SN)	NECESSARY	80.00	60.00
1	REAR REAR DOOR STICKER "6555-3333" (SN)	NECESSARY	80.00	60.00
			920.40	120.00
	LABOUR			
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF FRONT FENDER LH,FRONT FENDER INNER WHEEL HOUSE PANEL LH. }		4,500.00	600.00
	FRONT DOOR HINGE UPPER,FRONT DOOR HINGE LOWER,FRONT DOOR INNER LOCK,FRONT DOOR INNER LOCK LATCH LH,FRONT DOOR OUTER PILLAR PANEL LH,FRONT DOOR PILLAR INNER PANEL LH,FRONT DOOR CENTER PILLAR PANEL LH,REAR DOOR TOP HINGE,REAR DOOR BOTTOM HINGE,REAR DOOR INNER LOCK,REAR DOOR CHECK/ARRESTOR,REAR DOOR LOCK STRIKER-LATCH,REAR FENDER LH,FRONT SIDE ROCKER PANEL OUTER LH,FRONT SIDE ROCKER PANEL INNER LH AND FRONT FENDER RR BRACKET LH. }		-	-
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		4,000.00	1,000.00
	TOWING FEES.	NOT NECESSARY	120.00	-
	TO DISMANTLE AND REFITFRONT END SUSPENSION,UNDERCARRIAGE PARTS,FINAL CHECKING AND TESTING.	NOT NECESSARY	380.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	60.00
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-

Report Ref No. CS/FCI18012673/Kqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO TRANSFER OF DOOR FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.		170.00	120.00
	TO TRANSFER OF FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
			10,460.00	1,800.00
GRAND TOTAL			25,819.89	4,284.66
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,450.00

Report Ref No. CS/FCI18012673/Kqd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.