

22/03/2002

ASS REC BY:

REF:

CS3 / ALG / 7016541 / Bv6-1

Special Instruction:

Paper Survey

SUTURDAY

ASSIGNMENT (Office)From (Person): Jadyn of Alh Date/Time: 12072018

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKG 11558P Insured: BLG 2749Uat Workshop m/s Twincor Automotul Tel: 6842 0051of 2 Kaki Bukit Ave 2 #01-17Policy No: _____ Claim No: 0809098611SG-003

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 25082017
(Client's Record)

CA / REV / REP. / REV 24 HRS (WP)

H.O.D. Endorsement: _____

Date/Time: 25082017 4:15pm Person Contacted: Hui Xin Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	SKG 11558P - NS / INCT 1500392 / KTHD1
	BLG 2749U X
	Dismantle Part: 30082017
	After repair: 06-09-2017

16/7/18 Submit LS \$6400 (Real 3300, 349) 5 days

RECEIVED 17 JUL 2018

Catherine Chong (LKK Auto)

From: Kesaval, Jaclyn-M <Jaclyn-M.Kesaval@aig.com>
Sent: Thursday, 12 July, 2018 10:49 AM
To: Admin A; Catherine Chong (LKK Auto); 'assignments'
Subject: Our ref: 0809098611SG-003; Urgent Paper RI
Attachments: 0809098611SG_11_07_2018_RULINGS_JUDGMENTS_SENTENCES_C62334 -001.pdf

Hi,

Please assist to urgent paper RI on third party vehicle as they are unagreeable to physical RI stating the reason that LKK has done 3 rounds of survey.

Attached is their survey report.

Pictures are in upload in merimen. Please let me know if you are unable to excess the documents in merimen.

Thank you.

Jaclyn M K
AIG
Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore(079120)

Tel +(65) 6419 1953 | Fax +(65) 6835 7416

Jaclyn-M.Kesaval@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

MOTORCAR (Rear)

Rear Portion

NAC	INC	Item	CON	ACQ
1137	993036	Rear Number Plate		
1138	993037	Rear Number Plate Base		
1139	993038	Rear Number Plate Garnish		
1140	993039	Rear Number Plate Lamp		
1141	993040	Rear Bumper	DD	
1142	993041	Rear Bumper Upper		
1143	993042	Rear Bumper Lower		
1144	993043	Rear Bumper Side	lower spoiler SR	
1145	993044	Rear Bumper Tow Cover (L/R)		
1146	993045	Rear Bumper Clips	NEC	
1147	993046	Rear Bumper Bracket		
1148	993047	Rear Bumper Side Reinforcer	MS	2
1149	993048	Rear Bumper Reinforcement	BT	
1150	993049	Rear Bumper Beam	DD	
1151	993050	Rear Bumper Sponges		
1152	993051	Rear Bumper Damper		
1153	993052	Rear Bumper Protector		
1154	993053	Rear Bumper Pad		
1155	993054	Rear Bumper Moulding		
1156	993055	Rear Bumper Reflector	CRA	
1157	993056	Rear Bumper Lower Spoiler		
1158	993057	Reverse Sensor	DM	
1159	993058	Rear End Panel		
1160	993059	Rear End Panel Top Garnish	DD	
1161	993060	Rear End Panel Inner Trim		
1162	993061	Boot Compartment Inner Trim		
1163	993062	Rear LH Taillamp	CRA	
1164	993063	Rear LH Taillamp Garnish		
1165	993064	Rear LH Taillamp Panel		
1166	993065	Rear RH Taillamp	CRA	
1167	993066	Rear RH Taillamp Garnish		
1168	993067	Rear RH Taillamp Panel		
1169	993068	Rear Apron Panel		
1170	993069	Bootlid		
1171	993070	Bootlid Emblem		
1172	993071	Bootlid Handle		
1173	993072	Bootlid Moulding		
1174	993073	Bootlid Reflector		
1175	993074	Bootlid Lamp LH		
1176	993075	Bootlid Lamp RH		
1177	993076	Bootlid Lock		
1178	993077	Bootlid Rubber		
1179	993078	Bootlid Hinge		
1180	993079	Bootlid Spoiler		
1181	993080	Tailgate	DD	
1182	993081	Tailgate Emblem (Logo/Model)	NEC	
1183	993082	Tailgate Outer Handle		
1184	993083	Tailgate Moulding		
1185	993084	Tailgate Garnish		
1186	993085	Tailgate Reflector		
1187	993086	Tailgate Lamp		
1188	993087	Tailgate Protector		
1189	993088	Tailgate Wiper Arm		
1190	993089	Tailgate Wiper Blade		
1191	993090	Tailgate Wiper Nozzle		
1192	993091	Tailgate Wiper Motor		
1193	993092	Tailgate Glass		
1194	993093	Tailgate Glass Rubber		
1195	993094	Tailgate Glass Moulding	NEC	
1196	993095	Tailgate Glass Sealant	NEC	
1197	993096	Tailgate Lock	BT	
1198	993097	Tailgate Rubber	NEC	
1199	993098	Tailgate Hinge		
1200	993099	Tailgate Damper		
1201	993100	Tailgate Inner Board		

Vehicle No. **SKG 4558 P**

NAC	INC	Item	CON	ACQ
1202	993101	Stare Tyre Board		
1203	993102	Stare Tyre Plate		
1204	993103	Stare Tyre		
1205	993104	Stare Tyre Lock Screw		
1206	993105	Stare Tyre Cover		
1207	993106	Thrust Breakdown Sp		
1208	993107	CD Charger Assy		
1209	993108	Antenna		
1210	993109	Centre Exhaust Pipe Assy		
1211	993110	Centre Exhaust Mounting		
1212	993111	Rear Exhaust Pipe		
1213	993112	Rear Exhaust Chrome Pipe		
1214	993113	Rear Exhaust Mounting		
1215	993114	Rear Exhaust Heat Shield		
1216	993115	Rear LH Chassis Member		
1217	993116	Rear RH Chassis Member		
1218	993117	Rear LH Fender		
1219	993118	Rear LH Fender Protector		
1220	993119	Rear LH Fender Inner Panel		
1221	993120	Rear LH Fender Inner Trim		
1222	993121	Rear LH Fender Inner Garnish		
1223	993122	Rear LH Fender Inner Shield		
1224	993123	Rear LH Mudflap		
1225	993124	Rear LH Wheel Rim		
1226	993125	Rear LH Rim Cover		
1227	993126	Rear LH Tyre		
1228	993127	Rear RH Fender		
1229	993128	Rear RH Fender Protector		
1230	993129	Rear RH Fender Inner Panel		
1231	993130	Rear RH Fender Inner Trim		
1232	993131	Rear RH Fender Inner Garnish		
1233	993132	Rear RH Fender Inner Shield		
1234	993133	Rear RH Mudflap		
1235	993134	Rear RH Wheel Rim		
1236	993135	Rear RH Rim Cover		
1237	993136	Rear RH Tyre		
1238	993137	Rear Fender Extension Panel LH		
1239	993138	Rear Fender Extension Panel RH		
1240	993139	Rear Fender Inner Top Garnish		
1241	993140	Rear Fender 1/4 Glass		
1242	993141	Rear Fender 1/4 Glass Rubber		
1243	993142	Rear Fender 1/4 Glass Sealant		
1244	993143	Rear Windscreen Glass		
1245	993144	Rear Windscreen Rubber		
1246	993145	Rear Windscreen Moulding		
1247	993146	Rear Windscreen Sealant		
1248	993147	Third Brake Light		
1249	993148	Rear Fender Air Grille		
1250	993149	Fuel Lid		
1251	993150	Fuel Neck		
1252	993151	Fuel Tank		
1253	993152	Fuel Tank Bracket		
1254	993153	Fuel Tank Floor		
1255	993154	Shocks		

No of Items:






Assessor:

[Signature]
 6/1/17

Claim Documents

***SKG4558P (0809098611SG)**
[SLG2779U]
TP
YONG CHEE KIONG
Aug 25 2017 9:00AM
[Pow Huat]
Twincar Automotive Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View					
												Use Viewer			▼					
Assessment Reports												1 per page			<input checked="" type="checkbox"/>					
No	Finalized On		AIG Asia Pacific Insurance Pte. Ltd. (SG)									Thumbnail			Print					
1	28/08/17 09:10		Accident Statement												Load HTM					
															From: SC - Reg. No: SLG2779U, Claimant: POW HUAT					
Photos/Images												3 per page			<input checked="" type="checkbox"/>					
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)									Thumbnail			Print					
1	25/09/17 17:44		Odometer Reading												Load JPG					
2	25/09/17 17:44		General View												Load JPG					
3	25/09/17 17:44		General View												Load JPG					
4	25/09/17 17:44		Chassis Number												Load JPG					
5	25/09/17 17:44		General View												Load JPG					
6	25/09/17 17:44		General View												Load JPG					
7	25/09/17 17:44		General View												Load JPG					
8	25/09/17 17:44		General View												Load JPG					
9	25/09/17 17:44		General View												Load JPG					
10	25/09/17 17:44		General View												Load JPG					
11	25/09/17 17:44		General View												Load JPG					
12	25/09/17 17:44		General View												Load JPG					
13	25/09/17 17:44		General View												Load JPG					
14	25/09/17 17:44		General View												Load JPG					
15	25/09/17 17:44		General View												Load JPG					
16	25/09/17 17:44		General View												Load JPG					
17	25/09/17 17:44		General View												Load JPG					
18	25/09/17 17:44		General View												Load JPG					
19	25/09/17 17:44		General View												Load JPG					
20	25/09/17 17:44		General View												Load JPG					
21	25/09/17 17:44		General View												Load JPG					
22	25/09/17 17:44		General View												Load JPG					
23	25/09/17 17:44		General View												Load JPG					
24	25/09/17 17:44		General View												Load JPG					
25	25/09/17 17:44		General View												Load JPG					
26	25/09/17 17:44		General View												Load JPG					
27	25/09/17 17:44		General View												Load JPG					
28	25/09/17 17:44		General View												Load JPG					
29	25/09/17 17:44		General View												Load JPG					
30	25/09/17 17:44		General View												Load JPG					
31	25/09/17 17:44		General View												Load JPG					
32	25/09/17 17:44		General View												Load JPG					
33	25/09/17 17:44		General View												Load JPG					
34	25/09/17 17:44		General View												Load JPG					

35	25/09/17 17:44	General View		Load JPG	
36	25/09/17 17:44	General View		Load JPG	
37	25/09/17 17:44	General View		Load JPG	
38	25/09/17 17:44	General View		Load JPG	
39	25/09/17 17:44	General View		Load JPG	
40	25/09/17 17:44	General View		Load JPG	
41	25/09/17 17:44	General View		Load JPG	
42	25/09/17 17:44	General View		Load JPG	
43	25/09/17 17:44	General View		Load JPG	
44	25/09/17 17:44	General View		Load JPG	
45	25/09/17 17:44	General View		Load JPG	
46	25/09/17 17:44	General View		Load JPG	
47	25/09/17 17:44	General View		Load JPG	
48	25/09/17 17:44	General View		Load JPG	
49	25/09/17 17:44	General View		Load JPG	
50	25/09/17 17:44	General View		Load JPG	
51	25/09/17 17:44	General View		Load JPG	
52	25/09/17 17:44	General View		Load JPG	
53	25/09/17 17:44	General View		Load JPG	
54	25/09/17 17:44	General View		Load JPG	
55	25/09/17 17:45	Photographs of Damaged Parts		Load JPG	
56	25/09/17 17:45	Photographs of Damaged Parts		Load JPG	
57	25/09/17 17:45	Photographs of Damaged Parts		Load JPG	
58	25/09/17 17:45	Photographs of Damaged Parts		Load JPG	
59	25/09/17 17:45	Photographs of Damaged Parts		Load JPG	
60	25/09/17 17:45	Photographs of Damaged Parts		Load JPG	
61	25/09/17 17:45	Photographs of Damaged Parts		Load JPG	
62	25/09/17 17:45	Photographs of Damaged Parts		Load JPG	
63	25/09/17 17:45	Photographs of Damaged Parts		Load JPG	
64	25/09/17 17:45	Photographs of Damaged Parts		Load JPG	
65	25/09/17 17:45	Photographs of Damaged Parts		Load JPG	
66	25/09/17 17:45	Photographs of Damaged Parts		Load JPG	
67	25/09/17 17:45	Photographs of Damaged Parts		Load JPG	
68	25/09/17 17:45	Photographs of Damaged Parts		Load JPG	
69	25/09/17 17:45	Photographs of Damaged Parts		Load JPG	
70	25/09/17 17:45	Photographs of Damaged Parts		Load JPG	
71	25/09/17 17:45	Photographs of Damaged Parts		Load JPG	
72	25/09/17 17:45	Photographs of Damaged Parts		Load JPG	
73	25/09/17 17:45	Photographs of Damaged Parts		Load JPG	
74	25/09/17 17:45	Photographs of Damaged Parts		Load JPG	
75	25/09/17 17:45	Photographs of Damaged Parts		Load JPG	
76	25/09/17 17:45	Photographs of Damaged Parts		Load JPG	
77	25/09/17 17:45	Photographs of Damaged Parts		Load JPG	
78	25/09/17 17:45	Photographs of Damaged Parts		Load JPG	
79	25/09/17 17:45	Photographs of Damaged Parts		Load JPG	
80	25/09/17 17:45	Photographs of Damaged Parts		Load JPG	
81	25/09/17 17:45	Photographs of Damaged Parts		Load JPG	
82	25/09/17 17:45	Photographs of Damaged Parts		Load JPG	
83	25/09/17 17:45	Photographs of Damaged Parts		Load JPG	
84	25/09/17 17:45	Photographs of Damaged Parts		Load JPG	
85	25/09/17 17:45	Photographs of Damaged Parts		Load JPG	

86	25/09/17 17:45	Photographs of Damaged Parts		Load JPG	
87	25/09/17 17:45	Photographs of Damaged Parts		Load JPG	
88	25/09/17 17:45	Photographs of Damaged Parts		Load JPG	
89	25/09/17 17:45	Photographs of Damaged Parts		Load JPG	
90	25/09/17 17:45	Photographs of Damaged Parts		Load JPG	
91	25/09/17 17:45	Photographs of Damaged Parts		Load JPG	
92	25/09/17 17:45	Photographs of Damaged Parts		Load JPG	
93	25/09/17 17:45	Photographs of Damaged Parts		Load JPG	
94	25/09/17 17:45	Photographs of Damaged Parts		Load JPG	
95	25/09/17 17:45	Photographs of Damaged Parts		Load JPG	
96	25/09/17 17:45	Photographs of Damaged Parts		Load JPG	
97	25/09/17 17:45	Photographs of Damaged Parts		Load JPG	
98	25/09/17 17:45	Photographs of Damaged Parts		Load JPG	
99	25/09/17 17:45	Photographs of Damaged Parts		Load JPG	
100	25/09/17 17:45	Photographs of Damaged Parts		Load JPG	
101	25/09/17 17:45	Photographs of Damaged Parts		Load JPG	
102	25/09/17 17:45	Photographs of Damaged Parts		Load JPG	
103	25/09/17 17:45	Photographs of Damaged Parts		Load JPG	
104	25/09/17 17:46	Photo After Spray		Load JPG	
105	25/09/17 17:46	Photo After Spray		Load JPG	
106	25/09/17 17:46	Photo After Spray		Load JPG	
107	25/09/17 17:46	Photo After Spray		Load JPG	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG17016541/WBE2

Date: 08/11/2017

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100482521
Claimant Vehicle No :	SKG4558P	Insured Vehicle No :	SLG2779U
Date of Loss:	25/08/2017	Nature of Claim:	TP
		Claim No:	0809098611SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKG4558P	Engine No:	LF10504911
Make & Model:	MAZDA 5, 2.0 (A)	Chassis No:	JM6CR10F280303039
Reg. Date:	06/06/2008 (Man. Year: 2008)	Odometer:	100839 km
Colour:	Red		
Engine Capacity:	1999 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Goodyear 3 mm	Rear Left Side:	Goodyear 4 mm
Front Right Side:	Goodyear 3 mm	Rear Right Side:	Goodyear 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	25/08/2017	
Date Inspected:	30/08/2017	Inspected At: Twincar Automotive Pte Ltd (HQ) 2 KAKI BUKIT AVEUNE 2 #01-17 Singapore 417921
Estimated Period of Repair:	4.0 days	

Adjuster: Teo Cheng Ming Wilson

Manager: CATHERINE CHONG KAI LING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	0.00 F	*-F
2	1		*REAR BUMPER SIDE LOWER SPOILER	Scratched	0.00 F	*-F
3	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*-F
4	2		*REAR BUMPER SIDE RETAINER	Distorted	0.00 F	*-F
5	1		*REAR BUMPER REINFORCEMENT	Bent	0.00 F	*-F
6	1		*REAR BUMPER BEAM	Dented	0.00 F	*-F
7	1		*REAR BUMPER REFLECTOR	Cracked	0.00 F	*-F
8	1		*REVERSE SENSOR	Damaged	0.00 F	*-F
9	1		*REAR END PANEL TOP GARNISH	Dented	0.00 F	*-F
10	1		*REAR LH TAILLAMP	Cracked	0.00 F	*-F
11	1		*REAR RH TAILLAMP	Cracked	0.00 F	*-F
12	1		*TAILGATE	Dented	0.00 F	*-F
13	1		*TAILGATE EMBLEM LOGO MAZDA 5	Necessary	0.00 F	*-F
14	1		*TAILGATE GLASS MOULDING	Necessary	0.00 F	*-F
15	1		*TAILGATE GLASS SEALANT	Necessary	0.00 F	*-F
16	1		*TAILGATE LOCK	Bent	0.00 F	*-F
17	1		*TAILGATE RUBBER	Necessary	0.00 F	*-F

F=Franchise part

Total Parts (S\$)	0.00	0.00
--------------------------	-------------	-------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >

Constant Appraiser Services

Qualified Automobile Accident Damage Appraisers/Loss Adjusters

Blk 2 Rivervale Link, #09-02 Singapore 545040

Tel/Fax: 6886 1106 Mobile: 9007 5234

Email: constant_as@yahoo.com.sg

RCB No. 53138015K

Automobile Inspection Report

To: Yong Chee Kiong
Blk 171 Toa Payoh Lor 1
#18-1130
Singapore 310171

Date : 26/03/2018

Reference No : CAS/18-03/062

General Information

Registration No. : SKG 4558P
Accident Date : 25/08/2017

Particulars of Damaged Vehicle

Colour	: Red	Make & Model	: Mazda 5
Engine Capacity	: 1999 cc	Pre-Accident Condition	: Good
Mileage (KM)	: 100840	Engine No.	: LF10504911
Chassis No.	: JM6CR10F280303039	Steering	: In Order
Registration Date	: 06/06/2008	Brake	: In Order

Tyre Condition

	Size	Make	Balance
R/H Front Tyre	205/55R16	GOODYEAR	80%
L/H Front Tyre	205/55R16	GOODYEAR	80%
R/H Rear Tyre	205/55R16	GOODYEAR	80%
L/H Rear Tyre	205/55R16	GOODYEAR	80%

Inspection

Repairer : Twincar Automotive Pte Ltd
2 Kaki Bukit Ave 2, #01-17 Kaki Bukit Autohub, Singapore 417921

Adjustment And Recommendation Cost Of Repair

Repairer's Estimate : \$12,754.20
Revised Amount : \$9,700.00
Less Excess : -
Nett Total : \$9,700.00

Remarks

- (A) Survey was done on 30/08/2017
- (B) Re-survey was done on 30/08/2017
- (C) Re-survey after repair was done on 06/09/2017
- (D) The survey was conducted entirely on WITHOUT PREJUDICE basis.
- (E) We have NOT given any instruction to authorize the repair of the vehicle.

NOTE: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage/item in this survey, kindly notified the company within 7 (seven) days from the date hereof. Otherwise, the revised amount shall be deemed to be valid.

Constant Appraiser Services

Vehicle No : SKG 4558P

Our ref : CAS/18-03/062

Adjustment On Repair Costs And Replacement Of Parts:

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)	
<u>PARTS REPLACEMENT – LIST ITEMS</u>						
1	1pc	Rear bumper	Dented/Broken	1,870.00	1,870.00 ^{915.40}	DD ✓
2	4pcs	Rear bumper center bracket @ \$46.00	Broken	184.00	184.00	BR ✓
3	4pcs	Rear bumper center bracket holder @ \$42.00	Necessary	168.00	168.00	NEC ✓
4	2pcs	Rear bumper lower spoiler L/R @ \$460.00	Broken	920.00	920.00	BR ✓
5	2pcs	Rear bumper reflector L/R @ \$47.30 ^{35.00}	Broken	94.60	94.60 ^{70.00}	BR ✓
6	1pc	Rear bumper reinforcement	Dented/Twisted	137.00	137.00	DT ✓
7	2pcs	Rear bumper side retainer L/R @ \$33.00	Necessary	66.00	66.00	NEC ✓
8	1pc	Rear end panel	Dented/Warped	586.00	586.00	RX
9	1pc	Rear end panel inner top garnish	Deformed	97.90	97.90	CHT ✓
10	1pc	Rear tailgate	Dented/Warped	2,827.50	2,827.50	DD ✓
11	1pc	Rear tailgate '5' emblem	Necessary	25.80	25.80	NEC ✓
12	1pc	Rear tailgate 'logo' emblem	Necessary	58.00	58.00	NEC ✓
13	1pc	Rear tailgate 'mazda' emblem	Necessary	33.00	33.00	NEC ✓
14	2pcs	Rear tailgate damper L/R @ \$149.00	Bent/Jammed	298.00	298.00	SVC X
15	2pcs	Rear tailgate hinges L/R @ \$43.00	Repair	86.00	-	
16	1pc	Rear tailgate mechanism lock	Bent/Jammed	289.00	289.00	BT ✓
17	1pc	Rear tailgate mechanism lock striker	Bent	26.00	26.00	BT ✓
18	1pc	Rear tailgate mechanism lock striker cover	Serviceable	18.20	-	
19	4pcs	Rear tailgate rubber guide stopper L/R @ \$21.00	Necessary	84.00	84.00	NEC ✓
20	1pc	Rear tailgate weather strip	Distorted	131.00	131.00	DIS ✓
21	2pcs	Rear taillamp back rubber seal L/R @ \$43.00 ^{30.00}	Necessary	86.00	86.00 ^{60.00}	NEC ✓
22	2pcs	Rear taillamp L/R @ \$1,171.00 ^{672.20}	Cracked/Broken	2,342.00	2,342.00 ^{1344.40}	CRA ✓
23	1pc	Rear tool tray garnish	Serviceable	321.00	-	
				10,749.00	10,323.80	7435.80
Less 20%				(2,149.80)	(2,064.76)	1487.16
Sub total				8,599.20	8,259.04	5948.61
<u>PARTS REPLACEMENT – SPECIAL NETT ITEMS</u>						
1	1set	Rear bumper clips – set	Necessary	30.00	30.00	NEC ✓
2	1set	Rear bumper reverse sensor – set	Damaged	350.00	250.00 ²⁰⁰	CRA ✓
3	1set	Rear end panel inner top garnish clips – set	Necessary	30.00	30.00	NEC ✓
4	1pc	Rear number plate	Dented/Grazed	25.00	25.00	NNX

Constant Appraiser Services

Vehicle No : SKG 4558P

Our ref : CAS/18-03/062

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)	
<u>PARTS REPLACEMENT – SPECIAL NETT ITEMS (CONT'D)</u>						
5	1pc	Rear number plate holder	Twisted	50.00	30.00	NNX
6	1pc	Rear tailgate windscreen sealant	Necessary	100.00	50.00 100.00	NECV
7	2sets	Rear taillamp clips L/R – set @ \$30.00 25.00	Necessary	60.00	50.00 60.00	NECV
Sub total				9,244.20	8,784.04	
<u>LABOUR & MISC. CHARGES</u>						
1		To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor		100.00	50.00 80.00	✓
2		To remove, reinstall tailgate windscreen		300.00	100.00 150.00	✓
3		To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)		140.00	100.00 120.00	✓
4		To re-spray painting on the rear bootlid, rear end panel, rear fender (L/R); spare tyre panel and rear bumper		1,500.00	800.00 1,200.00	✓
5		To remove and reinstall exhaust pipe		150.00	-	
6		To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident		1,200.00	600 800.00 1,000.00	✓
7		To apply anti-rust chemical on repaired and replaced panel		120.00	60.00 90.00	✓
Grand total				12,754.20	11,424.04	8268.6
Recommended cost of lump sum repair (To its pre-accident condition)					9,700.00	6600.0

L/S 6600/2
 repair days 4 days 5 days

Constant Appraiser Services

Vehicle No : SKG 4558P

Our ref : CAS/18-03/062

Adjustment/Recommendations

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a lump sum of **\$9,700.00** on a contractual basis. Under normal circumstances, the repair period would be about **8 (Eight)** working days.

Yours faithfully,

Constant Appraiser Services



Lim Yong Tian (Sebastian)

Licensed Appraiser

Adv. Dip. In Mechanical Engineering (AUS)

MSAAA




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CS3/AIG17016541/Bvbe2-1		
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 17-07-2018		
		Code : AIG		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLG 2779U	Veh. Inspected	SKG 4558P	
Policy No.		Coverage (\$)	0.00	
Claim No.	0809098611SG-003	Excess (\$)	0.00	
Assign From	JACLYN	Assign Date	12/07/2018	
2. Vehicle Particulars & Condition				
Make & Model	MAZDA 5	c.c	1999	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	JM6CR10F280303039	Colour	RED	
Odometer	100839	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	GOODYEAR	3 mm	
L/H Front Tyre	205/55 R16	GOODYEAR	3 mm	
R/H Rear Tyre	205/55 R16	GOODYEAR	4 mm	
L/H Rear Tyre	205/55 R16	GOODYEAR	4 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	25/08/2017	Inspection Date	30/08/2017	
Survey held at	TWINCAR AUTOMOTIVE PTE LTD 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKG 4558P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DENTED	1,870.00	915.40
4	REAR BUMPER CENTER BRACKET @\$46.00	BROKEN	184.00	184.00
4	REAR BUMPER CENTER BRACKET HOLDER @\$42.00	NECESSARY	168.00	168.00
2	REAR BUMPER LOWER SPOILER L/R @\$460.00	BROKEN	920.00	920.00
2	REAR BUMPER REFLECTOR L/R @\$47.30	BROKEN	94.60	70.00
1	REAR BUMPER REINFORCEMENT	DENTED	137.00	137.00
2	REAR BUMPER SIDE RETAINER L/R @\$33.00	NECESSARY	66.00	66.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	586.00	-
1	REAR END PANEL INNER TOP GARNISH	CUT	97.90	97.90
1	REAR TAILGATE	DENTED	2,827.50	2,827.50
1	REAR TAILGATE '5' EMBLEM	NECESSARY	25.80	25.80
1	REAR TAILGATE 'LOGO' EMBLEM	NECESSARY	58.00	58.00
1	REAR TAILGATE 'MAZDA' EMBLEM	NECESSARY	33.00	33.00
2	REAR TAILGATE DAMPER L/R @\$149.00	SERVICEABLE	298.00	-
2	REAR TAILGATE HINGES L/R @\$43.00	TO REPAIR SEE LABOUR	86.00	-
1	REAR TAILGATE MECHANISM LOCK	BENT	289.00	289.00
1	REAR TAILGATE MECHANISM LOCK STRIKER	BENT	26.00	26.00
1	REAR TAILGATE MECHANISM LOCK STRIKER COVER	SERVICEABLE	18.20	-
4	REAR TAILGATE RUBBER GUIDE STOPPER L/R @\$21.00	NECESSARY	84.00	84.00
1	REAR TAILGATE WEATHER STRIP	DISTORTED	131.00	131.00
2	REAR TAILLAMP BACK RUBBER SEAL L/R @\$43.00	NECESSARY	86.00	60.00
2	REAR TAILLAMP L/R @\$1171.00	CRACKED	2,342.00	1,344.40
1	REAR TOOL TRAY GARNISH	SERVICEABLE	321.00	-
	LESS 20% DISCOUNT		-2,149.80	-1,487.40
			8,599.20	5,949.60
SPECIAL NETT ITEMS				
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	30.00	30.00
1	SET REAR BUMPER REVERSE SENSOR (SN)	CRACKED	350.00	200.00
1	SET REAR END PANEL INNER TOP GARNISH CLIPS (SN)	NECESSARY	30.00	30.00

Report Ref No. CS3/AIG17016541/Bvbe2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	25.00	-
1	REAR NUMBER PLATE HOLDER (SN)	NOT NECESSARY	50.00	-
1	REAR TAILGATE WINDSCREEN SEALANT (SN)	NECESSARY	100.00	50.00
2	SETS REAR TAILLAMP CLIPS L/R @\$30.00	NECESSARY	60.00	50.00
			645.00	360.00
	LABOUR			
	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING AND REWIRE FOR PARKING SENSOR.		100.00	50.00
	TO REMOVE, REINSTALL TAILGATE WINDSCREEN.		300.00	100.00
	TO REMOVE, REINSTALL ROOF TOP TRIM UPHOLSTERY, CUSHION SEAT, TRIM GARNISH, TRIM LINER CARPET. (TO FR).		140.00	100.00
	TO RE-SPRAY PAINTING ON THE REAR BOOTLID, REAR END PANEL, SPARE TYRE PANEL AND REAR BUMPER.		1,500.00	800.00
	TO REMOVE AND REINSTALL EXHAUST PIPE.	NOT NECESSARY	150.00	-
	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF REAR END PANEL AND REAR TAILGATE HINGES L/R.		1,200.00	600.00
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.		120.00	60.00
			3,510.00	1,710.00
GRAND TOTAL			12,754.20	8,019.60
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				6,400.00

Report Ref No. CS3/AIG17016541/Bvbe2-1

LIM TEOW GUAN

Asst. Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.