



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBH 2091H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER (WCP) (CONSISTENT)	DEFORMED	660.00	660.00
1	FRT BUMPER BRKT KIT (WCP) (CONSISTENT)	NECESSARY	50.00	50.00
1	FRT LWR IMPACT DAMP (WCP) (CONSISTENT)	NOT NECESSARY	140.00	-
1	FRT BUMPER C-MEMBER (WCP) (CONSISTENT)	NOT NECESSARY	280.00	-
1	FRONT BUMPER DAMPING (WCP) (CONSISTENT)	NOT NECESSARY	70.00	-
1	FRT GRILLE MOULDING (WCP) (CONSISTENT)	NOT NECESSARY	200.00	-
1	GRILLE (WCP) (CONSISTENT)	NOT NECESSARY	200.00	-
1	GRILLE MOULDING (WCP) (CONSISTENT)	NOT NECESSARY	120.00	-
1	FRT BUMPER SUPPORT (WCP) (CONSISTENT)	BROKEN	200.00	200.00
1	RAD GRILLE BADGE (WCP) (CONSISTENT)	NOT NECESSARY	50.00	-
1	RIGHT HEADLAMP ASSY (WCP) (CONSISTENT)	SCRATCHED	350.00	350.00
1	SET FRT BUMPER TRIM (WCP) (CONSISTENT)	SCRATCHED	140.00	140.00
1	R/F REPEATED LAMP (WCP) (CONSISTENT)	CRACKED	30.00	30.00
1	R/F WING (WCP) (CONSISTENT)	BUCKLED	200.00	200.00
1	FRONT WING MNTG KIT (WCP) (CONSISTENT)	NECESSARY	50.00	50.00
1	R/F LWR WING BRACKET (WCP) (CONSISTENT)	BENT	50.00	50.00
1	R/F UPPER WING MLDG (WCP) (CONSISTENT)	NOT NECESSARY	80.00	-
1	R/F WHEELHOUSE COVER (WCP) (CONSISTENT)	DEFORMED	85.00	85.00
1	FRONT PART (WCP) (CONSISTENT)	NOT NECESSARY	220.00	-
1	R/UPPER FRONT PANEL (WCP) (CONSISTENT)	NOT NECESSARY	70.00	-
1	WASHER RESERVOIR (WCP) (CONSISTENT)	DEFORMED	140.00	140.00
1	RIGHT FRONT DOOR (WCP) (CONSISTENT)	TO REPAIR SEE LABOUR	880.00	-
1	R/F DOOR MOULDING (WCP) (CONSISTENT)	NOT NECESSARY	85.00	-
1	R/F TRACK CONT ARM (WCP) (CONSISTENT)	BENT	230.00	230.00
1	R/F BALL JOINT (WCP) (CONSISTENT)	NECESSARY	45.00	45.00
1	R/F STEERING KNUCKLE (WCP) (CONSISTENT)	BENT	460.00	460.00
1	R/F SHOCK ABSORBER (WCP) (CONSISTENT)	BENT	230.00	230.00
1	R/F S-ABS BRKT (WCP) (CONSISTENT)	NECESSARY	50.00	50.00
1	R/F STRUT BEARING (WCP) (CONSISTENT)	NECESSARY	35.00	35.00
1	R/S-ABSORB BOOT (WCP) (CONSISTENT)	NECESSARY	23.00	23.00

Report Ref No. CC4/ASM18012689/Gga3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	R/F SUSPN BUFFER (WCP) (CONSISTENT)	NECESSARY	35.00	35.00
1	R/F WHEEL (WCP) (CONSISTENT)	BENT	180.00	180.00
1	R/F WHEEL COVER (WCP) (CONSISTENT)	CUT	65.00	65.00
1	R/RADIATOR AIR GUIDE (WCP) (CONSISTENT)	NOT NECESSARY	60.00	-
1	R/F WHEEL BEARING (WCP) (CONSISTENT)	NECESSARY	170.00	170.00
1	R/F BEARING HUB (WCP) (CONSISTENT)	NECESSARY	230.00	230.00
	COST PLUS 15%		924.45	556.20
			7,087.45	4,264.20
	<u>SPECIAL NETT ITEMS</u>			
1	AUDATEX FEE (SN)(CONSISTENT)	NECESSARY	42.00	42.00
1	ANTIFREEZE 4 LTR (SN)(CONSISTENT)	NOT NECESSARY	48.00	-
1	TOP UP AIRCON GAS (SN)(CONSISTENT)	NOT NECESSARY	100.00	-
1	R/F DOOR ROC STICKER (SN)(CONSISTENT)	NECESSARY	25.00	25.00
1	R/F TYRE (SN)(CONSISTENT)	PUNCTURE	320.00	320.00
			535.00	387.00
	<u>LABOUR</u>			
	WHEEL ALIGNMENT.		100.00	100.00
	TOWING FEE.		60.00	60.00
	PANEL /MECHANICAL.INCLUSIVE OF THE REPAIR OF RIGHT FRONT DOOR .		922.50	684.00
	PAINTWORK.		607.50	607.50
	PAINT/MATERIAL COSTS.		277.69	239.39
			1,967.69	1,690.89
GRAND TOTAL			9,590.14	6,342.09
RECOMMENDED COST OF REPAIRS				6,342.09

Report Ref No. CC4/ASM18012689/Gga3q2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.